

Surveyor
Merimen

Marcus

ASSIGNMENT (Office)

From (Person)

Eliza Ho

of

MSG

Date/Time

11/4/18 @ 9:31am

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGU 96801

Insured:

at Workshop m/s

Tan lim Motor

Tel:

6858 5151

of

51 Defu Lane 10

Policy No:

B28951086QMX

Claim No:

555098

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

07/04/2018

CA / ☒ REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:15am @ 11/4/18

Person Contacted:

Caymen

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

11/4-

SGU 96801 -X

Report to merimen

12/4-

authorise repair by kenny ong

12/4-

11:40 pm inform caymen authorise repair excess \$500/-

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

00 / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGU9680Jat Workshop m/s Tarkun

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 27k.

IDAC Accident Report: _____ Consistent? : Yes or No

QA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or NoLum Sum: 131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Date / Time Action / Instruction LTA 20947Veh No: SGU9680J Yr Regn: 5-1 07Type: LM.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: Toyota Corolla AHIS o.c. 1598Colour: Gold A/C: Insured / Std / NI / NASp. Reading: 63627 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0537EC107148948Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/70R14 mic

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 7/4/18 D.O.A. 11/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Int.

The U/C / Chassis frame / Body Structure affected due to collision.

26/4/18 confirmed final by 733.75 with willian. (Red: 1231.50 : 62%)

RECEIVED 30 APR 2018

Date/Time, File Pass to?

1) 3014 Typist

Date/Time, File Return to?

2) _____

Report Format: 00Lump Sum / I.B.I: (\$) 733.75Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RG \$

Photos

Others

TOTAL

150

10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2018 12:57 Sendback Est	10 Apr 2018 15:12 S\$1,965.25	11 Apr 2018 09:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NG ATI @ NG BOON SENG, ID: S2098400G		
Vehicle Reg. No.:	SGU9680J	Date of Loss:	07/04/2018 17:00 - :59 [130 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	B28951086QMX (Comprehensive) Coverage: 08/05/2017 - 07/05/2018
		Excess:	S\$500.00
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/04/2018]		
Driver/Custodian:	NG TECK GUAN (40 / Male), NRIC: S7727139B		
		Vehicle Source:	Drive/Walk-In
Adj Asg. Remarks:	REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18006653/Utd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 11-04-2018		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SGU 9680J
Policy No.	B28951086QMX	Coverage (\$)		0.00
Claim No.	555098	Excess (\$)		0.00
Assign From	MERIMEN (ELIZA HO)	Assign Date		11/04/2018
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	07/04/2018	Inspection Date	11/04/2018	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

View Received Message

This mail is associated with :

SGU9680J (555098)

OD

Apr 7 2018 5:00PM

[NG ATI @ NG BOON SENG]

Tan Lim Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 12/04/2018 10:34 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$733.75) - SGU9680J - Claim Handler: Eliza Ho Teng Boon

Approved:733.75:A IF C

DOCUMENTS SUMMARY

There are no documents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8400G
Vehicle Details	
Vehicle No.:	SGU9680J
Vehicle to be Exported:	No
Intended De-registration Date:	11 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Beige
Manufacturing Year:	2007
Engine No.:	3ZZ4661679
Chassis No.:	MR053ZEC107148948
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$14,924.00
Original Registration Date:	30 May 2007
First Registration Date:	30 May 2007
Transfer Count:	1
Actual ARF Paid:	\$13,425.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,333.00
COE Rebate Amount:	\$20,933.00
Total Rebate Amount:	\$20,933.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 11 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8400G

Vehicle Details

Vehicle No.: SGU9680J
Vehicle to be Exported: Yes
Intended De-registration Date: 10 Apr 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA ALTIS 1.6 AUTO
Primary Colour: Beige
Manufacturing Year: 2007
Engine No.: 3ZZ4661679
Chassis No.: MR053ZEC107148948
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$14,924.00
Original Registration Date: 30 May 2007
First Registration Date: 30 May 2007
Transfer Count: 1
Actual ARF Paid: \$13,425.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 29 May 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$25,333.00
COE Rebate Amount: \$20,947.00
Total Rebate Amount: \$20,947.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Apr 2018

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD004042018
Policy No:	B28951086QMX	Date of Loss:	07/04/2018
Vehicle Reg. No.:	SGU9680J	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG ATI @ NG BOON SENG		
Driver:	NG TECK GUAN		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	30/05/2007
Vehicle Colour:	BEIGE		
Engine No:	3ZZ4661679	Chassis No:	MR053ZEC107148948
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	TAN LIM MOTOR PTE LTD (DEFU)		

Not Authorized
Halt
EXPASS \$500
1/1/4/1/8
Who photo before repair.
P/P \$
3 day.

COST OF CLAIMS

	Amount
Parts	715.25
Miscellaneous Items	0.00
Labour	800.00
Paintwork Labour	450.00
Towing	0.00
Calculated Gross Total (S\$)	1,965.25
- Excess (S\$)	500.00
(S\$)	1,465.25
+ GST 7.00% (S\$)	102.57
Nett Amount (S\$)	1,567.82

This claim is handled by: SAM LOW PUI MUN

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Apr 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Tan Lim Motor Pte Ltd/SGU9680J/10/04/2018 15:12

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*n/s front fender <i>B-1500</i>	0.00	0.00	*90.00 F ✓
2	1		*front fender inner liner <i>70.0</i>	0.00	0.00	*15.00 F ✓
3	5		*front fender inner liner clips <i>see</i>	0.00	0.00	*7.50 F ✓
4	1		*n/s front fender indication light <i>11</i>	0.00	0.00	*15.00 F X
5	1		*front fender indication light chrome garnish <i>11</i>	0	0.00	*50.00 FS X
6	1		*front fender 1/4 garnish <i>11</i>	0.00	0.00	*15.00 F X
7	1		*n/s front wheel rim <i>147 012</i>	0	0.00	*250.00 FS X
8	1		*front shock absorber <i>11</i>	0.00	0.00	*75.00 F q
9	1		*front shock absorber top mount <i>11</i>	0.00	0.00	*50.00 F q
10	1		*front wheel bearing <i>11</i>	0.00	0.00	*40.00 F q
11	1		*front wheel bearing hub <i>11</i>	0.00	0.00	*70.00 F X

F=Franchise part. S=SpcNett.

Sub Total (S\$)	677.50
+ Margin on L,N Items 10.00% (S\$)	37.75
Total Parts (S\$)	715.25

Tan Lim Motor Pte Ltd/SGU9680J/10/04/2018 15:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1-112.5
102
123.75
733.75

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Putty and spray painting of the affected portion.	New	350 450.00
Labour Items			
2	To check steering geometry and computer wheel alignment.	New	60 120.00
3	To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	New	11X 250.00
4	To transfer of n/s front wheel rim and on wheel balancing.	New	11X 30.00
5	Panel beating, knocking and straighten the n/s front fender wheel house panel, remove and renewal of parts, adjust and realign the same.	New	200 400.00
Gross Labour Cost (S\$)			1,250.00

Tan Lim Motor Pte Ltd/SGU9680J/10/04/2018 15:12. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216

Tel : 6858 5151 (24 hours) Fax : 6858 0877

email@tlmotor.com.sg www.tlmotor.com.sg

Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD004042018
Policy No:	B28951086QMX	Date of Loss:	07/04/2018
Vehicle Reg. No.:	SGU9680J	Driveable?	
Driver Age/Info:	40 / MALE	Party At Fault:	DRIVER
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG ATI @ NG BOON SENG		
Driver:	NG TECK GUAN		

Make/Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Vehicle Reg. Date:	30/05/2007
Vehicle Colour:	BEIGE	Chassis No:	MR053ZEC107148948
Engine No:	3ZZ4661679		
Odometer:	0 KM		

Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		

Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	TAN LIM MOTOR PTE LTD (DEFU)		

*NOT Authorized
Halt
Excess \$500
1/1/18
The whole company
P/P
3 day.*

COST OF CLAIMS

	Amount
Parts	715.25
Scellaneous Items	0.00
Labour	800.00
Paintwork Labour	450.00
Towing	0.00
Calculated Gross Total (S\$)	1,965.25
- Excess (S\$)	500.00
(S\$)	1,465.25
+ GST 7.00% (S\$)	102.57
Nett Amount (S\$)	1,567.82

This claim is handled by: SAM LOW PUI MUN

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Apr 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Tan Lim Motor Pte Ltd/SGU9680J/10/04/2018 15:12

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*n/s front fender 3-6507	0.00	0.00	*90.00 F
2	1		*front fender inner liner 70.7	0.00	0.00	*15.00 F
3	5		*front fender inner liner clips 11	0.00	0.00	*7.50 F
4	1		*n/s front fender indication light 11	0.00	0.00	*15.00 F X
5	1		*front fender indication light chrome garnish 11	0	0.00	*50.00 FS X
6	1		*front fender 1/4 garnish 11	0.00	0.00	*15.00 F X
7	1		*n/s front wheel rim 147 012	0	0.00	*250.00 FS X
8	1		*front shock absorber 11	0.00	0.00	*75.00 F q
9	1		*front shock absorber top mount 11	0.00	0.00	*50.00 F q
10	1		*front wheel bearing 11	0.00	0.00	*40.00 F q
11	1		*front wheel bearing hub 11	0.00	0.00	*70.00 F X

F=Franchise part, S=SpaNett.

Sub Total (S\$) 677.50

+ Margin on L,N Items 10.00% (S\$) 37.75

Total Parts (S\$) 715.25

Tan Lim Motor Pte Ltd/SGU9680J/10/04/2018 15:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	Putty and spray painting of the affected portion.	New	350 450.00
<u>Labour Items</u>			
2	To check steering geometry and computer wheel alignment.	New	60 120.00
3	To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	New	11X 250.00
4	To transfer of n/s front wheel rim and on wheel balancing.	New	11X 30.00
5	Panel beating, knocking and straighten the n/s front fender wheel house panel, remove and renewal of parts, adjust and realign the same.	New	200 400.00
Gross Labour Cost (S\$)			1,250.00

Tan Lim Motor Pte Ltd/SGU9680J/10/04/2018 15:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: TAN LIM MOTOR PTE LTD**

51 DEFU LANE 10

SINGAPORE 539216

ZZE121TH (SGU 9680J)

ATT:AH HWA

NO: DLI9202165

PAGE: 1

DATE: 19/04/2018

A/C CODE: LDTL178

TERMS: CR

P/O NO: SGU 9680J

Mo 90271

OD 201804004

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 1812-1H020-1	FENDER FR LH	DB1D24	1	90.00	90.00
2 T53876-02130	FENDER LINER FR LH	DBEE21	1	15.00	15.00
3 T90467-07166	CLIP,FENDER LINER	DD1AS3-6	5	1.50	7.50
TOTAL QUANTITY:			7	TOTAL	SIN 112.50
				ADD GST @ 7%	7.88
				GRAND TOTAL	SIN 120.38

Print / YAM / 19/04/2018 9:06:28 AM

SALESMAN: YAM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



E. & O. E.
PARTS

GOODS RECEIVED BY



4) Goods supplied

No. 51 Defu Lane 10 Singapore 539216
Tel: 6858 5151 (24 hours) Fax: 6858 0877
email@tlimotor.com.sg
GST Regn. No.: M2-8922054-2

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18006653/UTD3N2

Date: 02/05/2018

REFERENCE

Insured/Claimant: NG ATI @ NG BOON SENG Policy No: B28951086QMX
Date of Loss: 07/04/2018 Nature of Claim: OD Claim No: 555098

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGU9680J
Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4661679
Reg. Date: 30/05/2007 (Man. Year: 2007) Chassis No: MR053ZEC107148948
Colour: Gold Odometer: 63627 km
Engine Capacity: 1598 cc
Market Value/New Car Price: S\$27,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70R14 Rear Tyre Size: 185/70R14
Front Left Side: Michelin 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	715.25	123.75	591.50	82.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	260.00	540.00	67.50
Paintwork Labour	450.00	350.00	100.00	22.22
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,965.25	733.75	1,231.50	62.66
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	1,465.25	233.75	1,231.50	84.05
+ GST 7.00/7.00% (S\$)	102.57	16.36	86.21	84.05
Nett Amount (S\$)	1,567.82	250.11	1,317.71	84.05

INSPECTION

Date of Assignment: 11/04/2018 Present Location: Tan Lim Motor Pte Ltd (Defu)
Date Inspected: 11/04/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
51 Defu Lane 10
Singapore 539216

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 May 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGU9680J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*n/s front fender (WCP)	Badly Dented	90.00 F	*90.00 F
2	1	*front fender inner liner (WCP)	Torn	15.00 F	*15.00 F
3	5	*front fender inner liner clips (WCP)	Necessary	7.50 F	*7.50 F
4	1	*n/s front fender indication light (WCP)	Not Necessary	15.00 F	*- F
5	1	*front fender indication light chrome garnish	Not Necessary	50.00 FS	*- FS
6	1	*front fender 1/4 garnish (WCP)	Not Necessary	15.00 F	*- F
7	1	*n/s front wheel rim (Cut)	Old Damaged	250.00 FS	*- FS
8	1	*front shock absorber (WCP)	Not Necessary	75.00 F	*- F
9	1	*front shock absorber top mount (WCP)	Not Necessary	50.00 F	*- F
10	1	*front wheel bearing (WCP)	Not Necessary	40.00 F	*- F
11	1	*front wheel bearing hub (WCP)	Not Necessary	70.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	677.50	112.50
+ Margin on L,N Items 10.00/10.00% (\$\$)	37.75	11.25
Total Parts (\$\$)	715.25	123.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Putty and spray painting of the affected portion.	New	450.00	350.00
<u>Labour Items</u>				
2	To check steering geometry and computer wheel alignment.	New	120.00	60.00
3	To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	New	250.00	-
4	To transfer of n/s front wheel rim and on wheel balancing.	New	30.00	-
5	Panel beating, knocking and straighten the n/s front fender wheel house panel, remove and renewal of parts, adjust and realign the same.	New	400.00	200.00
Gross Labour Cost (S\$)			1,250.00	610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >