



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2011 KING LONG XMQ6117K (PC1085T)

Date of Loss

March 23, 2018

Time of Loss

7.35

Loss Description

PC1085T (INSD) HIT REAR OF XD9583U (TP)

Comment

Workshop Details

Total Rebate Amount

14612

Nett Loss Amount

\$60,388.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

08/19/2018



Days of work completion *

131



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

PC1085T

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

12/02/2011



Mileage

Age of Vehicle

6

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT... 2011

CATEGORY

Driver Name

ASSESSMENT INFO...

2011

FNOL INFORMATI...

CHEN GUOTONG

POST SURVEY INF...

CATEGORY	Make	
----------	------	----------------------

POLICY INFORMAT... KING LONG XMQ6117K

ASSESSMENT INFO...	KING LONG
--------------------	--

CATEGORY	Model	
----------	-------	----------------------

POLICY INFORMAT...

ASSESSMENT INFO...	XMQ6117K
--------------------	---------------------------------------

CATEGORY	Type	
----------	------	----------------------

POLICY INFORMAT...

ASSESSMENT INFO...	
--------------------	----------------------

CATEGORY	Type of Paint	
----------	---------------	----------------------

POLICY INFORMAT...

ASSESSMENT INFO...	
--------------------	----------------------

CATEGORY	Chassis No	
----------	------------	----------------------

POLICY INFORMAT... LA6R1FSH6BB103088

ASSESSMENT INFO...	
--------------------	----------------------

CATEGORY Date of Birth

FNOL INFORMAT... October 4, 1981

POST SURVEY INF...	mm/dd/yyyy
--------------------	---

CATEGORY Age

FNOL INFORMAT... 36

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMAT... Unknown

POST SURVEY INF...	
--------------------	----------------------

CATEGORY Education Qualification

FNOL INFORMAT... Other

POST SURVEY INF...	
--------------------	----------------------

CATEGORY Driving Experience

LA6R1FSH6BB103088

CATEGORY Engine No

POLICY INFORMAT... ISBE428521985875

ASSESSMENT INFO... ISBE428521985875

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO... 6693

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO... 0

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO... 75000

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... January 1, 2018

POST SURVEY INF... mm/dd/yyyy



CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF... mm/dd/yyyy



CATEGORY Address

FNOL INFORMATI... 100 JALAN SULTAN #02-16, SULTAN
PLAZA, 199001, Singapore

POST SURVEY INF...

CATEGORY

Address type

FNOL INFORMATI...

Personal Correspondence

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

Male

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

G8062881T

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Detailed Assessment

Inspection Date *

04/11/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

1500

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

11R22.5

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

Fair



Tyre Condition

Spare wheel

Rear Tyre Size

11R22.5(D)

Front left side

DOUBLECOIN8mm

Front right side

DOUBLECOIN8mm

Rear left side

DOUBLECOIN8/8mm

Rear right side

DOUBLECOIN8/8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)
☐		1	1			FRONT WINDSCREEN (WCP) (10%)			Broken	3850				3850	Reviewing
☐		2	8			SEALANT (WCP) (10%)			Necessary	44				352	Reviewing
☐		3	1			FRONT DASHBOARD PANEL ASSY			Serviceable	0	0	0	0	0	Deny
☐		4	1			FRONT FLOOR PLYWOOD			Serviceable	0	0	0	0	0	Deny
☐		5	1			FRONT FLOOR BOARD VINYL			Serviceable	0	0	0	0	0	Deny
☐		6	1			CLUTCH PEDAL (WCP) (10%)			Bent	341				341	Reviewing
☐		7	1			CLUTCH PIPE			Serviceable	0	0	0	0	0	Deny
☐		8	1			FRONT DASHBOARD STRUCTURAL (WCP) (10%)			Bent	1980				1980	Reviewing
☐		9	2			WIPER BLADES (WCP) (10%)			Cut	82.5				165	Reviewing
☐		10	2			WIPER ARM (WCP) (10%)			Bent	154				308	Reviewing
☐		11	1			WIPER LINKAGE (WCP) (10%)			Bent	396				396	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
☐		12	1			WIPER MOTOR (WCP) (10%)			Damaged	451				451	Reviewing
☐		13	1			FRONT BODY PANEL (WCP) (10%)			Deformed	2420				2420	Reviewing
☐		14	1			FRONT KING LONG LOGO (WCP) (10%)			Necessary	308				308	Reviewing
☐		15	1			FRONT BUMPER (WCP) (10%)			Cracked	2640				2640	Reviewing
☐		16	1			FRONT BUMPER STRUCTURAL			Repair	0	0	0	0	0	Deny
☐		17	2			FRONT LIGHT (WCP) (10%)			Cracked	1056				2112	Reviewing
☐		18	2			SPORT LIGHT (WCP) (10%)			Cracked	308				616	Reviewing
☐		19	1			ERP BRACKET (WCP) (10%)			Necessary	165				165	Reviewing
☐		20	1			WIRING COVER			Serviceable	0	0	0	0	0	Deny
☐		21	1			FRONT PANEL STRUCTURAL (WCP) (10%)			Bent	1100				1100	Reviewing

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMO
☐		1		LABOUR CHARGES	2300	0	0	Reviewing		
☐		2		SPRAY PAINTING	1100	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMO
		3		TOWING FEE	100	0	0	Reviewing		

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	DAYS OF REPAIR : 9 DAYS	Reviewing		

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$19,204.00			Claim Amount	\$19,204.00			

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$3,500.00	\$3,500.00
Excess	-\$1,500.00	-\$1,500.00
Spare Parts	\$17,204.00	\$17,204.00

Submit for Review

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

Submit All

EDIT		SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	FINAL LUMP SUM	Reviewing	16500		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount

\$15,000.00

Claim Amount

\$15,000.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Miscellaneous	\$16,500.00	\$16,500.00
Excess	-\$1,500.00	-\$1,500.00

Submit for Review