

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 6294Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DENTED / CRACKED	435.00	435.00
1	REAR BUMPER STEP GARNISH (CONSISTENT)	SERVICEABLE	57.90	-
1	REAR BUMPER SPONGE (CONSISTENT)	SERVICEABLE	74.30	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	SERVICEABLE	347.00	-
1	O/S REAR BUMPER SIDE RETAINER (CONSISTENT)	SERVICEABLE	29.50	-
10	REAR BUMPER CLIPS @\$2.00 (CONSISTENT)	NECESSARY	20.00	20.00
1	O/S REAR BUMPER CORNER GARNISH (CONSISTENT)	CRACKED	98.30	98.30
1	O/S REAR BUMPER CORNER GARNISH SIDE RETAINER (CONSISTENT)	* CHECK	29.50	-
1	O/S TAILLAMP (CONSISTENT)	CUT	384.90	384.90
	LESS 20% DISCOUNT		-295.28	-187.64
			1,181.12	750.56
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	220.00	-
			220.00	-
	<u>LABOUR</u>			
	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS.		700.00	400.00
	TO FOCUS TAILLAMPS ,TO CHECK REAR WIRING AND LIGHTING OPERATION.		50.00	20.00
	TO REMOVE AND REFIT REVERSE SENSOR ASSY .		80.00	50.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		600.00	320.00
			1,430.00	790.00
	GRAND TOTAL		2,831.12	1,540.56



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$23.60 NETT)		1,540.56

Report Ref No. CC4/ASM18006686/Kea3q2

KONG SENG CHEONG

Licensed Appraiser