

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB3519L

Ref. No : BUS/04/18/5012

Reg. Date : 10/04/2018

Vehicle Type : DOUBLE DECK

Make : ALEXANDER DENNIS

Model : ENVIRO 500

Name of Driver : R Magaindaran A/L S R

Ramalingam

Type of Accident : HEAD TO REAR

Date / Time of Accident : 09/04/2018 06:00:00 PM

Accident Reported Date / Time: 10/04/2018 12:00:00 AM

Surveyor is Required? Ye

Survey by China Tai Ping

Vehicle is Towed Back? : No


Towed Back Date/Time

Replacement Vehicle issued? : No


Accident Repair Job Card No : Special Instruction to ARC,if any :

SMB3519L - FRONT RIGHT PORTION GX9001D (TP) - INSURED WITH CHINA

Prepared Date : 10/04/2018 11:27:06 AM









Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No :

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

1,590.00

0.00 0.00

Total Spray Painting Charges

1,200.00

1,431.28

Total Material Charges Other Charges

1,431.28

TOTAL

0.00 4,221.28 0.00

Lum Sum Total

0.00

0.00

No. of Repair Days

3.00

0.00 9002 days - P/P

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

Prepared / Adjusted Date

Remarks

01/01/1900 12:00:00 AM

01/01/1900 12:00:00 AM

Prepared Date : 10/04/2018 05:36:36 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 4 - Spare Parts / Material Usage

Part - Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
20590172 /2		6011052	R/H CORNER BUMPER	1	1,181.40	10.00	1,063.26	Replace	Replace	No
30106507		6011242	EXT PANEL, R/H	1	408.91	10.00	368.02	Replace	Reptice	No
TOTAL MATERIALS 1,431.28							1,431.28			
	TOTAL MATERIALS(Discounted)							1,431.28	1,431.28	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	то	TAL SUPPLEMENTARY	MATERIA	ALS					

BUS/04/18/5012 Page: 4

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO REPAIR RH FRONT PORTION	1,590.00	0.00 1060		
Total Labour	1,590.00	0.00		

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	1,200.00	0.00 892			
Total Spray Painting & Panel Beating	1,200.00	0.00			

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		
The Society of the Section of the Se		