



⊖ Please enter the required fields in General & Workshop Details



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

General Details

Involving 1 2011 LAMBORGHINI GALLARDO LP550-2
XXXXXX (SE98S)

Date of Loss 9 April 2018

Time of Loss 11.15

Loss Description SE98S (INSD) C/W WALL

Comment

Workshop Details

Total Rebate Amount 163249

Nett Loss Amount \$186,751.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion * 379

Maximum value is 365



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SE98S

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

28/02/2011



Mileage

24690

Age of Vehicle

7

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2011

2011

Make

LAMBORGHINI
GALLARDO LP550-2

LAMBORGHINI

Model

XXXXXX

GALLARDO LP55

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

DARYL TEO JIN-WEI (ZHANG
JINWEI)

Date of Birth

24 September 1977

dd/mm/y

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		
Type of Paint		
Chassis No	ZHWGE52Z1BLA10542	ZHWGE52Z1BLA
Engine No	CEH004320	CEH004320
Engine Capacity		5204
Sum Insured	0	0
Market Value	0	350000

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Age	41	
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	21	
Driver License #		
License Type		
License Issue Date		dd/mm/y 
License Expiration Date		dd/mm/y 
Address	BLK 125 TAMPINES STREET 11, #12-494, 521125, Singapore	

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Address type	Residential	
Gender	Male	
Marital status	Single	
Identification #	S77277261	



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

12/04/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

20000

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS

⊖ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRONT BUMPERS			Damaged	4550		10		4095	Reviewing	
		2	1			LEFT FRONT GRID			Bent	580		10		522	Reviewing	
		3	1			RIGHT FRONT GRID			Deformed	580		10		522	Reviewing	
		4	1			GRID			Bent	350		10		315	Reviewing	
		5	1			BUMPER STRUCTURE			Bent	650		10		585	Reviewing	
		6	1			BUMPER DIFFUSER (CARBON)			Damaged	8950		10		8055	Reviewing	
		7	1			FRONT LEFT SIDE MARKER			Cracked	580		10		522	Reviewing	
		8	1			FRONT RIGHT SIDE MARKER			Cracked	580		10		522	Reviewing	
		9	1			REAR BUMPERS			Damaged	2650		10		2385	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		10	1			FENDER, FRONT LH			Damaged	3900		10		3510	Reviewing	
		11	1			FENDER, FRONT RH			Damaged	4360		10		3924	Reviewing	
		12	1			REAR FENDER, LH			Dented	14600		10		13140	Reviewing	
		13	1			FRONT LH WHEELHOUSE APRON, FRONT PORTION			Damaged	500		10		450	Reviewing	
		14	1			FRONT LH WHEELHOUSE APRON, REAR PORTION			Damaged	350		10		315	Reviewing	
		15	1			LEFT SIDE VIEW MIRROR			Cracked	4750		10		4275	Reviewing	
		16	1			RIGHT SIDE VIEW MIRROR			Serviceable	0	0	0	0	0	Deny	
		17	1			RH PLATE EXTERNAL REAR - VIEW MIRROR RIGHT CONVEX			Serviceable	0	0	0	0	0	Deny	
		18	1			LH PLATE EXTERNAL REAR-VIEW MIRROR LEFT NONSPHERICAL			Missing	160		10		144	Reviewing	
		19	1			WINDSCREEN			Cracked	6150		10		5535	Reviewing	
		20	1			RH REAR OMOKINETIC DRIVE SHAFT			Bent	1330		10		1197	Reviewing	
		21	1			RH ABS SENSOR			Damaged	35		10		31.5	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		22	1		KIT REAR AXLE UNTIL THE VIN ALA09565- INCLUDES: LH RH UPPER LOWER ARM- NUT M14-REAR LH RH HUB CARRIER- CONNECTING ROD-SCREW			Damaged	4250		10		3825	Reviewing	
		23	1		HEADLIGHT, LH			Cracked	5850		10		5265	Reviewing	
		24	1		HEADLIGHT, RH			Cracked	5850		10		5265	Reviewing	
		25	1		POWER STEERING RACK			Broken	5505		10		4954.5	Reviewing	
		26	1		SIDE MEMBER COVER, OUTER RH			Repair	0	0	0	0	0	Deny	
		27	1		SIDE MEMBER COVER, OUTER LH			Damaged	1400		10		1260	Reviewing	
		28	2		ELECTRIC FAN			Damaged	700		10		1260	Reviewing	
		29	1		RH WATER RADIATOR			Damaged	1950		10		1755	Reviewing	
		30	1		A/C CONDENSER			Damaged	760		10		684	Reviewing	
		31	1		RH SUPPORT			Damaged	480		10		432	Reviewing	
		32	1		RH CONVEYOR			Damaged	500		10		450	Reviewing	
		33	1		RH CONVEYOR			Damaged	145		10		130.5	Reviewing	
		34	1		RH CONVEYOR			Damaged	145		10		130.5	Reviewing	

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		35	2		SHOCK ABSORBER (STANDARD / LIFTING SYSTEM - UNTIL THE VIN ALA09701 REPLACE PER AXLE) STANDARD			Bent	2675		10		4815	Reviewing	
		36	2		RIM (SCORPIUS-FOR SUPERLEGGERA LP 570-4 MODEL)			Cut	5925		10		10665	Reviewing	
		37	2		RIM (SCORPIUS-FOR SUPERLEGGERA LP 570-4 MODEL)			Cut	6375		10		11475	Reviewing	
		38	1		RH FRONT BRAKE CALIPER (ORANGE FRONT CALIPERS-FROM VIN ALA09374)			Cut	2150		10		1935	Reviewing	
		39	1		STREAMLINE SHROUD			Damaged	3510		10		3159	Reviewing	
		40	1		STREAMLINE SHROUD, REAR			Damaged	250		10		225	Reviewing	
		41	1		COVER PLATE (ADDITIONAL)			Damaged	241		10		216.9	Reviewing	
		42	1		COVER LEFT HAND (ADDITIONAL)			Damaged	241		10		216.9	Reviewing	
		43	1		LEFT SUPPORT (ADDITIONAL)			Damaged	213		10		191.7	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		44	1			COVER RIGHT HAND (ADDITIONAL)			Damaged	241		10		216.9	Reviewing	
		45	1			RIGHT SUPPORT (ADDITIONAL)			Damaged	213		10		191.7	Reviewing	
		46	1			OIL COOLER (ADDITIONAL)			Damaged	566		10		509.4	Reviewing	
		47	1			PIPE (ADDITIONAL)			Bent	787		10		708.3	Reviewing	
		48	1			CONNECTING ROD (ADDITIONAL)			Bent	168		10		151.2	Reviewing	
		49	2			CONNECTING ROD (ADDITIONAL)			Bent	168		10		302.4	Reviewing	
		50	1			RIGHT SUPPORT (ADDITIONAL)			Bent	56		10		50.4	Reviewing	
		51	1			RIGHT SUPPORT (ADDITIONAL)			Bent	56		10		50.4	Reviewing	
		52	1			RIGHT SUPPORT (ADDITIONAL)			Bent	56		10		50.4	Reviewing	
		53	2			SUPPORT (ADDITIONAL)			Bent	175		10		315	Reviewing	
		54	1			FRONT RIGHT HAND HUB CARRIER (ADDITIONAL)			Damaged	570		10		513	Reviewing	
		55	2			BEARING (ADDITIONAL)			Necessary	252.5		10		454.5	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		56	1			RIGHT HAND ABS SENSOR (ADDITIONAL)			Damaged	120		10		108	Reviewing	
		57	1			REAR LEFT HAND WHEELHOUSE (ADDITIONAL)			Damaged	2548		10		2293.2	Reviewing	
		58	1			REAR RIGHT HAND WHEELHOUSE (ADDITIONAL)			Damaged	390		10		351	Reviewing	
		59	1			FRONT RIGHT HAND WHEELHOUSE (ADDITIONAL)			Damaged	552		10		496.8	Reviewing	
		60	1			FRONT RIGHT HAND WHEELHOUSE (ADDITIONAL)			Damaged	247		10		222.3	Reviewing	
		61	1			STREAMLINE SHROUD (ADDITIONAL)			Cracked	165		10		148.5	Reviewing	
		62	1			PUMP (ADDITIONAL)			Damaged	500		10		450	Reviewing	
		63	1			PIPE (ADDITIONAL)			Bent	150		10		135	Reviewing	
		64	1			COOLER EXIT CONE (ADDITIONAL)			Damaged	247		10		222.3	Reviewing	
		65	1			FRONT RIGHT HAND MEMBER (ADDITIONAL)			Bent	6340		10		5706	Reviewing	
		66	1			REAR FENDER LEFT HAND (ADDITIONAL)			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		67	1			FRONT RIGHT HAND LOWER ARM (ADDITIONAL)			Bent	572		10		514.8	Reviewing	
		68	1			FRONT RIGHT HAND UPPER ARM (ADDITIONAL)			Bent	500		10		450	Reviewing	
		69	1			REAR CONNECTING ROD (ADDITIONAL)			Bent	546		10		491.4	Reviewing	
		70	1			RIGHT HAND PROTECTION (ADDITIONAL)			Damaged	30		10		27	Reviewing	
		71	1			COWL TOP COVER, RIGHT HAND SIDE (ADDITIONAL)			Cracked	650		10		585	Reviewing	
		72	1			RIGHT HAND BRACKET (ADDITIONAL)			Bent	60		10		54	Reviewing	
		73	1			RIGHT HAND BRACKET (ADDITIONAL)			Bent	100		10		90	Reviewing	
		74	1			RIGHT HAND BRACKET (ADDITIONAL)			Bent	115		10		103.5	Reviewing	
		75	1			CONVEYOR (ADDITIONAL)			Cracked	150		10		135	Reviewing	
		76	1			LEFT HAND BRACKET (ADDITIONAL)			Bent	156		10		140.4	Reviewing	
		77	1			FRONT SHOCK ABSORBER (ADDITIONAL)			Bent	4485		10		4036.5	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		78	2			FRONT BRAKE DISC (ADDITIONAL)			Damaged	885		10		1593	Reviewing	
		79	2			REAR BRAKE DISC (ADDITIONAL)			Damaged	1200		10		2160	Reviewing	
		80	1			MASTER ECU (ADDITIONAL)			Damaged	3500		10		3150	Reviewing	
		81	1			SLAVE ECU (ADDITIONAL)			Damaged	3500		10		3150	Reviewing	
		82	1			SPEED SENSOR (ADDITIONAL)			Damaged	275		10		247.5	Reviewing	
		83	1			WATER TANK (ADDITIONAL)			Deformed	475		10		427.5	Reviewing	
		84	1			CAR PLATE (FRONT & REAR) (ADDITIONAL)			Necessary	100		10		90	Reviewing	
		85	1			FRONT LEFT HAND HEADLAMP COVER (ADDITIONAL)			Necessary	650		10		585	Reviewing	
		86	1			FRONT EMBLEM (ADDITIONAL)			Necessary	880		10		792	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		TO SUPPLY LABOUR TO REMOVE AND REPLACE FRONT AND REAR BRAKE DISC INCLUSIVE OF BRAKE SYSTEM BLEEDING (ADDITIONAL)	350	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		2		TO SUPPLY LABOUR TO REMOVE AND REPLACE MASTER AND SLAVE ECU (ADDITIONAL)	400	0	0	Reviewing		
		3		TO PERFORM CODING OF ECU AND CHECK ELECTRICAL ERRORS AFTER REPLACEMENT WITH LAMBORGHINI ORIGINAL TESTER (ADDITIONAL)	750	0	0	Reviewing		
		4		TO REMOVE AND REPAIR ROOF LINING. ROOF LINING DROP AFTER STRAIGHTENING JOB DUE TO TWISTED ROOF REPAIR (ADDITIONAL)	500	0	0	Reviewing		
		5		TO REPAIR 1 PC OF STARTER MOTOR. TO REPLACE 1 PC OF ALTERNATOR. TO SKIM COMMUTATOR. (ADDITIONAL)	650	0	0	Reviewing		
		6		TO SUPPLY LABOUR TO INSTALL FRONT WINDSCREEN WITH SUPPLY OF SILICONE AND GASKET (ADDITIONAL)	550	0	0	Reviewing		
		7		TOWING FROM MALAYSIA TO SINGAPORE WORKSHOP	1000	0	0	Reviewing		
		8		TO CHECK ELECTRICAL SYSTEM AND REPAIR WIRE HARDNESS FOR FRONT BUMPER	200	0	0	Reviewing		
		9		TO TRANSFER FRONT BUMPER COMPONENT TO FRONT BUMPER	180	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		10		TO REMOVE AND REINSTALL FRONT INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS	150	0	0	Reviewing		
		11		TO REMOVE AND REINSTALL EXHAUST SILENCER FOR NECESSARY REPAIRS	0	0	0	Deny		
		12		TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS FOR FRONT BUMPER	1800	0	0	Reviewing		
		13		TO CHECK ELECTRICAL SYSTEM AND REPAIR WIRE HARDNESS FOR REAR BUMPER	200	0	0	Reviewing		
		14		TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE	0	0	0	Deny		
		15		TO REMOVE, REPLACE AND / OR TRANSFER REAR REVERSE SENSORS & CONTROL UNIT	100	0	0	Reviewing		
		16		TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS FOR REAR BUMPER	2100	0	0	Reviewing		
		17		TO CONDUCT CHASSIS ALIGNMENTS	300	0	0	Reviewing		
		18		TO SPRAY PAINTING, BLENDING ON EFFECTED AND ADJACENT AREA INCLUDING RIGHT HAND FENDER, LEFT HAND FENDER AND REAR LEFT HAND FENDER	4500	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		19		TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	280	0	0	Reviewing		
		20		TO REMOVE, REPLACE AD REINSTALL SUSPENSION FOR FRONT RIGHT HAND AND REAR RIGHT HAND	500	0	0	Reviewing		
		21		TO INSPECTION, DIAGNOSE, RESET AND PERFORM CODING PROGRAMMING ON :- 12.1) REAR REVERSE CAMERA AND SENSOR SYSTEMS. 12.2) REAR AIR SUSPENSION SYSTEM. 12.3) SECURITY LOCK AND REAR BOOT SYSTEM.	400	0	0	Reviewing		
		22		TO REMOVE AND REPAIR DRIVE SHAFT	150	0	0	Reviewing		
		23		TO REMOVE AND REPLACE RIM TYRES, INCLUDING TYRES BALANCING	280	0	0	Reviewing		
		24		TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA FOR ROOF TOP INCLUDE REMOVE ROOF LINING, GARNISHES, TRIM, ETC	1800	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS

ⓘ Please enter the required fields in General & Workshop Details



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

DAYS OF
REPAIR : 21
DAYS

Reviewing



2

STANDARD
TYRES
(FRONT)-2PCS

Reviewing

1000

CUT



3

STANDARD
TYRES (REAR)
- 2PCS

Reviewing

500

O/S CUT /
N/S NOT
NECESSARY

4

SET RR NO.
PLATE
(FRONT)

Reviewing

60

CRACKED





⊖ Please enter the required fields in General & Workshop Details



Assessment Details

[General & Workshop Details](#)[Vehicle & Driver Details](#)[Vehicle Condition](#)[Taxes & Ratio](#)[Parts & Labour](#)[Miscellaneous](#)[Summary](#)

Claim Amount	\$139,524.80	Claim Amount	\$139,524.80
--------------	--------------	--------------	--------------

CATEGORY

ESTIMATE

REVISED AMOUNT

Spare Parts

\$140,824.80

\$140,824.80

Labour

\$17,140.00

\$17,140.00

Miscellaneous

\$1,560.00

\$1,560.00 —

Excess

-\$20,000.00

-\$20,000.00

[Submit for Review](#)



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



1

FINAL
LUMP
SUM

Reviewing

118000





SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount		\$98,000.00			Claim Amount		\$98,000.00	
CATEGORY		ESTIMATE			REVISED AMOUNT			
Miscellaneous		\$118,000.00			\$118,000.00			
Excess		-\$20,000.00			-\$20,000.00			
Submit for Review								