

ASS. REC. BY:

REF: CS/CTU 8006779 /Subs

Special Instruction:

Surveyor: Sebastian  
Maiman

ASSIGNMENT (Office)

From (Person): Chang Boon Sen of CTU

Date/Time: 11/04/2018 5:07pm

Estimated Cost: Bill to:

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLQ 1748M

Insured: SJJ 9974J

at Workshop m/s Kah Motor

Tel:

of 6A Mandai Estate

Policy No: DMHCSN1742691700

Claim No: SNM/SD01884 C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 04/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

H.O.D. Endorsement:

Date/Time: 12/04/2018 9:36am

Person Contacted: Jason

Vehicle  IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 1748M - X
	SJJ 9974J - NA /MSI09D10026 /SI DA: 070509
18/6/18	@ 1037am Jason will check & call back
18/6/18	@ 11am Jason said TP convert to OD claim.



**...CLAIM SUBFOLDER...(New Assignment)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Apr 2018		11 Apr 2018 17:07 <a href="#">Assign</a>				<a href="#">New Assignment</a> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:									
Main Claimant:	<b>CHLOE LIM HUI</b>								
Vehicle Reg. No.:	<b>SLQ1748M</b>	Date of Loss:	04/04/2018 00:00 - :59						
Claim Type:	<b>TP / SNM18D01884C02</b>	Policy/Cover Note No.:	DMHCSN1742691700						
Vehicle Reg. No. (Insured):	<b>SJJ9974J</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:</b>								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]</b>								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/04/2018]</b>								
Adj Asg. Remarks:	EST \$46,225.19, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b>				<a href="#">View All</a>   <a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<input type="checkbox"/> <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"> <a href="#">View All</a>   <a href="#">Search Tasks</a>   <a href="#">Create New Task</a>   <a href="#">Complete</a> </span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

*12/4/2018 @ 9:56am  
Jason Veh in  
8288 6309*

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/04/2018 10:51
Date Of Accident	04/04/2018 08:05
Exact Location Of Accident	KJE > BKE (B4 BKE EXIT)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLQ1748M
Insured/Policyholder	
Name Of Registered Owner	CHLOE LIM HUI
NRIC No	S9043031I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97596807
Alternative Phone No	OFFICE-97596807
Vehicle Particulars	
Manufacturer	HONDA
Model	HR-V-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MU007106
Cover Note Number	
Driver	
Name of Driver	LIM YAOFENG
NRIC No	S8930578J
Date Of Birth	31/08/1989
Occupation	INDOOR
Date Of Driving Pass	27/03/2009
Driving Experience	9 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97596807
Fax Number	
Contact Number	
EEmail Address	LIMYAOFENG@GMAIL.COM

Address -  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured SPOUSE  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : LEE EE PERNG  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

AS ATTACHED ANNEX D&E

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? YES  
 Remarks/ Reasons: FILE TOO LARGE  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SJJ9974J  
 Vehicle Make/Model/Colour TOYOTA  
 Details Of Properties FRONT / SERIOUS DAMAGE  
 Vehicle Category PRIVATE HIRE  
 Name of Driver JIMI EU SHENG QIANG  
 NRIC/Passport Number S1373450Z  
 Contact Number 98557577  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	GBC6837Z
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	REAR / MODERATE
Vehicle Category	GOODS VEHICLE
Name of Driver	CHANDAN BISWAS ASOKE BISWAS
NRIC/Passport Number	G7005011R
Contact Number	81282622
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**DETAILS OF INJURED PERSON 1**

Name	LEE EE PERNG RACHEL
Approximate Age	
Injuries Sustain	NOT SURE
Injured person in which vehicle?	SLQ1748M
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Vehicle No SLG1748M

**SKETCH PLAN**

Annex D

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

*W* 4/4/18 0930


*Amita*

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Please continue to Annex E

Sketch Plan Pg. 2

Vehicle No SLQ1748M

Annex E

Describe Circumstances of the Accident

I was driving along KJE towards BLE (just bt BICE exit)  
Suddenly a van in front of me jam ~~braked~~ braked. I was able  
to stop in time as I have sufficient safety distance. However,  
car behind me hit the back of my car. Upon impact my car  
(SJJ9974J) moved in front abit and hit the van in front. My  
car boot was badly damaged. The front was slightly damaged as  
well due to the impact making me hit the van in front.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

 / 4/4/18 0930

 Anikta



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

<b>Customer</b>	: CHINA TAIPING INSURANCE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT18001398	<b>Page</b>	1
<b>Registration No</b>	: SLQ1748M	<b>Date</b>	: 4. Apr 2018	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: JHMUR1810GX202305	<b>Svc Advisor</b>	: JASON HENG	<b>Engine No</b>	: L15B4532305
<b>Model</b>	: HRV DX-SIN CVT YM 2016	<b>Date   Time</b>	: 4. Apr 2018 9:52:44 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: CHLOE LIM HUI	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 4/4/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
68100-T7A-J20ZZ	TAIL GATE COMP ✓ DT	1	838.90		838.90	58.72	897.62
74440-T7A-003	WEATHERSTRIPTAILGATE ✓ Deform.	1	96.80		96.80	6.78	103.58
74890-T7A-J12ZR	GARNISH ASSYRR.LICENSE ?	1	189.80		189.80	13.29	203.09
39530-T7A-003	CAMERA ASSYRR.VIEW ?	1	611.00		611.00	42.77	653.77
74800-T7A-J02	LOCK ASSYTAILGATE ✓ DMG.	1	76.60		76.60	5.36	81.96
74810-T4N-H01	SWITCH ASSYTAILGATE OPENER ?	1	103.20		103.20	7.22	110.42
74813-T5A-003	STRIKER ASSYTAILGATE ✓ NEC	1	24.70		24.70	1.73	26.43
74827-SWA-A10	STOPPERTAILGATE ✓ NEC	2	3.80		7.60	0.53	8.13
74827-S2G-010	PROTECTORLICENSE PLATE X 77	2	2.00		4.00	0.28	4.28
84431-T7A-J01ZA	LINING ASSYTAILGATE ✓ Deform.	1	133.40		133.40	9.34	142.74
84433-T7A-J01ZA	LINING ASSYTAILGATE UPPER ✓ ?	1	58.10		58.10	4.07	62.17
84435-T7A-J01ZA	LINING ASSYR.TAILGATE SIDE ?	1	20.90		20.90	1.46	22.36
84485-T7A-J01ZA	LINING ASSYL.TAILGATE SIDE ?	1	20.90		20.90	1.46	22.36
84441-S2K-000ZB	POCKETTAILGATE PULL ✓ cut	1	14.90		14.90	1.04	15.94
75722-T7W-A01	EMBLEMRR. ✓ NEC	1	12.90		12.90	0.90	13.80
75725-T8N-T00	EMBLEM,RR. I-VTEC ✓ NEC	1	14.10		14.10	0.99	15.09
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER ✓ ✓ NEC	1	19.30		19.30	1.35	20.65
73226-SZW-000	DAMPERSTD 5X5 ✓ NEC	1	8.30		8.30	0.58	8.88
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER ✓ NEC	1	19.30		19.30	1.35	20.65
76711-T6A-003	CAPPIVOT ✓ NEC	1	4.70		4.70	0.33	5.03
91501-S70-003	FASTENER BW/SHIELD ✓ NEC	4	3.20		12.80	0.90	13.70



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838 Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
Registration No : SLQ1748M  
Chassis No : JHMUR1810GX202305  
Model : HRV DX-SIN CVT YM 2016  
Owner's Name : CHLOE LIM HUI  
Ins Policy No. :  
Date of Accident : 4/4/2018

Document No. : SQT18001398  
Date : 4. Apr 2018  
Customer No. : WZC008  
Svc Advisor : JASON HENG  
Engine No : L15B4532305  
Date | Time : 4. Apr 2018 9:52:44 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91502-S70-003	FASTENER B ✓ NEC	2	4.90		9.80	0.69	10.49
91536-SS0-J01	FASTENER AW/SHIELD ✓ NEC	2	3.50		7.00	0.49	7.49
BO-WS-SEALANT	WINDSCREEN SEALANT (N) ✓ NEC	2	60.00		120.00	8.40	128.40
84610-T7A-J01ZA	BASE COMPR.TRUNK SIDE LINING ?	1	144.20		144.20	10.09	154.29
84660-T7A-J01ZA	BASE COMPL.TRUNK SIDE LINING ?	1	144.20		144.20	10.09	154.29
84640-T7A-J01ZA	LINING ASSYRR.PANEL ✓ Deform.	1	43.00		43.00	3.01	46.01
84521-T7A-J01ZA	BOARD ASSYTRUNK FLOOR ✓ Deform.	1	186.00		186.00	13.02	199.02
84550-T7A-J00	BOX ASSY,CARGO FLOOR ✓ CRK.	1	126.90		126.90	8.88	135.78
66100-T7A-300ZZ	PANEL COMPR. ✓ DT	1	365.70		365.70	25.60	391.30
04655-T7A-310ZZ	PANEL SETRR.FLOOR ✓ DT	1	662.20		662.20	46.35	708.55
72841-SH3-315	OILSHEET ✓ NEC	3	39.90		119.70	8.38	128.08
65513-T7A-300ZZ	STIFFENERRR.JACK UP ✓ NEC (photo)	1	60.20		60.20	4.21	64.41
65750-T5B-300ZZ	CROSSMEMBER COMPR.FLOOR ?	1	81.20		81.20	5.68	86.88
04636-T7A-310ZZ	PANEL SET,R.RR.OUTSIDE ✓ DT	1	602.30		602.30	42.16	644.46
04646-T7A-300ZZ	PANEL SETL.RR.OUTSIDE R	1	602.30		602.30	42.16	644.46
75450-SAA-013	OUTLETRR AIR ?	1	24.70		24.70	1.73	26.43
63320-T7A-300ZZ	GUTTER COMPR.RR. ?	1	75.30		75.30	5.27	80.57
63720-T7A-300ZZ	GUTTER COMPL.RR. ?	1	75.30		75.30	5.27	80.57
65540-T7A-310ZZ	STIFFENER COMPR.RR.FRAME UPP ?	1	103.20		103.20	7.22	110.42
65590-T7A-310ZZ	STIFFENER COMPL.RR.FRAME UPP ?	1	103.20		103.20	7.22	110.42
04656-T7A-330ZZ	FRAME B SETR.RR. ?	1	413.50		413.50	28.95	442.45
04657-T7A-320ZZ	FRAME B SETL.RR. ?	1	421.70		421.70	29.52	451.22
71501-T7B-000	FACE RR.BUMPER ✓ DT	1	762.60		762.60	53.38	815.98
33505-T7A-J01	REFLECTOR ASSYR.RR. ?	1	151.80		151.80	10.63	162.43
33555-T7A-J01	REFLECTOR ASSYL.RR. ✓ CRK	1	151.80		151.80	10.63	162.43
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER ✓ cut	1	92.30		92.30	6.46	98.76
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER ✓ cut	1	92.30		92.30	6.46	98.76
71593-T7A-000	SPACERR.RR.BUMPER SIDE ✓ NEC	1	11.50		11.50	0.81	12.31
71598-T7A-000	SPACERL.RR.BUMPER SIDE ✓ NEC	1	11.50		11.50	0.81	12.31
91505-TM8-003	CLIPBUMPER ✓ NEC	8	2.00		16.00	1.12	17.12

Printed on 10/4/2018 12:01:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

Registration No : SLQ1748M  
Chassis No : JHMUR1810GX202305  
Model : HRV DX-SIN CVT YM 2016  
Owner's Name : CHLOE LIM HUI  
Ins Policy No. :  
Date of Accident : 4/4/2018

Document No. : SQT18001398 Page 3  
Date : 4. Apr 2018  
Customer No. : WZC008  
Svc Advisor : JASON HENG  
Engine No : L15B4532305  
Date | Time : 4. Apr 2018 9:52:44 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
38387-TZ5-A01	ANTENNA ASSYLF. ?	1	58.10		58.10	4.07	62.17
74940-TZ5-A01	BUZZER ASSYSMART ✓ CRK	1	59.30		59.30	4.15	63.45
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ✓ DMG	1	320.00		320.00	22.40	342.40
74410-T7B-003	PROTECTOR,R,RR.WHEEL ARCH X nn	1	172.10		172.10	12.05	184.15
74450-T7B-003	PROTECTOR,L,RR.WHEEL ARCH ✓ Deform	1	172.10		172.10	12.05	184.15
74552-T7A-010	FENDERR,RR.INNER ?	1	90.40		90.40	6.33	96.73
74592-T7A-010	FENDERL,RR.INNER ?	1	90.40		90.40	6.33	96.73
74646-T7A-010	COVERRR.FLOOR UN ✓ Deform	1	118.30		118.30	8.28	126.58
33502-T7A-J01	LAMP UNITR. ✓ CRK	1	428.70		428.70	30.01	458.71
33552-T7A-J01	LAMP UNITL. ✓ CRK	1	428.70		428.70	30.01	458.71
34150-T7A-J01	LIGHT ASSY,R,LID ?	1	264.60		264.60	18.52	283.12
34155-T7A-J01	LIGHT ASSYL,LID ✓ CRK	1	264.60		264.60	18.52	283.12
18307-T7A-901	SILENCER COMPEXHUAST ✓ DT	1	528.00		528.00	36.96	564.96
04711-T7A-N00ZZ	FACE,FR.BUMPER ✓ CUT	1	466.20		466.20	32.63	498.83
71102-T7B-000	FACE FR. BUMPER LOWER R	1	344.20		344.20	24.09	368.29
71103-T7A-000	GRILLEFR.BUMPER ✓ CRK ?	1	77.50		77.50	5.43	82.93
71193-T7A-000	SPACERR.FR.BUMPER SIDE ✓ NEC	1	10.40		10.40	0.73	11.13
71198-T7A-000	SPACERL.FR.BUMPER SIDE ✓ NEC	1	10.40		10.40	0.73	11.13
91505-TM8-003	CLIPBUMPER ✓ NEC	22	2.00		44.00	3.08	47.08
33100-T7S-E11	HEADLIGHT ASSY,R. ✓ CRK	1	1661.00		1661.00	116.27	1777.27
71140-T7A-000	BEAMR.FR.BUMPER UPPER ?	1	23.90		23.90	1.67	25.57
33150-T7S-E11	HEAD LIGHT ASSY,L. ✓ CRK	1	1479.70		1479.70	103.58	1583.28
71190-T7A-000	BEAML,FR.BUMPER UPPER ?	1	23.90		23.90	1.67	25.57
71105-T7A-000	GARNISHR.FR.FOG LIGHT ?	1	21.10		21.10	1.48	22.58
71106-T7A-000	GARNISHL,FR.FOG LIGHT ?	1	21.10		21.10	1.48	22.58
33900-SLE-J51	LIGHT ASSYR,FR.FOG ?	1	237.90		237.90	16.65	254.55
33961-T7A-J00	BRACKETR.FOG LIGHT ?	1	49.00		49.00	3.43	52.43
33950-SLE-J51	LIGHT ASSYL,FR.FOGLIGHT ?	1	235.00		235.00	16.45	251.45
33966-T7A-J00	BRACKETL.FOG LIGHT ?	1	49.00		49.00	3.43	52.43
60100-T7A-000ZZ	HOOD COMP ENGINE R	1	785.20		785.20	54.96	840.16

Printed on 10/4/2018 12:01:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer** : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

**Registration No** : SLQ1748M

**Chassis No** : JHMUR1810GX202305

**Model** : HRV DX-SIN CVT YM 2016

**Owner's Name** : CHLOE LIM HUI

**Ins Policy No.** :

**Date of Accident** : 4/4/2018

**Document No.** : SQT18001398

**Date** : 4. Apr 2018

**Customer No.** : WZC008

**Svc Advisor** : JASON HENG

**Engine No** : L15B4532305

**Date | Time** : 4. Apr 2018 9:52:44 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Page 4

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
60120-T7A-000ZZ	HINGE COMPR.HOOD ✓ BT	1	39.10		39.10	2.74	41.84
60170-T7A-000ZZ	HINGE COMPL.HOOD ✓ BT	1	39.10		39.10	2.74	41.84
80050-TG7-000	LABLE AIR CON ✓ NEC	1	0.80		0.80	0.06	0.86
19043-PNB-A00	LABELCOOLANT INFORMATION ✓ NEC	1	4.90		4.90	0.34	5.24
71126-T7B-Z01	SET,FR.GRILLE ASSY ?	1	265.50		265.50	18.59	284.09
71122-T7A-901	MOLDINGFR.GRILLE UPPER ✓ PRK	1	186.10		186.10	13.03	199.13
71123-T7A-901	MOLDINGFR.GRILLE ?	1	42.80		42.80	3.00	45.80
71150-T7A-000	BEAMR.FR.GRILLE SIDE UPPER ?	1	38.70		38.70	2.71	41.41
71152-T7A-000	BEAML.FR.GRILLE SIDE UPPER ?	1	4.50		4.50	0.32	4.82
71151-T7A-000	BEAMR.FR.GRILLE SIDE UPPER ?	1	17.20		17.20	1.20	18.40
71130-T7A-010ZZ	BEAM COMP,FR.BUMPER ✓ DT	1	236.60		236.60	16.56	253.16
60400-T7A-901ZZ	BULKHEAD COMP,FR. ✓	1	425.90		425.90	29.81	455.71
80110-T7A-003	CONDENSER COMP ?	1	568.10		568.10	39.77	607.87
19010-50T-902	RADIATOR COMP ?	1	1187.40		1187.40	83.12	1270.52
08CLA-P9911LK8	COOLANTANTI-FREEZE ?	5	23.20		116.00	8.12	124.12
<b>Sum Item</b>					<b>19781.10</b>	<b>1,384.69</b>	<b>21,165.79</b>
BG02R	REPLACE RR. WINDSCREEN.(N) ✗	2.6	100.00	✓	260.00	18.20	278.20
BOSUN	SUNDRIES	1	200.00	80	200.00	14.00	214.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	200.00	160	200.00	14.00	214.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00	110	160.00	11.20	171.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	800.00	560	800.00	56.00	856.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	800.00	560	800.00	56.00	856.00
BMI01D	REMOVE & INSTALL ROOF LINING GARNISHES SEATS	1	800.00	X	800.00	56.00	856.00
BMF00D	REMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	800.00	280	800.00	56.00	856.00
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	100.00	80	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR FLOOR PANEL	1	100.00	80	100.00	7.00	107.00
BP00R	APPLY BODY UNDERSIDE COATING-(N):	1	250.00	✓	250.00	17.50	267.50

Printed on 10/4/2018 12:01:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer** : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

**Registration No** : SLQ1748M

**Chassis No** : JHMRU1810GX202305

**Model** : HRV DX-SIN CVT YM 2016

**Owner's Name** : CHLOE LIM HUI

**Ins Policy No.** :

**Date of Accident** : 4/4/2018

**Document No.** : SQT18001398

**Date** : 4. Apr 2018

**Customer No.** : WZC008

**Svc Advisor** : JASON HENG

**Engine No** : L15B4532305

**Date | Time** : 4. Apr 2018 9:52:44 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Page 5

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BOMISC1	RESET & CALIBRATE SMART ENTRY SYSTEM (N)	1	160.00	✓	160.00	11.20	171.20
BOMISC1	RESET & CALIBRATE REAR VIEW CAMERA (N)	1	160.00	✓	160.00	11.20	171.20
BOMISC1	REMOVE & REFIX TAILGATE SPOILER (N)	1	160.00	✓	160.00	11.20	171.20
BMU30A	STRAIGHTEN ALIGN & PULL BACK EXHAUST SYSTEM. (N)	1	200.00	✓	200.00	14.00	214.00
BKOT00A	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT <i>Photo</i>	1	1800.00	1500?	1800.00	126.00	1926.00
BKRP21B	CUT OFF & RENEW RR FLOOR PANEL RR L FENDER.	1	7000.00	4480 + 560 = 5040	7000.00	490.00	7490.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P) <i>450 / panel</i>	1	3500.00	2700	3500.00	245.00	3745.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	160.00	120	160.00	11.20	171.20
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	380.00	300	380.00	26.60	406.60
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	330.00	250?	330.00	23.10	353.10
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	2500.00	2240	2500.00	175.00	2675.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2500.00	1350	2500.00	175.00	2675.00
<b>Sum Labor</b>					<b>23420.00</b>	<b>1,639.40</b>	<b>25,059.40</b>

Survey By \_\_\_\_\_

Date & Time \_\_\_\_\_

Excess \_\_\_\_\_

Status \_\_\_\_\_

Signature \_\_\_\_\_

**Total Amount** 43,201.10 3,024.09 46,225.19

**Total (Inclusive of GST)** 46,225.19

*Sebastian 12/4/18*

*22/9/18*

*- Part by part repair.*

*- Question Mark Item*

*Photo.*

*18 days.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Printed on 10/4/2018 12:01:23 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

*- Photo Before Paint*

*90036121*

*sebastianyeang@lkk-auto.com*

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Apr 2018		11 Apr 2018 17:07 <a href="#">Edit Adj Rpt</a>	<b>S\$26,163.10</b> <a href="#">Edit Estimates</a>	<b>S\$26,163.10</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>CHLOE LIM HUI</b>								
Vehicle Reg. No.:	<b>SLQ1748M</b>	Date of Loss:	04/04/2018 00:00 - :59 [9 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D01884C02</b>	Policy/Cover Note No.:	DMHCSN1742691700						
Vehicle Reg. No. (Insured):	<b>SJJ9974J</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Kah Motor Co Sdn Bhd (HQ)</b> 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Sebastian Yeang Wai Keen</b> ] ... <b>[Final Rpt due 20/04/2018]</b>								
Adj Asg. Remarks:	EST \$46,225.19, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SLQ1748M (SNM18D01884C02)**  
**[SJJ9974J]**  
**TP**  
**CHLOE LIM HUI**  
**Apr 4 2018 12:00AM**  
**[-]**  
**Kah Motor Co Sdn Bhd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View In Browser</a> ▼	
<b>Photos/Images</b>			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	18/06/18 11:46	<b>General View</b>	 Load PDF	
<b>Documentation</b>			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	11/04/18 17:07	<b>REPAIR EST</b>	 Load PDF	
2	11/04/18 17:07	<b>TP GIA REPORT</b>	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a> <a href="#">Save</a> <a href="#">Print</a>
There are no document checklists configured.	
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>	
<p><b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer</p> <p>Note: Remarks are private unless you show it to other parties.</p>	



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118006779/SVBS2

Date: 27/06/2018

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN1742691700

Claimant Vehicle No: SLQ1748M Insured Vehicle No: SJJ9974J

Date of Loss: 04/04/2018 Nature of Claim: TP Claim No: SNM18D01884C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLQ1748M**

Make & Model: HONDA HR-V, 1.5 (A) Engine No: L15B4532305

Reg. Date: 29/06/2017 (Man. Year: 2017) Chassis No: JHMRU1810GX202305

Colour: Red Odometer: 12118 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16

Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm

Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,981.10	11,303.10	8,678.00	43.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,220.00	14,860.00	8,360.00	36.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>43,201.10</b>	<b>26,163.10</b>	<b>17,038.00</b>	<b>39.44</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,024.08</b>	<b>1,831.42</b>	<b>1,192.66</b>	<b>39.44</b>
<b>Nett Amount (S\$)</b>	<b>46,225.18</b>	<b>27,994.52</b>	<b>18,230.66</b>	<b>39.44</b>

## INSPECTION

Date of Assignment: 11/04/2018

Date Inspected: 12/04/2018 Inspected At: Kah Motor Co Sdn Bhd (HQ)  
6A MANDAI ESTATE, SINGAPORE 729903  
Singapore 729903

Estimated Period of Repair: 18.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$8,354.30 NETT)

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)
<b>Parts:</b> M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLQ1748M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE COMP	Dented	838.90 FS	*838.90 FS
2	1		*WEATHERSTRIP TAILGATE	Deformed	96.80 FS	*96.80 FS
3	1		*GARNISH ASSYRR.LICENCE	*Check	189.80 FS	*- FS
4	1		*CAMERA ASSYRR.VIEW	*Check	611.00 FS	*- FS
5	1		*LOCK ASSY TAILGATE	Damaged	76.60 FS	*76.60 FS
6	1		*SWITCH ASSY TAILGATE OPENER	*Check	103.20 FS	*- FS
7	1		*STRIKER ASSY TAILGATE	Necessary	24.70 FS	*24.70 FS
8	2		*STOPPER TAILGATE	Necessary	7.60 FS	*7.60 FS
9	2		*PROTECTOR LICENCE PLATE	Not Necessary	4.00 FS	*- FS
10	1		*LINING ASSY TAILGATE	Deformed	133.40 FS	*133.40 FS
11	1		*LINING ASSY TAILGATE UPPER	*Check	58.10 FS	*- FS
12	1		*LINING ASSYR. TAILGATE SIDE	*Check	20.90 FS	*- FS
13	1		*LINING ASSYL. TAILGATE SIDE	*Check	20.90 FS	*- FS
14	1		*POCKET TAILGATE PULL	Cut	14.90 FS	*14.90 FS
15	1		*EMBLEMRR.	Necessary	12.90 FS	*12.90 FS
16	1		*EMBLEM,RR. I-VTEC	Necessary	14.10 FS	*14.10 FS
17	1		*RUBBER CR.WINDSHIELD DAMPER	Necessary	19.30 FS	*19.30 FS
18	1		*DAMPERSTD 5X5	Necessary	8.30 FS	*8.30 FS
19	1		*RUBBER CL.WINDSHIELD DAMPER	Necessary	19.30 FS	*19.30 FS
20	1		*CAPPIVOT	Necessary	4.70 FS	*4.70 FS
21	4		*FASTENER BW/SHIELD	Necessary	12.80 FS	*12.80 FS
22	2		*FASTENER B	Necessary	9.80 FS	*9.80 FS
23	2		*FASTENER AW/SHIELD	Necessary	7.00 FS	*7.00 FS
24	2		*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
25	1		*BASE COMPR.TRUNK SIDE LINING	*Check	144.20 FS	*- FS
26	1		*BASE COMPL.TRUNK SIDE LINING	*Check	144.20 FS	*- FS
27	1		*LINING ASSYRR.PANEL	Deformed	43.00 FS	*43.00 FS
28	1		*BOARD ASSYTRUNK FLOOR	Deformed	186.00 FS	*186.00 FS
29	1		*BOX ASSY, CARGO FLOOR	Cracked	126.90 FS	*126.90 FS
30	1		*PANEL COMPR.	Dented	365.70 FS	*365.70 FS
31	1		*PANEL SETRR.FLOOR	Dented	662.20 FS	*662.20 FS
32	3		*OILSHEET	Necessary	119.70 FS	*119.70 FS
33	1		*STIFFENERRR.JACK UP	Necessary	60.20 FS	*60.20 FS
34	1		*CROSSMEMBER COMPR. FLOOR	*Check	81.20 FS	*- FS
35	1		*PANEL SET,R.RR.OUTSIDE	Dented	602.30 FS	*602.30 FS
36	1		*PANEL SETL.RR.OUTSIDE	Repair	602.30 FS	*- FS
37	1		*OUTLETRR AIR	*Check	24.70 FS	*- FS
38	1		*GUTTER COMPR.RR.	*Check	75.30 FS	*- FS
39	1		*GUTTER COMPL.RR.	*Check	75.30 FS	*- FS
40	1		*STIFFENER COMPR.RR.FRAME UPP	*Check	103.20 FS	*- FS
41	1		*STIFFENER COMPL.RR.FRAME UPP	*Check	103.20 FS	*- FS
42	1		*FRAME B SETR.RR.	*Check	413.50 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*FRAME B SETL.RR.	*Check	421.70 FS	*- FS
44	1		*FACE RR.BUMPER	Dented	762.60 FS	*762.60 FS
45	1		*REFLECTOR ASSYR.RR.	*Check	151.80 FS	*- FS
46	1		*REFLECTOR ASSYL.RR.	Cracked	151.80 FS	*151.80 FS
47	1		*FACER.RR.BUMPER CORNER	Cut	92.30 FS	*92.30 FS
48	1		*FACEL.RR.BUMPER CORNER	Cut	92.30 FS	*92.30 FS
49	1		*SPACERR.RR.BUMPER SIDE	Necessary	11.50 FS	*11.50 FS
50	1		*SPACERL.RR.BUMPER SIDE	Necessary	11.50 FS	*11.50 FS
51	8		*CLIPBUMPER	Necessary	16.00 FS	*16.00 FS
52	1		*ANTENNA ASSYL.F.	*Check	58.10 FS	*- FS
53	1		*BUZZER ASSYSMART	Cracked	59.30 FS	*59.30 FS
54	4		*ACT RR.SENSOR	Damaged	320.00 FS	*320.00 FS
55	1		*PROTECTOR,R,RR.WHEEL ARCH	Not Necessary	172.10 FS	*- FS
56	1		*PROTECTOR,L,RR.WHEEL ARCH	Deformed	172.10 FS	*172.10 FS
57	1		*FENDERR.RR.INNER	*Check	90.40 FS	*- FS
58	1		*FENDERL.RR.INNER	*Check	90.40 FS	*- FS
59	1		*COVERRR.FLOOR UN	Deformed	118.30 FS	*118.30 FS
60	1		*LAMP UNITR.	Cracked	428.70 FS	*428.70 FS
61	1		*LAMP UNITL.	Cracked	428.70 FS	*428.70 FS
62	1		*LIGHT ASSY,R.LID	*Check	264.60 FS	*- FS
63	1		*LIGHT ASSYL.LID	Cracked	264.60 FS	*264.60 FS
64	1		*SILENCER COMPEXHAUST	Dented	528.00 FS	*528.00 FS
65	1		*FACE,FR.BUMPER	Cut	466.20 FS	*466.20 FS
66	1		*FACE FR.BUMPER LOWER	Repair	344.20 FS	*- FS
67	1		*GRILLEFR.BUMPER	*Check	77.50 FS	*- FS
68	1		*SPACERR.FR.BUMPER SIDE	Necessary	10.40 FS	*10.40 FS
69	1		*SPACERL.FR.BUMPER SIDE	Necessary	10.40 FS	*10.40 FS
70	1		*CLIPBUMPER	Necessary	44.00 FS	*44.00 FS
			22pcs			
71	1		*HEADLIGHT ASSY,R.	Cracked	1,661.00 FS	*1,661.00 FS
72	1		*BEAMR.FR.BUMPER UPPER	*Check	23.90 FS	*- FS
73	1		*HEAD LIGHT ASSY,L.	Cracked	1,479.70 FS	*1,479.70 FS
74	1		*BEAML.FR.BUMPER UPPER	*Check	23.90 FS	*- FS
75	1		*GARNISHR.FR.FOG LIGHT	*Check	21.10 FS	*- FS
76	1		*GARNISHL.FR.FOG LIGHT	*Check	21.10 FS	*- FS
77	1		*LIGHT ASSYR.FR.FOG	*Check	237.90 FS	*- FS
78	1		*BRACKETR.FOG LIGHT	*Check	49.00 FS	*- FS
79	1		*LIGHT ASSYL.FR.FOGLIGHT	*Check	235.00 FS	*- FS
80	1		*BRACKETL.FOG LIGHT	*Check	49.00 FS	*- FS
81	1		*HOOD COMP ENGINE	Repair	785.20 FS	*- FS
82	1		*HINGE COMPR.HOOD	Bent	39.10 FS	*39.10 FS
83	1		*HINGE COMPL.HOOD	Bent	39.10 FS	*39.10 FS
84	1		*LABLE AIR CON	Necessary	0.80 FS	*0.80 FS
85	1		*LABELCOOLANT INFORMATION	Necessary	4.90 FS	*4.90 FS
86	1		*SET,FR,GRILLE ASSY	*Check	265.50 FS	*- FS
87	1		*MOLDINGFR.GRILLE UPPER	Cracked	186.10 FS	*186.10 FS
88	1		*MOLDINGFR.GRILLE	*Check	42.80 FS	*- FS
89	1		*BEAMR.FR.GRILLE SIDE UPPER	*Check	38.70 FS	*- FS
90	1		*BEAML.FR.GRILLE SIDE UPPER	*Check	4.50 FS	*- FS
91	1		*BEAMR.FR.GRILLE SIDE UPPER	*Check	17.20 FS	*- FS
92	1		*BEAM COMP,FR.BUMPER	Dented	236.60 FS	*236.60 FS
93	1		*BULKHEAD COMP,FR.	Repair	425.90 FS	*- FS
94	1		*CONDENSER COMP	*Check	568.10 FS	*- FS
95	1		*RADIATOR COMP	*Check	1,187.40 FS	*- FS
96	5		*COOLANT ANTI-FREEZE	*Check	116.00 FS	*- FS
97	1		*SUNDRIES	Necessary	200.00 FS	*80.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
<b>Total Parts (\$\$)</b>					<b>19,981.10</b>	<b>11,303.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REPLACE RR. WINDSCREEN.	New	260.00	260.00
2	REMOVE & RENEW REVERSE SENSORS.	New	200.00	160.00
3	INSPECT RR LIGHTING MECHANISM. PERFORM WATER.	New	160.00	120.00
4	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &.	New	800.00	560.00
5	REMOVE & INSTALL REAR COMPARTMENT LININGS.	New	800.00	560.00
6	REMOVE & INSTALL ROOF LINING GARNISHES SEATS.	New	800.00	0.00
7	REMOVE & INSTALL FUEL TANK FUEL PIPES.	New	800.00	280.00
8	BODY JOINT SEALANT FOR TAILGATE.	New	100.00	80.00
9	BODY JOINT SEALANT FOR END PANEL.	New	100.00	80.00
10	BODY JOINT SEALANT FOR FLOOR PANEL.	New	100.00	80.00
11	APPLY BODY UNDERSIDE COATING.	New	250.00	250.00
12	RESET & CALIBRATE SMART ENTRY SYSTEM.	New	160.00	160.00
13	RESET & CALIBRATE REAR VIEW CAMERA.	New	160.00	160.00
14	REMOVE & REFIX TAILGATE SPOILER.	New	160.00	160.00
15	STRAIGHTEN ALIGN & PULL BACK EXHAUST SYSTEM.	New	200.00	200.00
16	PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT. *Check	New	1,800.00	0.00
17	CUT OFF & RENEW RR FLOOR PANEL RR L FENDER.	New	7,000.00	5,040.00
18	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	New	3,500.00	2,700.00
19	INSPECT FR LIGHTING MECHANISM & FOCUS.	New	160.00	120.00
20	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	New	380.00	300.00
21	REMOVE & INSTALL RADIATOR WITH FITTINGS. *Check	New	330.00	0.00
22	STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	New	2,500.00	2,240.00
23	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	New	2,500.00	1,350.00
<b>Gross Labour Cost (S\$)</b>			<b>23,220.00</b>	<b>14,860.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >