

COMFORTDELGRO ENGINEERING PTE LTD

EQ

REPAIR ESTIMATE*

VEHICLE NO : SHB 4222U

DATE 11/4/2018 14:12

MAKE :

J4

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Under Cover ✓			\$ 225.00	
	<i>Rear Bumper clips</i> ✓	<i>10</i>	<i>\$22</i>		
	SUB TOTAL			\$ 828.60	
	LESS 20%			\$ 165.72	
	DISCOUNTED TOTAL			\$ 662.88	
	Rear Bumper Reverse Sensor ✕			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00	Nett
				\$ 385.70	
	Labour Charge			<i>200</i>	
	Panel Beating			\$ 250.00	
	Spray Painting Charge			\$ 250.00	<i>200</i>
	Wiring Charge			\$ 50.00	<i>X</i>
	R/Refix Reverse Sensor			\$ 120.00	<i>20</i>
	TOTAL LABOUR			\$ 670.00	
	ESTIMATE TOTAL			\$ 1,718.58	
<div> <div> <i>Kalvin / UCK</i> <i>11/4/18 1430 hrs.</i> <i>2 Days</i> <i>4/5</i> <i>After Repair photo</i> </div> <div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p> </div> </div> <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					