

12/06/2017

ASS. REC. BY:

REF: CS/CT118006783/Urbn2

Special Instructions:

ASSIGNED:

Manning

ASSIGNMENT (Office)

Medmen

From (Person):

Irene Tay

of

CTI

Date/Time:

12042018 1:41pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 7674D

Insured:

SJR1188Y

at Workshop m/s:

TRANS Eurokars

Tel:

9129 7928

of

5 Ubi Close

Policy No:

DMPCSN1516521712

Claim No:

SJM18D01839C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A:

08042018

CA / REV / REP. / REV 24 HRS WP

13.04.2018 @ 4pm

I.L.O.D. Endorsement:

Date/Time:

12042018 2:15pm

Person Contacted:

Ronald

Vehicle IN

OUT

Date/Time

Action/Instruction (✓) Estimate

SKZ 7674D

SJR 1188Y

12/6/18 9am confirmed final of \$2466.62 with cothease.

3 days

Red. \$ 2933.83, 54%

Submit in Merman

REF: CTL

ASSIGNMENT

Form

Date: 13/04/2018

Estimated Cost

CD / TP / WS / TP RES / CD RES / EVA / INV / MV

As Inspected Vehicle No.:

SKZ 9674D

at Workshop only

Trung Eurokars

at

5 ubi close

Insured

Policy No.

Claims No.

Subs Insured

Excess:

(Client's Record)

Make of Veh.

Honda

(Policy Condition)

4pm

Remarks: The veh had commenced its repair at the time of inspection.

Bot. or Market Value:

IDAC Accident Report

Consistent? Yes or No

Est. Repair:

Consistent? Yes or No

Lump Sum

3 days Res: Yes or No

CA / REV / REP. / 24 HRS

3 Val: Yes or No

Date

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

15/5/18 vehicle hasn't send in for repair
summit pull.

RECEIVED 16 MAY 2018

Value Time File Pass No.

Report

Date/Time File Return No.



Prelim. Report



Final Report

Report Format:

TP

Lump Sum / L.B.T. IS

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp. IS



Inter. Insp. IS



Tech. Insp. IS



Comp. Insp. IS

Survey File

Inspection

1. 2. 3.

4. 5. 6.

7. 8. 9.

10. 11. 12.

13.

SKZ 9674D 2 16
Type: M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or: CA /

Make:

Mazda 3

1496

Colour:

Red

A/C Insured / Std / NI / NA

Sp. Rating:

33506

T-Radio Insured / Std / NI / NA

Eng No.

G.No.

JM6BM 42A860334695

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Ins. / Jammed / Leaked / Burnt or

Brake: Ins. / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L

mm

R/Bal.

L

mm

L/Bal.

L

mm

L/Bal.

L

mm

D.O.A.

8/4/18

D.O.I.

13/4/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt.

The U/C / Chassis frame / Body Structure altered due to collision

Janice Lee (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, June 09, 2018 10:10 AM
To: SUR; Marcus Chua (LKKAUTO)
Subject: FW: SKZ9674D - FINALISATION OF COR
Attachments: 2206_001.pdf; IMG_5528.JPG; IMG_5527.JPG

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi 408933, #02-25 | S(408933)

From: catherinechua@eurokars.com.sg [mailto:catherinechua@eurokars.com.sg]

Sent: Saturday, 9 June 2018 10:06 AM

To: Marcus Chua (LKKAUTO) <Marcus@lkkauto.com>

Cc: ronald.yap@eurokars.com.sg; Catherine Chua <cs-a@lkkauto.com>

Subject: SKZ9674D - FINALISATION OF COR

Dear Marcus

Our COR computation and B4 paint photo are attached for your agreement.

COR: \$2466.62 before GST

3 repair days (not including preparation estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

Kindly confirm the above as soon as possible.

Thanks n Regards

Catherine Chua

Insurance Claims Executive

Trans Eurokars Pte Ltd

DID: 6603 6121

FAX: 6476 7417



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

not submit
3 day
take photo before repair
13/4/18
EUROKARS GROUP

CHINA TAIPING INSURANCE P/L

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

ATTN :

MOTOR CLAIMS

FAX :

NAME : Mr Veera Koti Naga Sankaram

WIP : 16541

ADDRESS : 26 Canberra Drive

EXCESS :

#09-14

DATE: 10-Apr-18

Singapore 768428

TEL : 90218725

VEH NO :

SKZ9674D

DATE IN :

CONTACT PERSON :

RONALD 6395 7875

CHASSIS NO :

JM6BM42A8G0334695

MILEAGE :

TYPE OF CLAIM :

THIRD PARTY CLAIM

MODEL :

MAZDA3 1.5L

DATE REG.:

17-Feb-16

POLICY NO. :

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	RHS FRONT FENDER	1	MB45A-52-111B \$ - 333.90
2	STAY(RHS), FRONT FENDER	1	MB4YA-52-10Y \$ - 39.90
3	RHS FRONT MUDGUARD	1	MB45A-56-130H \$ 97.00
4	FASTENER, MUDGUARD	10	MB45A-56-146A \$ 28.00
5	WHEEL,DISC (RHF)	1	M9965-D0-6560 \$ 1,101.70
TOTAL PARTS			\$ 1,600.50
LESS 10%			\$ 160.05
TOTAL PARTS COST			\$ 1,440.45

Labour Description

1	TO REPLACE RHS FRONT FENDER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,320.00
2	TO RESPRAY RHS FRONT FENDER, bumper	945	\$ 1,260.00
3	MZ-BR-WHEBAL TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	11X	NETT \$ 120.00
4	MZ-BR-WHEALI TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	200	NETT \$ 560.00
5	MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
6	MZ-BR-REPROG TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
7	MZ-BR-SUNDRI SUNDRIES.	30	NETT \$ 100.00
TOTAL LABOUR			\$ - \$ 3,960.00
TOTAL PARTS			\$ - \$ 1,440.45

TOTAL	\$ -	\$ 5,400.45
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED. BEFORE THE REPAIRS ARE BEING CARRIED OUT, TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$300 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorised Signature

- LINK Auto Consultants will notify the Repairer of the following:
- To resurvey / re-spray painting
 - To replace / damaged parts) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No legal action is allowed
 - Supplier warranty items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



CHINA TAIPING INSURANCE P/L		NAME : Mr Veera Koti Naga Sankaram		WIP : 16541	
3 ANSON ROAD		ADDRESS : 26 Canberra Drive		EXCESS :	
#16-00 SPRINGLEAF TOWER		#09-14		DATE: 10-Apr-18	
SINGAPORE 079909		Singapore 768428			
ATTN. : MOTOR CLAIMS		TEL : 90218725			
FAX :					
VEH NO :	SKZ9674D	DATE IN :		CONTACT PERSON :	RONALD 6395 7875
CHASSIS NO :	JM6BM42A8G0334695	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA3 1.5L	DATE REG.:	17-Feb-16	POLICY NO. :	

NATURE OF WORKS

Parts Description			REVISED	PRICES
NO	QTY			
1	1	MB45A-52-111B	\$ 333.90	\$ 333.90
2	1	MB4YA-52-10Y	\$ 39.90	\$ 39.90
3	1	MB45A-56-130H		\$ 97.00
4	10	MB45A-56-146A	\$ 28.00	\$ 28.00
5	1	M9965-D0-6560		\$ 1,101.70
TOTAL PARTS			\$ 401.80	\$ 1,600.50
LESS 10%			\$ 40.18	\$ 160.05
TOTAL PARTS COST			\$ 361.62	\$ 1,440.45

Labour Description

1	TO REPLACE RHS FRONT FENDER. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 660.00	\$ 1,320.00
2	TO RESPRAY RHS FRONT FENDER.	\$ 945.00	\$ 1,260.00
3	MZ-BR-WHEBAL TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.		\$ 120.00
4	MZ-BR-WHEALI TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	\$ 200.00	\$ 560.00
5	MZ-BR-ELECTR TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
6	MZ-BR-REPROG TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
7	MZ-BR-SUNDRI SUNDRIES.	\$ 30.00	\$ 100.00
TOTAL LABOUR		\$ 2,105.00	\$ 3,960.00
TOTAL PARTS		\$ 361.62	\$ 1,440.45
TOTAL		\$ 2,466.62	\$ 5,400.45
LESS EXCESS		\$ -	\$ -
TOTAL AFTER EXCESS		\$ 2,466.62	
GST 7%		\$ 172.66	\$ -
GRAND TOTAL		\$ 2,639.28	\$ -

REMARKS:

3 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18006783/URBN2

Date: 21/06/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1516521702
Claimant Vehicle No :	SKZ9674D	Insured Vehicle No :	SJR1188Y
Date of Loss:	08/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01839C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKZ9674D	Engine No:	P520350641
Make & Model:	MAZDA 3, 1.6 L (A)	Chassis No:	JM6BM42A8G0334695
Reg. Date:	17/02/2016 (Man. Year: 2016)	Odometer:	33506 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Toyo 8 mm	Rear Left Side:	Toyo 8 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,540.45	391.62	1,148.83	74.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	2,075.00	1,785.00	46.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,400.45	2,466.62	2,933.83	54.33
+ GST 7.00/7.00% (\$\$)	378.03	172.66	205.37	54.33
Nett Amount (\$\$)	5,778.48	2,639.28	3,139.20	54.33

INSPECTION

Date of Assignment:	12/04/2018	
Date Inspected:	13/04/2018 Inspected At:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave Singapore 729648
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2018)
Parts:	143	MAZDA 3 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ9674D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RHS FRONT FENDER	Badly Dented	333.90 FL	*333.90 FL
2	1		*STAY (RHS), FRONT FENDER	Necessary	39.90 FL	*39.90 FL
3	1		*RHS FRONT MUDGUARD	Not Necessary	97.00 FL	*- FL
4	10		*FASTENER,MUDGUARD	Necessary	28.00 FL	*28.00 FL
5	1		*WHEEL,DISC (RHF)	Repair	1,101.70 FL	*- FL
6	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					1,700.50	431.80
- List Item Discount on L Items 10.00/10.00% (S\$)					160.05	40.18
Total Parts (S\$)					1,540.45	391.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE RHS FRONT FENDER.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,320.00	660.00
2	TO RESPRAY RHS FRONT FENDER,BUMPER	New	1,260.00	945.00
3	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	-
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	200.00
5	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
6	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	150.00
Gross Labour Cost (S\$)			3,860.00	2,075.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >