

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 16 Apr 2018

## **Preliminary Advice**

|                    |                                                       |                         |              |
|--------------------|-------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SJK9169L                                            |                         |              |
| TP Vehicle No      | : SFR9899Z                                            | Accident Date           | : 09/04/2018 |
| Make               | : BMW 730LI                                           | Assignment Date         | : 12/04/2018 |
| Date of Inspection | : 13/04/2018                                          | Est. Duration of Repair | : 4.00       |
| Inspection At      | : TORQUE5 (HQ)                                        |                         |              |
|                    | 8 KAKI BUKIT AVE 4 #01-49/50/51/52/53/54 PREMIER @ KB |                         |              |
|                    | SINGAPORE 415875                                      |                         |              |

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 15,454.50 |
| Revised Amount              | :S\$ | 5,230.40  |
| Check Items (Estimated)     | :S\$ | 1,044.60  |
| Total                       | :S\$ | 6,275.00  |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

( ) The vehicle is economical/not economical for repair.

( x ) The above survey was conducted on a 'without prejudice' basis.