



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving

1 2014 MITSUBISHI FUSO FP51SDR3VDEA MITXXX (XE706L)

Date of Loss

29 March 2018

Time of Loss

0.00

Loss Description

XE706L (INSD) C/W XD2863H

Comment

### Workshop Details

Total Rebate Amount

36471

Nett Loss Amount

\$58,529.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion \*

10/06/2018



Days of work completion \*

59



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Vehicle & Driver Details

Vehicle Registration#

XE706L

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date \*

16/06/2015



Mileage

139041

Age of Vehicle

2

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2014

ASSESSMENT INFO...

2014

### Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

POST SURVEY INF...

|                    |                                         |
|--------------------|-----------------------------------------|
| CATEGORY           | Make                                    |
| POLICY INFORMAT... | mitsubishi fuso fp51sdr3vdea            |
| ASSESSMENT INFO... | <input type="text" value="mitsubishi"/> |

|                    |                                                |
|--------------------|------------------------------------------------|
| CATEGORY           | Model                                          |
| POLICY INFORMAT... | mitxxx                                         |
| ASSESSMENT INFO... | <input type="text" value="fuso fp51sdr3vdea"/> |

|                    |                      |
|--------------------|----------------------|
| CATEGORY           | Type                 |
| POLICY INFORMAT... |                      |
| ASSESSMENT INFO... | <input type="text"/> |

|                    |                      |
|--------------------|----------------------|
| CATEGORY           | Type of Paint        |
| POLICY INFORMAT... |                      |
| ASSESSMENT INFO... | <input type="text"/> |

|                    |              |
|--------------------|--------------|
| CATEGORY           | Chassis No   |
| POLICY INFORMAT... | fp51sda10143 |

|                    |                                                                                                                             |
|--------------------|-----------------------------------------------------------------------------------------------------------------------------|
| CATEGORY           | Date of Birth                                                                                                               |
| FNOL INFORMATI...  |                                                                                                                             |
| POST SURVEY INF... | <input type="text" value="dd/mm/yyyy"/>  |

|                    |     |
|--------------------|-----|
| CATEGORY           | Age |
| FNOL INFORMATI...  |     |
| POST SURVEY INF... |     |

|                    |                      |
|--------------------|----------------------|
| CATEGORY           | Occupation           |
| FNOL INFORMATI...  |                      |
| POST SURVEY INF... | <input type="text"/> |

|                    |                         |
|--------------------|-------------------------|
| CATEGORY           | Education Qualification |
| FNOL INFORMATI...  |                         |
| POST SURVEY INF... | <input type="text"/>    |

|                    |                    |
|--------------------|--------------------|
| CATEGORY           | Driving Experience |
| FNOL INFORMATI...  |                    |
| POST SURVEY INF... |                    |

|          |                  |
|----------|------------------|
| CATEGORY | Driver License # |
|----------|------------------|

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... OM457297610

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI...  
POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI...

POST SURVEY INF...  

CATEGORY License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...  

CATEGORY Address

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI...

FNOL INFORMATION

POST SURVEY INF...

CATEGORY

Gender

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Marital status

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

Identification #

FNOL INFORMATI...

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous

Summary

## Detailed Assessment

Inspection Date \*

13/04/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

3000

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

295/80R22.5

## Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



## Tyre Condition

Spare wheel

Rear Tyre Size

295/80R22.5(D)

Front left side

TBBTIRES8mm

Front right side

TBBTIRES8mm

Rear left side

TBBTIRES8/8mm

Rear right side

TBBTIRES8/8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous

Summary

### Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

### Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

☒ Yes   ☐ No

Part Supplied by AXA

## Assessment Details

General & Workshop Details   Vehicle & Driver Details   Vehicle Condition   Taxes & Ratio   Parts & Labour   Miscellaneous   Summary   **Parts**

Add

Approve

Deny

|                                                                                     | EDIT                                                                                | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME       | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION | LIST PRICE | DEPR/ BTTR% | DISC OUNT% | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-------|-----------|----------|------|-----------------|-------------|------------------------|-----------|------------|-------------|------------|-----------|-----------------|----------------|
|    |    | 1     | 1         |          |      | FRONT BUMPER    |             |                        | Bent      | 1227       |             |            |           | 1227            | Reviewing      |
|    |    | 2     | 1         |          |      | FRONT PANEL     |             |                        | Bent      | 1402       |             |            |           | 1402            | Reviewing      |
|    |    | 3     | 1         |          |      | FRONT CARPLATE  |             |                        | Bent      | 38         |             |            |           | 38              | Reviewing      |
|    |    | 4     | 1         |          |      | GRILL UPPER     |             |                        | Cracked   | 480        |             |            |           | 480             | Reviewing      |
|    |    | 5     | 1         |          |      | GRILL LOWER     |             |                        | Cracked   | 568        |             |            |           | 568             | Reviewing      |
|    |    | 6     | 1         |          |      | BUMPER STEP     |             |                        | Cracked   | 230        |             |            |           | 230             | Reviewing      |
|    |    | 7     | 1         |          |      | PANEL LOCK LH   |             |                        | Bent      | 188        |             |            |           | 188             | Reviewing      |
|    |    | 8     | 1         |          |      | PANEL LOCK RH   |             |                        | Bent      | 188        |             |            |           | 188             | Reviewing      |
|  |  | 9     | 1         |          |      | LATCH LH        |             |                        | Bent      | 35         |             |            |           | 35              | Reviewing      |
|  |  | 10    | 1         |          |      | LATCH RH        |             |                        | Bent      | 35         |             |            |           | 35              | Reviewing      |
|  |  | 11    | 1         |          |      | BUMPER SIDE LH  |             |                        | Deformed  | 246        |             |            |           | 246             | Reviewing      |
|  |  | 12    | 1         |          |      | BUMPER SIDE RH  |             |                        | Deformed  | 246        |             |            |           | 246             | Reviewing      |
|  |  | 13    | 1         |          |      | CORNER PANEL LH |             |                        | Cracked   | 407        |             |            |           | 407             | Reviewing      |

|  | EDIT | SR NO | QUAN TITY | MATERIAL | SIDE | PART NAME           | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION   | LIST PRICE | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | PART PRICE(NET) | ACTION (PARTS) |
|--|------|-------|-----------|----------|------|---------------------|-------------|------------------------|-------------|------------|--------------|------------|-----------|-----------------|----------------|
|  |      | 14    | 1         |          |      | CORNER PANEL RH     |             |                        | Cracked     | 407        |              |            |           | 407             | Reviewing      |
|  |      | 15    | 1         |          |      | HEADLAMP GARNISH LH |             |                        | Deformed    | 98         |              |            |           | 98              | Reviewing      |
|  |      | 16    | 1         |          |      | HEADLAMP GARNISH RH |             |                        | Cracked     | 98         |              |            |           | 98              | Reviewing      |
|  |      | 17    | 1         |          |      | FOG LAMP GARNISH LH |             |                        | Deformed    | 98         |              |            |           | 98              | Reviewing      |
|  |      | 18    | 1         |          |      | FOGLAMP GARNISH RH  |             |                        | Serviceable | 0          | 0            | 0          | 0         | 0               | Deny           |
|  |      | 19    | 1         |          |      | WATER TANK          |             |                        | Deformed    | 518        |              |            |           | 518             | Reviewing      |

#### Labour

|  | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME                                      | LABOUR R&R | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMOVE |
|--|------|-------|-------------------------|------------------------------------------------|------------|---------------|-------|-----------------|---------|--------|
|  |      | 1     |                         | SPRAY PAINT                                    | 450        | 0             | 0     | Reviewing       |         |        |
|  |      | 2     |                         | PANEL BEAT BUMPER BRACKET & BUMPER TOP PANEL } | 1200       | 0             | 0     | Reviewing       |         |        |
|  |      | 3     |                         | LABOUR }                                       | 0          | 0             | 0     | Reviewing       |         |        |

# Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Ratio    Parts & Labour    Miscellaneous    Summary

Add

Approve

Deny

| EDIT |  | SR NO | NAME                    | ACTION    | AMOUNT | COMMENT   | REMOVE |
|------|--|-------|-------------------------|-----------|--------|-----------|--------|
|      |  | 1     | DAYS OF REPAIR : 6 DAYS | Reviewing |        |           |        |
|      |  | 2     | LOGO                    | Reviewing | 100    | NECESSARY |        |

# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount \$5,259.00

Claim Amount \$5,259.00

| CATEGORY      | ESTIMATE    | REVISED AMOUNT |
|---------------|-------------|----------------|
| Labour        | \$1,650.00  | \$1,650.00     |
| Miscellaneous | \$100.00    | \$100.00       |
| Excess        | -\$3,000.00 | -\$3,000.00    |
| Spare Parts   | \$6,509.00  | \$6,509.00     |

Submit for Review