

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 7153X

MAKE :

MODEL : HYUNDAI i40

DATE 12/4/2018 10:46

EQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓ <i>Returned</i>			\$ 603.60
	Rear Bumper Clips ✓ <i>in</i>			\$ 22.00
	SUB TOTAL			\$ 625.60
	LESS 20%			\$ 125.12
	DISCOUNTED TOTAL			\$ 500.48
	Rear Bumper Rubber Mat X <i>4x</i>			\$ 50.00
				\$ 50.00
	Labour Charge			<i>200</i>
	Panel Beating			\$ <del>250.00</del>
	Spray Painting Charge			\$ <del>500.00</del>
	Wiring Charge			\$ <del>50.00</del>
	R/Refix Reverse Sensor			\$ <del>120.00</del>
	TOTAL LABOUR			\$ 920.00
	ESTIMATE TOTAL			\$ 1,470.48
	<i>Kahn' 11/11/11</i>			
	<i>// 12/4/18 1400h</i>			
	<i>2 Rep.</i>			
	<i>4/s</i>			
	<i>After Repair photo</i>			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplementary items must be approved and is subject to final approval by LKK Auto Consultants Company

Acknowledged by: Repairer  
Signature:  
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.