Berveyor REF: COI / LA	W18006904/DGb9V	Special Instruction:	
, J .	GNMENT (Office)	Purl by Part: #57	60-89
From (Person): Sir / Madam of Benedict Chan	GINIVIETY (OTHER)	Third Parties:	
Estimated Cost: Bill to:	Date/Time: 1904200	Claimant:	
			Appraisal & Formteam
OD/TP Re-inspection / (Evaluation)		Workshop: (ar L	
To Inspect Vehicle No: SGM 12028		The second secon	in riulo
0 1/0 - 1	Insured: SJA 43061		
at Workshop m/s (ar Life Auto	Tel: 6273 3810		
BIK 1007 Bukit Merith		Mar. 0.4 00 have	
Policy No:	Claim No: 8(-50831.	0017 CM DC MC	
Sum Insured:	Excess:		
Make of Veh:	D.O.A 01 05 201		
Client's Record)		SJE	
		H.O.D. Endorsement/Date:	
Date/Time: Person Contacted:	Vehicle IN / O	JT	
Date/Time: Confirmed with			gina! 6 days)
Date/Time: Submit Final Fig			
Date/Time Action/Instruction	Tank fel	Dila Al in	
Shm 12018 - NEA /CALIYOO	8331 (61	DOB- 01 0514	(M. (Mar) - M. (M. (1 + 4 + 4 + 4 + 4 + 4 + 4 + 4 + 4 + 4 +
I SUM HOUSE - X			7777777777
05/04/18 To Stomit PIP 47	54.26 . DIT 4 de	1, 8, ~.4	M \$1006.65 (7)
From Team and In	depended energe 1	opt seen and	churched.
FTA recommended LIS	in whereis indepen	and was 117	
Bietra photo point ?	note show PEAS CA	ringed. So roro	mount.
should be ? !? eve	a of valice is mo	a then 3 years	«(»\.
(and be no parts .	Mail Cod ,	110	
	τ.	V NO 141	
Para(1): Parts found not replaced (To	highlight R or UB,	ID Etc.)	
(1)	mgmight K or OB,	LR, Etc)	
Para(2) : Comments on consists	(D.) N (C.)	3160	
Para(2): Comments on consistency of d	amages (Parts Not Cons	stent: NC)	
BEACHAIT D. 2. 2	APR 2018		
RECEIVED 2 1	HILL EVIN		
Para(3): Nett Value		232	
		Fee Charged:	Date:
Market Value :	Inspected/	Basic & Add	700
Column V. I	Evaluated by:	Transport	
Salvage Value :	-11	Photos	
Nett Value :		Others	
		Total	
1) Date/Time 79 4 18 File Pass to MA	2) Date/Time	File Return to	
Date/Time File Pass to			
1 110 1 433 10	4) Date/Time	File Return to	

BENEDICT CHAN & COMPANY

Advocates & Solicitors

Commissioner for Oaths/Notary Public

14 Fort Road Singapore 439075 Tel: 6220 6088 Fax: 6220 6087 GST Registration No. M90358364E

We do not accept service of court documents by fax

Our Ref :

BC 50831.0614.CLA.DC.mc

Your Ref:

To be advised

Please quote our reference number when replying

=6 APR 2018

BY FAX (62564315)/BY POST

M/s LKK Auto Consultants Pte Ltd 51 Ubi Avenue 1 #01-25 Paya Ubi Industrial Park Singapore 408933.

Dear Sirs.

ACCIDENT INVOLVING SGM 1202B AND SJA 4506H AT CARPARK OF IKEA TAMPINES ON 01.05.2014

We act for Mr Chua Poh Yong, whose motor car No. SGM 1202B was damaged in the abovementioned accident.

The damage to our client's said motor car was repaired at M/s Car Life Auto Engineering Services in accordance with a survey report prepared by M/s JAS Appraisal Services.

There is now a pending claim in MC/MC 4764/2015 by our client for damages for the damage caused to our client's said motor car and consequential losses and expenses incurred by our client as a result thereof.

For the purpose of the proceedings as well as for parties to explore the possibilities of resolving the matter amicably, parties have agreed to appoint M/s LKK Auto Consultants Pte Ltd, as the Single Joint Expert.

We accordingly enclose herewith a copy each of the following for your reference:-

accident report by our client; 1)

accident report by the Defendant, the driver of SJA 4506H; 2)

survey report by M/s JAS Appraisal Services with coloured photographs of 3) motor car No. SGM 1202B; and

re-survey report by M/s FormTeam Consultancy Pte Ltd dated 24.07.2015. 4)

Please be informed that our client's motor car has been scrapped and is not available for re-inspection.

M/S BENEDICT CHAN & COMPANY

We look forward to receiving the Single Joint Expert report as soon as possible.

Thank you.

Yours faithfully,

BENEDICT CHAN & COMPANY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available
 aforesaid.

	\sim	and the same of	1177	ТΛ	IENI
-	-	IUCI	4 I O		

Date Of Report 02/05/2014 18:01

Date Of Accident 01/05/2014 12:00

Exact Location Of Accident IKEA CARPARK (TAMPINES BRANCH)

Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGM1202B

Insured/Policyholder

Name Of Registered Owner CHUA POH YONG (CAI BAORONG)

NRIC No S7602607F

Vehicle Particulars

Manufacturer TOYOTA

Model YARIS E AUTO

Exact Purpose for which vehicle was being used

at time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

140

If No, Please state action to be taken

Third Party Private Car

Insurance Company

Vehicle Category

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.

Type Of Coverage Comprehensive

Fleet Policy No.

Policy Number DMPSCN3065781306

Cover Note Number

Driver

Name of Driver CHUA POH YONG (CAI BAORONG)

 NRIC No
 \$7602607F

 Date Of Birth
 23/01/1976

 Occupation
 Indoor

 Date Of Driving Pass
 12/02/2004

Driving Experience 10 Years And 2 Months

Gender Female

Mobile Number (Local) +65-96552932

Fax Number Contact Number

EMail Address pohyong@powerworks.com.sg

Address BLK 578 ANG MO KIO AVENUE 10 #11-1941

Postcode 560578

Was driver an employee of the Insured's Company No

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

Owner

-

arance Company of Driver's Own Vehicle

3

General Information of the Accident

Type Of Accident

Collision- Head to Side

Weather Conditions

Clear

Road Surface

Dry

Other Information

Was any foreign vehicle involved in this accident?

No

Was any body injured in the Accident?

No

Was any other material or property damaged?

Yes

Was there any video captured by Car Camera?

No

Details of Police Action

Was the accident reported to the police?

No

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

No

If Yes, against whom?

Circumstances of Accident

ON 01/05/2014 AROUND 12PM WHEN ENTERING INTO IKEA CARPARK (TAMPINES BRANCH) TOWARDS THE RAMP TO 2ND STOREY OF CARPARK (STRAIGHT DIRECTION) (SGM1202B) SUDDENLY A CAR SJA4506H TURN INTO RIGHT AND HIT SGM1202B, AS A RESULT SGM1202B, FENDER, BUMPER, SPOILER, AND LAMP AND RETAINER WAS DAMAGE AT DRIVER'S SIDE.

Are accident photos available for attachment?

Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJA4506H

Vehicle Make/Model/Colour

HONDA STREAM 1.8 RSZ A

Details Of Properties

Name of Driver

MAISARAH BINTE MOHAMED AFFENDI

NRIC/Passport Number

S8702596I

Contact Number

90705292

Address

Postcode

Insurance Company Name

NTUC Income Insurance Co-operative Ltd

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any withit misrepresentation or with ording of material facts may allow insurance completies to repudiate policy flability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for investigation.
- 5. The report will be forwarded by the insurers of the GrA Records Management Centre established by the General insurance Association of Singepore (GIA) for archiving and that clause of this report will for a fee be made evaluable upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this

Sketch Plan

Mi	r	d	ř	v		
0		L,	1			

Stimuly I to company 5)A 45064

Describe Circumstances of the Accident

CAT	tolk (street)	strainst du	richin ICS	6m. 2028	2 Sudden	T.
Cor	230 H576 H	const ho	n into	mount	and but	
5011	1707B A	s a res	wit so	m 12725	frode	SHAPK.
Opr. KI	, word lamp	mad net	HIMLI V	Vas dam	ist at de	Wer sid

Declaration

I/We declare the foregoing particulars are true in every respect.

1127am

Driver's Signature (if onver is not the policyholder). Date & Time

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

578. 九年30. 678. 12. 12. 12. 12. 12. 12. 12. 12. 12. 12. 12. 12. 12. 12. 12. 12.	ACCIDENT STATEMENT
Date Of Report	02/05/2014 10:07
Date Of Accident	01/05/2014 12:20
Exact Location Of Accident	IKEA CARPARK TAMPINES
Country/State of Loss	Singapore
STATE AS A MEDICAL TRACK TO THE STATE OF THE PARTY.	SETALLS OF CURLYENIOLE

第一个人的对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对对	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJA4506H	
Insured/Policyholder		

Name Of Registered Owner	MOHD AFFENDI BIN M LANEE
NRIC No	S1249858F

Vel	hic	le	Parti	cu	lars

Manufacturer	HONDA
--------------	-------

Model	STREAM-1.8 RSZ (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy Yes for repair to your vehicle?

If No. Please state action to be taken

Vehicle Category Private Car

Insurance Company

Name of Insurance Company NTUC Income Insurance Co-operative Ltd

Type Of Coverage Comprehensive

Fleet Policy No

Policy Number 5025252014-06

Cover Note Number

Driver

Name of Driver MAISARAH BINTE MHD AFFENDI

NRIC No. S8702596I Date Of Birth 13/02/1987 Occupation Indoor Date Of Driving Pass 01/02/2008

Driving Experience 6 Years And 3 Months

Gender Female

(Local) +65-90705292 Mobile Number

Fax Number Contact Number

EMail Address NOEMAIL

Address BLK 304 TAMPINES ST 32 #09-76

Postcode Was driver an employee of the Insured's Company No If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

Children

General Information of the Accident

Type Of Accident

Collision- Side Road Major Road

Weather Conditions

Road Surface

Clear Dry

Other Information

Was any foreign vehicle involved in this accident?

Was any body injured in the Accident?

No No

Was any other material or property damaged?

Yes

Was there any video captured by Car Camera?

No

Details of Police Action

Was the accident reported to the police?

No

If Yes Please state which Police Station

Was notice of intended Prosecution given?

No

If Yes, against whom?

Circumstances of Accident

AS PER SKETCH PLAN ATTACHED

Are accident photos available for attachment?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

SGM1202B

Sketch Plan Pg.1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Sketch Plan		144114141	1	FERRIS	
	refar to	apparl's	A		
		H_{1}			

Describe Circumstances of the Accident

I was traveiling on the number mood in Ikea compark (Level I) and was about T	D
him and to the right to make an exit-I dod my furrounding checks espe	
the left side before turning out and As I was inching all due to t	D NO
sight of any approaching vehicle, I was hit out on the left side of	the
car-	

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholders Signature / Date &


Driver's Signature (If driver is not the policyholder) / Date & Time

2/5/2014

Witnessed by Reporting Centre Personnel

Appendix A

A-SJA 4506H B-SGM 1202B









22 Sin Ming Lane #06-83 Midview City Singapore 573969 Hand phone No. 98467316 Co. Reg. No. 53202241J

AUTOMOBILE INSPECTION REPORT

Chua Poh Yong

Our Reference

: JASTP/C2/117

Block 578 #11-1941

Ang Mo Kio Avenue 10

Date

: 11th June 2014

Singapore 560578

REFERENCE

Assigned By

: Repairers, owner's behalf

Insured Vehicle: Not Advised

Type of Claim

: Third Party Claim

Policy No.

: Not Advised

Date of Assessment

: 7th May 2014

Claim No

: Not Advised

Date of Inspection Date of Accident

: 7th May 2014 : 1st May 2014

Sum Insured Excess

: Not Advised : Not Advised

Name of Workshop

: Car Life Auto Engineering Services

Block 1002 #01-75 Bukit Merah Lane 3 Singapore 159719

PARTICULARS OF DAMAGED VEHICLE

Registration No.

: SGM 1202 B

Gen. Condition : Good

Make & Model

: Toyota Yaris : 2006

Body Paintwork: Good Air Con

: Fitted

Year of Registration Engine Capacity

: 1497cc

Seat Belt

: Fitted : Fitted

Engine No. Chassis No.

Colour

: 1NZX483955 : MR054HY9104019569 Radio/CD Steering

: Serviceable : Serviceable

Odometer Reading

: 232625Km : Silver

Hand Brake Foot Brake

: Serviceable

CONDITION OF TYRES

Front o/s tyre

: Falken 195/50 R 15 approximately 60%

Front n/s tyre

: Falken 195/50 R 15 approximately 60%

Rear o/s tyre Rear n/s tyre

: Falken 195/50 R 15 approximately 60% : Falken 195/50 R 15 approximately 60%

Note: The above percentages denote the remaining estimated life of the tyre thread.

22 Sin Ming Lane #06-83 Midview City Singapore 573969 Hand phone No. 98467316 Co. Reg. No. 53202241J

Our Reference

: JASTP/C2/117

Registration No.

: SGM 1202 B

GENERAL REMARKS

At the time of inspection, we noted that this vehicle has sustained impact damages on the front RH portion.

The vehicle was inspected thoroughly based on the repairer's estimate. We have listed the breakdown as per schedule attached.

Original Quotation

\$ 6,205.89

Revised Quotation

: \$ 5,760.89 (Part by Part)

Less Excess

. \$

Nett Liability

: \$ 5,760.89

Thirty-four (34) photographs were taken during our inspection.

Under normal circumstances, the estimated repair period would be approximately six (6) working days.

In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a 'Without Prejudice' basis. We hope that this report will be of assistance to you in dealing with this matter.

Should you discover any discrepancy in this report, please kindly notify us within two (2) weeks or this report will be treated as valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/ or other accidents in other legal proceedings.

22 Sin Ming Lane #06-83 Midview City Singapore 573969 Hand phone No. 98467316 Co. Reg. No. 53202241J

CONDITION/

REMARKS

REVISED

QUOTATION

ORIGINAL

QUOTATION

Our Reference

QTY

JASTP/C2/117

Registration No.

SGM 1202 B

DESCRIPTION

		LIST PARTS	6			
1	рс	Front bumper	deformed	\$	368.15	\$ 368.15 —
	pc	Front bumper RH retainer	necessary	\$	85.70	\$ 85.70
	pc	Front bumper reinforcement No 7kAo	bent	\$	372.90	\$ 372.90 더시
	pc	Front bumper lower spoiler	torn	\$	329.00	\$ 329.00
	pc	Front bumper grille	deformed	\$	67,20	\$ 67.20 SV 4
	pc	Front RH fender	badly dented	S	519.32	\$ 519.32 -
	рс	Front RH fender cowling	deformed	\$	115.00	\$ 115.00
	pc	RH headlamp	cracked	\$	487.60	\$ 487.60
	pc	RH headlamp bracket	bent	\$	75.10	\$ 75.10
	рс	Wiper washer tank No Philip	deformed	\$	115.40	\$ 115.40 NH
		Front RH tyre rim	bent	\$	288.01	\$ 288.01
	pc	E DILL	distanted	\$	427.10	\$ 427.10
	pc	Staaring rock & pinion	distorted	\$	1,573.60	\$ 1,573.60 —
	pc set	Steering rack & pinion Clip 14375	necessary	\$	57.10	\$ 57.10
1	SCL	Steering rack & pinion Clip 4325-69 3244-26	neecomy	\$	4,881.18	\$ 4,881.18
		2744 16	Less 25%	\$	1,220.30	\$ 1,220.30
		7 /		S	3,660.89	\$ 3,660.89
		LABOUR CHARGES				
		To remove and check all electrical components,				
		wirings and control unit and test for function.		\$	60.00	\$ 30 -
		To remove the affected parts and all relevant				
		fittings and attachments to commence repairs.				
		Jack up, straighten, cut and weld the above				1
		listed parts. Panel beat and reshape the affected				6001-
		area. Replace and realign where necessary.		\$	1,000.00	\$ 920.00
		To putty and spray painting on accident affected	17			600/-
		area and to touch up paint work.	Spis	\$	800.00	\$ 720.00
		To apply undercoating on the replaced and repa	ired			
		portion for rust protection.		\$	280.00	\$ 100.00
						70

22 Sin Ming Lane #06-83 Midview City Singapore 573969 Hand phone No. 98467316 Co. Reg. No. 53202241J

Our Reference

JASTP/C2/117

DESCRIPTION

Registration No.

QTY

SGM 1202 B

LABOUR CHARGES			
To jack up vehicle to facilitate replacement of undercarriage components.	s	260.00	\$ 150 -
To remove and replace front RH tyre including wheel balancing.	s	50.00	\$ 30 - 45.00
To check steering geometry and computer wheel			601

The repairers have agreed to undertake repairs at our adjusted amount of \$ 5,760.89 (Five thousand seven hundred sixty and cents eighty-nine only).

David Thor

alignment.

Automobile Appraiser

4 295

CONDITION/

REMARKS

ORIGINAL

OUOTATION

6,205.89

\$

5,760.89

REVISED

QUOTATION

FormTeam Consultancy Pte Ltd

Our Reference :

RRN15-030726/RI/BC/cg

Your Reference:

MT/CA/TP/009/0827631-002/JL/LC

Date

24-Jul-2015

Motor Claims Department NTUC Income Co-Operative Limited 1 Maritime Square #10-01 Harbourfront Centre Singapore 099253

Attention

Ms Juliana Lec

Dear Sir/Mdm,

RE-INSPECTION OF VEHICLE NO .

SGM 1202B

Pursuant to your instructions on 27 Mar 2015, we have conducted a reinspection of the above vehicle at 1002 Bukit Merah Lane 3 #01-75 S 159719 on 20 July 2015.

We recommend a repair cost of

\$4,000.00

(see report) based on lump sum repair and

No. 33, Uhi Ave 3 #102-15, Vertex Singapore 408868 Tel : (65) 6500 1788

Fax: (65) 6509 6221

Co.Reg No: 2008192861) GST Reg No: 200819280D

Email: motorsurvey@fta.com.sg

the estimated duration of repairs would take

04 days

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

FormTeam Consultancy Pte Ltd

Adjusters & Surveyors (Licensed Appraiser)

Benjamin Chua

MSAAA

Licensed Appraiser

(Email: benchua@fta.com.sg)

Encl. Re inspection Report

FormTeam Consultancy Pte Ltd

AUTOMOBILE ASSESSMENT REPORT

PAGE: 1

Our Reference :

RRN15-030726/RI/BC/cg

Your Reference :

MT/CA/TP/009/0827631-002/JL/LC

Date

24-Jul-2015

Attention

Ms Juliana Lee

TO: Motor Claims Department

NTUC Income Co Operative Limited

1 Maritime Square

#10-01 Harbourfront Centre

Singapore 099253

Dear Sir/Madam,

Vehicle No

: SGM 1202B

Model

: Toyota Yaris E (A)

Milcage

: 270351 km

Chassis No

: MR054HY9104019569

Workshop

: M/S Car Life Auto Engineering Services

Pursuant to your instructions on 27 Mar 2015, we have conducted a reinspection of the above vehicle at 1002 Bukit Merah Lane 3 #01-75 S'159719 on 20 July 2015.

We are pleased to submit hereunder an adjustment of the Repairers bill which we trust should serve your purpose: -

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
	PARTS REPLACEMENT-LIST ITEMS				
1.	Front Bumper	Deformed		368.15	368.15
1	Front Bumper RH Retainer	Necessary		85.70	85.70
1	Front Bumper Reinforcement	Not Affected	No Photo	372.90	8
			Shown		
1	Front Bumper Lower Spoiler	Torn		329.00	329.00
1	Front Bumper Grille	Reusable		67.20	81
1	Front RH Fender	Badly Dented		519.32	519.32
1	Front RH Fender Cowling	Deformed		115.00	115.00
1	RH Headlamp	Cracked		487.60	487.60
1	RH Headlamp Bracket	Bent		75.10	75.10
1	Wiper Washer Tank	Deformed		115.40	115.40
1	Front RH Tyre Rim	Bent		288.01	288.01
1	Front RH Lower Arm	Distorted		427.10	427.10
1	Steering Rack & Pinion	Distorted		1,573.60	1,573.60
set	Clip	Necessary		57.10	57.10
	List Items Sub-Total			4,881.18	4,441.08
	Original Less 25% Revised Less 25%			1,220.30	1,110.27
	Total Parts Amount			3,660.89	3,330.81

FormTeam Consultancy Pte Ltd

PAGE: 2

Our Reference :

RRN15-030726/RI/BC/cg

Your Reference:

MT/CA/TP/009/0827631-002/JL/LC

QTY	DESCRIPTION	SUBMITTED	REVISED
	LABOUR & MISC		
1	To remove and check all electrical components, wirings and control unit and test for function.	40,00	40.00
2	To remove the affected parts and all relevant fittings and attachments to commence repairs. Jack up, straighten, cut and weld the above listed parts. Panel beat and reshape the affected area. Replace and realign where necessary. (including all repair parts)	920.00	600.00
3	To putty and spray painting on accident affected area and to touch up paint work.	720.00	700,00
4	To apply undercoating on the replaced and repaired portion for rust protection.	100.00	60.00
5	To jack up vehicle to facilitate replacement of undercarriage components.	180.00	180.00
6	To remove and replace front RH tyre including wheel balancing.	45.00	25.00
7	To check steering geometry and computer wheel alignment.	95.00	65.00
	Total Labour Amount	2,100.00	1,670.00
	Total Parts and Labour	5,760.89	5,000.81