

# Boon Automobile Service

Blk 5033 Ang Mo Kio Industrial Park 2  
#01-267 Singapore 569536  
Tel:64820801 Email: CS.Boonauto@gmail.com

To: MSIG INSURANCE (SINGAPORE) PTE LTD  
Date: 17-04-2018  
Our Ref: DC-20181204YP2228S

Vehicle No. : YP2228S  
Accident Date: 12-04-2018  
Name of Owner: PEEL & SEAL TRADING  
Insurance Co.: MSIG  
Model: ISUZU NHR85AUE4AR1  
Chassis No.: JAANHR85EF7100568

## RE: ESTIMATED COST FOR REPAIR VEHICLE NO. YP2228S

List Item:	List Price
1 1pc Front Grille	\$ 290.00
2 1pc Headlamp RHS	\$ 240.00
3 1pc Headlamp cover protector rubber garnish	\$ 95.00
4 1pc Headlamp lower moulding	\$ 53.00
5 1pc Headlamp lower finisher	\$ 55.00
6 6pcs Headlamp lower finisher clip 6pcs 3.20	\$ 19.20
7 1pc Front indicator lamp RHS	\$ 57.00
8 1pc Side lamp	\$ 120.00
9 1pc Side mirror with arm	\$ 42.00
10 1pc Side mirror with arm cover cap	\$ 38.00
11 1pc Front panel	\$ 540.00
12 1pc Front Side panel	\$ 360.00
13 4pc Side panel clips	\$ 20.00
14 1pc NH Logo sticker	\$ 55.00
15 1pc Emblem Izusu	\$ 92.00
16 1pc Front Bumper	\$ 498.00
17 1pc Front Bumper Braket Left & Right 80each	\$ 160.00
18 4pcs Front bumper fastener screw 5each	\$ 20.00
19 1pc Front Corner Panel	\$ 138.00
20 1pc Front Door RHS	\$ 890.00
21 1pc Front Door Pillar	\$ 960.00
22 1pc Windscreen Nozzle	\$ 28.00
23 1pc Windscreen Nozzle Wiper	\$ 34.00
24 1set Windscreen Sealant	\$ 100.00
25 1pc Windscreen molding	\$ 88.00
26 1pc Inner Seal	\$ 65.00
Total	\$ 5,057.20
Less 15%	\$ 758.58
Balance	<b>\$ 4,298.62</b>

### Labour charges:

1 Towing charges	\$ 150.00
2 To check electrical lighting concerned	\$ 80.00
3 To rust- proofing of the affected areas	\$ 200.00
4 To remove and refit front windscreen glass	\$ 250.00
5 To remove and refit interior fittings, trimmings. Garnish and others to enable repair	\$ 280.00
6 To place vehicle on jig bench and correct front chassis frame, door pillar & structure	\$ 2,000.00
7 To check side slip	\$ 60.00
8 Labour to dismantle and install above mentioned items , panel beating knocking and straighten necessary portion, replace damaged parts, re-assemble and re-fit with new parts.	\$ 1,800.00
9 To dismantle and re-install instrument dashboard, check electrical lightings and re-run, re-route wire harness	\$ 380.00
10 To putty, apply primer & spray painting on the affected areas	\$ 2,400.00
11 To check and connect wiring functions	\$ 120.00
	<b>\$ 7,720.00</b>

**Repair Cost Total \$ 12,018.62**