

A.S.S. REC. BY:

REF:

CS3 / MSN 18006955 / G124 best

Special Instruction:

Survivor:

GQ

ASSIGNMENT (Office)

From (Person):

Medmen

Christina Wong

of

MSN

Date/Time:

16042018 956am

Estimated Cost:

Bill to:

OD / EV / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 2057J

Insured:

FBK 87372

at Workshop m/s

Nee Huat Auto

Tel:

9684 8774

of

Blk 1 Kaki Bukit Ave 6 #02-27

Policy No:

MSD / VMFT / 18-990134

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13042018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

16042018 1056am

Person Contacted:

Richard

Vehicle IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

GY 2057J - X

FBK 87372 - X

17/4/18

Dismantled

19/4/18

After Repair

(00/11/11)

PKS

REF: MSU1

6794M

Surrender

\*Mileage

## ASSIGNMENT

From: Date: 16042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 6Y 2057J

at Workshop m/s: Nee Hunt Auto

of: Blk 1 Kaki Bukit Ave 6 #02-27

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 6Y 2057J Yr Regn: 26 Jan 2005

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Liteace C.C. 2184

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 245787 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: CR 425011104

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 185/60 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 16-04-18

5:20pm

W/S

Rear O/S

Date / Time Action / Instruction

Estimated repair range \$3,200 - \$4,000

13/6/18 Submit PRS Report

13/6/2018

RECEIVED 13 JUN 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

) \$ + RS. \$

)

)

)

Report Format :

Lump Sum / I.B.I. (\$) )

120

50

10

180



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS3/MSG18006955/Gz4b

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 16-04-2018



Code : MSG

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	FBK 8737Z	Veh. Inspected	GY 2057J
Policy No.	MSD/VMT/18-990134	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	16/04/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	13/04/2018	Inspection Date	16/04/2018
Survey held at	NEE HUAT AUTO SERVICES 1 KAKI BUKIT AVE 6 #02-27 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2018		16 Apr 2018 09:58 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	MUHAMMAD FAZRYAN BIN AZMAN, ID: S9300758A		
Main Claimant:	OCTOPUS DESIGN & CONSULTANT PTE LTD, Co. Reg. No.: 200516794M		
Vehicle Reg. No.:	GY2057J	Date of Loss:	13/04/2018 00:00 - :59 [158 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMFT/18-990134 Coverage: 11/03/2018 - 10/03/2019
Vehicle Reg. No. (Insured):	FBK8737Z	Policy No. (Claimant):	
		Excess:	
Repairer:	M/s. Nee Huat Auto Services (HQ) 1 Kaki Bukit Ave 6 #02-27, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 17/04/2018]		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.		

ALL ASSOCIATED TASKS							<a href="#">View All</a>	<a href="#">Search Tasks</a>	<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	
No results.										

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6794M
Vehicle Details	
Vehicle No.:	GY2057J
Vehicle to be Exported:	No
Intended De-registration Date:	07 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACE 5DR
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	3C4007204
Chassis No.:	CR425011104
Maximum Power Output:	-
Open Market Value:	\$18,669.00
Original Registration Date:	26 Jan 2005
First Registration Date:	26 Jan 2005
Transfer Count:	1
Actual ARF Paid:	\$934.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$21,466.00
COE Rebate Amount:	\$5,285.00
Total Rebate Amount:	\$5,285.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 07 Jun 2018

OK

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Apr 2018		16 Apr 2018 09:58 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>MUHAMMAD FAZRYAN BIN AZMAN</b> , ID: S9300758A									
Main Claimant: <b>OCTOPUS DESIGN &amp; CONSULTANT PTE LTD</b> , Co. Reg. No.: 200516794M									
Vehicle Reg. No.: <b>GY2057J</b>		Date of Loss: 13/04/2018 07:00 - :59 <b>[158 Months and 18 Days From LTA Reg Date (Man Yr)]</b>							
Claim Type: <b>TP / MSC/V/18-000548</b>		Policy/Cover Note No.: MSD/VMS/18-990134 (TP, Fire & Theft) Coverage: 11/03/2018 - 10/03/2019							
Vehicle Reg. No. (Insured): <b>FBK8737Z</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>M/s. Nee Huat Auto Services (HQ)</b> 1 Kaki Bukit Ave 6 #02-27, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Christina Wong</b> - 6643 1311]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Imm.Advice due 17/04/2018]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*GY2057J (MSC/V/18-000548)**  
**[FBK8737Z]**






































**TP**














































**OCTOPUS DESIGN & CONSULTANT PTE LTD**

**Apr 13 2018 7:00AM**

**[MUHAMMAD FAZRYAN BIN AZMAN]**

**M/s. Nee Huat Auto Services**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View In Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
2	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
3	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
4	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
5	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
6	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
7	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
8	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
9	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
10	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
11	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
12	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
13	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
14	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
15	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
16	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
17	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
18	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
19	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
20	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
21	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
22	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
23	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
24	18/04/18 14:27	General View	 Load JPG	<input checked="" type="checkbox"/>
25	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
34	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	18/04/18 14:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	04/06/18 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
51	04/06/18 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
52	04/06/18 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
53	04/06/18 11:38	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
54	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
55	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	04/06/18 11:41	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/04/18 09:43	FBM4159H GIA Rpt	 Load PDF	
2	16/04/18 09:43	FBK8737Z GIA Rpt	 Load PDF	
3	16/04/18 09:45	PRI & LTA Search	 Load PDF	
4	12/06/18 10:21	TP Survey Report	 Load PDF	
5	12/06/18 10:21	TP Survey Report Pictures	 Load PDF	

## Documents Checklist



DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18006955/GZ4BE2

Date: 14/06/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/18-990134
Claimant Vehicle No :	GY2057J	Insured Vehicle No :	FBK8737Z
Date of Loss:	13/04/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000548

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	GY2057J	Engine No:	3C4007204
Make & Model:	TOYOTA LITEACE, 2.2 5 DR (A)	Chassis No:	CR425011104
Reg. Date:	26/01/2005 (Man. Year: 2004)	Odometer:	245787 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	16/04/2018	
Date Inspected:	16/04/2018 Inspected At:	M/s. Nee Huat Auto Services (HQ) 1 Kaki Bukit Ave 6 #02-27, Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	0.0 days	

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,200.00 -\$4,000.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 14 Jun 2018)

**Parts:** N/A TOYOTA LITEACE 2.2 5 DR (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GY2057J)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >