

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0214/18

DATE : 09-APR-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 68299199
FAX : 68299247/9248
ATTN : CLAIM MANAGER

OWNER'S NAME : WONG KOK HONG
ADDRESS : 11 FARRER PARK ROAD
#23-05
S(210011)
TELEPHONE NO : 91018500

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SLP8095Y
MODEL CODE : FDRARBZJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0 MY2014
ENGINE NO : MR20469395W
CHASSIS NO : SJNFBAJ11UZ028909
MILEAGE : 15482 KM
DATE IN : 09/04/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH — 96450079
ACCIDENT DATE : 08/04/2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLP0095Y

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR LH FRONT DOOR AND LH REAR DOOR.	650.00	
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	600.00	
3 ZZ/003	RENEW LH REAR WHEEL RIM AND WHEEL BALANCING.	15.00	

	TOTAL LABOUR CHARGES	1265.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLP8095Y

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			50.00	
2	WHEEL-ALUMINIUM REAR LH	D0300-4E538			1638.70	
3	REAR FENDER WHEEL ARC MLDG LH	93829-4EA0A	483.00			
4	LH REAR DOOR LOWER PVC MLDG	82871-4EA0A	264.80			
5	LH FRONT FRONT DOOR LOWER PVC MLDG	80871-4EA0A	323.60			
SUB TOTAL			1071.40	0.00	1688.70	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			214.28	0.00	0.00	
GRAND TOTAL			857.12	0.00	1688.70	
OVERALL TOTAL			2545.82			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLP8095Y

TOTAL LABOUR CHARGES	1265.00
TOTAL SPARE PARTS CHARGES	2545.82

GRAND TOTAL	3810.82 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.