

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 5	REAR MUDGUARD LHS/RHS	Reviewing	500	DEFORMED	
☐	 6	REAR MUDGUARD BRACKET LHS/RHS	Reviewing	400	BENT	
☐	 7	U-BOLT	Reviewing	1080	BENT	
☐	 8	REAR DECK LOWER VERTICAL WOOD LHS/RHS	Reviewing	2800	DEFORMED	
☐	 9	REAR DECK LOWER HORIZONTAL WOOD	Reviewing	0	*Check	
☐	 10	BOLT & NUT SET	Reviewing	490	NECESSARY	
☐	 11	REAR DECK FLOOR PANEL	Reviewing	0	*Check	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONCITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐		10	1			HEADLAMP LHS			Cut	450		15		382.5
☐		11	1			FRONT TURN SIGNAL LAMP LHS			Cracked	250		15		212.5
☐		12	1			REAR VIEW MIRROR LHS			Cut	100		15		85
☐		13	1			REAR RIM LHS			Bent	450		15		382.5
☐		14	1			REAR WHEEL BEARING AND OIL SEAL LHS ("Check \$275.00)				0		15		0
Labour														
Add Approve Deny														
	EDIT	SR NO	REPAIR/REPLACE (LABOUR)			PART NAME		LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)		COMMENT	

☐		1				TO REMOVE & REFIT DAMAGED PARTS. CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.		1200	0	0	Reviewing			
☐		2				TO CHECK FOR & RECTIFY WIRING FAULTS, ETC.		150	0	0	Reviewing			
☐		3				TO REMOVE & REFIX FRONT DOOR COMPARTMENTS.		150	0	0	Reviewing			
☐		4				TO REMOVE & REFIX FUEL TANK ASSY.		250	0	0	Reviewing			
☐		5				TO REMOVE, REFIX AND REALIGN REAR CANOPY ASSY. TO REMOVE, REFIX & REALIGN REAR WOODEN DECK ASSY. TO REPLACE ALL DAMAGED PARTS.		3600	0	0	Reviewing			
☐		6				TO PANEL BEAT AND REALIGN BOTH MAIN CHASSIS FRAMES AND ALL CHASSIS CROSSMEMBERS.		5800	0	0	Reviewing			

Detailed Assessment

Inspection Date *

04/17/2018



Condition of Vehicle at time of survey

General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

2800

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

215/75 R17.5

Rear Tyre Size

215/75 R17.5

FNOL INFORMATI... 29 TUAS VIEW WALK 2, 637563,
Singapore

POST SURVEY INF...

CATEGORY Address type
FNOL INFORMATI... Personal Correspondence
POST SURVEY INF...

CATEGORY Gender
FNOL INFORMATI... Male
POST SURVEY INF...

CATEGORY Marital status
FNOL INFORMATI... Unknown
POST SURVEY INF...

CATEGORY Identification #
FNOL INFORMATI... G2731595Q

CATEGORY

Make

POLICY INFORMAT...

ISUZU

ASSESSMENT INFO...

ISUZU

CATEGORY

Model

POLICY INFORMAT...

NPR75UH5A

ASSESSMENT INFO...

NPR75UH5A

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

JAANPR75HF7105940

CATEGORY

Date of Birth

FNOL INFORMATI...

July 28, 1992

POST SURVEY INF...

mm/dd/yyyy



Age

FNOL INFORMATI...

25

POST SURVEY INF...

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

Driving Experience

Accelerated
workshop survey

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Additional Instructions

EXCESS \$800+\$2000(Additional)=\$2800

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Add

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
TEO Kitty	4/13/18 4:48 PM	21207.5	21207.5	Open	Share	Clone

Accelerated
workshop survey

Claim Handler

TEO Kitty
6568804602
kitty.teo@axa.com.sg

Documents

History

Invoices

Messages

Notes

Metrics

Assessment

EXCESS \$800+\$2000(Additional)=\$2800

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
AUTHORIZE LETTER.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	April 26, 2018
PRELI ADVISED.pdf	Evidence	Others	LKK AUTO CONSULTANTS PTE LTD (OD)	April 17, 2018
SURVEY PHOTOS.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	April 17, 2018