

ASS. REC. BY:

REF:

CS/CTU8007003 / Dtb n2

Special Instruction:

SURVIVAL

ASSIGNMENT (Office)

m/wman

From (Person):

Adeline Chng

of

CFL

Date/Time:

16042018 1156pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 3454M

Insured:

GA 7972B

at Workshop m/s

Chunni Motor

Tel:

6542 5119

of

Blk 10 AMK Ind Park 2A #01-05

Policy No:

PMCV3N3050581703

Claim No:

SNM18D01943002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

13042018

CA / REV / REP. / REV 24 HRS 'wpi

17-04-2018

H.O.D. Endorsement:

Date/Time:

16042018 5pm

Person Contacted:

Lynn

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SHD 3454M - CS/A261607721 / Hlyg342

DIA: 12-11-16

GA 7972B - CS/LPC11005125 / G441

DIA: 160311

REF:

ASSIGNMENT

COE 2024 Aug

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____


Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 11 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 3454 M Regn. 2016 MS

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: N.A. T/Radio: Insured / Std / NI / NA

Eng/No: D4FDGU668604

C/No: KMH1B41WUMGU93317

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. S mm R/Bal. S mm

L/Bal. S mm L/Bal. S mm

D.O.A. 13/04/2018 D.O.I. 17/04/2018

Survey held at Chunnip AMIC

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Front & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

08/05/18 China Taping GQ 7972B
Jmagul 4/5 17500 - after 11 days 2/2

Red: \$ 12304.50, 41/1

RECEIVED 08 MAY 2018

Date/Time, File Pass to?

☐ : Preli. Report1) typist☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 11

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

220

Report Format: 7P

Lump Sum / I.B.I. (\$) 17500

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2018		16 Apr 2018 16:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		NG KAH KOO HOLDING PTE LTD							
Main Claimant:		COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R							
Vehicle Reg. No.:		SHD3454M	Date of Loss:	13/04/2018 10:00 - :59					
Claim Type:		TP / SNM18D01943C02	Policy/Cover Note No.:	DMCVSN3050581703					
Vehicle Reg. No. (Insured):		GQ7972B	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer:		Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 25/04/2018]							
Adj Asg. Remarks:		DEAR KALVIN, PLEASE CONDUCT THIRD PARTY SURVEY, CHECK CONSISTENCY OF THE DAMAGES ON WITHOUT PREJUDICE BASIS.							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD618049181 / ComfortDelGro Engineering Pte Ltd - Layan
 ENTRY DATE & TIME: 13/04/2018 14:01
 SUBMITTED BY: Catherine Por Moy Juan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/04/2018 14:01
Date Of Accident	13/04/2018 10:30
Exact Location Of Accident	PIE(TUAS)BF KPE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD3454M
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	TAN YEW SWEE
NRIC No	S1479890J
Date Of Birth	22/04/1961
Occupation	OUTDOOR
Date Of Driving Pass	10/07/1981
Driving Experience	36 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	TANYEWSWEE7815@GMAIL.COM

Address 5 03-09 WOODLANDS DRIVE 72
Postcode 738091
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : -
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GQ7972B
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver NG SEE BOON
NRIC/Passport Number S1381250J
Contact Number 91260442
Address
Postcode
Insurance Company Name
Nature Of Damage FRT & REAR

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time: 13 APR 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time: 13 APR 2018

@ 13:30 hrs


Reporting Centre Personnel's Signature

Name:

LISA DIONG

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/4/2018 @ 10:30hrs, my taxi (A) SHD 3454M was travelling along Pte Road towards Bus 34 KPE Exit. With 1 male passenger on board.

I was on the extreme right lane. I saw in front of me vehicles slow down, so I follow too. There was a loud impact coming from the rear portion and caused my taxi (A) to lose control and surge forward and colliding into the vehicle (C) GBE 84XL rear portion. My taxi (A) front and rear portions were damaged. I assessed the damages to my taxi (A) and come to know that there were 4 vehicles involved in the chain accident. No injury in this accident.

The parties involved in the accident are:

A. SHD 3454M.

B. GQ 797JB, Mr. Ng See Boon, S13812601, d/p: 9176 044.

C. GBE 84XL.

D. SGX 3693X, Mr. Abu Bakar Saman.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature

Date & Time: 13 APR 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time: 13 APR 2018

@ 13:30hrs

Reporting Centre Personnel's Signature

Name:

LISA DIONG

NRIC/FIN No.:

FAX : 6542 6039 ChinaTaiping

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet Vst			\$ 1,526.00 ✓
	Bonnet Hinge (LH/RH) fcy		\$ 91.30	\$ 182.60 X
	Bonnet Lock Vst			\$ 50.90 ✓
	Bonnet Absorber HA		\$ 73.90	\$ 147.80 X
	Bonnet Insulator SVL			\$ 243.00 X
	Bonnet Insulator Clips HA			\$ 8.40 X
	Radiator Grille broken			\$ 1,480.00 ✓
	Radiator Grille H Emblem HL			\$ 290.80 ✓
	Radiator Grille Chrome Moulding broken			\$ 395.50 ✓
	Front Bumper Cover KAC			\$ 1,052.20 ✓
	Front Bumper Sponge torn			\$ 142.20 ✓
	Front Bumper Reinforcement KAC			\$ 526.10 ✓
	Front Bumper Lip HA			\$ 62.50 X
	Front Bumper Bracket Top (LH/RH) HA	S	22.40	\$ 44.80 X
	Front Bumper Bracket (LH/RH) HA	S	24.60	\$ 49.20 X
	Front Bumper Retainer Mounting HA	S	9.20	\$ 18.40 X
	Headlamp Support Top Cover deformed			\$ 398.00 ✓
	Headlamp Support Panel Assy R Vst			\$ 1,067.50 ? ✓
	Headlamp (LH/RH) broken	S	1,388.00	\$ 2,776.00 ✓
	Radiator R Vst			\$ 850.20 ? -
	Radiator Fan Blade,Cowling,Motor Assy R NA			\$ 792.95 ? X
	Radiator Bracket (RH/LH) SVL	S	6.50	\$ 13.00 X
	Radiator Guard SVL	S	35.00	\$ 70.00 X
	Horn Unit (LH/RH) SVL	S	86.75	\$ 173.50 X
	Horn Wire HA			\$ 156.50 X
	Front Fender (LH) Dented			\$ 619.00 ✓
	Front Fender Shield (LH) HA			\$ 169.80 X
	Air Cleaner Assy SAE CRACK			\$ 188.00 ✗ L
	Air Duct R Vst			\$ 206.05 ? ✓
	Air Flow Sensor HA			\$ 633.35 X
	Aircon Condenser R Vst			\$ 1,137.35 ? ✓
	Inter Cooler R Punctured			\$ 921.90 ? ✓
	Inter Cooler Mounting (2 PCS) HA			\$ 25.90 X
	Hose B To Inter Cooler HA			\$ 229.70 X
	Hose C To Inter Cooler Inlet HA			\$ 113.30 X
	Pipe To Inter Cooler HA			\$ 167.05 X
	Pipe To Inter Cooler Outlet HA			\$ 244.55 X
	SUB TOTAL			\$ 17,174.00
	LESS 20%			\$ 3,434.80
	DISCOUNTED TOTAL			\$ 13,739.20

13622-70
10902-16 //

SHD 3454M

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Number Plate <i>SVC</i>			\$ 25.00	Nett X
	Front No Plate Trim Cover <i>HN</i>			\$ 30.00	Nett X
	Front Fender Advertisement Logo (LH) <i>HLC</i>		100.00 =	\$ 100.00	Nett ✓
				\$ 155.00	
	Labour Charge				
	Panel Beating			\$ 1,000.00	800/-
	Spray Painting Charge			\$ 600.00	500/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	30/-
	Towing Charge		1440/- =	\$ 50.00	HN
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	TOTAL LABOUR			\$ 1,900.00	
	Boot Lid <i>✓</i>			\$ 1,681.40	✓
	Boot Lid Rubber <i>deformed</i>			\$ 115.80	✓
	Boot Lid Hinge (LH/RH) <i>✓</i>		\$ 178.10	\$ 356.20	X
	Boot Lid Lock Upper <i>✓</i>			\$ 137.90	✓
	Boot Lid Lock Lower <i>✓</i>			\$ 31.70	X
	Boot Lid 'H' Emblem <i>HLC</i>			\$ 27.20	✓
	Boot Lid CRDI Plate <i>HLC CRACK</i>			\$ 41.00	✓
	Boot Lid Lamp (LH/RH) <i>✓</i>		\$ 556.80	\$ 1,113.60	✓
	Boot Lid Trimboard <i>SVC</i>			\$ 172.70	X
	Boot Lid Trimboard Clips (10pcs) <i>HN</i>			\$ 11.00	X
	Bootlid Moulding <i>HN</i>			\$ 85.00	X
	Bootlid i40 Emblem <i>HLC</i>			\$ 41.00	✓
	Bootlid Lower Garnish <i>mounting cracks</i>			\$ 398.00	X
	Rear Bumper <i>Deformed</i>			\$ 603.60	✓
	Rear Bumper Reinforcement <i>crack</i>			\$ 504.35	✓
	Rear Bumper Reinforcement Bracket (LH/RH) <i>✓</i>		\$ 180.00	\$ 360.00	✓
	Rear Bumper Clip 10 pcs <i>HLC</i>			\$ 22.00	✓
	Rear Bumper Bracket <i>HN</i>		\$ 49.00	\$ 98.00	X
	Rear Bumper Sponge <i>✓</i>			\$ 143.40	✓
	Rear Bumper Under Cover <i>deformed</i>			\$ 225.00	✓
	Rear Bumper Reflector Lamp (LH/RH) <i>HN</i>		\$ 32.00	\$ 64.00	X
	Tail Lamp (LH/RH) <i>crack</i>		\$ 565.60	\$ 1,131.20	✓
	Rear Panel <i>Deformed</i>			\$ 592.30	✓
	Rear Panel Garnish <i>deformed</i>			\$ 57.70	✓
	Rear Panel Lower Panel <i>Deformed</i>			\$ 495.50	✓
	Spare Tyre Holder <i>HN</i>			\$ 28.80	X
	Spare Tyre Panel <i>HN</i>			\$ 900.50	X
	Spare Tyre Panel Cushion <i>HN</i>			\$ 209.05	X
	Rear Towing Hook <i>HN</i>			\$ 94.60	X
	Member Assy- Rear Floor Centre <i>HN</i>			\$ 170.75	X

SHD 3454M

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Exhaust Pipe Insulator <i>NH</i>		\$ 58.55	\$ 117.10	X
	Exhaust Silencer <i>2 1/2"</i>		\$ 954.00	\$ 1,908.00	2 ✓
	Exhaust Pipe Hanger <i>NH</i>		\$ 58.55	\$ 117.10	X
	Exhaust Pipe Centre <i>NH</i>			\$ 1,150.30	X
			<i>9598.95</i>		
	SUB TOTAL			\$ 13,205.75	
	LESS 20%		<i>7679.16</i>	\$ 2,641.15	
	DISCOUNTED TOTAL			\$ 10,564.60	
	Boot Lid Comfort Logo & Tel No. Sticker <i>NH</i>			\$ 30.00	Nett ✓
	Rear Bumper Reverse Sensor <i>Storage</i>			\$ 135.70	Nett ✓
	Rear Bumper Advertisement Logo <i>NH</i>			\$ 50.00	Nett ✓
	Rear ^{number} Bumper 140 Plate <i>Set</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>NH</i>		\$ 100.00	\$ 200.00	Nett ✓
			<i>465.70</i>	\$ 465.70	
	Labour Charge				
	Panel Beating			\$ 1,400.00	800/-
	Spray Painting Charge			\$ 1,000.00	700/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	30/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Exhaust Pipe			\$ 360.00	60/-
			<i>1660/-</i>		
	TOTAL LABOUR			\$ 2,980.00	
	ESTIMATE TOTAL			\$ 29,804.50	
	<i>17/04/2018 @ 1500</i>			<i>22247.02</i>	
	<i>Not Actual</i>			<i>1/5/17500/-</i>	
	<i>2/5/11 days</i>				
	<i>LKK Auto</i>				
	LKK Auto Consultants hence notify the Repairee of the following:				
	• To resurvey before/after spray painting				
	• To display damaged part(s) during resurvey				
	• Parts prices are subject to confirmation				
	• Third party survey is on a "Without Prejudice" basis				
	• No illegal modification(s) is allowed				
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company				
	Acknowledged by Repairee				
	Signature:				
	Date:				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18007003/DRBN2

Date: 11/05/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3050581703
Claimant Vehicle No :	SHD3454M	Insured Vehicle No :	GQ7972B
Date of Loss:	13/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01943C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD3454M	Engine No:	D4FDGU668604
Make & Model:	HYUNDAI I40, 1.7 GDi (A)	Chassis No:	KMHLB41UMGU093317
Reg. Date:	18/08/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 5 mm	Rear Left Side:	Hankook 5 mm
Front Right Side:	Hankook 5 mm	Rear Right Side:	Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	24,924.50	19,147.02	5,777.48	23.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,880.00	3,100.00	1,780.00	36.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,804.50	22,247.02	7,557.48	25.36
Approved Total (Overridden) (S\$)		17,500.00		
(S\$)	29,804.50	17,500.00	12,304.50	41.28
+ GST 7.00/7.00% (S\$)	2,086.32	1,225.00	861.32	41.28
Nett Amount (S\$)	31,890.82	18,725.00	13,165.82	41.28

INSPECTION

Date of Assignment:	16/04/2018	
Date Inspected:	17/04/2018 Inspected At:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint Singapore 568047
Estimated Period of Repair:	11.0 days	

Adjuster: BRYAN TANI

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 May 2018)	
Parts:	N/A	HYUNDAI I40 1.7 GDi (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD3454M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,526.00 FL	*1,526.00 FL
2	2		*BONNET HINGE (LH/RH)	Repair	182.60 FL	*- FL
3	1		*BONNET LOCK	Bent	50.90 FL	*50.90 FL
4	2		*BONNET ABSORBER	Not Necessary	147.80 FL	*- FL
5	1		*BONNET INSULATOR	Serviceable	243.00 FL	*- FL
6	1		*BONNET INSULATOR CLIPS	Not Necessary	8.40 FL	*- FL
7	1		*RADIATOR GRILLE	Broken	1,480.00 FL	*1,480.00 FL
8	1		*RADIATOR GRILLE H EMBLEM	Necessary	290.80 FL	*290.80 FL
9	1		*RADIATOR GRILLE CHROME MOULDING	Broken	395.50 FL	*395.50 FL
10	1		*FRONT BUMPER COVER	Buckled	1,052.20 FL	*1,052.20 FL
11	1		*FRONT BUMPER SPONGE	Torn	142.20 FL	*142.20 FL
12	1		*FRONT BUMPER REINFORCEMENT	Buckled	526.10 FL	*526.10 FL
13	1		*FRONT BUMPER LIP	Not Necessary	62.50 FL	*- FL
14	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
15	2		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
16	2		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	18.40 FL	*- FL
17	1		*HEADLAMP SUPPORT TOP COVER	Deformed	398.00 FL	*398.00 FL
18	1		*HEADLAMP SUPPORT PANEL ASSY	Bent	1,067.50 FL	*1,067.50 FL
19	2		*HEADLAMP (LH/RH)	Broken	2,776.00 FL	*2,776.00 FL
20	1		*RADIATOR	Bent	850.20 FL	*850.20 FL
21	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Not Necessary	792.95 FL	*- FL
22	2		*RADIATOR BRACKET (RH/LH)	Serviceable	13.00 FL	*- FL
23	2		*RADIATOR GUARD	Serviceable	70.00 FL	*- FL
24	2		*HORN UNIT (LH/RH)	Serviceable	173.50 FL	*- FL
25	1		*HORN WIRE	Not Necessary	156.50 FL	*- FL
26	1		*FRONT FENDER (LH)	Dented	619.00 FL	*619.00 FL
27	1		*FRONT FENDER SHIELD (LH)	Not Necessary	169.80 FL	*- FL
28	1		*AIR CLEANER ASSY	Cracked	188.00 FL	*188.00 FL
29	1		*AIR DUCT	Bent	206.05 FL	*206.05 FL
30	1		*AIR FLOW SENSOR	Not Necessary	633.35 FL	*- FL
31	1		*AIRCON CONDENSER	Bent	1,137.35 FL	*1,137.35 FL
32	1		*INTER COOLER	Punctured	921.90 FL	*921.90 FL
33	1		*INTER COOLER MOUNTING (2 PCS)	Not Necessary	25.90 FL	*- FL
34	1		*HOSE B TO INTER COOLER	Not Necessary	229.70 FL	*- FL
35	1		*HOSE C TO INTER COOLER INLET	Not Necessary	113.30 FL	*- FL
36	1		*PIPE TO INTER COOLER	Not Necessary	167.05 FL	*- FL
37	1		*PIPE TO INTER COOLER OUTLET	Not Necessary	244.55 FL	*- FL
38	1		*BOOT LID	Bent	1,681.40 FL	*1,681.40 FL
39	1		*BOOT LID RUBBER	Deformed	115.80 FL	*115.80 FL
40	2		*BOOT LID HINGE (LH/RH)	Repair	356.20 FL	*- FL
41	1		*BOOT LID LOCK UPPER	Bent	137.90 FL	*137.90 FL
42	1		*BOOT LID LOCK LOWER	Repair	31.70 FL	*- FL
43	1		*BOOT LID H EMBLEM	Necessary	27.20 FL	*27.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*BOOT LID CRDI PLATE	Necessary	41.00 FL	*41.00 FL
45	2		*BOOT LID LAMP (LH/RH)	Cracked	1,113.60 FL	*1,113.60 FL
46	1		*BOOTLID TRIMBOARD	Serviceable	172.70 FL	*- FL
47	10		*BOOTLID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
48	1		*BOOTLID MOULDING	Not Necessary	85.00 FL	*- FL
49	1		*BOOT LID I40 EMBLEM	Necessary	41.00 FL	*41.00 FL
50	1		*BOOTLID LOWER GARNISH	Mounting Cracked	398.00 FL	*398.00 FL
51	1		*REAR BUMPER	Dented	603.60 FL	*603.60 FL
52	1		*REAR BUMPER REINFORCEMENT	Cracked	504.35 FL	*504.35 FL
53	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent	360.00 FL	*360.00 FL
54	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
55	2		*REAR BUMPER BRACKET	Not Necessary	98.00 FL	*- FL
56	1		*REAR BUMPER SPONGE	Torn	143.40 FL	*143.40 FL
57	1		*REAR BUMPER UNDER COVER	Distorted	225.00 FL	*225.00 FL
58	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	64.00 FL	*- FL
59	2		*TAIL LAMP (LH/RH)	Cracked	1,131.20 FL	*1,131.20 FL
60	1		*REAR PANEL	Dented	592.30 FL	*592.30 FL
61	1		*REAR PANEL GARNISH	Deformed	57.70 FL	*57.70 FL
62	1		*REAR PANEL LOWER PANEL	Dented	495.50 FL	*495.50 FL
63	1		*SPARE TYRE HOLDER	Not Necessary	28.80 FL	*- FL
64	1		*SPARE TYRE PANEL	Not Necessary	900.50 FL	*- FL
65	1		*SPARE TYRE PANEL CUSHION	Not Necessary	209.05 FL	*- FL
66	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
67	1		*MEMBER ASSY-REAR FLOOR CENTRE	Not Necessary	170.75 FL	*- FL
68	2		*EXHAUST PIPE INSULATOR	Not Necessary	117.10 FL	*- FL
69	2		*EXHAUST SILENCER	Bent	1,908.00 FL	*1,908.00 FL
70	2		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
71	1		*EXHAUST PIPE CENTRE	Not Necessary	1,150.30 FL	*- FL
72	1		*FRONT NUMBER PLATE	Serviceable	25.00 FS	*- FS
73	1		*FRONT NO PLATE TRIM COVER	Not Necessary	30.00 FS	*- FS
74	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
75	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	30.00 FS	*30.00 FS
76	1		*REAR BUMPER REVERSE SENSOR	Shorted	135.70 FS	*135.70 FS
77	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
78	1		*REAR NUMBER PLATE	Bent	50.00 FS	*50.00 FS
79	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **31,000.45** **23,792.35**
 - List Item Discount on L Items 20.00/20.00% (\$\$) 6,075.95 4,645.33

Total Parts (\$\$) **24,924.50** **19,147.02**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,400.00	1,600.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,200.00
3	WIRING CHARGE	New	100.00	60.00
4	TUFF KOTE	New	100.00	60.00
5	TOWING CHARGE	New	50.00	-
6	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE/REFIX EXHAUST PIPE	New	360.00	60.00
Gross Labour Cost (\$\$)			4,880.00	3,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >