

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1804-031

DATE : 12-Apr-2018

POLICY NO. : AUTO&GEN P10028686R00

VEHICLE REG. NO. : SJM1748H

VEHICLE MAKE : HONDA AIRWAVE 1.5 (A)

TO Motor Claim Department
 EQ Insurance Company Limited
 22 Gemmill Lane, Singapore 069257
 Tel: 6223 9433
 Fax: 6224 3903

FOR SURVEYOR

Rasul - Hp 90010068 / Return
 4 days - Lumpsum / after
 13/04/18 @ 1125 repair
 Require wheel alignment readings
 by repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Front Side Mirror Assy LH	1	\$ 720.00	\$ Repair 720.00
2	Front Fender LH	1	\$ 580.00	\$ M / 580.00
3	Front Fender Shield LH	1	\$ 140.00	\$ DE / 140.00
4	Front Fender Clips	10	\$ 5.00	\$ M / 50.00
5	Front Honda Rim LH	1	\$ 650.00	\$ RR 650.00
6	Front ABS Sensor LH	1	\$ 290.00	\$ X 290.00
7	Front Disk Rotor LH	1	\$ 220.00	\$? 220.00
8	Front Knuckle LH	1	\$ 160.00	\$ X? 160.00
9	Front Bearing LH	1	\$ 100.00	\$ X? 100.00
10	Front Wheel Hub LH	1	\$ 300.00	\$ X? 300.00
11	Front Tie Rod LH	1	\$ 160.00	\$ X? 160.00
12	Front Tie Rod End LH	1	\$ 100.00	\$ X? 100.00
13	Front Absorber LH	1	\$ 380.00	\$? 380.00
14	Front Absorber Top Mount LH	1	\$ 50.00	\$? 50.00
15	Front Lower Arm LH	1	\$ 300.00	\$ X? 300.00
	Total Spare Parts			\$ 4,200.00
	SPECIAL NETT			
	LABOUR			
16	Spray painting Front Bumper, Door LH, Fender LH and Skirting	1	\$ 800.00	\$ 500 800.00
17	Remove, Refit and Repair Affected Accident Parts Inc. Wheelhse	1	\$ 800.00	\$ 350 800.00
18	Remove and Refit Undercarriage	1	\$ 350.00	\$ 150? 350.00
19	Wheels Computer Alignment	1	\$ 80.00	\$ 60 80.00
20	Check and rectify electrical wiring	1	\$ 30.00	\$ X 30.00
	Total Labour			\$ 2,060.00
	Amount Before Excess			\$ 6,260.00
	Add GST @ 7%			438.20
	Total Amount Payable			\$ 6,698.20

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed.