

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD			Ref:	NS/INC18007023/K1qbn2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	19-04-2018 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBE 3953E	Veh. Ir	nspected	SHA 4513K	
	Policy No.	5095313880	Coverage (\$)		0.00	
	Claim No.	MT/0990416-002	Exces	s (\$)	0.00	
	Assign From		Assign	n Date	16/04/2018	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI SONATA	c.c		1991	
	Engine No.	HIDDEN	Year o	f Reg.	2011	
	Chassis No.	KMHET41VMBA807519	Colou	r	BLUE	
	Odometer	512943	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/60 R16	WEST	LAKE	7 mm	
	L/H Front Tyre	215/60 R16	WEST		7 mm	
	R/H Rear Tyre	215/60 R16	WEST		7 mm	
	L/H Rear Tyre	215/60 R16	WEST		7 mm	
4.	<u> </u>					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	13/04/2018	Inspec	tion Date	16/04/2018	
	Survey held at	at COMFORTDELGRO ENGINEERING PTE LTD				
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					