



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 1985J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER (CONSISTENT)	DEFORMED	663.80	663.80
1	FRONT BUMPER ENFORCEMENT (CONSISTENT)	NOT NECESSARY	218.80	-
1	FRONT BUMPER RETAINER (CONSISTENT)	NECESSARY	12.20	12.20
1	HEADLAMP (CONSISTENT)	CUT	912.10	912.10
1	HEADLAMP BRACKET (CONSISTENT)	NECESSARY	29.10	29.10
1	FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	537.20	-
1	FOG LAMP (CONSISTENT)	NOT NECESSARY	250.40	-
1	WIPER WASHER TANK (CONSISTENT)	NOT NECESSARY	72.90	-
1	FRONT LOWER SPOILER (CONSISTENT)	CRACKED	498.60	498.60
	LESS 20% DISCOUNT		-639.02	-423.16
			2,556.08	1,692.64
	<u>LABOUR</u>			
	TO REMOVE & REPLACE FRONT BUMPER, ENFORCEMENT, HEADLAMP, FENDER & TO PANEL BEAT ALIGN.		1,000.00	500.00
	TO PUTTY & SPRAY PAINT FRONT BUMPER, FENDER & OTHER AFFECTED AREA.		800.00	500.00
	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP.		80.00	30.00
	TUFF KOTE.		280.00	20.00
			2,160.00	1,050.00
	GRAND TOTAL		4,716.08	2,742.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,200.00

Report Ref No. CC4/ASM18007039/T1ea3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.