

ASS. REC. BY:

REF: CS/FCL18007056/Uthbnz

Special Instruction:

Surveyor: Rafiqul ASSIGNMENT (Office)

From (Person): CWS May Chua of FCL Date/Time: 17042018 82AM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 4990T Insured: SH 7600E

at Workshop m/s: Pegasus @ SME Tel: 8328 8418

of Blok 1 Kaki Bukit Ave 6 #02-15

Policy No: \_\_\_\_\_ Claim No: D18002904MFSH

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 16042018  
(Client's Record)

CA / REV / REP. / REV 24 HRS DS: \_\_\_\_\_ H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 17042018 1008am Person Contacted: Gang Vehicle  IN /  OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 4990T - X
	SH 7600E - NS/INCL 2019268 / HIKI <span style="float: right;">DUA: 02.10.12</span>
3/5/18	Revert na email preli advice.

F01

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD  / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL7 49907

at Workshop n/s regosus

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

OAD Accident Rpt: Q Consistent?: Yes or No

GLA / PR Seen: Q Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 1.71 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SL7 49907 Yr Regn: 10/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: Mazda 5 C.C. 1998

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 30737 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6CW1071H0126471

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 215/55-16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mm

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 16/4/18 D.O.I. 17/4/18

Survey held at: Leah Valley

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

11A 61780 Zoom 8.11?

7/6/18 cont. work final by 8119.24 with AH.yay.  
Ured to 3849.84, 32%

RECEIVED 08 JUN 2018

Date/Time, File Pass to?  : Preli. Report

1) 08/6/18 Marcus  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

\$ - RS, \$I

Photos OSP

Others 8/6/18

TOTAL

2x15 = 30

170+30

50

50+50

99

449

Report Format: TP

Lump Sum / I.B.I.: (\$ 8119.24)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002904MFSH

Date: 3/5/2018

Our Ref: CS/FCI18007056/Utb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLT 4990T.**

Please be informed that we had conducted the inspection of the abovementioned vehicle 17/04/2018 at the premises of M/s Pegasus and have the following to report: -

Workshop Estimate Amount	: <u>S\$ 11,923.80</u>
Revised Estimate Amount	: <u>S\$ 6,403.36</u>
"Check" Items Amount	: <u>S\$ 3,752.28</u>
Market Value	: <u>S\$ _____</u>
LTA Reimbursement Value	: <u>S\$ _____</u>
Nett Value	: <u>S\$ _____</u>

**Description of Damage:**

The vehicle sustained damages at the rear portion.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully

Marcus

Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	16-04-2018	<b>Our Ref No.</b> D18002904MFSH
<b>Accident Date</b>	16-04-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SH7600E	<b>Third Party Vehicle.</b> SLT4990T
<b>Survey Location</b>	NO. 1 KAKI BUKIT AVENUE 6 #02-15AUTOBAY @ KAKI BUKIT	
<b>Contact Person.</b>	GARY SEAH	
<b>Contact No.</b>	0/ 83388418	<b>Fax No.</b> 0
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PEGASUS @ SME MOTOR	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MAY CHUA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Thursday, 3 May 2018 5:12 PM  
**To:** Admin-D (LKKAuto); 'Claim Workflow System'; assignments  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18002904MFSH/1  
**Attachments:** PRELI ADVISED SLT 4990T.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLT 4990T**

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 17 April 2018 10:10 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18002904MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 17 April, 2018 8:02 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [MAYCHUA@MSFIRSTCAPITAL.COM.SG](mailto:MAYCHUA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18002904MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department



Mail

More

8 of 976

COMPOSE

TOWING BILL FOR SLT4990T inbox

- Inbox
- Starred
- Sent Mail
- Drafts (4)
- GOOGLE SHEET
- Injures lawyer LEE S...
- More

Pegasus +

No Hangouts contacts  
Find someone

**Pegasus Engineering** Dear Poo Yee, Kindly advise do you receive any towing bill for this vehicle n...

**Poo Yee Chai** Dear Ying, We still have not received the towing bill for April 2018 from our...

**Pegasus Engineering** Hi Poo Yee, May I know, do you able to check any towing bill for this case. a...

**Poo Yee Chai**

To me


Hi Ying,

Checked with our towing report, please find attachment for your action.

11/19/20	2018-04-18	MAZDA	SLT 4990T	BAYSHORE	AUTOBAY	PEGASUS ENGINEERING & TRADING PTE LTD	Chong Qi Wei	R/R ACC	100.00
----------	------------	-------	-----------	----------	---------	---------------------------------------	--------------	---------	--------

Best Regards,  
Poo Yee

11:30 AM (2)



SLT4990T

Total \$119.24

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 7200G

### Vehicle Details

Vehicle No.: SLT4990T  
Vehicle to be Exported: No  
Intended De-registration Date: 17 Apr 2018  
Vehicle Make: MAZDA  
Vehicle Model: MAZDA5 WAGON 2.0 AT EU6  
Primary Colour: Blue  
Manufacturing Year: 2017  
Engine No.: PE10524943  
Chassis No.: JM6CW1071H0126471  
Maximum Power Output: 111.0 kW (148 bhp)  
Open Market Value: \$17,537.00  
Original Registration Date: 31 Oct 2017  
First Registration Date: 31 Oct 2017  
Transfer Count: 0  
Actual ARF Paid: \$17,537.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 30 Oct 2027  
PARF Rebate Amount: \$13,152.00

### Intended COE Rebate Details

COE Expiry Date: 30 Oct 2027  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$51,000.00  
COE Rebate Amount: \$48,628.00  
**Total Rebate Amount: \$61,780.00**

The information contained herein is correct as at 17 Apr 2018

OK



GST / ROC Company No : 201101753C

Third Party Insurer : FIRST CAPITAL  
 Insured's Veh No : SH7600E  
 Date of accident : 16/04/2018

Grab Rentals Pte Ltd  
 18 Sin Ming Lane  
 #01-08 Midview City  
 Singapore 573960

*not allowed  
 take photos before part  
 17/4/18*

Quotation No : AR/QO18/04-1067  
 Quotation Date : 16/04/2018

Estimate To Repair MAZDA 5  
 Vehicle No : SLT4990T  
 Chassis No : JM6CW1071H0126616

Pages : 1 of 2

S/NO	QUANTITY	DESCRIPTION	AMOUNT
<b>SPARE PARTS</b>			
1	1PC	REAR GATE <i>body id</i>	\$1,550.80
2	1PC	REAR GATE LOGO <i>nee</i>	\$68.50
3	1PC	REAR GATE "MAZDA" PLATE <i>nee</i>	\$45.80
4	1PC	REAR GATE "5" PLATE <i>nee</i>	\$35.50
5	1PC	REAR GATE "SKYACTIVE" PLATE <i>nee</i>	\$140.20
6	1PC	REAR GATE OUTER GARNISH	\$450.80
7	1PC	REAR GATE LOCK <i>twi/subst</i>	\$280.50
8	1PC	REAR GATE INNER RUBBER <i>twi</i>	\$170.50
9	1PC	REAR GATE INNER TRIMBOARD <i>u1</i>	\$450.20
10	2PC	REAR GATE INNER TRIM (SIDE) @\$175.50 <i>u1</i>	\$351.00
11	1PC	REAR GATE INNER TRIM TOP <i>u1</i>	\$210.60
12	16PC	INNER TRIM CLIPS <i>u1</i>	\$144.00
13	2PC	REAR GATE ABSORBER @\$195.70 <i>u1</i>	\$391.40
14	1PC	REAR BUMPER <i>17.5</i>	\$950.80
15	2PC	REAR BUMPER RETAINER @\$55.80 <i>set</i>	\$111.60
16	10PC	REAR BUMPER CLIPS @\$6 <i>nee</i>	\$60.00
17	1PC	REAR BUMPER REINFORCEMENT <i>set</i>	\$150.80
18	2PC	TAIL LAMP @\$615 <i>u1</i>	\$1,230.00
19	1PC	REAR END PANEL <i>body id</i>	\$485.50
20	1PC	REAR END PANEL TOP GARNISH <i>twi</i>	\$105.50
21	1PC	REAR SPARE TYRE FLOOR PANEL <i>crumpled/duc</i>	\$910.50
22	1PC	REAR SPARE TYRE TOP BOARD COVER <i>u1</i>	\$295.80
23	1PC	REAR EXHAUST BOX <i>body id</i>	\$1,035.95
24	1PC	REAR EXHAUST BOX CHROME FINISHER <i>set</i>	\$185.00
25	1PC	REAR EXHAUST BOX CENTRE PIPE <i>u</i>	
26	6PC	REAR EXHAUST RUBBER HOLDER @\$38.50 <i>u1</i>	\$231.00
27	1PC	REAR SPARE TYRE TOOLS TRAY <i>u1</i>	
28	1PC	REAR BUMPER REFLECTOR LH <i>BRD</i>	\$25.00
LESS 20%			\$10,042.25
			\$2,008.45
			\$8,033.80
<b>MISC ITEMS</b>			
29	1PC	REAR WINDSCREEN GUM <i>sealant</i>	\$60.00
30	1PC <i>set</i>	REVERSE SENSOR <i>shiled</i>	\$250.00
Total			\$310.00

*Handwritten notes and calculations on the right side of the table, including a large vertical sum of 6342.45 and other smaller figures like 40 and 200.*

Please conduct the survey at  
 Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883  
 GARY 8338 8418





GST / ROC Company No : 201101753C

Third Party Insurer : FIRST CAPITAL

Insured's Veh No : SH7600E

Date of accident : 16/04/2018

Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

Quotation No : AR/QO18/04-1067

Quotation Date : 16/04/2018

Estimate To Repair MAZDA 5  
Vehicle No : SLT4990T  
Chassis No : JM6CW1071H0126616

Pages : 2 of 2

S/NO	QUANTITY	DESCRIPTION	AMOUNT
<b>LABOUR &amp; MISC. CHARGES</b>			
1		WIRE CHECKING	\$30.00 ✓
2		REMOVE & REFIX REAR WINDSCREEN	\$120.00 ✓
3		REMOVE & REFIX CUSHION AND SEATS	\$180.00 60
4		REMOVE & REFIX EXHAUST BOX	\$180.00 60
5		CAVITY PROTECTION ON ALL AFFECTED AREAS	\$150.00 90
6		TOWING FEE (KING ROLLER)	\$120.00 <del>100</del> 100
7		LABOUR CHARGE	\$1,600.00 1200
8		SPRAY PAINTING	\$1,200.00 1100
Total			\$3,580.00
			8119.24
Sub Total			\$11,923.80
GST (7.00%)			\$834.67
Total			\$12,758.47

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883  
GARY 8338 8418

12013.08



GST / ROC Company No : 201101753C

Third Party Insurer : FIRST CAPITAL

Insured's Veh No : SH7600E

Date of accident : 16/04/2018

Grab Rentals Pte Ltd  
18 Sin Ming Lane  
#01-08 Midview City  
Singapore 573960

Quotation No : AR/QO18/04-1067

Quotation Date : 16/04/2018

**SUPPLEMENTARY**

MAZDA 5

Vehicle No :

SLT4990T

Chassis No :

JM6CW1071H0126616

Pages : 2 of 2

S/NO	QUANTITY	DESCRIPTION	AMOUNT
1	2 PC	<b>PARTS</b> REAR BUMPER CENTRE HOLDER	<i>Ref</i> \$56.60
		Total	\$56.60
		LESS 20%	\$11.32
			\$45.28
		<b>Sub Total</b>	\$45.28
		<b>GST (7.00%)</b>	\$3.17
		<b>Total</b>	\$48.45

Please conduct the survey at

Pegasus Engineering @ SME c/o 1 Kaki Bukit Ave 6 Autobay@Kaki Bukit #02-15/16/17/18, Singapore 417883

GARY 8338 8418




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007056/Utbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 7600E	Veh. Inspected	SLT 4990T
Policy No.		Coverage (\$)	0.00
Claim No.	D18002904MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	17/04/2018
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 5 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6CW1071H0126471	Colour	BLUE
Odometer	30737	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R16	TOYO	6 mm
L/H Front Tyre	215/55 R16	TOYO	6 mm
R/H Rear Tyre	215/55 R16	TOYO	6 mm
L/H Rear Tyre	215/55 R16	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/04/2018	Inspection Date	17/04/2018
Survey held at	SME MOTOR - BLK 1 KAKI BUKIT AVE 6 #02-15		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>8 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 4990T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR GATE	BADLY DENTED	1,550.80	1,550.80
1	REAR GATE LOGO	NECESSARY	68.50	68.50
1	REAR GATE "MAZDA" PLATE	NECESSARY	45.80	45.80
1	REAR GATE "5" PLATE	NECESSARY	35.50	35.50
1	REAR GATE "SKYACTIVE" PLATE	NECESSARY	140.20	140.20
1	REAR GATE OUTER GARNISH	NOT NECESSARY	450.80	-
1	REAR GATE LOCK	TWISTED / SHORTED	280.50	280.50
1	REAR GATE INNER RUBBER	TWISTED	170.50	170.50
1	REAR GATE INNER TRIMBOARD	NOT NECESSARY	450.20	-
2	REAR GATE INNER TRIM (SIDE) @\$175.50	NOT NECESSARY	351.00	-
1	REAR GATE INNER TRIM TOP	NOT NECESSARY	210.60	-
16	INNER TRIM CLIPS	NOT NECESSARY	144.00	-
2	REAR GATE ABSORBER @\$195.70	NOT NECESSARY	391.40	-
1	REAR BUMPER	DISTORTED	950.80	950.80
2	REAR BUMPER RETAINER @\$55.80	BENT	111.60	111.60
10	REAR BUMPER CLIPS @\$6.00	NECESSARY	60.00	60.00
1	REAR BUMPER REINFORCEMENT	BENT	150.80	150.80
2	TAIL LAMP @\$615.00	NOT NECESSARY	1,230.00	-
1	REAR END PANEL	BADLY DENTED	485.50	485.50
1	REAR END PANEL TOP GARNISH	TWISTED	105.50	105.50
1	REAR SPARE TYRE FLOOR PANEL	CRUMPLED / BUCKLED	910.50	910.50
1	REAR SPARE TYRE TOP BOARD COVER	NOT NECESSARY	295.80	-
1	REAR EXHAUST BOX	BENT / DENTED	1,035.95	1,035.95
1	REAR EXHAUST BOX CHROME FINISHER	BENT	185.00	185.00
1	REAR EXHAUST BOX CENTRE PIPE (NPA)	TO REPAIR SEE LABOUR	-	-
6	REAR EXHAUST RUBBER HOLDER @\$38.50	NOT NECESSARY	231.00	-
1	REAR SPARE TYRE TOOLS TRAY (NPA)	NOT NECESSARY	-	-
1	REAR BUMPER REFLECTOR LH	BROKEN	55.00	55.00
2	REAR BUMPER CENTRE HOLDER (ADDITIONAL)	BENT	56.60	56.60

Report Ref No. CS/FCI18007056/Utn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-2,030.77	-1,279.81
			8,123.08	5,119.24
	<b>SPECIAL NETT ITEMS</b>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			310.00	240.00
	<b>LABOUR</b>			
	WIRE CHECKING.		30.00	30.00
	REMOVE & REFIX REAR WINDSCREEN.		120.00	120.00
	REMOVE & REFIX CUSHION AND SEATS.		180.00	60.00
	REMOVE & REFIX EXHAUST BOX.		180.00	60.00
	CAVITY PROTECTION ON ALL AFFECTED AREAS.		150.00	90.00
	TOWING FEE (KING ROLLER).		120.00	100.00
	LABOUR CHARGE INCLUSIVE OF THE REPAIR OF REAR EXHAUST BOX CENTRE PIPE.		1,600.00	1,200.00
	SPRAY PAINTING.		1,200.00	1,100.00
			3,580.00	2,760.00
	<b>GRAND TOTAL</b>		<b>12,013.08</b>	<b>8,119.24</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>8,119.24</b>

Report Ref No. CS/FCI18007056/Utbn2

**CHUA KANG SENG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.