

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS18007067/AVBN2**Date:** 15/05/2018REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle No :

SLM1018H

Insured Vehicle No :

SLK1191A

Date of Loss: 15/04/2018

Nature of Claim:

TP

Claim No:

DMPU1800044H

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLM1018H**

Make & Model: NISSAN QASHQAI, 1.2 (A)

Reg. Date: 15/03/2017 (Man. Year: 2016)

Colour: White

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: HRA2306543A

Chassis No: SJNFEAJ11U1775605

Odometer: 25097 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17

Front Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

Rear Tyre Size:

215/60R17

Rear Left Side:

Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,342.20	2,306.75	12,035.45	83.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,310.00	1,210.00	3,100.00	71.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,652.20	3,516.75	15,135.45	81.15
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	18,652.20	2,800.00	15,852.20	84.99
+ GST 7.00/7.00% (S\$)	1,305.65	196.00	1,109.65	84.99
Nett Amount (S\$)	19,957.85	2,996.00	16,961.85	84.99

INSPECTION

Date of Assignment: 16/04/2018

Date Inspected: 18/04/2018 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2018)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SLM1018H/15/05/2018 08:11	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT R/H FENDER	Dented	622.70 F	*622.70 FL
2	1	*FRONT R/H DOOR	Dented	1,104.80 F	*1,104.80 FL
3	1	*FRONT R/H DOOR SIDE MIRROR ASSY	Not Necessary	611.50 F	*- FL
4	1	*FRONT R/H DOOR INNER GEAR MOTOR ASSY	Not Necessary	487.90 F	*- FL
5	1	*REAR R/H DOOR	Repair	1,104.80 F	*- FL
6	1	*FRONT R/H FENDER PROTECTOR	Deformed	483.00 F	*483.00 FN
7	10	*FRONT R/H FENDER PROTECTOR CLIP	Necessary	65.00 F	*20.00 FN
8	1	*FRONT R/H FENDER COWLING	Not Necessary	87.50 F	*- FN
9	10	*FRONT R/H FENDER COWLING CLIP	Not Necessary	65.00 F	*- FN
10	1	*FRONT R/H DOOR SIDE MIRROR COVER	Not Necessary	141.10 F	*- FN
11	1	*FRONT R/H DOOR SIDE MIRROR SIGNAL LAMP	Not Necessary	160.00 F	*- FN
12	1	*FRONT R/H DOOR LOWER PROTECTOR COVER	Not Necessary	323.60 F	*- FN
13	10	*FRONT R/H DOOR LOWER PROTECTOR COVER CLIP	Not Necessary	65.00 F	*- FN
14	1	*FRONT R/H DOOR OUTER HANDLE	Repair	165.20 F	*- FN
15	2	*FRONT R/H DOOR FRAME STICKER	Necessary	72.00 F	*72.00 FN
16	1	*FRONT R/H DOOR INNER LOCK	Not Necessary	279.70 F	*- FN
17	1	*FRONT R/H DOOR INNER RUBBER	Not Necessary	132.20 F	*- FN
18	1	*FRONT R/H DOOR INNER TRIM BOARD	Not Necessary	1,869.50 F	*- FN
19	1	*FRONT R/H LOWER ARM	Not Necessary	245.50 F	*- FN
20	2	*REAR R/H DOOR FRAME STICKER	Not Necessary	72.00 F	*- FN
21	1	*REAR R/H DOOR LOWER PROTECTOR COVER	Not Necessary	323.60 F	*- FN
22	10	*REAR R/H DOOR LOWER PROTECTOR COVER CLIP	Not Necessary	65.00 F	*- FN
23	1	*FRONT R/H KNUCKLE ARM	Not Necessary	583.20 F	*- FN
24	1	*FRONT R/H KNUCKLE ARM BEARING	Not Necessary	332.30 F	*- FN
25	1	*FRONT R/H SHOCK ABSORBER	Not Necessary	547.50 F	*- FN
26	1	*FRONT R/H DRIVE SHAFT	Not Necessary	1,223.10 F	*- FN
27	1	*FRONT STEERING RACK	Not Necessary	1,428.00 F	*- FN
28	1	*FRONT R/H RIM	Cut	1,681.50 FS	*580.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	14,342.20	2,882.50
- List Item Discount on L Items 0.00/30.00% (\$)	0.00	518.25
- Nett Item Discount on N Items 0.00/10.00% (\$)	0.00	57.50

Total Parts (\$) **14,342.20** **2,306.75**

LKK Auto Consultants Pte Ltd/SLM1018H/15/05/2018 08:11. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT R/H DOOR,GLASS,GEAR MOTOR,LOCK,RUBBER,FRAME STICKER & TRIM BOARD	New	380.00	80.00
2	TO REMOVE & REFIT FRONT R/H UNDERCARRIAGE	New	380.00	-
3	TO REMOVE & REFIT DRIVE SHAFT & STEERING RACK	New	450.00	-
4	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
5	TUFF KOTE	New	150.00	-
6	PANEL BEATING	New	1,400.00	400.00
7	SPRAY PAINTING	New	1,400.00	650.00
Gross Labour Cost (\$\$)			4,310.00	1,210.00

LKK Auto Consultants Pte Ltd/SLM1018H/15/05/2018 08:11. Not valid without Reference section.

< END OF ESTIMATES >