

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/III18007094/KPA3Q2

**Date:** 27/04/2020

#### REFERENCE

|   |                             |                       |
|---|-----------------------------|-----------------------|
| Handling Insurer: India International Insurance Pte Ltd | Policy No:                  | MCOM0015              |
| <b>Claimant</b>   |                             |                       |
| <b>Vehicle No :</b> SHC5354K                            | <b>Insured Vehicle No :</b> | SHA7611R              |
| Date of Loss: 13/04/2018                                | Nature of Claim: TP         | Claim No: MCT18040386 |

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |   |                               |
|-----------------------------|---|-------------------------------|
| Reg No:                     | SHC5354K                                    |                               |
| Make & Model:               | RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) | Engine No: M9R8839C001991     |
| Reg. Date:                  | 30/09/2014 (Man. Year: 2014)                | Chassis No: VF1ABL15AUC279373 |
| Colour:                     | Metallic White/Red                          | Odometer: 429516 km           |
| Engine Capacity:            | 1995 cc                                     |                               |
| Market Value/New Car Price: | N/A   |                               |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>           |                               |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

#### CONDITION OF TYRES

|                   |               |                  |             |
|-------------------|---------------|------------------|-------------|
| Front Tyre Size:  | 215/60 R16    | Rear Tyre Size:  | 215/60 R16  |
| Front Left Side:  | Linglong 8 mm | Rear Left Side:  | Falken 6 mm |
| Front Right Side: | Linglong 8 mm | Rear Right Side: | Falken 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---|-------------------|-------------------|-------------------|---------------|
| Parts   | 36,770.24         | 2,554.34          | 34,215.90         | 93.05         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour  | 11,420.00         | 480.00            | 10,940.00         | 95.80         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing  | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>48,190.24</b>  | <b>3,034.34</b>   | <b>45,155.90</b>  | <b>93.70</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>2,450.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 48,190.24         | 2,450.00          | 45,740.24         | 94.92         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 3,373.32          | 171.50            | 3,201.82          | 94.92         |
| <b>Nett Amount (S\$)</b>                        | <b>51,563.56</b>  | <b>2,621.50</b>   | <b>48,942.06</b>  | <b>94.92</b>  |
| <b>+ Loss of Use (3.0 x S\$40.00/day) (S\$)</b> |                   | 120.00            |                   |               |
| <b>+ Car Rental (3.0 x S\$101.46/day) (S\$)</b> |                   | 304.38            |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>3,045.88</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>3,000.00</b>   |                   |               |

#### INSPECTION

|                             |            |  |
|-----------------------------|------------|--|
| Date of Assignment:         | 16/04/2018 |  |
| Date Inspected:             | 16/04/2018 | Inspected At: Trans-cab Auto Services Pte Ltd<br>No 2 Ang Mo Kio Street 63<br>Singapore 569111 |
| Estimated Period of Repair: | 2.0 days   |  |

---

**Adjuster:** KENNETH KONG

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|  |  |
|--|--|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 26 Mar 2020)  |
| <b>Parts:</b> 143  | RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)   |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SHC5354K) |  |
| <b>Validity:</b>   | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>   | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

| No. | Qty | Part No. | Particulars                             | Condition        | Repairer's  | Amount       |
|-----|-----|----------|---|------------------|-------------|--------------|
| 1   | 1   |          | *BUMPER COVER REAR                      | Buckled / Dented | 1,108.46 FL | *1,108.46 FL |
| 2   | 1   |          | *BUMPER LOWER REAR                      | Dented / Cut     | 768.84 FL   | *768.84 FL   |
| 3   | 1   |          | *BUMPER BRACKET CTR REAR                | Serviceable      | 113.47 FL   | *- FL        |
| 4   | 1   |          | *BUMPER BRACKET SIDE RH REAR            | Serviceable      | 135.97 FL   | *- FL        |
| 5   | 1   |          | *BUMPER RETAINER RH REAR                | Serviceable      | 44.99 FL    | *- FL        |
| 6   | 1   |          | *BUMPER REFLECTOR RH                    | Serviceable      | 43.61 FL    | *- FL        |
| 7   | 1   |          | *BUMPER BRACKET SIDE LH REAR            | Serviceable      | 135.97 FL   | *- FL        |
| 8   | 1   |          | *BUMPER RETAINER LH REAR                | Serviceable      | 44.99 FL    | *- FL        |
| 9   | 1   |          | *BUMPER REFLECTOR LH                    | Serviceable      | 43.61 FL    | *- FL        |
| 10  | 1   |          | *BUMPER BEAM REAR                       | Bent             | 777.52 FL   | *777.52 FL   |
| 11  | 1   |          | *BUMPER BEAM BRACKET LH REAR            | Repair           | 225.95 FL   | *- FL        |
| 12  | 1   |          | *BUMPER BEAM BRACKET RH REAR            | Repair           | 225.95 FL   | *- FL        |
| 13  | 1   |          | *BOOT REAR                              | Repair           | 2,872.68 FL | *- FL        |
| 14  | 1   |          | *BOOT FINISHER                          | Serviceable      | 470.06 FL   | *- FL        |
| 15  | 1   |          | *BOOT WEATHERSTRIP                      | Serviceable      | 323.05 FL   | *- FL        |
| 16  | 1   |          | *BOOT REFLECTOR LAMP LH                 | Serviceable      | 493.35 FL   | *- FL        |
| 17  | 1   |          | *BOOT REFLECTOR LAMP RH                 | Serviceable      | 493.35 FL   | *- FL        |
| 18  | 1   |          | *BOOT BADGE RENAULT                     | Not Necessary    | 225.36 FL   | *- FL        |
| 19  | 1   |          | *BOOT BADGE                             | Not Necessary    | 225.36 FL   | *- FL        |
| 20  | 1   |          | *BOOT STRUT LH                          | Serviceable      | 276.08 FL   | *- FL        |
| 21  | 1   |          | *BOOT STRUT RH                          | Serviceable      | 276.08 FL   | *- FL        |
| 22  | 1   |          | *BOOT HINGE LH                          | Repair           | 367.84 FL   | *- FL        |
| 23  | 1   |          | *BOOT HINGE RH                          | Repair           | 367.84 FL   | *- FL        |
| 24  | 1   |          | *BOOT INNER TRIM                        | Serviceable      | 586.45 FL   | *- FL        |
| 25  | 1   |          | *BOOT SWITCH                            | Serviceable      | 168.13 FL   | *- FL        |
| 26  | 1   |          | *BOOT LOCK                              | Repair           | 202.67 FL   | *- FL        |
| 27  | 1   |          | *BOOT LOCK CATCH                        | Repair           | 74.40 FL    | *- FL        |
| 28  | 2   |          | *LICENCE PLATE LAMP                     | Serviceable      | 50.52 FL    | *- FL        |
| 29  | 2   |          | *BOOT RUBBER PLUG                       | Serviceable      | 221.81 FL   | *- FL        |
| 30  | 1   |          | *DOOR PANEL REAR LH                     | Repair           | 2,844.66 FL | *- FL        |
| 31  | 1   |          | *FENDER PANEL INNER TRIM REAR LH        | Serviceable      | 671.45 FL   | *- FL        |
| 32  | 1   |          | *FENDER PANEL REAR LH                   | Repair           | 3,299.13 FL | *- FL        |
| 33  | 1   |          | *WHEELARCH REAR LH                      | Serviceable      | 543.47 FL   | *- FL        |
| 34  | 1   |          | *FENDER PANEL INNER TRIM REAR RH        | Serviceable      | 671.45 FL   | *- FL        |
| 35  | 1   |          | *FENDER PANEL REAR RH                   | Repair           | 3,299.13 FL | *- FL        |
| 36  | 1   |          | *WHEELARCH REAR RH                      | Serviceable      | 543.47 FL   | *- FL        |
| 37  | 1   |          | *TAILLAMP RH                            | Serviceable      | 552.55 FL   | *- FL        |
| 38  | 1   |          | *TAILLAMP PANEL RH                      | Repair           | 986.70 FL   | *- FL        |
| 39  | 1   |          | *TAILLAMP LH                            | Serviceable      | 552.55 FL   | *- FL        |
| 40  | 1   |          | *TAILLAMP PANEL LH                      | Repair           | 986.70 FL   | *- FL        |
| 41  | 1   |          | *OUTER PANEL REAR (END PANEL)           | Repair           | 1,471.77 FL | *- FL        |
| 42  | 1   |          | *OUTER PANEL REAR (END PANEL)TRIM       | Serviceable      | 404.56 FL   | *- FL        |
| 43  | 1   |          | *SPARE WHEEL PANEL(LUGGAGE FLOOR PANEL) | Repair           | 2,189.88 FL | *- FL        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                              | Condition     | Repairer's  | Amount    |
|-----|-----|----------|--|---------------|-------------|-----------|
| 44  | 1   |          | *SPARE WHEEL PANEL TRIM                  | Serviceable   | 612.21 FL   | *- FL     |
| 45  | 1   |          | *EXHAUST REAR                            | Repair        | 7,489.05 FL | *- FL     |
| 46  | 1   |          | *EXHAUST CAP REAR                        | Repair        | 230.49 FL   | *- FL     |
| 47  | 1   |          | *SET PARKING AID                         | Not Necessary | 700.00 FS   | *- FS     |
| 48  | 1   |          | *SET REAR BUMPER CLIP                    | Necessary     | 66.00 FS    | *66.00 FS |
| 49  | 1   |          | *SET BUMPER BRACKET CTR CLIP             | Necessary     | 33.00 FS    | *33.00 FS |
| 50  | 1   |          | *SET BUMPER BRACKET SIDE CLIP LH RR      | Not Necessary | 10.00 FS    | *- FS     |
| 51  | 1   |          | *SET BUMPER RETAINER RH REAR RR          | Not Necessary | 20.00 FS    | *- FS     |
| 52  | 1   |          | *SET BUMPER BRACKET SIDE CLIP LH RR      | Not Necessary | 10.00 FS    | *- FS     |
| 53  | 1   |          | *SET BUMPER RETAINER CLIP LH RR          | Not Necessary | 20.00 FS    | *- FS     |
| 54  | 1   |          | *SET BUMPER LOWER REAR RIVET             | Not Necessary | 22.00 FS    | *- FS     |
| 55  | 1   |          | *SET BUMPER LOWER REAR CLIP              | Necessary     | 66.00 FS    | *66.00 FS |
| 56  | 1   |          | *EXHAUST MOUNTING REAR                   | Serviceable   | 17.82 FS    | *- FS     |
| 57  | 1   |          | *SET BOOT FINISHER CLIP                  | Not Necessary | 24.20 FS    | *- FS     |
| 58  | 1   |          | *BOOT STICKER TRANS-CAB                  | Not Necessary | 30.00 FS    | *- FS     |
| 59  | 1   |          | *BOOT STICKER 6555-3333                  | Not Necessary | 30.00 FS    | *- FS     |
| 60  | 1   |          | *BOOT INNER TRIM CLIP                    | Not Necessary | 45.00 FS    | *- FS     |
| 61  | 1   |          | *SET FENDER PANEL WHEELARCH REAR RH CLIP | Not Necessary | 35.00 FS    | *- FS     |
| 62  | 1   |          | *SET FENDER PANEL WHEELARCH REAR LH CLIP | Not Necessary | 35.00 FS    | *- FS     |
| 63  | 1   |          | *FENDER INNER TRIM CLIP LH               | Not Necessary | 28.00 FS    | *- FS     |
| 64  | 1   |          | *FENDER INNER TRIM CLIP LH               | Not Necessary | 28.00 FS    | *- FS     |
| 65  | 1   |          | *TAILLAMP CLIP RH                        | Not Necessary | 5.00 FS     | *- FS     |
| 66  | 1   |          | *TAILLAMP CLIP LH                        | Not Necessary | 5.00 FS     | *- FS     |
| 67  | 2   |          | *REAR WINDSCREEN SEALANT                 | Not Necessary | 80.00 FS    | *- FS     |
| 68  | 1   |          | *WINDSCREEN MOULDING                     | Not Necessary | 100.00 FS   | *- FS     |
| 69  | 1   |          | *REAR WINDSCREEN INNER SPONGE SEAL       | Not Necessary | 100.00 FS   | *- FS     |
| 70  | 1   |          | *SPARE TYRE RIM (ROUE 7J 16H 2547)       | Serviceable   | 385.00 FS   | *- FS     |
| 71  | 1   |          | *SPARE TYRE                              | Serviceable   | 33.00 FS    | *- FS     |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                  |                 |
|--|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>40,641.60</b> | <b>2,819.82</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 3,871.36         | 265.48          |
| <b>Total Parts (\$\$)</b>                                  | <b>36,770.24</b> | <b>2,554.34</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's       | Amount        |
|---------------------------------|---|----------|------------------|---------------|
| <b>Labour Items</b>             |   |          |                  |               |
| 1                               | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION  | New      | 4,500.00         | 220.00        |
| 2                               | PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME. | New      | 4,200.00         | 200.00        |
| 3                               | TO RUST-PROOFING OF THE AFFECTED AREAS  | New      | 170.00           | 0.00          |
| 4                               | TO REINSTALL REAR BUMPER PARKING SENSOR   | New      | 170.00           | 60.00         |
| 5                               | TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.  | New      | 170.00           | 0.00          |
| 6                               | TO REPAIR AND REALIGN REAR EXHAUST PIPE   | New      | 170.00           | 0.00          |
| 7                               | TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE                                       | New      | 170.00           | 0.00          |
| 8                               | TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST  | New      | 170.00           | 0.00          |
| 9                               | TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.                             | New      | 170.00           | 0.00          |
| 10                              | TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING   | New      | 380.00           | 0.00          |
| 11                              | TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST   | New      | 380.00           | 0.00          |
| 12                              | TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST  | New      | 170.00           | 0.00          |
| 13                              | TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT   | New      | 220.00           | 0.00          |
| 14                              | TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST   | New      | 380.00           | 0.00          |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>11,420.00</b> | <b>480.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >