



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD  
5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX  
SINGAPORE 069110

INV No. AC2004925  
INV Date 14/07/2020  
Reference CC4/EQI18007116/Kps3q2  
Code EQI



#### PROFESSIONAL SERVICE FEE

Vehicle No. FBM 6460Z  
Insured Veh. GBE 5332J  
Claim No.  
Policy No. DMCPHQ18-000589  
Accident Date 14/04/2018  
Inspection Date 02/05/2018

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD		Ref : CC4/EQI18007116/Kps3q2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 14-07-2020		
		Code : EQI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	GBE 5332J	<b>Veh. Inspected</b>	FBM 6460Z
	<b>Policy No.</b>	DMCPHQ18-000589	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>		<b>Excess (\$)</b>	0.00
	<b>Assign From</b>		<b>Assign Date</b>	17/04/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	BAJAJ PULSAR	<b>c.c</b>	200
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
	<b>Chassis No.</b>	MD2A55FZ6GCA12992	<b>Colour</b>	YELLOW /BLACK
	<b>Odometer</b>	10253	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	100/80 R17	MRF	4 mm
	<b>L/H Front Tyre</b>			mm
	<b>R/H Rear Tyre</b>	130/70 R17	MRF	4 mm
	<b>L/H Rear Tyre</b>			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	14/04/2018	<b>Inspection Date</b>	02/05/2018
	<b>Survey held at</b>	SUPREME AUTO SERVICE PTE LTD 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 6460Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	MIRROR ASSEMBLY (L/H)	BROKEN	56.00	56.00
1	MIRROR ASSEMBLY (R/H)	CUT	56.00	56.00
1	FRONT LEVER BRAKE LONGER	DENTED	28.00	28.00
1	WEIGHT HANDLE BAR	DENTED	16.00	16.00
1	SILENCER END CHAMBER ASSEMBLY	DENTED	189.00	189.00
1	TUBE REAR HUGGER MOUNTING (RS200) AL	DENTED	38.00	38.00
1	REAR ASSEMBLY HUGGER	BENT	52.00	52.00
1	BOLT MIRROR MOUNTING THREAD L/H	NECESSARY	6.00	6.00
1	BOLT MIRROR MOUNTING THREAD R/H	NECESSARY	6.00	6.00
1	REAR TYRE	SERVICEABLE	150.00	-
	LESS 10% DISCOUNT		-	-44.70
			597.00	402.30
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	NUMBER PLATE (SN)	BENT	25.00	25.00
			25.00	25.00
	<b><u>LABOUR</u></b>			
	TO CHANGE TYRE & PERFORM WHEEL BALANCING.	NOT NECESSARY	30.00	-
	TO PROVIDE TRANSPORT SERVICE CHARGE.		60.00	25.00
	TO REMOVE & REPLACE THE PARTS MENTIONED ABOVE PANEL BEAT & REALIGN THE NECESSARY AFFECTED AREAS.		380.00	120.00
	TO CHECK WIRING SYSTEM.		30.00	10.00
	TO APPLY PUTTY & SPRAY PAINT ON AFFECTE AREAS.		380.00	150.00
	TO PERFORM COMPUTERISED ALIGNMENT.	NOT NECESSARY	40.00	-
			-	-
			-	-
			-	-
			920.00	305.00
	<b>GRAND TOTAL</b>		<b>1,542.00</b>	<b>732.30</b>

Report Ref No. CC4/EQ118007116/Kps3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			550.00
---	--	--	--------

Report Ref No. CC4/EQ18007116/Kps3q2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBM 6460Z

INSPECTION







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBM 6460Z

RE-INSPECTION

