5/5/2010



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inter	nationale Des Experts En Auton	nobile			
λXΑ	INSURANCE PTE	LTD	Ref : CC4/ASM1800	7141/Kua3			
SH AXA	ENTON WAY #24- TOWERSINGAPO	01 RE 068811	Date: 17-04-2018 Code: ASM				
1.	260年107日平38	Policy Particu	lars :- THIRD PARTY CLA	IM			
	Insured Veh.	SLR 822H	Veh. Inspected	SLN 4133H			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	S8M00E3I	Excess (\$)	0.00			
	Assign From		Assign Date	17/04/2018			
2.		Vehicle I	Particulars & Condition				
	Make & Model		c.c	0			
	Engine No.	HIDDEN	Year of Reg.				
	Chassis No.		Colour				
	Odometer		Steering				
	Brakes		Modification				
	General						
3.		Co	onditions of Tyres				
		Size	Make	Balance			
	R/H Front Tyre			mm			
	L/H Front Tyre			mm			
	R/H Rear Tyre			mm			
	L/H Rear Tyre			mm			
4.		Desc	cription of Damages	THE RESERVE TO SERVE THE PARTY OF THE PARTY			
5.		Ge	eneral Information				
	Accident Date	15/04/2018	Inspection Date	17/04/2018			
	Survey held at	ESTEEM PERFORMANCI	E PTE LTD				
1	**************************************	BLK 5033 ANG MO KIO INDUSTRIA #01-259 SINGAPORE 569536	L PARK 2				
5a.	· 图 · 文祖 · 李建		Remarks				



Repair Estimates	S	LN 4133 H	Resory Bapa
Parts (a) Cost / List Price Items	\$	11,390.38	Mesony Bapa.
Plus/Less25%_	\$	2,847.60	
Total of Cost / List	\$	8,542.79	
(b) Nett Price Items Less Total of Nett Item			LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" has s
(c) Special Nett Items	\$	200.00	No illegal mortification(s) is a swed Supplementary item; and the result liver and is subject to final approval from insurant. Company
Total Parts Cost	\$	8,742.79	Acknowledged by Repairer
Labour	\$	5,120.00	Signature: Date:
Total	\$	13,862.79	

The above total will be subjected to 7% G.S.T.

Nar	me of Surveyor	*	Kennern
Cor	npany	*	LKIC
Sur	vey conducted on	÷	/7/4/18 at
Rer	marks By Surveyor		
(a)	The repair of this vehicle is author	prized	/ is not authorized until further notice.
			^
(b)	Recommended Days of Repair	1	$\mathcal{O}_{\mathcal{S}_{day(s)}}$ day(s)
(b)	Recommended Days of Repair Resurvey	:	Required / Not Required
33.50	15 (S)	:	(A)



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperl.com.sg

Spare Parts

Vehicle No. : Make & Model :

Chassis No

-

SLN 4133 H

TOYOTA PRIUS JTDKB3FU803556649 Submit By

Year Manufacture : Engine No. : Carmen Lim

2017

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor		1	\$200.00	S.N	?
2	Rear bumper	CPA	1	\$497.50		
3	Rear bumper clip	M	10	\$40.00		
4	Rear bumper side retainer LH	Dil	1	\$112.70		
5	Rear bumper side retainer RH	Sn	1	\$112.70		X
6	Rear bumper reinforcement	n	1	\$398.90		X
7	Rear bumper lower garnish centre	0,1	1	\$582.60	Tan.	
8	Rear bumper lower garnish LH	cm	1	\$149.70		
9	Rear bumper under cover	cn	1	\$355.20		_
10	Rear bumper under cover LH	cm	1	\$187.60		_
11	Rear bumper under cover clip	m	- 4	\$14.00		
12	Tail lamp LH - UPPER		1	\$498.75		2
13	Tail lamp LH - LOWER		1	\$511.60		1
14	Tail end panel	By	1	\$596.60		_
15	Tail end panel garnish	Sm	1	\$151.60		λ
16	Tail end panel garnish clip	n	10	\$35.00		×.
17	Boot weatherstrip	Sm	1	\$353.10		×
18	LH rear fender	Ry	1	\$883.60		
19	LH rear fender undershield	CM	1	\$92.30		
20	LH rear fender undershield clip	M	10	\$30.00		_
21	LH rear fender air duct	pel	1	\$115.60		
22	LH rear inner trim	ne form	1	\$387.63		
23	LH rear lower arm		1	\$398.65		7

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : Make & Model:

Chassis No :

SLN 4133 H

JTDKB3FU803556649

TOYOTA PRIUS

Submit By

Carmen Lim

Year Manufacture :

Engine No.

2017

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH rear knuckle arm	1	\$895.60		_
25	LH rear knuckle bearing	1	\$421.90		
26	LH rear wheel hub	1			
27	LH rear wheel hub lock nut	1	\$17.30		7
28	LH rear shock absorber	1	\$359.40		7
29	LH rear shock absorber top mouting	1	\$165.70		1
30	LH rear shock absorber stopper	1	\$85.70		7
31	LH rear rim nJ	1	\$1,555.10		
32	LH rear tyre	1	\$350.00		7
33	LH rear hub cab	1	\$195.95		
34	LH side skirt	1	\$798.40		2
35	LH side skirt clip	10	\$40.00		2
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No.	:	SLN 4133 H	Submit By :	Carmen Lim
Make & Model	48	TOYOTA PRIUS	Year of Manufacture :	2017

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER,		
	LHR DOOR,LH SIDE SKIRT,TAILDOOR,SPARE TYRE WELL		
	PANEL)	\$2,000.00	12001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER,		
	LHR DOOR,LH SIDE SKIRT,TAILDOOR,SPARE TYRE WELL		
	PANEL)	\$1,800.00	10001
3	To check wiring	\$50.00	201
4	To remove & refit reverse sensor to assit work load	\$120.00	501
5	To tuff coat	\$250.00	601
6	To remove & refit spare tyre, spare tyre board, carpet trim		
	to assist work load.	\$150.00	1201
7	To remove & refit undercarriage to assist work load.	\$250.00	?
8	To do wheel alignment.	\$120.00	601
9	To remove & refit Door trim, door glass, window regulator,		
	door lock to assist work load.	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

La	h	0		-
		v	ч	

Vehicle No.	: _	SLN 4133 H	Submit By :	Carmen Lim
Make & Model	: _	TOYOTA PRIUS	Year of Manufacture :	2017

S/No	Labour Description	Esimated Price	Adjusted Price
10	To remove & refit petrol tank to assist work load.	\$150.00	Price 662
11	Towing	\$110.00	601
_			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

S8M00E3I

Our ref:

CC4/ASM18007141/Kua3

Date:

18.04.2018

The Motor Claims Department M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


SLN 4133H

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17.04.2018 at the premises of M/s Esteem Performance Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	13,862.79
Revised Estimate Amount	: S\$	8,165.19
"Check" Items Amount	: S\$	2,669.13
Total (Including Check Items)	: S\$	10,834.32
Market Value	: S\$	92,000.00 (est.)
LTA Reimbursement Value	: S\$	47,274.00 (est.)
Nett Value	: S\$	44,726.00 (est.)

Description of Damage: The vehicle sustained damages at the N/S Rear Portion and U/C



Comments/Present Status:


Damages Consistent

Estimated normal period for repairs: 8.0 days

Yours faithfully,

KENNETH KONG

Licensed Appraiser



				٨	
Repair Estimates	SLN	I 4133 H	Finalisec	d	Not Nothanie
arts (a) Cost / List Price Items	\$	11,390.38	9894	10 02072	Not Nothaniel Resorry Bepair
Plus/Less25%	\$	2,847.60	73.98.	54	
Total of Cost / List	\$	8,542.79	Has.	62	
(b) Nett Price Items	P.44			LKK Aut	lo Consultants hence notify airer of the following:
Less				 To resum To displa 	vey before/after spray painting ay damaged partisi during reservey
Total of Nett Item				 Parts price Third part 	ces are subject to confirmation (If survey is on a "Without President" Fire
(c) Special Nett Items	\$	200.00		No illegal Supplem	entary items of the state of
otal Parts Cost	\$	8,742.79			1 to final approval from hisural. Company (ged by Repairer
bour	\$	5,120.00	>480·	Signature: Date:	
otal	\$	13,862.79	9975.6	Y	
ne above total will be subjected to Name of Surveyor	7% G.S.T.		,	enser	T.
Company	M 19-		4	ensor. W	
Survey conducted on	: _		17/4/10	The second second	al
Remarks By Surveyor					
(a) The repair of this vehicle is	officerized / is	not authorized	until further no	otice.	
(b) Recommended Days of Rep		10/00/00/2004 - Processor - Pr	08	day(s))
(c) Resurvey	; Re	equired / Not Re	equired		
(d) Excess	:\$		_ (^	
(e) Signature of surveyor	:		L	<u>é</u>	Date: 17/4/18



Blk 5033 Arig Mo Klo, Ind Park 2 #01 251/ 259, 569536. Fol: 165 6484 1221 Fax: 165-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. Make & Model: Chassis No

SLN 4133 H

TOYOTA PRIUS

JTDKB3FU803556649

Submit By

Year Manufacture Engine No.

Carmen Lim 2017

Cost / List

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	54	1	\$200.00	S.N	R
2	Rear bumper	CPS	1	\$497.50	7.	<u> </u>
3	Rear bumper clip	Ma	10	\$40.00		-
4	Rear bumper side retainer LH	Dil	1	\$112.70 V	1	1
5	Rear bumper side retainer RH	Sn	1	\$112.70	I I I I I I I I I I I I I I I I I I I	X
6	Rear bumper reinforcement	n	1	\$398.90		X
7	Rear bumper lower garnish centre	011	1	\$582.60	+ '	
8	Rear bumper lower garnish LH	cn.	1	\$149.70	1	-
9	Rear bumper under cover	cn	1	\$355.20	+	
10	Rear bumper under cover LH	cm	1	\$187.60	1	
11	Rear bumper under cover clip	m	4	\$14.00		
12	Tail lamp LH - UPPER	Su	1	\$498.75		×
13	Tail lamp LH - LOWER	h	1	\$511.60		7
14	Tail end panel	By	1	\$596,60	7	~
15	Tail end panel garnish	Sm	1	\$151.60		X
16	Tail end panel garnish clip	n	10	\$35.00		Κ.
17	Boot weatherstrip	Sn	1	\$353.10		×
18	LH rear fender .	A,	1	\$883.60	1	
19	LH rear fender undershield	cm	1	\$92.30	1	_
20	LH rear fender undershield clip	na	10	\$30.00	1	
21	LH rear fender air duct	pel	1	\$115.60	1	
22	LH rear inner trim	me form	1	\$387.63	1.	-
23	LH rear lower arm	Ry	1	\$398.65	1	2

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 Company Reg No. 200005485N / GST No. 20-0005485-N

4443.68

Spare Parts

Vehicle No. :

Chassis No :

Make & Model :

SLN 4133 H TOYOTA PRIUS JTDKB3FU803556649

Submit By

Year Manufacture : Engine No. :

Cost / List

Carmen Lim

2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by
24	LH rear knuckle arm	1	\$895.60		Surveyor
25	LH rear knuckle bearing	1	\$421.90		
26	LH rear wheel hub	1	V121.00		
27	LH rear wheel hub lock nut	1	\$17.30		7
28	LH rear shock absorber	1	\$359.40		12
29	LH rear shock absorber top mouting	. 1	\$165.70		1
30	LH rear shock absorber stopper	. 1	\$85.70		1
31	LH rear rim nu	1	\$1,555.10		
32	LH rear tyre	1	\$350.00		7
33	LH rear hub cab	1	2102.02		1,
34	LH side skirt	1			7
35	LH side skirt clip	10	\$798.40		X
36		10	\$40.00		8
37			-		
38					<u> </u>
39					
40					
41					
42					
43					
44		_			
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829 Company Reg No. 200005485N / GST No. 20-0005485-N

Zunt, ax



PERFORMANCE Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536, Tel: +65-6484 1221 Fax: +65-6484 7829 Websile: www.esteeinperl.com.sg

South to the transfer

Labour

Vehicle No.	:	SLN 4133 H	Submit By
Make & Model	:	TOYOTA PRIUS	Year of M

bmit By ; Carmen Lim

Year of Manufacture : 201

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT	1	11100
0.777117	REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER,		
	LHR DOOR, LH SIDE SKIRT, TAILDOOR, SPARE TYRE WELL		
	PANEL)	\$2,000.00	12000
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER,		
	LHR DOOR,LH SIDE SKIRT,TAILDOOR,SPARE TYRE WELL		
_	PANEL)	\$1,800.00	10001
3	To check wirlng	\$50.00	201
4	To remove & refit reverse sensor to assit work load	\$120.00	50/
5	To luff coat	\$250.00	601
6	To remove & refit spare tyre, spare tyre board, carpet trim		
	to assist work load,	\$150.00	1201
7	To remove & reflt undercarriage to assist work load.	\$250.00	7
8	To do wheel alignment.	\$120.00	601
9	To remove & refit Door trim, door glass, window regulator,		
	door lock to assist work load.	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

7/80.0

La	b	0		r
-	×	v	u	

Vehicle No.	:	SLN 4133 H	Submit By	Carmen Lim
Make & Model	:	TOYOTA PRIUS	Year of Manufacture ;	2017

	Esimated Price	Adjusted Price
To remove & refit petrol tank to assist work load.	\$150.00	Price 601.
Towing	\$110.00	601
	16213-31	
		11-2-
		Towing \$110.00

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536

Spare Parts

Tel:64841221 Fax:64847829

Vehicle No.

SLN 4133 H

Submit By

CARMEN LIM

Make & Model:

TOYOTA PRIUS JTDKB3FU803556649

Year Manufacture :

2017

Chassis No :

Engine No.

Cost / List

Supplementary

-	oupplementary					
S/No.	Part Description		Qty	Unit Price	Price	Disposition by
1	LH rear door	Bu	1	\$1,221.40	1	Surveyor
2	LH rear door hinge top	n	1	\$78.34	X	
3	LH rear door hinge bottom	Dis	1	\$78.34		
4	LH rear door lock	n	1	\$437.80	1/	+
5	LH rear door checker	Sin	1	\$155.60	× /	
6	LH rear door weatherstip	Ju	1	\$187.30	-	-
7	LHR door glass outer moulding lower	Sm	1	\$133.70	×	-
8	LHR door glass outer moulding upper	M	1	\$127.83	_ \	
9	LHR power window motor	h	1	\$578.40	X	
10	LHR power window regulator	12	1	\$198.73	×	
11	LH rear door quarter glass	1	1	\$122.75	× .	0 310 15 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1
12	LH rear door quarter glass moulding	Sen	1	\$75.80	-	
13	LH Taillamp panel	n	1	\$123.15	 	
14	LH Taillamp clip assy	M	4	\$10.00		
15	LH rear fender mudflat	mil	1	\$95.30	,	
16	Floor panel LH	By	1	\$189.60		
17		-7	1	\$109.00		New York
18			1			
19			1			
20			4			
21			1			
22			1			
23			1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

は37-4キン

Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE 6 Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030

Operating Hours : Monday to Friday, 09:00 – 17:00 UEN: S66SS0020G / GST Reg. No.: M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the <u>same</u> Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS: Original Report No: MHH118049960 Vehicle Registration No: SLR822H Name(as shownin NRIC): RAVINDRAN RAMON __NRIC/FIN/Passport No : _S8230945D (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate Address _Singapore(Contact (Tel) ______Mobile No. : 97955165 **Email Address** Date of Accident : 15/04/2018 __Time of Accident : __0615HRS Place of Accident : ALONG SCOTTS ROAD TOWARDS STEVEN ROAD Insurance Company: AXA INSURANCE PTE LTD (B) ADDITIONALINFORMATION / AMENDMENTS: I have made a report on the above mentioned accident and would like to include additional information or make the following amendments: Type of vehicle category should be unknown Policyholder / Driver's Signature Reporting Centre Personnel's Signature Date:

Name: Jerleen NRIC/FIN No .: Date:

GIARMIC unddeviduosfures, V3



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To: AXA Insurance Pte Ltd

Date: 02/05/2019

Survey Details:

Date of loss	15-Apr-18
Date of appointment	17-Apr-18
Date of survey	17-Apr-18
Location of survey	ESTEEM PERFORMANCE PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLN 4133H
Make and Model	TOYOTA PRIUS
Date of registration	3/5/2017
Excess	5/5/202/
Market Value	\$92,000
Parf Rebate	\$47,200
Nett Loss	\$44,800

Repair details:

Initial Estimate	\$ 13,862.79
	/

Proposed/Revised repair cost:

Parts	\$ 7,195.58
Check items (estimate)	\$
Labour	\$ 2,780.00
Total	\$ 9,975.58
Lump Sum(if applicable)	-

Number of days for repair	8



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

08 RECOMMENDED REPAI	IR DAYS + 1S	UNDAY + 2PRS	= 11 DAYS

Mandate:

Liability(TP)	80%		
Proposed repair cost (W/GST)	\$ 8,539.10	\$	
Loss of use	12	Ś	-
Loss of rental (11DAYS X \$79.95) W/GST	\$ 703.56	Ś	-
Loss of income	2	\$	-
LTA search fees	\$ 7.45	Š	-
Others	2	Ś	-
Proposed Total	\$ 9,250.11	\$	-

Menu



« MANDATE IA> - S8M00E3I [ACCIDENT INVOLVING SLR 822H & SLN 4133H ON 15/04/2018]

Type

Question

Message

Liability: 50% - 80% - Both parties moving straight. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$9250.11(claim LOR) base on 80%. Mandate IA had been uploaded in Smartclaims. Kindly give us your approval/instruction. - Cecilia 02/05/2019

Reply

Menu



Re:<MANDATE IA> - S8M00E3I [ACCIDENT INVOLVING SLR 822H & SLN 4133H ON 15/04/2018]

Type

Q Question

Message

PLS PROCEED AS PROPOSED

Reply

LKK AUTO CONSULTANTS PTE LTD (TP) -

Menu



Re:RE: Re:RE: Re:<MANDATE IA> - S8M00E3I [ACCIDENT INVOLVING SLR 822H & SLN 4133H ON 15/04/2018]

Type

Question

Message

TP is not ARC, pls attempt settlement at max 90%.

Reply



Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Your Ref: SLH 822 H

Our Ref: CIV1301714 / SLN 4133 H

Date:

29-03-19

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way #27-01 AXA Tower Singapore 068811

RE

: ACCIDENT INVOLVING

SLN 4133 H & SLH 822 H

ACCIDENT DATE

15-04-2018

ACCIDENT ALONG

JUNCTION OF DAYCOTT RD AND STEVEN RD

We are the workshop for the owner of motor vehicle no: SLN 4133 H which was involved in the captioned accident. The vehicle was surveyed by an independent appraiser and the claims below are based on its recommendation sum being for the repair cost and the period of repair (Strictly on a Without Prejudice Basis)

As the	accident was caused by the negligent act of your insured for your consideration.	SLH 822 H	we are su	bmitting these
1	Cost of repair		S \$	10,673.87
2	Loss of rental 11 days @ \$ 79.95 / day		S S	879.45
3	Surveyor Fee		SS	0.00
4	GIA report fees (S\$ 15.00 for search fee & S\$ 14.00 for each report fee)		S \$	0.00
5	LTA Fee		S \$	7.45
			S \$	11,560.77

We enclosed herewith the following documents to support the claims:-

- a) Authorization letter
- b) Final repair bill(s)
- c) LTA search
- d) GIA report(s) / result
- e) Insurance certificate, etc.....

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible. Thank you.

Yours faithfully

Carmen Lim

Claims Executive

Email: carmen@esteemperf.com.sg



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

The state of		Affiliated to Federation Inter	rnationale Des Experts En Autor	mobile		
AX.	A INSURANCE PT	E LTD	Ref : CC4/ASM1800	7141/Kga3s2		
AX/	HENTON WAY #24 A TOWERSINGAP FN: KIAN CHUAN	4-01 ORE 068811	Date: 09-07-2019 Code: ASM			
1.		Policy Particul	lars :- THIRD PARTY CLA	IM		
	Insured Veh.	SLR 822H	Veh. Inspected	SLN 4133H		
	Policy No.	GA300046/1	Coverage (\$)	0.00		
	Claim No.	S8M00E3I	Excess (\$)	0.00		
	Assign From	KIAN CHUAN	Assign Date	17/04/2018		
2.		Vehicle P	articulars & Condition			
	Make & Model	TOYOTA PRIUS (A)	c.c	1798		
	Engine No.	HIDDEN	Year of Reg.	2017		
	Chassis No.	JTDKB3FU803556649	Colour	METALLIC PEARL WHITE		
	Odometer	68477	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM		
	General	GOOD				
	Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	195/65R15	YOKOHAMA	9 mm		
	L/H Front Tyre	195/65R15	YOKOHAMA	9 mm		
	R/H Rear Tyre	195/65R15	YOKOHAMA	9 mm		
	L/H Rear Tyre	195/65R15	YOKOHAMA	9 mm		
91	。据他可靠至108		iption of Damages			
	DAMAGES SEE D	STAINED DAMAGES AT THE ETAILS.	N/S REAR PORTION AND UN	NDERCARRIAGE.		
THE STATE OF	THE STATE OF	Gen	eral Information			
	Accident Date	15/04/2018	Inspection Date	17/04/2018		
	Survey held at	385 SIN MING DRIVE				
	Repairer	ESTEEM PERFORMANCE F	PTE LTD			
a.		THE RESERVE	Remarks			
	A)THE INSPECTION B)IN ACCORDANCE	N WAS CONDUCTED ON A"\ E TO YOUR INSTRUCTIONS	NITHOUT PREJUDICE" BASI , WE HAVE NOT AUTHORISE	S. ED REPAIRS.		
b.	A DATE OF THE PARTY OF THE PART		ate Days of Repair	C. 100 A. 1. 12 B. 100 A.		
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:	8 Working Days	The state of the s		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 4133H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS		1 1 1 1 1	(4)
1	REAR BUMPER (CONSISTENT)	CRACKED	497.50	497.50
10	REAR BUMPER CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	DISTORTED	112.70	112.70
- 8	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	SERVICEABLE	112.70	112.70
	REAR BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	398.90	
1	REAR BUMPER LOWER GARNISH CENTRE (CONSISTENT)	DISTORTED	582.60	582.60
1	REAR BUMPER LOWER GARNISH LH (CONSISTENT)	CRACKED	149.70	149.70
1	REAR BUMPER UNDER COVER (CONSISTENT)	CRACKED	355.20	355.20
1	REAR BUMPER UNDER COVER LH (CONSISTENT)	CRACKED	187.60	187.60
4	REAR BUMPER UNDER COVER CLIP (CONSISTENT)	NECESSARY	14.00	14.00
1	TAIL LAMP LH - UPPER (CONSISTENT)	SERVICEABLE	498.75	
-1	TAIL LAMP LH - LOWER (CONSISTENT)	SERVICEABLE	511.60	
1	TAIL END PANEL (CONSISTENT)	BENT	596.60	596.60
-1	TAIL END PANEL GARNISH (CONSISTENT)	SERVICEABLE	151.60	-
10	TAIL END PANEL GARNISH CLIP (CONSISTENT)	NOT NECESSARY	35.00	1
1	BOOT WEATHERSTRIP (CONSISTENT)	SERVICEABLE	353.10	
1	LH REAR FENDER (CONSISTENT)	BENT	883.60	883.60
1	LH REAR FENDER UNDERSHIELD (CONSISTENT)	CRACKED	92.30	92.30
10	LH REAR FENDER UNDERSHIELD CLIP (CONSISTENT)	NECESSARY	30.00	30.00
1	LH REAR FENDER AIR DUCT (CONSISTENT)	DENTED	115.60	115.60
1	LH REAR INNER TRIM (CONSISTENT)	DEFORMED	387.63	387.63
1	LH REAR LOWER ARM (CONSISTENT)	BENT	398.65	398.65
1	LH REAR KNUCKLE ARM (CONSISTENT)	BENT	895.60	895.60
1	LH REAR KNUCKLE BEARING (CONSISTENT) }	NECESSARY	421.90	421.90
1 1	LH REAR WHEEL HUB (CONSISTENT) }			
1	LH REAR WHEEL HUB LOCK NUT (CONSISTENT)	SERVICEABLE	17.30	
100	LH REAR SHOCK ABSORBER (CONSISTENT)	BENT	359.40	359.40
1 1	LH REAR SHOCK ABSORBER TOP MOUNTING CONSISTENT)	SERVICEABLE	165.70	
1 1	H REAR SHOCK ABSORBER STOPPER (CONSISTENT)	SERVICEABLE	85.70	

Report Ref No. CC4/ASM18007141/Kga3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By	Our Adjusted
1	LH REAR RIM (CONSISTENT)	Malia distribution	Workshop (\$))	(\$)
	[2] [GEO]	DENTED	1,555.10	1,555.1
	LH REAR TYRE (CONSISTENT)	SERVICEABLE	350.00	
	LH REAR HUB CAB (CONSISTENT)	CRACKED	195.95	195.9
54-320	LH SIDE SKIRT (CONSISTENT)	SERVICEABLE	798.40	
	LH SIDE SKIRT CLIP (CONSISTENT)	NOT NECESSARY	40.00	
1	LH REAR DOOR (CONSISTENT) (ADDITIONAL)	BUCKLED	1,221.40	1,221.40
1	LH REAR DOOR HINGE TOP (CONSISTENT) (ADDITIONAL)	TO REPAIR SEE LABOUR	78.34	
	LH REAR DOOR HINGE BOTTOM (CONSISTENT) (ADDITIONAL)	DISTORTED	78.34	78.34
1	LH REAR DOOR LOCK (CONSISTENT) (ADDITIONAL)	TO REPAIR SEE LABOUR	437.80	
	LH REAR DOOR CHECKER (CONSISTENT) (ADDITIONAL)	SERVICEABLE	155.60	
1	LH REAR DOOR WEATHERSTRIP (CONSISTENT) (ADDITIONAL)	SERVICEABLE	187,30	
1	LHR DOOR GLASS OUTER MOULDING LOWER (CONSISTENT) (ADDITIONAL)	SERVICEABLE	133.70	
1	LHR DOOR GLASS OUTER MOULDING UPPER (CONSISTENT) (ADDITIONAL)	NECESSARY	127.83	127.83
1	LHR POWER WINDOW MOTOR (CONSISTENT) (ADDITIONAL)	SERVICEABLE	578.40	
1	LHR POWER WINDOW REGULATOR (CONSISTENT) (ADDITIONAL)	SERVICEABLE	198.73	0.4
1	LH REAR DOOR QUARTER GLASS (CONSISTENT) (ADDITIONAL)	SERVICEABLE	122.75	(i
1	LH REAR DOOR QUARTER GLASS MOULDING (CONSISTENT) (ADDITIONAL)	SERVICEABLE	75.80	102
1	LH TAILLAMP PANEL (CONSISTENT) (ADDITIONAL)	TO REPAIR SEE LABOUR	123,15	02
4	LH TAILLAMP CLIP ASSY (CONSISTENT) (ADDITIONAL)	NECESSARY	10.00	10.00
1 1	LH REAR FENDER MUDFLAT (CONSISTENT) (ADDITIONAL)	MISSING	95.30	95.30
1 1	FLOOR PANEL LH (CONSISTENT) (ADDITIONAL)	BENT	189.60	189.60
ı	LESS 25% DISCOUNT	The same of the sa	-3,801.11	-2,398.52
		1	11,403.31	7,195.58
5	SPECIAL NETT ITEMS		31,712.01	7,700.00
1 F	REVERSE SENSOR (SN) (CONSISTENT)	SERVICEABLE	200.00	

Report Ref No. CC4/ASM18007141/Kga3s2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR		200.00	
	LABOUR TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER, LHR DOOR, LH SIDE SKIRT, TAIL DOOR, SPARE TYRE WELL PANEL.) INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT, LH REAR DOOR HINGE TOP, LH REAR DOOR LOCK AND LH TAILLAMP PANEL.	BUCKLED	2,000.00	1,200.0
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, END PANEL, LHR FENDER, LHR DOOR, LH SIDE SKIRT, TAIL DOOR, SPARE TYRE WELL PANEL)		1,800.00	1,000.0
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR TO ASSIST WORK LOAD.		120.00	50.00
	TO TUFF COAT.		250.00	60.00
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.		150.00	120.00
- 1	TO REMOVE & REFIT UNDERCARRIAGE TO ASSIST WORK LOAD.		250.00	150.00
	TO DO WHEEL ALIGNMENT.		120.00	60.00
- 1	TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD.	NOT NECESSARY	120.00	
	TO REMOVE AND REFIT PETROL TANK TO ASSIST WORK LOAD.		150.00	60.00
- 1	TOWING.		110.00	60.00
			5,120.00	2,780.00
10	GRAND TOTAL		16,723.31	9,975.58

RECOMMENDED COST OF REPAIRS	BEAT STREET, S	9,975,58

Report Ref No. CC4/ASM18007141/Kga3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.