



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 1343P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	LH SIDE PANEL L8 (CONSISTENT)	DEFORMED	330.70	330.70
1	WHEEL ARCH TRIM (CONSISTENT)	DEFORMED	124.20	124.20
1	LH SIDE PANEL L7 (CONSISTENT)	TO REPAIR SEE LABOUR	330.70	-
1	LH SIDE PANEL L9 (CONSISTENT)	TO REPAIR SEE LABOUR	248.20	-
1	LH SIDE PANEL L10 (CONSISTENT)	TO REPAIR SEE LABOUR	980.40	-
1	REAR TAIL LAMP COVER LH (CONSISTENT)	TO REPAIR SEE LABOUR	974.70	-
	LESS 10% DISCOUNT		-	-45.49
			2,988.90	409.41
	<u>SPECIAL NETT ITEMS</u>			
1	PRIMER (CONSISTENT)(SN)	NECESSARY	80.00	80.00
4	SEALANT SIKAFLEX @\$37.00 (CONSISTENT)(SN)	NECESSARY	148.00	148.00
			228.00	228.00
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF LH SIDE PANEL L7,LH SIDE PANEL L9,LH SIDE PANEL L10 AND REAR TAIL LAMP COVER LH.		1,590.00	1,060.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		616.00	500.00
			2,206.00	1,560.00
	GRAND TOTAL		5,422.90	2,197.41
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,050.00

Report Ref No. CC4/ASM18007145/Sea3q2

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.