


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB1343P
 Ref. No : BUS/04/18/7022
 Reg. Date : 01/01/1900
 Vehicle Type : BUS -12M
 Make : MAN
 Model : MAN
 Name of Driver : Tian Hongfeng
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 11/04/2018 08:24:00 AM
 Accident Reported Date / Time : 12/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : AXA
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 left rear body scratched
 TP: SBA3897E (AXA)
 Prepared Date : 13/04/2018 09:06:48 AM



Sebastian
 17/4/18
 - Lump Sum Repair
 - Photo Before Paint
 920 36121
 sebastianyeang@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,590.00	0.00
Total Spray Painting Charges :	616.00	0.00
Total Material Charges :	509.93	509.93
Other Charges :	0.00	0.00
TOTAL :	2,715.93	0.00
Lum Sum Total :	2,700.00	0.00
No. of Repair Days :	4.00	0.00
Prepared / Adjusted By :		3 days
Arc / Surveyor Sign Off Date :	13/04/2018 01:15:45 PM	01/01/1900 12:00:00 AM


Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/04/2018 01:15:45 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :



Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
A01001-CW557		6010001	LH SIDE PANEL L7	1	330.70	100.00	0.00	Repair	Repair R	No
A01001-CW558		6010002	LH SIDE PANEL L8	1	330.70	10.00	297.63	Replace	Replace ✓ Dg	No
A01001-CW559		6010003	LH SIDE PANEL L9	1	248.20	100.00	0.00	Repair	Repair R	No
A01001-CW560		6010004	LH SIDE PANEL L10	1	980.40	100.00	0.00	Repair	Repair R	No
F01001-CW271		6010060	REAR TAIL LAMP COVER LH	1	974.70	100.00	0.00	Repair	Repair R	No
5029		6010330	WHEEL ARCH TRIM	1	124.20	10.00	111.78	Replace	Replace ✓	No Dg
	COMMO N	4006314	SEALANT SIKAFLEX	4	37.00	0.00	148.00	Replace	Replace ✓	No N.E.C
	COMMO N	4006313	PRIMER	1	80.00	0.00	80.00	Replace	Replace ✓	No N.E.C
TOTAL MATERIALS							637.41	637.41		
TOTAL MATERIALS(Discounted)							509.93	509.93		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,590.00	0.00 1060
Total Labour	1,590.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	0.00 500
Total Spray Painting & Panel Beating	616.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		