

22/03/2018

ASS. REC. BY:

REF:

CS/TCU18007167 / Agb

Special Instruction:

Surveyor

Action

ASSIGNMENT (Office)

From (Person): CUS Lawrence Jm

of TCU

Date/Time: 17/04/2018 7:32pm

Estimated Cost:

Bill to:

OD / H / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJH 1576M

Insured:

SHC 7139C

at Workshop m/s

mg Solution

Tel:

6764 4165

of

23 Kaki Bukit Ave 4

Policy No:

Claim No:

DI8002896MTSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

13042018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time: 18/04/2018 9:47am

Person Contacted:

Jack

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJH 1576M - NA / TNC12013945/e1

DUA: 170912

SHC 7139C - CS / TCU14010562 / H19663

DUA: 040614

17/4/18 @ 3:55pm Informed Lawrence, we have pending estimate from repairer.

29/6/18 @ 10:04am revert to Lawrence by email.

US \$4500, 9 days (Red \$25175.12, 85%)

MOTOR SURVEY ASSIGNMENT

Date	16-04-2018	Our Ref No. D18002896MFSH
Accident Date	13-04-2018	Claim Type. Third Party
Insured Vehicle	SHC7139C	Third Party Vehicle. SJH1576M
Survey Location	23 KAKI BUKIT AVE 4 AAS KAKI BUKIT CENTRE#02-03	
Contact Person.	JAMIE YAN	
Contact No.	67444165/ 0	Fax No. 67444604
Survey Type	WITHOUT PREJUDICE: PENDING ID'S VIDEO TP0 DETERMINE LIABILITY	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	MG SOLUTION PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 29 June 2018 10:04 AM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002896MFSH/1
Attachments: CSFC118007167Aqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SJH 1576M.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 19 April 2018 3:55 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002896MFSH/1

Dear Lurene,

Please be informed that we have inspected the vehicle SJH 1576M on 18/04/18.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 18 April 2018 9:48 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002896MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 19 April 2018 3:55 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002896MFSH/1

Dear Lurene,

Please be informed that we have inspected the vehicle SJH 1576M on 18/04/18.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 18 April 2018 9:48 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002896MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 17 April, 2018 7:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002896MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3705B
Vehicle Details	
Vehicle No.:	SJH1576M
Vehicle to be Exported:	Yes
Intended De-registration Date:	18 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8 A
Primary Colour:	Brown
Manufacturing Year:	2008
Engine No.:	R18A1771876
Chassis No.:	RN61064651
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$17,554.00
Original Registration Date:	28 Jul 2008
First Registration Date:	28 Jul 2008
Transfer Count:	1
Actual ARF Paid:	\$17,554.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jul 2018
PARF Rebate Amount:	\$8,777.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$15,501.00
COE Rebate Amount:	\$425.00
Total Rebate Amount:	\$9,202.00

The information contained herein is correct as at 18 Apr 2018

OK

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Stream Price Range Depreciation 2008 Vehicle Type

Advanced
Search

Used Car Comparison

--- Comparing 4 Vehicles ---

Honda Stream 1.8A



Add to Shortlist

Honda Stream 1.8A



Add to Shortlist

Honda Stream 1.8A



Add to Shortlist

Honda Stream 1.8A R



Add to Shortlist

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

	Honda Stream 1.8A	Honda Stream 1.8A	Honda Stream 1.8A	Honda Stream 1.8A R
Price	\$14,800	\$16,800	\$15,888	\$20,800
Instalment	\$5,206	\$3,949	\$1,881	\$2,463
Registration Date	01-Jul-2008	28-Jul-2008	24-Oct-2008	08-Nov-2008
Manufactured	2008	2008	2008	2008
Mileage	136,538 km	-	-	-
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,799 cc	1,799 cc	1,799 cc	1,799 cc
Road Tax	\$978 /yr	\$978 /yr	\$978 /yr	\$978 /yr
Power	103.0 kW (138 bhp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)	103.0 kW (138 bhp)
Curb Weight	1,370 kg	1,370 kg	1,370 kg	1,385 kg
Features	1.8L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Auto Climatic Aircon Control, Reverse Sensors, Knockdown Rear Seats, 4 x Disc Brake.	1.8L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Auto Climatic Aircon Control, Reverse Sensors, Knockdown Rear Seats, 4 x Disc Brake.	Responsive 1.8L I-VTEC Engine, Smooth 5 Speed Auto Transmission, Dual SRS Airbags, Digital Climate Control Aircon, Auto Retractable Side Mirrors.	1.8L I-VTEC Engine, 5 Speed Auto Transmission, SRS Airbags, Sunroof, Control, Knockdown Rear Seats.
Accessories	Sport Rims, Alpine Car Stereo System, Electrical Retractable Side Mirrors, Upholstery Leather Seats.	Sports Rims, Pioneer Touchscreen Audio System, Roof Mount DVD Player, Tweeter Speakers, Blind-spot Mirrors, Upholstery Leather Seats.	Sports Rims, Retractable Wing Mirrors, Pioneer Audio System, Reverse Sensors And Camera, Solar Film, Leather Seats, Knockdown Rear Seats.	Sport Rims, Pioneer Audio System, Reverse Sensors And Camera, Solar Film, Leather Seats, Retractable Side Mirrors.
Description	Excellent Choice For Renewal Of COE! 1 Owner Only! Very Low Mileage! Extended Warranty Available! Professional Evaluation Services Available! Well Kept By Previous Owner In Superb Condition, A Car Not To Be Missed! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Be First To Appreciate It In Pristine Condition Today!	Ideal For Short Term Usage! \$0 Down-payment! High Trade-in! STA Certified Cars! Stylish MPV Designed To Give You Superb Handling, Well Maintained By Previous Owner. For You To View And Believe! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Visit Us At Our Air-con Showroom To Appreciate It In Pristine Condition Today!	1 Owner, Well Maintained, Regular Serviced Done. Low Available, Trade In Welcomed. Low Depreciation For A 7 Seaters.	Ideal For Short Term Usage! \$0 Down-payment! High Trade-in! STA Certified Cars! Stylish MPV Designed To Give You Superb Handling, Well Maintained By Previous Owner. For You To View And Believe! Buy It From Us With A Peace Of Mind, A Company Accredited With Outstanding Awards, Professional After Sales Service Assured. Visit Us At Our Air-con Showroom To Appreciate It In Pristine Condition Today!
COE	\$14,689	\$15,501	-	\$14,400
OMV	\$20,627	\$19,860	\$20,565	\$25,032
ARF	\$20,627	\$19,860	\$20,565	\$25,032
Depreciation	-	-	\$10,880 /yr	\$14,890 /yr
No. of Owners	1	2	1	2
Type of Vehicle	MPV	MPV	MPV	MPV
Category	PARF Car	PARF Car	PARF Car	PARF Car
Availability	Available	Available	Available	Available
SELLER INFORMATION				
Seller	Dickson Automobile	Dickson Automobile	Beata Car	Dickson Automobile

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/04/2018 14:53
Date Of Accident	13/04/2018 21:30
Exact Location Of Accident	JUNCTION OF SENGKANG EAST AVE & SENGKANG EAST RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH1576M
Insured/Policyholder	
Name Of Registered Owner	SHADRACH CHEW TZE EE
NRIC No	S7903705B
Email Address	SCHEWTZE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90624302
Alternative Phone No	OFFICE-88888888

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5079728470-01
Cover Note Number	

Driver

Name of Driver	SHADRACH CHEW TZE EE
NRIC No	S7903705B
Date Of Birth	07/02/1979
Occupation	INDOOR
Date Of Driving Pass	25/05/1999
Driving Experience	18 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90624302
Fax Number	
Contact Number	OFFICE-88888888
Email Address	SCHEWTZE@GMAIL.COM

Address	8 UPPER SERANGOON CRESCENT #12-18
Postcode	534032
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 13/04/2018 AT ABOUT 2130HRS AT JUNCTION OF SENGKANG EAST AVE AND SENGKANG EAST ROAD. I WAS TRAVELLING ON THE CENTRE LANE ALONG SENGKANG EAST AVE TOWARDS SENGKANG CENTRAL AND WHEN COMING TOWARDS THE ABOVE MENTIONED JUNCTION, A VEHICLE (B) FROM THE OPPOSITE DIRECTION MAKING A RIGHT TURN WITHOUT GIVING WAY AND WITHOUT STOPPING FOR MY ON COMING TRAFFIC HENCE COLLIDED ONTO MY FRONT PORTION OF MY VEHICLE (A) CAUSING DAMAGES TO MY VEHICLE. I WISH TO STATE THAT DURING THE INCIDENT THE TRAFFIC LIGHT WAS 'GREEN' TO MY FAVOUR. (A) SJH1576M (B) SHC7139C

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC7139C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No Of Passenger (Including Driver)

APPENDIX


APCANN

- [illegible]



...the ...

[Signature]



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/04/2018 at about 2130 hrs at Junction of Sengkang East Ave and Sengkang East Road. I was travelling in centre lane along Sengkang East Ave towards Sengkang Central and when coming towards the above mentioned junction, a Vehicle (B) from the opposite direction making a Right turn without giving way and without stopping for my on coming traffic hence collided with my front portion of my Vehicle (A) causing damages to my vehicle. I wish to state that during the incident the traffic light was 'GREEN' to my favour.

(A) SJH 1576 M

(B) SAC 7134 C

DECLARATION

I/We declare the foregoing particulars are true and correct.

Signature of Injured Party
Date & Time

Signature of Police Officer
Date & Time

Signature of Witness
Date & Time

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: FIRST CAPITAL INSURANCE	DATE	: 17/04/2018
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJH1576M		
MODEL	: HONDA STREAM 1.8A		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>			
	DATE : 13-Apr-18		
	TIME : 21:30HRS		
THIRD PARTY REQUESTOR / CONTACT	: JACK LI		

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET <i>Distorted</i>	1	\$ 1,030.00	\$ 1,030.00
2	BONNET INSULATOR <i>Not in</i>	1	\$ 290.00	\$ 290.00
3	BONNET WEATHERSTRIP <i>Not in</i>	1	\$ 92.00	\$ 92.00
4	BONNET HINGE <i>Not in</i>	2	\$ 133.00	\$ 266.00
5	BONNET LOCK <i>Not in</i>	1	\$ 320.00	\$ 320.00
6	BONNET LOCK BRACE PANEL <i>Not in</i>	1	\$ 168.00	\$ 168.00
7	FRONT BUMPER <i>Distorted</i>	1	\$ 922.30	\$ 922.30
8	FRONT BUMPER SIDE RETAINER RH <i>Not in</i>	2	\$ 84.60	\$ 169.20
9	FRONT BUMPER BRACKET <i>Not in</i>	2	\$ 63.00	\$ 126.00
10	FRONT BUMPER REINFORCEMENT <i>Not in</i>	1	\$ 512.30	\$ 512.30
11	FRONT BUMPER LOWER GRILLE <i>Not in</i>	1	\$ 288.90	\$ 288.90
12	FRONT BUMPER FOG LIGHT COVER <i>Not in</i>	2	\$ 177.90	\$ 355.80
13	CENTRE GRILLE <i>Not in</i>	1	\$ 522.60	\$ 522.60
14	CENTRE GRILLE MOULDING <i>Not in</i>	1	\$ 366.20	\$ 366.20
15	CENTRE GRILLE LOGO <i>Not in</i>	1	\$ 95.80	\$ 95.80
16	HEADLAMP <i>Not in</i>	2	\$ 758.30	\$ 1,516.60
17	HEAD LAMP LOWER BRACKET <i>Not in</i>	2	\$ 95.00	\$ 190.00
18	FRONT FENDER <i>LH Buckled</i>	2	\$ 933.50	\$ 1,867.00

19	FRONT FENDER INNER COWLING <i>2</i>	2	\$ 213.00	\$ 426.00	+
20	FRONT FENDER OUTER GARNISH <i>2</i>	2	\$ 188.90	\$ 377.80	+
21	FRONT WINDSCREEN MOULDING <i>Not in</i>	1	\$ 133.90	\$ 133.90	x
22	FRONT SUPPORT PANEL <i>Buckled</i>	1	\$ 846.00	\$ 846.00	\$ 62840.
23	HORN <i>Not in</i>	2	\$88.70	\$177.40	+
24	AIRCON CONDENSOR <i>Distorted</i>	1	\$ 1,200.00	\$ 1,200.00	✓
25	AIRCON FAN COWLING <i>2</i>	1	\$ 144.20	\$ 144.20	+
26	AIRCON FAN MOTOR <i>Not in</i>	1	\$ 277.90	\$ 277.90	x
27	AIRCON FAN BLADE	1	\$ 144.20	\$ 144.20	+
28	RADIATOR <i>Distorted</i>	1	\$ 1,511.70	\$ 1,511.70	-
29	RADIATOR FAN COWLING <i>2</i>	1	\$188.40	\$ 188.40	+
30	RADIATOR FAN MOTOR <i>Not in</i>	1	\$ 244.50	\$ 244.50	+
31	RADIATOR FAN BLADE	1	\$ 122.80	\$ 122.80	+
32	RADIATOR SPARE TANK <i>Not in</i>	1	\$ 92.10	\$ 92.10	+
33	DASHBOARD <i>torn</i>	1	\$930.00	\$ 930.00	-
34	AIR BAG SENSOR <i>2</i>	2	\$398.00	\$ 796.00	- 379.60
35	AIR BAG CONTROL UNIT <i>Activated</i>	1	\$1,355.20	\$ 1,355.20	- 1087.
36	COIL SPRING SENSOR	1	\$ 293.70	\$ 293.70	-
37	FRONT STEERING WHEEL AIR BAG <i>2 Activated</i>	1	\$2,477.10	\$ 2,477.10	- 1820.90
38	FRONT PASSENGER AIR BAG	1	\$3,288.50	\$ 3,288.50	- 2236.80
39	SAFETY BELT <i>Activated</i>	2	\$986.40	\$ 1,972.80	- 1360.
			TOTAL PRICE	\$ 26,098.90	
			LESS 20%	\$ 5,219.78	
			SUB TOTAL PRICE	\$ 20,879.12	

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT NUMBER PLATE <i>Bent</i>	1	\$ 50.00	\$ 50.00	-
2	FRONT BUMPER CLIPS (SET) <i>Not in</i>	1	\$ 33.00	\$ 33.00	-
3	FRONT BUMPER LOWER GRILLE CLIPS(SET) <i>Not in</i>	1	\$ 30.00	\$ 30.00	+
4	CENTRE GRILLE CLIP(SET) <i>Not in</i>	1	\$ 22.00	\$ 22.00	-
5	BONNET INSULATOR CLIP(SET) <i>Not in</i>	1	\$ 20.00	\$ 20.00	+
6	HEADLAMP CLIP(SET) <i>Not in</i>	1	\$ 25.00	\$ 25.00	✓
7	FRONT FENDER COWLING CLIPS(SET) <i>Not in</i>	1	\$ 22.00	\$ 22.00	+
8	FRONT WINDSCREEN SEALANT <i>Not in</i>	1	\$ 80.00	\$ 80.00	+
9	DASHBOARD CLIP <i>Not in</i>	1	\$ 24.00	\$ 24.00	+
			TOTAL	\$ 306.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

130

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 3,000.00	1000
2	TO SPRAY PAINT AFFECTED AREA	\$ 3,000.00	1000
3	TUFF COAT	\$ 250.00	40
4	WIRING AND BULB CHECKING	\$ 120.00	30
5	TO REFOCUS HEADLAMP	\$ 80.00	x
6	TO REMOVE AND REFIX AIR BAG SENSOR	\$ 550.00	300
7	RESET AIRBAG	\$ 550.00	80
8	TO REMOVE AND REFIX FRONT WINDSCREEN	\$ 120.00	x
9	TO REMOVE AND REFIX FRONT SAFETY BELT	\$ 120.00	60
10	TO REMOVE AND REFIX FRONT DASHBOARD	\$ 700.00	220
TOTAL		\$	8,490.00

2730

ESTIMATE REPORT

TOTAL PARTS COST : \$ 21,185.12
TOTAL LABOUR COST : \$ 8,490.00
TOTAL REPAIR COST : \$ 29,675.12

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

PART BY PART / LUMP SUM :

NO OF DAYS :

FAX :

L/S 09 Pays.

Total: 15600.72

L/S 4510 (Nett Value)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007167/Aqbaq2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7139C	Veh. Inspected	SJH 1576M
Policy No.		Coverage (\$)	0.00
Claim No.	D18002896MFSH	Excess (\$)	0.00
Assign From	LURENE JAW	Assign Date	17/04/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	RN61064651	Colour	BRONZE
Odometer	104970	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65R15	MICHELIN	6 mm
L/H Front Tyre	205/65R15	MICHELIN	6 mm
R/H Rear Tyre	205/65R15	MICHELIN	6 mm
L/H Rear Tyre	205/65R15	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	13/04/2018	Inspection Date	18/04/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 1576M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DISTORTED	1,030.00	1,030.00
1	BONNET INSULATOR	NOT NECESSARY	290.00	-
1	BONNET WEATHERSTRIP	NOT NECESSARY	92.00	-
2	BONNET HINGE @\$133.00	NOT NECESSARY	266.00	-
1	BONNET LOCK	BENT	320.00	85.10
1	BONNET LOCK BRACE PANEL	NOT NECESSARY	168.00	-
1	FRONT BUMPER	DISTORTED	922.30	688.00
2	FRONT BUMPER SIDE RETAINER RH @\$84.60	NECESSARY	169.20	64.00
2	FRONT BUMPER BRACKET @\$63.00	NOT NECESSARY	126.00	-
1	FRONT BUMPER REINFORCEMENT	BENT	512.30	258.80
1	FRONT BUMPER LOWER GRILLE	DEFORMED	288.90	132.60
2	FRONT BUMPER FOG LIGHT COVER @\$177.90	NOT NECESSARY	355.80	-
1	CENTRE GRILLE	CRACKED	522.60	237.00
1	CENTRE GRILLE MOULDING	CUT	366.20	253.30
1	CENTRE GRILLE LOGO	NECESSARY	95.80	29.30
2	HEADLAMP @\$758.30	CRACKED	1,516.60	1,381.60
2	HEAD LAMP LOWER BRACKET @\$95.00	CRACKED	190.00	71.60
2	FRONT FENDER @\$933.50	N/S BUCKLED	1,867.00	486.50
2	FRONT FENDER INNER COWLING @\$213.00	NOT NECESSARY	426.00	-
2	FRONT FENDER OUTER GARNISH @\$188.90	NOT NECESSARY	377.80	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	133.90	-
1	FRONT SUPPORT PANEL	BUCKLED	846.00	628.40
2	HORN @\$88.70	NOT NECESSARY	177.40	-
1	AIRCON CONDENSOR	DISTORTED	1,200.00	1,200.00
1	AIRCON FAN COWLING	NOT NECESSARY	144.20	-
1	AIRCON FAN MOTOR	NOT NECESSARY	277.90	-
1	AIRCON FAN BLADE	NOT NECESSARY	144.20	-
1	RADIATOR	DISTORTED	1,511.70	1,511.70
1	RADIATOR FAN COWLING	NOT NECESSARY	188.40	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	244.50	-
1	RADIATOR FAN BLADE	NOT NECESSARY	122.80	-

Report Ref No. CS/FCI18007167/Aqbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR SPARE TANK	NOT NECESSARY	92.10	-
1	DASHBOARD	TORN	930.00	930.00
2	AIR BAG SENSOR @\$398.00	ACTIVATED	796.00	379.60
1	AIR BAG CONTROL UNIT	ACTIVATED	1,355.20	1,087.00
1	COIL SPRING SENSOR	ACTIVATED	293.70	293.70
1	FRONT STEERING WHEEL AIR BAG	ACTIVATED	2,477.10	1,880.90
1	FRONT PASSENGER AIR BAG	ACTIVATED	3,288.50	2,236.80
2	SAFETY BELT @\$986.40	ACTIVATED	1,972.80	1,360.00
	LESS 20% DISCOUNT		-5,219.78	-3,245.18
			20,879.12	12,980.72
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	BENT	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	33.00	33.00
1	SET FRONT BUMPER LOWER GRILLE CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET CENTRE GRILLE CLIP (SN)	NECESSARY	22.00	22.00
1	SET BONNET INSULATOR CLIP (SN)	NOT NECESSARY	20.00	-
1	SET HEADLAMP CLIP (SN)	NECESSARY	25.00	25.00
1	SET FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	22.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	DASHBOARD CLIP (SN)	NOT NECESSARY	24.00	-
			306.00	130.00
	<u>LABOUR</u>			
	TO PANEL BEAT ,REMOVE AND REPLACE PARTS.		3,000.00	1,000.00
	TO SPRAY PAINT AFFECTED AREA.		3,000.00	1,000.00
	TUFF COAT.		250.00	40.00
	WIRING AND BULB CHECKING .		120.00	30.00
	TO REFOCUS HEADLAMP .	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIX AIR BAG SENSOR .		550.00	300.00
	RESET AIRBAG.		550.00	80.00
	TO REMOVE AND REFIX FRONT WINDSCREEN.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX FRONT SAFETY BELT .		120.00	60.00

Report Ref No. CS/FCI18007167/Aqbq2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIX FRONT DASHBOARD .		700.00	220.00
			8,490.00	2,730.00
GRAND TOTAL			29,675.12	15,840.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CS/FCI18007167/Aqbq2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.