

ASS. REC. BY:

REF:

CS3 / ETL 18007197 / R14b5

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Yee Pei Li of ETL Date/Time: 18042018 11:17am

Estimated Cost: Bill to:

OD / TI / WS / TT RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XD 9525M Insured: XD 5056B

at Workshop m/s Koh Kok Leung Tel: 6897 8787

of No. 24 Tuen Ave 2

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 16042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 11:00pm

H.O.D. Endorsement:

Date/Time: 18042018 1:22pm Person Contacted: Kathy Vehicle: INK 6897

Date/Time	Action/Instruction (x) Estimate
	XD 9525M - x
	XD 5056B - x

(08/11/13)

Director: *Ram*

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: *X09525M*at Workshop m/s *KKL*of *24, MOD DR 2*Insured: *EHI / PRS*

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *X09525M* Yr Regn: _____ /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____Make: *V6/V0* C.C. _____Colour: *MULTI* A/C: Insured / Std / NI / NASp. Reading: *422732* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *YN2IFE102EA256 . 021*Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: *295/80 R22-5*R: *-*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *TRIANGLE*Front RearR/Bal. *8* mm R/Bal. *8/8* mmL/Bal. *8* mm L/Bal. *8/8* mmD.O.A. _____ D.O.I. *26/04/08*Survey held at *KKL*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rem O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ESTIMATE RANGE COST OF REPAIR - 3K-6K - 4 days

RECEIVED 25 APR 2010

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 18 April, 2018 11:17 AM
To: admin-d@lkkauto.com
Subject: OI : XD5056B / TP : XD9525M/IAS / DOA : 16/04/2018
Attachments: XD9525M - PRI NOTICE n SAS.pdf; Your ref : SB/PO/ACC/2018-8708 / ERGO ref : XD5056B / DOA : 10.04.2018 (25.5 KB)

Dear Catherine,

We have rejected to their PRS list, please assist to conduct this survey from ORACLE LAW CORPORATION,

ADDRESS : KOH KOK LEONG CONSTRUCTION PTE LTD
NO 24 TUAS AVENUE 2
SINGAPORE 639455

PERSON TO CONTACT : 6897 8787 EXT 106

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Try to obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please update the survey status via Survey.Report@ergo.com.sg.

Attached is third party's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
ERGO INSURANCE PTE LTD		Ref: CS3/EGI18007197/R1z4bs2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER		Date: 16-05-2018	
FIVESINGAPORE 038985			
Code: EGI			
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	XD 5056B	Veh. Inspected	XD 9525M
Policy No.		Coverage (\$)	0.00
Claim No.	DSMCV1800795	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	18/04/2018
2. Vehicle Particulars & Condition			
Make & Model	VOLVO	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	YN21FE1DZEA756021	Colour	MULTI
Odometer	422732 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	TRIANGLE	8 mm
L/H Front Tyre	295/80 R22.5	TRIANGLE	8 mm
R/H Rear Tyre	295/80 R22.5 (D)	TRIANGLE	8/8 mm
L/H Rear Tyre	295/80 R22.5 (D)	TRIANGLE	8/8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.			
5. General Information			
Accident Date	16/04/2018	Inspect Date / Time	20/04/2018 (05:44 PM)
Survey held at	KOH KOCK LEONG ENTERPRISE PL NO.24 TUAS DRIVE 2 SINGAPORE 638638		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000- \$6,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/EGI18007197/R1z4bs2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K. LAU CPT (RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.