

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGE 4281U (Insd veh)	Model:	TOYOTA HARRIER (A)
	SLL 251L (TP veh)		
Date of Accident:	16/04/2018		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	11,571.19
Final Repair Cost	:	\$	3,994.63
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	300.00 2 days
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	4,295.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	KIM CHWEE AUTO PTE LTD	:	\$ 4,295.00

NUR SHAQILAH BTE ABDOL
WAHAB

01/02/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18007199/Uja3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN: STACEY NG

Date : 01-02-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGE 4281U	Veh. Inspected	SLL 251L
Policy No.	GA094711/1	Coverage (\$)	0.00
Claim No.	S8M00EBO	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	17/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZSU600090112	Colour	WHITE
Odometer	25265	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55R18	BRIDGESTONE	6 mm
L/H Front Tyre	235/55R18	BRIDGESTONE	6 mm
R/H Rear Tyre	235/55R18	BRIDGESTONE	6 mm
L/H Rear Tyre	235/55R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/04/2018	Inspection Date	18/04/2018
Survey held at	KIM CHWEE AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 251L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE (CONSISTENT)	NOT NECESSARY	1,400.30	-
1	TAILGATE REAR LOGO (CONSISTENT)	NOT NECESSARY	68.10	-
1	TAILGATE HARRIER EMBLEM (CONSISTENT)	NOT NECESSARY	68.10	-
1	TAILGATE WEATHERSTRIP(CONSISTENT)	TWISTED	429.10	322.10
1	REAR BUMPER (CONSISTENT)	DENTED / DEFORMED	1,533.10	1,381.10
1	REAR BUMPER LOWER SKIRTING (CONSISTENT)	WARPED	866.30	589.10
1	REAR BUMPER REFLECTOR (CONSISTENT)	NOT NECESSARY	66.80	-
1	REAR BUMPER SPONGE (CONSISTENT)	TORN	295.40	295.40
2	REAR BUMPER SIDE RETAINERS @ \$85.10 (CONSISTENT)	NECESSARY	170.20	170.20
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	820.10	-
1	REAR END PANEL TOP GARNISH (CONSISTENT)	TWISTED	366.50	366.50
2	TAILLAMPS @ \$850.10 (CONSISTENT)	NOT NECESSARY	1,700.20	-
1	SET REAR REVERSE SENSOR (CONSISTENT)	SHORTED	260.00	260.00
	LESS 25% DISCOUNT		-	-861.10
			8,104.20	2,583.30
LABOUR				
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX, SEAT, CUSHION UPHOLSTERY.		120.00	60.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		980.00	520.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	500.00
			2,710.00	1,150.00
GRAND TOTAL			10,814.20	3,733.30
RECOMMENDED COST OF REPAIRS				3,733.30

Report Ref No. CC4/ASM18007199/Uja3s2



Report Ref No. CC4/ASM18007199/Uja3s2

A handwritten signature in black ink, appearing to be 'Ch' followed by a stylized flourish.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.