

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 03 May 2018)
Parts: N/A TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBF6865B)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

00 6448

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE RUBBER <i>MISSING</i>	0.00	0.00	*25.00 F ✓
2	1		*DOOR RUBBER - RH <i>at</i>	0.00	0.00	*45.00 F ✓
3	1		*VACUUM PUMP <i>Best</i>	0.00	0.00	*130.00 F ✓
Sub Total (S\$)						200.00
+ Margin on L,N Items 15.00% (S\$)						30.00
Total Parts (S\$)						230.00 >30

Report was unsubmitted during this print-out.
 Generated using **Merimen e-Claims IEAS**

SUPP >30.00
 PARTS >990.00
 SN 65.00
 LAB. 1860.00

 5145.00

Adrian Lij
 03/05/18
888

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 18 Apr 2018)
 Parts: N/A TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database)
 Labour: Repair/c (Price-per-minuted Standard List)
 Print Code: Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

006448

Estimates on Parts

No.	Qty	Part No	Particulars	>Disc	%Depr	Amount	
1	1	17	FRONT WINDSCREEN PILLAR OUTER - RH	0.00	0.00	150.00 F	✓
2	1	18	FRONT WINDSCREEN PILLAR INNER - RH	0.00	0.00	130.00 F	✓
3	1	19	CORNER PANEL - RH	0.00	0.00	75.00 F	✓
4	1	20	FRONT GRILLE	0.00	0.00	50.00 F	✓
5	1	21	FRONT GRILLE LOGO	0.00	0.00	40.00 F	✓
6	1	22	FRONT GRILLE CLIP - WHITE	0.00	0.00	10.00 F	✓
7	1	23	FRONT GRILLE CLIP - BLACK	0.00	0.00	10.00 F	✓
8	1	24	FRONT BUMPER	0.00	0.00	100.00 F	✓
9	1	25	FRONT BUMPER REINFORCEMENT	0.00	0.00	140.00 F	✓
10	1	26	FRONT BUMPER BRACKET - RH	0.00	0.00	35.00 F	✓
11	1	27	FRONT BUMPER FOG LAMP - RH	0.00	0.00	100.00 F	✓
12	1	28	FRONT BUMPER FOG LAMP COVER - RH	0.00	0.00	50.00 F	✓
13	2	29	HEAD LAMP ASSY - RH - LH/RH	0.00	0.00	700.00 F	✓
14	1	30	HEAD LAMP LOWER RUBBER - RH	0.00	0.00	10.00 F	✓
15	1	31	FRONT DOOR - RH	0.00	0.00	50.00 F	✓
16	1	32	FRONT DOOR RUBBER - RH	0.00	0.00	10.00 F	✓
17	1	33	FRONT DOOR HINGE - TOP - RH	0.00	0.00	10.00 F	✓
18	1	34	FRONT DOOR HINGE - LOWER - RH	0.00	0.00	10.00 F	✓
19	1	35	FRONT DOOR SIGNAL LAMP - RH	0.00	0.00	5.00 F	✓
20	1	36	FRONT DOOR LOCK - RH	0.00	0.00	10.00 F	✓
21	1	37	FRONT DOOR EYE - RH	0.00	0.00	20.00 F	✓
22	1	38	FRONT DOOR STEP GARNISH - RH	0.00	0.00	10.00 F	✓
23	1	39	FRONT DOOR BOARD - RH	0.00	0.00	20.00 F	✓
24	1	40	FRONT DOOR REGULATOR GEAR - RH	0.00	0.00	10.00 F	✓
25	1	41	FRONT DOOR REGULATOR GEAR MOTOR - RH	0.00	0.00	10.00 F	✓
26	1	42	FRONT ABSORBER - RH	0.00	0.00	15.00 F	✓
27	1	43	FRONT LOWER ARM - RH	0.00	0.00	10.00 F	✓
28	1	44	FRONT TOP ARM - RH	0.00	0.00	10.00 F	✓
29	1	45	FRONT KNUCKLE ARM - RH	0.00	0.00	10.00 F	✓
30	1	46	FRONT KNUCKLER ARM BEARING - RH	0.00	0.00	10.00 F	✓
31	1	47	FRONT STABILIZER - RH - NO STOCK	0.00	0.00	10.00 F	✓
32	1	48	FRONT CROSSMEMBER - NO STOCK	0.00	0.00	10.00 F	✓

7014743

Sub Total (F) 3 329.50 2600
 Weight on W Hook (15.00) (SS) 149.45
 Total Parts (SS) 3 278.93 2990.

Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	FRONT DOOR COMPANY STICKER - RH <i>New</i>	30.00 ✓
2	1	FRONT NUMBER PLATE WITH CASING <i>new</i>	35.00 ✓
3	1	FRONT TYRE - RH <i>2 new</i>	280.00 X
4	1	FRONT TYRE RIM	250.00 X
Sub Total (\$\$)			595.00 <i>65</i>

006428

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	950.00 <i>800</i>
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS; RH FRONT FLOOR PANEL; RH FRONT WHEEL ARCH PANEL; RH CHASSIS; CUT/WELD; RH FRONT DOOR PILLAR; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00 <i>800</i>
3	TO CHECK WIRING	New	20.00 ✓
4	TO REMOVE, REFIX DASHBOARD	New	300.00 <i>22</i>
5	TO REMOVE; REFIX FRONT WINDSCREEN	New	120.00 <i>100</i>
6	TO 4 WHEEL ALIGNMENT	New	60.00 ✓
7	TO TRANSFER DOOR AND DOOR FITTING	New	30.00 ✓
8	TO REMOVE, REPLACE FRONT UNDERCARRIAGE AND FRONT CROSSMEMBER	New	500.00 ✓
Gross Labour Cost (\$\$)			3,130.00 <i>1860</i>

Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35 Not valid without Reference section
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment includes the latest and reliable CAR-ALIGN 6-MARKS repair to restore wheel alignment and the supported online system to provide accurate assessment and ready repairs.

Adrian Lim
P/P 24/04/18

08 days.

Excess \$800

Not Authorised.