



PROGRESSIVE AUTOMOTIVE PTE LTD

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

Tel.: 6741 5336 (6 Lines) Fax: 6741 7208

E-mail: progauto@progauto.com.sg

Reg. No.: 201006949C

We specialise in repairing, panel beating, spray painting of all kinds of Vehicles and also insurance claims. All enquiries are welcome.

INSURER: **EQ Insurance Company Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 0418-6448
Policy No:	DMCPHQ18-000643	Date of Loss:	16/04/2018
Vehicle Reg. No.:	GBF6865B	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HARCO ENGINEERING PTE LTD		
Driver:	THOZAPPAN JAYABAL		

Make/Model:	TOYOTA DYNA 150 D, 3.0 D (M)	Vehicle Reg. Date:	09/02/2017
Vehicle Colour:	BLUE		
Engine No:	1KD2609762	Chassis No:	KDY2318024583
Odometer:	46292 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	8

Description of Accident/Loss	HIT SIDE ROAD KERB
Remarks:	VEHICLE IS NOT IN WORKSHOP
Present Location:	PROGRESSIVE AUTOMOTIVE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	7,278.93
Miscellaneous Items	595.00
Labour	2,180.00
Paintwork Labour	950.00
Towing	0.00
Gross Total (S\$)	11,003.93
+ GST 7.00% (S\$)	770.28
Nett Amount (S\$)	11,774.21

This claim is handled by: **NG PEI WEN**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 18 Apr 2018)**Parts:** N/A TOYOTA DYNA 150 D 3.0 D (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT WINDSCREEN PILLAR; OUTER - RH <i>Bent</i>	0.00	0.00	*170.00 F ✓
2	1	NA	*FRONT WINDSCREEN PILLAR; INNER - RH <i>Repair</i>	0.00	0.00	*130.00 F ✓
3	1	NA	*CORNER PANEL - RH <i>Repair</i>	0.00	0.00	*75.00 F ✓
4	1	NA	*FRONT GRILLE <i>Missing</i>	0.00	0.00	*350.00 F ✓
5	1	NA	*FRONT GRILLE LOGO <i>Missing</i>	0.00	0.00	*40.00 F ✓
6	8	NA	*FRONT GRILLE CLIP - WHITE <i>3 in</i>	0.00	0.00	*20.00 F ✓
7	8	NA	*FRONT GRILLE CLIP - BLACK <i>3 in</i>	0.00	0.00	*20.00 F ✓
8	1	NA	*FRONT BUMPER <i>Best</i>	0.00	0.00	*250.00 F ✓
9	1	NA	*FRONT BUMPER REINFORCEMENT ?	0.00	0.00	*100.00 F ?
10	1	NA	*FRONT BUMPER BRACKET - RH <i>Best</i>	0.00	0.00	*95.00 F ✓
11	1	NA	*FRONT BUMPER FOG LAMP - RH <i>at</i>	0.00	0.00	*110.00 F ✓
12	1	NA	*FRONT BUMPER FOG LAMP COVER - RH <i>at</i>	0.00	0.00	*50.00 F ✓
13	2	NA	*HEAD LAMP ASSY - new <i>cracked</i>	0.00	0.00	700 350.00 F ✓
14	1	NA	*HEAD LAMP LOWER RUBBER - RH <i>new</i>	0.00	0.00	*15.00 F ✓
15	1	NA	*FRONT DOOR - RH <i>Distorted</i>	0.00	0.00	*560.00 F ✓
16	1	NA	*FRONT DOOR RUBBER - RH <i>at</i>	0.00	0.00	*80.00 F ✓
17	1	NA	*FRONT DOOR HINGE; TOP - RH <i>new</i>	0.00	0.00	*50.00 F ✓
18	1	NA	*FRONT DOOR HINGE; LOWER - RH <i>Best</i>	0.00	0.00	*50.00 F ✓
19	1	NA	*FRONT DOOR SIGNAL LAMP - RH <i>cracked</i>	0.00	0.00	*35.00 F ✓
20	1	NA	*FRONT DOOR LOCK - RH <i>new</i>	0.00	0.00	*130.00 F ✓
21	1	NA	*FRONT DOOR EYE - RH <i>new</i>	0.00	0.00	*70.00 F ✓
22	1	NA	*FRONT DOOR STEP GARNISH - RH <i>missing</i>	0.00	0.00	*90.00 F ✓
23	1	NA	*FRONT DOOR BOARD - RH ?	0.00	0.00	*380.00 F ?
24	1	NA	*FRONT DOOR REGULATOR GEAR - RH ?	0.00	0.00	*105.00 F ?
25	1	NA	*FRONT DOOR REGULATOR GEAR MOTOR - RH ?	0.00	0.00	*210.00 F ?
26	1	NA	*FRONT ABSORBER - RH ?	0.00	0.00	*55.00 F ?
27	1	NA	*FRONT LOWER ARM - RH ?	0.00	0.00	*190.00 F ?
28	1	NA	*FRONT TOP ARM - RH ?	0.00	0.00	*420.00 F ?
29	1	NA	*FRONT KNUCKLE ARM - RH ?	0.00	0.00	*350.00 F ?
30	1	NA	*FRONT KNUCKLER ARM BEARING - RH ?	0.00	0.00	*65.00 F ?
31	1	NA	*FRONT STAY LINK - RH - NO STOCK ?	0.00	0.00	*79.20 F ?
32	1	NA	*FRONT CROSSMEMBER - NO STOCK ?	0.00	0.00	*1,635.30 F ?

F=Franchise part.

Sub Total (\$\$)	6,329.50
+ Margin on L,N Items 15.00% (\$\$)	949.43
Total Parts (\$\$)	7,278.93

Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRONT DOOR COMPANY STICKER - RH <i>new</i>	30.00 ✓
2	1	FRONT NUMBER PLATE WITH CASING <i>new</i>	35.00 ✓
3	1	FRONT TYRE - RH <i>{ new</i>	280.00 X
4	1	FRONT TYRE RIM	250.00 X
Sub Total (S\$)			595.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	950.00 800 ✓
Labour Items			
2	TO KNOCK OUT DENTS; RH FRONT FLOOR PANEL; RH FRONT WHEEL ARCH PANEL; RH CHASSIS; CUT/WELD; RH FRONT DOOR PILLAR; REMOVE; REPLACE ACCIDENT PARTS	New	1,100.00 800 ✓
3	TO CHECK WIRING	New	20.00 ✓
4	TO REMOVE; REFIX DASHBOARD	New	300.00 220 ✓
5	TO REMOVE; REFIX FRONT WINDSCREEN	New	120.00 100 ✓
6	TO 4 WHEEL ALIGNMENT	New	60.00 ✓
7	TO TRANSFER DOOR AND DOOR FITTING	New	80.00 ✓
8	TO REMOVE; REPLACE FRONT UNDERCARRIAGE AND FRONT CROSSMEMBER	New	500.00 ??
Gross Labour Cost (S\$)			3,130.00

Progressive Automotive Pte Ltd/GBF6865B/18/04/2018 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian King
P/P 24/04/18

08 Days.

Excess \$800

Not Authorised.