



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9285 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SJT4958L

Report No. : PAS/TP/0190817

S/No.	Labour Descriptions	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	Towing.	\$ 100.00	\$ 85.00 50
2	To transfer tailgate component parts to new tailgate. (Include transfer rear spoiler and supply sealant)	\$ 150.00	\$ 130.00 60
3	To replace rear windscreen to new tailgate.	\$ 150.00	\$ 120.00 100
4	To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs. (Include remove roof lining)	\$ 180.00	\$ 150.00 60
5	To check electrical system, repair wire harness and focus headlamp.	\$ 80.00	\$ 50.00 30
6	To remove and reinstall RHR quarter glass for necessary repairs.	\$ 120.00	\$ 60.00 40
7	To remove and reinstall fuel tank, pipings, etc. for necessary repairs.	\$ 120.00	\$ 80.00 60
8	To remove and reinstall rear undercarriage for necessary repairs.	\$ 220.00	\$ 180.00 NR
9	To straighten, repair, realign center exhaust pipe and replace exhaust silencer.	\$ 100.00	\$ 80.00 NR
10	To straighten, repair, realign on affected area and replace damaged parts.	\$ 2,000.00	\$ 1,760.00 1200
11	To conduct chassis alignments.	\$ 350.00	\$ 300.00 200
12	To spray painting, blending on affected and adjacent area.	\$ 1,800.00	\$ 1,500.00 1200
13	To spray anti-rust coating on new and affected panels.	\$ 200.00	\$ 150.00 80
14	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 60.00	\$ 50.00 40
15	To conduct wheel alignment.	\$ 80.00	\$ 60.00 /
Labour Total :		\$ 5,710.00	\$ 4,755.00 2180
Total (Parts & Labour) :		\$ 20,843.50	\$ 17,544.90

For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 14,050.00

Under normal circumstances, the repairs should be completed within a reasonable period of **15 Working Days**.

175 Photographs were taken at the time of inspection.

13357.3
2ep: 10650
10 Days

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1210F
Vehicle Details	
Vehicle No.:	SJT4958L
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jun 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	AVEO 1.4AT 5DR T255
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	F14D37555291
Chassis No.:	KL1SA4871AB018182
Maximum Power Output:	69.0 kW (92 bhp)
Open Market Value:	\$10,322.00
Original Registration Date:	14 Oct 2009
First Registration Date:	14 Oct 2009
Transfer Count:	0
Actual ARF Paid:	\$10,322.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Oct 2019
PARF Rebate Amount:	\$5,677.00
Intended COE Rebate Details	
COE Expiry Date:	13 Oct 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$17,501.00
COE Rebate Amount:	\$1,911.00
Total Rebate Amount:	\$7,588.00

The information contained herein is correct as at 12 Jun 2018

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD		Ref : CS/ICS18007241/Gvbe2	
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 13-06-2018	
		Code : ICS	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	GBB 5745S	Veh. Inspected	SJT 4958L
Policy No.		Coverage (\$)	0.00
Claim No.	DMCV1700070H	Excess (\$)	0.00
Assign From	JANICE GOH	Assign Date	10/04/2018
2. Vehicle Particulars & Condition			
Make & Model	CHEVROLET AVEO	c.c	1399
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	KL1SA4871AB018182	Colour	RED
Odometer	63237	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/65 R14	TOYO	6 mm
L/H Front Tyre	175/65 R14	TOYO	6 mm
R/H Rear Tyre	175/65 R14	TOYO	6 mm
L/H Rear Tyre	175/65 R14	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/08/2017	Inspection Date	20/04/2018
Survey held at	UNI AUTOMOTIVE PL 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 4958L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	REPLACED	1,416.00	1,416.00
1	TAILGATE 3RD BRAKE LAMP ASSY	REPLACED	139.00	139.00
1	TAILGATE WINDSCREEN	REPLACED	730.00	730.00
1	TAILGATE WINDSCREEN MOULDING	REPLACED	89.00	89.00
1	TAILGATE WINDSCREEN WIPER ARM	REPLACED	101.00	101.00
1	TAILGATE WINDSCREEN WIPER MOTOR	REPLACED	323.00	323.00
2	TAILGATE HINGE R/L @\$52.00	REPLACED	104.00	104.00
2	TAILGATE STAY SUPPORT R/L @\$201.00	REPLACED	402.00	402.00
1	TAILGATE NO. PLATE GARNISH	REPLACED	212.00	212.00
2	TAILGATE NO. PLATE LAMP R/L @\$64.00	REPLACED	128.00	128.00
1	TAILGATE EMBLEM (LOGO)	REPLACED	44.00	44.00
1	TAILGATE EMBLEM (CHEVROLET)	REPLACED	59.00	59.00
1	TAILGATE EMBLEM (AVEO)	REPLACED	62.00	62.00
1	TAILGATE INNER TRIM	REPLACED	191.00	191.00
1	TAILGATE LOCK KEY CYLINDER	REPLACED	251.00	251.00
1	TAILGATE LOCK	REPLACED	87.00	87.00
1	TAILGATE LOCK STICKER	REPLACED	45.00	45.00
1	TAILGATE COMPARTMENT COVER	REPLACED	190.00	190.00
1	TAILGATE WEATHERSTRIP	REPLACED	105.00	105.00
2	TAILLAMP R/L @\$317.00	REPLACED	634.00	634.00
2	TAILLAMP PANEL R/L @\$144.00	O/S REPLACED / N/S REPAIRED SEE LABOUR	288.00	144.00
1	RR BUMPER	REPLACED	1,265.00	1,265.00
1	RR BUMPER GRILLE GARNISH	REPLACED	149.00	149.00
1	RR BUMPER ABSORBER	REPLACED	134.00	134.00
6	RR BUMPER CLIP @\$3.00	REPLACED	18.00	18.00
2	RR BUMPER RETAINER R/L @\$61.00	REPLACED	122.00	122.00
2	RR BUMPER BRACKET R/L @\$54.00	REPLACED	108.00	108.00
2	RR BUMPER SIDE BRACKET R/L @\$42.00	REPLACED	84.00	84.00
1	RR END PANEL	REPLACED	677.00	677.00
1	RR END PANEL GARNISH	REPLACED	181.00	181.00
1	RR SPARE TYRE COVER	REPLACED	277.00	277.00
1	RR SPARE TYRE INNER GARNISH	REPLACED	135.00	135.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RR SPARE PANEL	REPAIRED SEE LABOUR	1,975.00	-
2	RR FENDER R/L @\$934.00	O/S REPLACED / N/S REPAIRED SEE LABOUR	1,868.00	934.00
2	RR FENDER WHEEL HOUSE R/L @\$495.00	REPAIRED SEE LABOUR	990.00	-
2	RR QUARTER GLASS MOULDING R/L @\$199.00	O/S REPLACED	398.00	199.00
2	RR FENDER INNER TRIM R/L @\$288.00	REPLACED	576.00	576.00
10	RR FENDER INNER TRIM CLIP R/L @\$2.00	REPLACED	20.00	20.00
2	RR FENDER TOP GARNISH R/L @\$108.00	O/S REPLACED	216.00	108.00
2	RR FENDER COWLING R/L @\$81.00	O/S REPLACED	162.00	81.00
8	RR FENDER COWLING CLIP R/L @\$2.00	REPLACED	16.00	16.00
2	RR FENDER AIR VENT R/L @\$48.00	O/S REPLACED	96.00	48.00
1	RR FUEL CHARCOAL CANISTER	REPLACED	309.00	309.00
1	RR EXHAUST SILENCER	NOT NECESSARY	665.00	-
2	RR EXHAUST SILENCER MOUNTING @\$37.00	NOT NECESSARY	74.00	-
	LESS 10% DISCOUNT		-1,611.50	-1,089.70
			14,503.50	9,807.30
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE WINDSCREEN SEALANT (SN)	REPLACED	50.00	40.00
1	SET RR NO. PLATE (SN)	REPLACED	50.00	50.00
1	SET REVERSE SENSOR (SN)	REPLACED	250.00	200.00
1	RR END PANEL SEALANT (SN)	REPLACED	50.00	40.00
1	RR SPARE PANEL SEALANT (SN)	REPLACED	50.00	40.00
2	RR FENDER SEALANT R/L (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (SN)	NOT NECESSARY	80.00	-
			630.00	370.00
	<u>LABOUR</u>			
	TOWING.		100.00	50.00
	TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE. (INCLUDE TRANSFER REAR SPOILER AND SUPPLY SEALANT).		150.00	60.00
	TO REPLACE REAR WINDSCREEN TO NEW TAILGATE.		150.00	100.00
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, SEATS, ETC. FOR NECESSARY REPAIRS. (INCLUDE REMOVE ROOF LINING)		180.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL SYSTEM, REPAIR WIRE HARNESS AND FOCUS HEADLAMP.		80.00	30.00
	TO REMOVE AND REINSTALL RHR QUARTER GLASS FOR NECESSARY REPAIRS.		120.00	40.00
	TO REMOVE AND REINSTALL FUEL TANK, PIPINGS, ETC. FOR NECESSARY REPAIRS.		120.00	60.00
	TO REMOVE AND REINSTALL REAR UNDERCARRIAGE FOR NECESSARY REPAIRS.	NOT NECESSARY	220.00	-
	TO STRAIGHTEN, REPAIR, REALIGN CENTER EXHAUST PIPE AND REPLACE EXHAUST SILENCER.	NOT NECESSARY	100.00	-
	TO STRAIGHTEN, REPAIR, REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF N/S TAILLAMP PANEL, RR SPARE PANEL, N/S RR FENDER AND RR FENDER WHEEL HOUSE R/L.		2,000.00	1,200.00
	TO CONDUCT CHASSIS ALIGNMENTS.		350.00	200.00
	TO SPRAY PAINTING, BLENDING ON AFFECTED AND ADJACENT AREA.		1,800.00	1,200.00
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.		200.00	80.00
	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT.		60.00	40.00
	TO CONDUCT WHEEL ALIGNMENT.		80.00	60.00
			5,710.00	3,180.00
GRAND TOTAL			20,843.50	13,357.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,650.00

Report Ref No. CS/ICS18007241/Gvbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.