

REPAIR ESTIMATE*

A79

DATE 18/4/2018 15:41

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>x repair</i>			\$ 562.30
	Front Bumper Bracket Top (RH) <i>?</i>			\$ 22.40
	Front Bumper Side Bracket (RH) <i>?</i>			\$ 14.30
	<i>Front Fender (RH) x repair</i>			
	<i>Front RH Headlamp - \$138</i>			
	SUB TOTAL			\$ 599.00
	LESS 20%			\$ 119.80
	DISCOUNTED TOTAL			\$ 479.20
	Labour Charge			
	Panel Beating			\$ 250.00 <i>200</i>
	Spray Painting Charge			\$ 250.00 <i>40</i>
	TOTAL LABOUR			\$ 500.00
	ESTIMATE TOTAL			\$ 979.20
	<i>16/4/18</i>			
	<i>18/4/18 1610h</i>			
	<i>2 Reps</i>			
	<i>PIP</i>			
	<i>After Repair pls</i>			
	<div>LKK Auto Consultants hence notify the Repairer of the following:<ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</div>			
	Acknowledged by Repairer			
	Signature: _____			
	Date: _____			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			