

SS, REC. BY:

REF: CS/FCL18007280/Ktbz2

Special Instruction:

Supervisor: Kimath

ASSIGNMENT (Office)

From (Person): WS Hung Yin Min of TEL Date/Time: 19/04/2018 9:05am

Estimated Cost: Bill to:

OD (TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 9871M Insured: SHD 859561

at Workshop m/s Trans Cab Tel: 6287 6666

of No. 2A Mk St 63

Policy No: Claim No: D18002959MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 16/04/2018 (Client's Record)

CA / REV / REP. / REV 24 HRS (DS) H.O.D. Endorsement:

Date/Time: 19/04/2018 9:16am Person Contacted: Candy Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 9871M - CS/FCL15015961/Ktbz2 DCA: 020715
	SHD 859561 - X
	61 Day @ 15,400 (Red. 32707.26 @ 67%)

REF: FCL

ASSIGNMENT

From: _____ Date: 19042018

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHB 9871M

at Workshop m/s: Trans Cab

of No. 2 AMK 94 63

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Veh No: SHB 9871M Yr Regn: 08 / 13

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Renault Latitude c.c. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 607584 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VI1ABL15AUC 273329

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Giti 215/60R16
R: Falken _____


BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. 8 mm	R/Bal. 9 mm
L/Bal. 8 mm	L/Bal. 9 mm
D.O.A. 16/4/18	D.O.I. 19/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.



(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
20/4	File sent to Catherine

RECEIVED 15 AUG 2018

Date/Time. File Pass to? : Preli. Report

1) 15/8 Typist : Final Report

Date/Time. File Return to? _____

2) _____

Report Format: TP

Lump Sum / I.B.I: (\$ 15,400)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee: 170 + 570 = 570

Transportation: 50

S + RS: 50

Photo: 21

Other: 570

ESP 15/8/18

811



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002959MFSH

Date: 15/8/2018

Our Ref: CS/FCI18007280/K1b

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 9871M

Please be informed that we had conducted the inspection of the abovementioned vehicle 19/4/2018 at the premises of M/s Trans - Cab and have the following to report: -

Workshop Estimate Amount	: S\$ <u>48,107.26</u>
Revised Estimate Amount	: S\$ <u>15,400.00</u>
"Check" Items Amount	: S\$ <u>0.00</u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the Rear O./S portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-04-2018	Our Ref No. D18002959MFSH
Accident Date	16-04-2018	Claim Type. Third Party
Insured Vehicle	SHD8595G	Third Party Vehicle. SHB9871M
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY KONG	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 15 August 2018 1:45 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002959MFSH/1
Attachments: PRELI ADVISED SHB 9871M.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHB 9871M**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 19 April 2018 9:17 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: AUNGYINMIN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002959MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 19 April, 2018 9:05 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; AUNGYINMIN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002959MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHB9871M
Vehicle to be Exported:	Yes
Intended De-registration Date:	17 Apr 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000237
Chassis No.:	VF1ABL15AUC273329
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2021
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$54,952.00
COE Rebate Amount:	\$23,118.00
Total Rebate Amount:	\$32,491.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Apr 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9871M

AAD1804-178

Not Authorised
L/Sing &

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHB 9871M
VF1ABL15AUC273329
RENAULT
LATITUDE
16.4.2018
FCIL

PART			LIST
1	1 BUMPER COVER REAR	\$	<i>Am</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>CM</i> 768.84 ✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 113.47 X
4	1 BUMPER BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97 X
5	1 BUMPER RETAINER RH REAR	\$	<i>Di</i> 44.99 ✓
6	1 BUMPER REFLECTOR RH	\$	<i>CM</i> 43.61 ✓
7	1 BUMPER BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sm</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	<i>B</i> 777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95 X
13	1 BOOT REAR	\$	<i>B</i> 2,872.68 ✓
14	1 BOOT FINISHER	\$	<i>Sm</i> 470.06 X
15	1 BOOT WHEATERSTRIP	\$	<i>Di</i> 323.05 ✓
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 493.35 X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35 X
18	1 BOOT BADGE 'RENAULT'	\$	<i>Am</i> 225.36 ✓
19	1 BOOT BADGE	\$	<i>Am</i> 225.36 ✓
20	1 BOOT STRUT LH	\$	<i>Sm</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sm</i> 276.08
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>Sm</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sm</i> 168.13
26	1 BOOT LOCK	\$	<i>R</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81

} X

Trans-cab Auto Services Pte Ltd

AAD1804-178

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9871M

30	1 DOOR PANEL REAR LH	\$	R	2,844.66	X
31	1 FENDER PANEL INNER TRIM REAR LH	\$	Sm	671.45	X
32	1 FENDER PANEL REAR LH	\$	R	3,299.13	X
33	1 WHEELARCH REAR LH	\$	Sm	543.47	X
34	1 FENDER PANEL INNER TRIM REAR RH	\$	Sm	671.45	X
35	1 FENDER PANEL REAR RH	\$	Bu	3,299.13	✓
36	1 WHEELARCH REAR RH	\$	Sm	543.47	X
37	1 TAILLAMP RH	\$	CM	552.55	✓
38	1 TAILLAMP PANEL RH	\$	R	986.70	X
39	1 TAILLAMP LH	\$	Sm	552.55	X
40	1 TAILLAMP PANEL LH	\$	R	986.70	X
41	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	X
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	Sm	404.56	X
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	✓
44	1 SPARE WHEEL PANEL TRIM	\$	Sm	612.21	X
45	1 EXHAUST REAR	\$	R	7,489.05	✓
46	1 EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	38,713.60	58
10%	\$	3,871.36	
	\$	34,842.24	

Special Nett

1	1SET PARKING AID	\$	Short	700.00	✓
2	1SET REAR BUMPER CLIP	\$	R	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	R	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	R	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	R	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	R	10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	R	20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	R	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	R	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	Sm	17.82	X
11	1SET BOOT FINISHER CLIP	\$	R	24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	R	30.00	—
13	1 BOOT STICKER "6555-3333"	\$	R	30.00	—
14	1 BOOT INNER TRIM CLIP	\$	R	45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	R	35.00	X

Trans-cab Auto Services Pte Ltd

AAD1804-178

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9871M

16 1SET FENDER WHEELARCH REAR LH CLIP	\$	nn 35.00 X
17 1 FENDER INNER TRIM CLIP LH	\$	nn 28.00 X
18 1 FENDER INNER TRIM CLIP LH	\$	nn 28.00 X
19 1 TAILLAMP CLIP RH	\$	ME 5.00 ✓
20 1 TAILLAMP CLIP LH	\$	nn 5.00 X
21 2 REAR WINDSCREEN SELANT	\$	M 80.00 40SN
22 1 WINDSCREEN MOULDING	\$	M 100.00 ✓
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	M 100.00 40SN
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn 385.00 X
25 1 SPARE TYRE	\$	sn 330.00 X

TOTAL \$ 2,225.02

TOTAL PARTS \$ 37,067.26

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 } 8001
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 } 8001
To Rust-Proofing Of The Affected Areas.	\$	170.00 } 601
To reinstall rear bumper parking sensor.	\$	170.00 } 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 } 601
To repair and realign rear exhaust pipe.	\$	170.00 } 8001
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 } 8001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00 X

Trans-cab Auto Services Pte Ltd

AAD1804-178

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9871M

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	<i>100/</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>~</i> 380.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>~</i> 380.00	<i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	<i>120/</i>
To check steering geometry and computer wheel alignment	\$	<i>~</i> 220.00	<i>X</i>
To transfer of rear door fittings, attachment and perform water seepage test.	\$	<i>~</i> 380.00	<i>X</i>

TOTAL \$ 11,040.00

Over All Total \$ 48,107.26

48487.24

(LUMP SUM)

Repair Days

15 Days

5 days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007280/Ktbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 24-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 8595G	Veh. Inspected	SHB 9871M
Policy No.		Coverage (\$)	0.00
Claim No.	D18002959MFSH	Excess (\$)	0.00
Assign From	AUNGYM	Assign Date	19/04/2018
2. Vehicle Particulars & Condition			
Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	VF1ABL15AUC273329	Colour	METALLIC WHITE / RED
Odometer	607584	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	GITI	8 mm
L/H Front Tyre	215/60 R16	GITI	8 mm
R/H Rear Tyre	215/60 R16	FALKEN	9 mm
L/H Rear Tyre	215/60 R16	FALKEN	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/04/2018	Inspection Date	19/04/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3661 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9871M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	CRACKED	768.84	768.84
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	DISTORTED	44.99	44.99
1	BUMPER REFLECTOR RH	CRACKED	43.61	43.61
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	BOOT REAR	BENT	2,872.68	2,872.68
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	DISTORTED	323.05	323.05
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NECESSARY	225.36	225.36
1	BOOT BADGE	NECESSARY	225.36	225.36
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINGE LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-

Report Ref No. CS/FC118007280/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	BUCKLED	3,299.13	3,299.13
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	CRACKED	552.55	552.55
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	TO REPAIR SEE LABOUR	1,471.77	-
1	OUTER PANEL REAR (END PANEL) TRIM	SERVICEABLE	404.56	-
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	BENT	7,489.05	7,489.05
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
	LESS 10% DISCOUNT		-3,871.36	-1,773.06
			34,842.22	15,957.54
	<u>SPECIAL NETT ITEMS</u>			
1	SET PARKING AID (SN)	SHORTED	700.00	700.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-

Report Ref No. CS/FC118007280/Ktbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NECESSARY	30.00	30.00
1	BOOT STICKER "6555-3333" (SN)	NECESSARY	30.00	30.00
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NECESSARY	5.00	5.00
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	WINDSCREEN MOULDING (SN)	NECESSARY	100.00	100.00
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NECESSARY	100.00	40.00
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,225.02	1,110.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		4,500.00	800.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BEAM BRACKET LH REAR, BUMPER BEAM BRACKET RH REAR, BOOT HINGE LH, BOOT HINGE RH, BOOT LOCK, BOOT LOCK CATCH, DOOR PANEL REAR LH, FENDER PANEL REAR LH, TAILLAMP PANEL RH, TAILLAMP PANEL LH, OUTER PANEL REAR (END PANEL), SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL) AND EXHAUST CAP REAR.		4,200.00	880.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE. }		170.00	80.00
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE. }		170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	100.00
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.		170.00	120.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			11,420.00	2,160.00
GRAND TOTAL			48,487.24	19,227.54
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,400.00

Report Ref No. CS/FC118007280/Ktbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.