

REPAIR ESTIMATE*

MAKE :

DATE 17/4/2018 16:02

$$A \times A$$

DOA: 17.04.18

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X Repair			\$ 603.60
	Rear Bumper Clips X			\$ 22.00
	Rear Bumper Beacket , RH ?			\$ 49.00
	Rear Fender (RH) X Repair			\$ 2,020.10
	Rear Fender Inner Lining (RH) X			\$ 164.40
	Rear Windscreen Moulding X			\$ 60.00
	Rear Wheel Hub Cap,RH -			\$ 150.70
	SUB TOTAL			\$ 3,069.80
	LESS 20%			\$ 613.96
	DISCOUNTED TOTAL			\$ 2,455.84
	Rear Bumper Rubber Mat X			\$ 50.00
	Rear Windscreen Sealant X			\$ 46.00
				\$ 96.00
	Labour Charge			400
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Rear Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 2,070.00
	ESTIMATE TOTAL			\$ 4,621.84
	Kaluh / CLK / N 18/4/d 1505m. 2 Pcs P/P After Repai pht			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer Signature:			
	Date:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			