

ASS. REC. BY:

REF: CS/FCL18007293/Albnz

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): (WS) Filleen Lee of FCL Date/Time: 19042018 2:08pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKL 2381T Insured: SH 6688S

at Workshop m/s Modern Tel:

of Bldg 3023A Ubi Rd 1 #01-58

Policy No: Claim No: D18003035MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 17042018 (Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' H.O.D. Endorsement:

Date/Time: 19042018 3:57pm Person Contacted: Grace Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKL 2381T - x
	SH 6688S - CS/FCL18007293/K7bc2 DCA: 22.10.15
2014-	Revert pending estimate
	limp sum \$ 8350 (Red: 4880.04 : 3670)

ASS. RFC. BY: Adrian King

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

/	
N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: **Yes** or **No**

GIA / PR Seen: \_\_\_\_\_ Consistent?: **Yes** or **No**

Est. Repairs: \_\_\_\_\_ days Res.: **Yes** or **No**

Lum Sum: \_\_\_\_\_ % 3 Val.: **Yes** or **No**

**CA / REV / REP. / 24 HRS**

Vehicle: **IN / OUT**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKL2381T. Yr Regn: 2018, Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Nissan Sylphy c.c. 1798

Colour: White A/C: **Insured / Std / NI / NA**

Sp. Reading: 46080 T/Radio: **Insured / Std / NI / NA**

Eng/No: \_\_\_\_\_

C/No: MNTBAABITZ0004688

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Inorder / Jammed / Leaked / Burnt** or \_\_\_\_\_

Brake: **Inorder / Jammed / Leaked / Burnt** or \_\_\_\_\_

Modi: **Nil / S/Rim / STD A/Rim** or \_\_\_\_\_

Tyre Size: F: 195/60R16.

R: 195/60R16.

**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**

**TOYO / YOKO** or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. \_\_\_\_\_ D.O.I. 19/07/18

Survey held at Modern

Des. of Damages **Fr / Rear / O/S / N/S / U/C / Rooftop** or \_\_\_\_\_

\_\_\_\_\_

The **U/C / Chassis frame / Body Structure** affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap.

RECEIVED 24 MAY 2018

Date/Time, File Pass to?  : Preli. Report

1) 24/5 Typist  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format : TP

Lump Sum / I.B.I. (\$) 8350/-

Days Of Repair: 9

Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS, SI \_\_\_\_\_

Photos 039

Other 25/6/18

TOTAL

<u>3x15=45</u>
<u>170+45</u>
<u>50</u>
<u>50+50</u>
<u>130</u>
<u>495</u>

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	18-04-2018	<b>Our Ref No.</b> D18003035MFSH
<b>Accident Date</b>	17-04-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SH6668S	<b>Third Party Vehicle.</b> SKL2381T
<b>Survey Location</b>	BLK 3023A UBI ROAD 1 #01-58/61	
<b>Contact Person.</b>	GRACE CHIN	
<b>Contact No.</b>	67484422/ 0	<b>Fax No.</b> 67476720
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	MODERN AUTOMOTIVE PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	EILEEN LEE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

**MS First Capital Insurance Ltd**  
 36 Robinson Road  
 #16-01 City House  
 Singapore 068877  
 Tel : 6507 - 3848  
 Fax : 6507 - 3849

*Denise*

**Quotation**  
 DATE : 19.04.2018  
 VEH NO : SKL2381T  
 MODEL : Nissan Sylphy  
 D O A : 17.04.2018  
 YR REF : SH6668S

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SKL2381T (NISSAN SYLPHY)**

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<b>NO</b>	<b>LIST ITEMS</b>		
1	Front Bumper <i>debond</i>	1	476.50 ✓
2	Front Bumper Reinforcement <i>new</i>	1	512.40 X
3	Front Grille <i>new</i>	1	700.70 ✓
4	Rear Bumper <i>debond</i>	1	696.00 ✓
5	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
6	Rear Bumper Side Hclder - LH & RH <i>new</i>	2	64.80 ✓
7	Rear Bumper Impact Bracket - LH & RH <i>debond</i>	2	183.40 ✓
8	Rear End Panel <i>debond</i>	1	491.80 ✓
9	Bootlid <i>debond</i>	1	850.90 ✓
10	Bootlid Weatherstripe <i>at</i>	1	91.10 ✓
			\$ 4,097.60
	Less 30%		(1,229.28)
			\$ 2,868.32

*3385.20*  
*2509.64*

**NETT ITEMS**

1	Front Number Plate Garnish <i>debond</i>	1	127.80 ✓
2	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - LH & RH <i>new</i>	2	42.20 ✓
4	Front Bumper Sponge <i>debond</i>	1	206.30 ✓
5	Front Bumper Lower Grille <i>new</i>	1	255.30 X
6	Front Bumper Tow Cover	1	27.60 X
7	Front Grille Logo <i>new</i>	1	59.70 ✓
8	Front Grille Clips <i>new</i>	1 set	10.00 ✓
9	Headlamp - LH & RH <i>new</i>	2	2,458.20 ✓
10	Front Support Panel Top Cover <i>new</i>	1	370.40 X
11	Front Support Panel Top Cover Clips <i>new</i>	1 set	15.00 ✓

**RE: ESTIMATE FOR ACCIDENT REPAIR SKL2381T (NISSAN SYLPHY)**

12	Rear Bumper Centre Sponge	3 Deformed	1	88.10	/
13	Rear Bumper Side Sponge - LH & RH		2	70.00	/
14	Rear Bumper Reflector - LH & RH	new	2	114.40	X
15	Rear End Panel Top Garnish	Deformed	1	85.40	/
16	Taillamp - LH & RH	could	2	481.00	/
17	Bootlid Lock	Damaged	1	115.70	/
18	Bootlid Lock Sensor	the one	1	68.90	X
19	Bootlid Lower Chrome Moulding	ut	1	257.40	/
20	Bootlid Lower Chrome Moulding Clips	new	1 set	10.00	/
21	Bootlid Reflector - LH & RH	new	2	270.60	X
22	Nissan Logo		1	55.40	/
23	Sylphy Wording	2 new	1	64.60	/
24	Xtronic CVT Emblem		1	65.90	/
25	Spare Tyre Panel Top Cover	the one	1	240.40	X
26	Rear Exhaust Pipe	Repis	1	554.10	X
27	Rear Exhaust Mounting	the one	1	35.40	X
				<u>\$ 6,179.80</u>	
				(617.98)	
				<u>\$ 5,561.82</u>	

Less 10%

**S/NETT ITEMS**

1	Front Number Plate	Best	320	1	30.00	/
2	Front Number Plate Holder	Deformed		1	30.00	/
3	Reverse Sensor	Damaged		1	<del>280.00</del>	20
4	Rear End Panel Sealant	new		1	60.00	/
5	Rear Camera	the one		1	500.00	X
					<u>\$ 900.00</u>	

**TOTAL PARTS**

\$ 9,330.14

**LABOUR CHARGE**

1	To knocking & pull out front & rear side portion & renew damage parts	\$	<del>1,600.00</del>	1200
2	To putty & spray up paint works	\$	<del>1,400.00</del>	1000
3	To check wiring system	\$	<del>100.00</del>	60
4	To underseal	\$	<del>150.00</del>	60
5	To remove reverse sensor	\$	<del>100.00</del>	50
6	To remove rear camera	\$	<del>100.00</del>	50
7	To remove upholstery	\$	<del>150.00</del>	80

RE: ESTIMATE FOR ACCIDENT REPAIR SKL2381T (NISSAN SYLPHY)

8 To remove rear exhaust

\$ ~~150.00~~ 80

2660.

9 To transfer bootlid fittings

\$ ~~150.00~~ 80

\$ 3,900.00

GRAND TOTAL

**\$ 13,230.14**

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total 9239.07.  
1/5 (10%): 8350  
09 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18007293/Atbn2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-05-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6668S	Veh. Inspected	SKL 2381T
Policy No.		Coverage (\$)	0.00
Claim No.	D18003035MFSH	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	19/04/2018

### 2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	MNTBAAB17Z0004688	Colour	WHITE
Odometer	46080	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	17/04/2018	Inspection Date	19/04/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **9 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 2381T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	DEFORMED	476.50	476.50
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	512.40	-
1	FRONT GRILLE	CRACKED	700.70	700.70
1	REAR BUMPER	DEFORMED	696.00	696.00
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
2	REAR BUMPER SIDE HOLDER-LH & RH	NECESSARY	64.80	64.80
2	REAR BUMPER IMPACT BRACKET-LH & RH	DENTED	183.40	183.40
1	REAR END PANEL	DENTED	491.80	491.80
1	BOOTLID	BUCKLED	850.90	850.90
1	BOOTLID WEATHERSTRIPE	CUT	91.10	91.10
	LESS 30% DISCOUNT		-1,229.28	-1,075.56
			<b>2,868.32</b>	<b>2,509.64</b>
<b>NETT ITEMS</b>				
1	FRONT NUMBER PLATE GARNISH (N)	DEFORMED	127.80	127.80
1	SET FRONT BUMPER CLIPS (N)	NECESSARY	30.00	30.00
2	FRONT BUMPER SIDE HOLDER-LH & RH (N)	NECESSARY	42.20	42.20
1	FRONT BUMPER SPONGE (N)	DEFORMED	206.30	206.30
1	FRONT BUMPER LOWER GRILLE (N)	NOT NECESSARY	255.30	-
1	FRONT BUMPER TOW COVER (N)	NOT NECESSARY	27.60	-
1	FRONT GRILLE LOGO (N)	NECESSARY	59.70	59.70
1	SET FRONT GRILLE CLIPS (N)	NECESSARY	10.00	10.00
2	HEADLAMP-LH & RH (N)	CRACKED	2,458.20	2,458.20
1	FRONT SUPPORT PANEL TOP COVER (N)	NOT NECESSARY	370.40	-
1	SET FRONT SUPPORT PANEL TOP COVER CLIPS (N)	NECESSARY	15.00	15.00
1	REAR BUMPER CENTRE SPONGE (N)	DEFORMED	88.10	88.10
2	REAR BUMPER SIDE SPONGE-LH & RH (N)	DEFORMED	70.00	70.00
2	REAR BUMPER REFLECTOR-LH & RH (N)	NOT NECESSARY	114.40	-
1	REAR END PANEL TOP GARNISH (N)	DEFORMED	85.40	85.40
2	TAILLAMP-LH & RH (N)	CRACKED	481.00	481.00
1	BOOTLID LOCK (N)	DAMAGED	115.70	115.70

Report Ref No. CS/FC118007293/Atbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOOTLID LOCK SENSOR (N)	NOT NECESSARY	68.90	-
1	BOOTLID LOWER CHROME MOULDING (N)	CUT	257.40	257.40
1	SET BOOTLID LOWER CHROME MOULDING CLIPS (N)	NECESSARY	10.00	10.00
2	BOOTLID REFLECTOR-LH & RH (N)	NOT NECESSARY	270.60	-
1	NISSAN LOGO (N)	NECESSARY	55.40	55.40
1	SYLPHY WORDING (N)	NECESSARY	64.60	64.60
1	XTRONIC CVT EMBLEM (N)	NECESSARY	65.90	65.90
1	SPARE TYRE PANEL TOP COVER (N)	NOT NECESSARY	240.40	-
1	REAR EXHAUST PIPE (N)	TO REPAIR SEE LABOUR	554.10	-
1	REAR EXHAUST MOUNTING (N)	NOT NECESSARY	35.40	-
	LESS 10% DISCOUNT		-617.98	-424.27
			5,561.82	3,818.43
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	BENT	30.00	30.00
1	FRONT NUMBER PLATE HOLDER (SN)	DEFORMED	30.00	30.00
1	REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR CAMERA (SN)	NOT NECESSARY	500.00	-
			900.00	320.00
	<b><u>LABOUR</u></b>			
	TO KNOCKING & PULL OUT FRONT & REAR SIDE PORTION & RENEW DAMAGE PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST PIPE.		1,600.00	1,200.00
	TO PUTTY & SPRAY UP PAINT WORKS.		1,400.00	1,000.00
	TO CHECK WIRING SYSTEM.		100.00	60.00
	TO UNDERSEAL.		150.00	60.00
	TO REMOVE REVERSE SENSOR.		100.00	50.00
	TO REMOVE REAR CAMERA.		100.00	50.00
	TO REMOVE UPHOLSTERY.		150.00	80.00
	TO REMOVE REAR EXHAUST.		150.00	80.00
	TO TRANSFER BOOTLID FITTINGS.		150.00	80.00
			3,900.00	2,660.00

Report Ref No. CS/FCI18007293/Atbn2



GRAND TOTAL		13,230.14	9,308.07
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,350.00

Report Ref No. CS/FCI18007293/Atbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.