

22/03/2012

ASS. REC. BY:

REF: CS/FCL18007314 / Urbn2

Special Instruction:

Survivor:

Marlys

ASSIGNMENT (Office)

From (Person): LWS Secene Lor of FCL Date/Time: 19042018 449pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBC 6824K Insured: SHD 6999M

at Workshop m/s Liu's Brother Tel: 67411730

of Blk 1 Kaki Bukit Ave 6 #01-01

Policy No: Claim No: D18002870MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 12042018
(Client's Record)

CA / REV / REP. / REV 24 HRS DS 20-042018 H.O.D. Endorsement:

Date/Time: 19042018 512pm Person Contacted: Jasmine Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GBC 6824K - NA / INC 16012188 / CH4 DUA: 091716
	SHD 6999M - NS / INC 17011500 / H116M2 DUA: 10067A
	Revert Ann email

ASSIGNMENT

From: _____ Date: 20042018
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBC 6824K
 at Workshop n/s: Liu's Brother
 of: Blk 1 Kaki Bukit Ave 6 #01-01
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 45
 IDAC Accident Rpt: Consistent?: Yes or No
 GIA PR Sec: Consistent?: Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 - % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 'DS'
 Date: _____ Person Contacted: LIA 3203U
 Vehicle: IN / OUT

Veh No: GBC 6824K Regn: 7 / 13
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Car
 Make: Toyota Hiace c.c 2982
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 134527 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFHT02P000117978
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Good / S/Rim / STD A/Rim or
 Tyre Size: F: 195-415
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pirelli
 Front: 6 mm R/Bal. 6 mm
 Rear: 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 12/4/18 D.O.I. 20/4/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S R.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 20/4/18 Confound n/s \$2000 with Susan.
 Red: \$4051.80, 671.

RECEIVED 27 APR 2018

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) typist
 Date/Time, File Return to? _____
 2) _____
 Report Format: TP
 Lump Sum / I.B.T. (\$) 2000

Days Of Repair: 3
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	145
Transportation:	50
Photos:	34
Others:	
TOTAL	229



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002870MFSH

Our Ref: CS/FCI18007314/Urb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. GBC 6824K.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/04/2018 at the premises of M/s LIU'S BROTHER AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ 6,051.80 .
Revised Estimate Amount	: S\$ 2,505.60 .
"Check" Items Amount	: S\$.
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at n/s front portion.



Yours faithfully
MARCUS
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	13-04-2018	Our Ref No. D18002870MFSH
Accident Date	12-04-2018	Claim Type. Third Party
Insured Vehicle	SHD6999M	Third Party Vehicle. GBC6824K
Survey Location	1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT	
Contact Person.	SUSAN LOW	
Contact No.	67411730/ 0	Fax No. 67445746
Survey Type	WITHOUT PREJUDICE: LIABILITY CLEAR & QUANTUM TO BE AGREED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LIU'S BROTHER AUTO ENGINEERING WORKSHOP	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Receipt



Land Transport Authority
10 Sin Ming Drive
Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 19 Apr 2018 / 10:37:11

Receipt Date/Time : 19 Apr 2018 / 10:37:11

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180419-000494

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHD6999M As at 12 Apr 2018/10:40:00 Insurance Co: FIRST CAPITAL INS LTD				
1	Insurance Enquiry - SHD6999M Enquiry Fee 20180419103556152915	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx4559		Credit Card: Visa/MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GBC6824K
Vehicle to be Exported:	No
Intended De-registration Date:	20 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE MANUAL
Primary Colour:	Blue
Manufacturing Year:	2013
Engine No.:	1KD2304745
Chassis No.:	JTFHT02P600117979
Maximum Power Output:	-
Open Market Value:	\$25,820.00
Original Registration Date:	12 Jul 2013
First Registration Date:	12 Jul 2013
Transfer Count:	1
Actual ARF Paid:	\$1,291.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jul 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$58,502.00
COE Rebate Amount:	\$30,561.00
Total Rebate Amount:	\$30,561.00
Message	
<p>Please note that the National Environment Agency (NEA) is offering an incentive of up to \$3,500 for owners of older, more pollutive motorcycles which were registered before 1 July 2003, to de-register their motorcycles on or before 5 April 2023.</p> <p>The last registered owner of this motorcycle will receive \$2,000 if it is de-registered on or before 5 April 2023. If this motorcycle's COE is not renewed on or after 7 April 2018, the last registered owner will receive an additional \$1,500 upon its de-registration on or before 5 April 2023.</p>	



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1, Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417881
8088 No. 552917931, Tel: 6744 1730 / 731, Fax: 6744 5546, Email: liubro@total.com

Invoice/Ref No: GBC6824K180412

Estimate

Customer			
Name:	MS First Capital Insurance Limited	Date:	19-04-18
Address:	Motor Claims Department 36 Robinson Road #16-01 City House	Vehicle No:	GBC6824K
	Singapore 068877	Model/Make:	Toyota Hiace Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Door <i>scr/beat 1575.10</i>	\$ 1,632.50	<input checked="" type="checkbox"/>
2	Door "ROC" Sticker <i>re</i>	\$ 48.00	SN 30
3	Door "ROC" Sticker <i>Replaced</i>	\$ 48.00	X
4	Door Inner Rubber <i>re</i>	\$ 245.70	<input checked="" type="checkbox"/>
5	Bumper <i>scr all</i>	\$ 796.80	X
6	Bumper Side Bracket <i>re</i>	\$ 139.00	X
7	Bumper Clips 1 set <i>re</i>	\$ 50.00	X
8	Head Lamp <i>scr all</i>	\$ 930.70	X
9	Head Lamp Clip 1 set <i>re</i>	\$ 65.00	X
10	Corner Panel <i>re</i>	\$ 296.10	X
11	"Corporate" Advertisement Sticker <i>re</i>	\$ 400.00	SN 230
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	300
	To putty & spray painting & including touch up paint on accident affected area	\$ 600.00	500
	To check all wiring & electrical component for proper function	\$ 60.00	300
	To apply Rust Proofing, reseal tuff coating treatment on accident area	\$ 60.00	300
	To remove, replace and transfer door panel, fitting and mechanisms	\$ 80.00	X

Total Parts & Labour of estimate for damaged vehicle \$ 6,051.80

Total amount in Part By Part / Lump Sum Basis for repaired vehicle \$

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

1820.8
1365.6
2505.6

Not Addressed

*LKK
2/5 \$2000/-
20/4/18*

*take photo after repair
3 day.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18007314/Urban2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-05-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 6999M	Veh. Inspected	GBC 6824K
Policy No.		Coverage (\$)	0.00
Claim No.	D18002870MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	19/04/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTFHT02P600117979	Colour	BLUE
Odometer	134527	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	FIRENZA	6 mm
L/H Front Tyre	195 R15	FIRENZA	6 mm
R/H Rear Tyre	195 R15	FIRENZA	6 mm
L/H Rear Tyre	195 R15	FIRENZA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/04/2018	Inspection Date	20/04/2018
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 6824K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT LH DOOR	DENTED / BENT	1,632.50	1,575.10
1	FRONT LH DOOR "ROC" STICKER	REPEATED	48.00	-
1	FRONT LH DOOR INNER RUBBER	NECESSARY	245.70	245.70
1	FRONT LH BUMPER (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	796.80	-
1	FRONT LH BUMPER SIDE BRACKET	NOT NECESSARY	139.00	-
1	SET FRONT LH BUMPER CLIPS	NOT NECESSARY	50.00	-
1	FRONT LH HEAD LAMP (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	930.70	-
1	SET FRONT LH HEAD LAMP CLIP	NOT NECESSARY	65.00	-
1	FRONT LH CORNER PANEL	NOT NECESSARY	296.10	-
	LESS 25% DISCOUNT		-	-455.20
			4,203.80	1,365.60
SPECIAL NETT ITEMS				
1	FRONT LH "CORPORATE" ADVERTISEMENT STICKER (SN)	NECESSARY	400.00	230.00
1	FRONT LH DOOR "ROC" STICKER (SN)	NECESSARY	48.00	30.00
			448.00	260.00
LABOUR				
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCs.		600.00	300.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		600.00	500.00
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		60.00	50.00
	TO APPLY RUST PROOFING, RESEAL TUFF COATING TREATMENT ON ACCIDENT AREA.		60.00	30.00
	TO REMOVE, REPLACE AND TRANSFER DOOR PANEL, FITTING AND MECHANISMS.	NOT NECESSARY	80.00	-
			1,400.00	880.00
GRAND TOTAL			6,051.80	2,505.60



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00
---	--	--	----------

Report Ref No. CS/FCI18007314/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.