
From (Person):		Samo	100			(Office)			19042018	liskon
		outthe	LULI	of	FC	Socr	Da	te/Tim	of to 4 to 10	ייקסעוי
Estimated Cost:				www.companies.		îll to:				
To Inspect Veh							Insured:	SH	1959C	
nt Workshop m	ls			Trans	(ab		Tel:			
of				2AMK	84 63					
Policy No:	. 10					Claim No: _	D18(	00304	SMFSH	
Sum Insured:_						Excess:				
Make of Veh:		Dimension					D	O.A.	15042018	Š
CA / REV /	9042018	301pr	η	Person Co	ntacted;	Candy		-	Endorsement:	
Date/Time	Action/I	structio	on (	V ) [	Stimute					
	-					/Kpa3n2		- 1	DUA 31031	0
	SH 69"	590 -	(03	1016090	24514 /	aug I			DUA- 241009	
24/04/18	01	3.56	p.m.	revise	d to	dere	Le vi			

	ASSIGNMENT	
From Date 36042(	118 Veh No. 51+2 533	33 XYr Regn: 12, 14
From: Date: 0004-1	Type: M.Car / M.Cycle / Bus / Van	/ Lorry / Jaxi Prime Mover /
OD / P) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or	
To Inspect Vehicle No: SHC 5333 X	Make Reserve	loti Toda 00 188
at Workshop m/s Trans Cab	Colour M. WZiz / Re	
of No. 2 AMK\$-63	Sp.Reading 398299	
Insured.	Eng/No:	
Policy No.	CINO: VFIAB	6 15 Auc 27 9367
Claims No.	Gen. Cond: Good Fair / Poor / B	
Sum Insured: Excess:	Steering: Inorder? Jammed / Lea	ked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Lea	ked / Burnt or
Make of Veh:	Modi : MT / S/Rim / STD A/Rin	Control of the contro
	Tyre Size: F: Gi7i	215/60R16
(Policy Condition)	R: Falker	
Remark: The veh had commenced its	S O/S BS/DUN/EXNOVA/GY/FS/L	IZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or	
Bal. or Market Value:	Front 0	Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. d mm	R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. mm	L/Bal. 6 mm
Est Repairs: 02 days Res.: Yes or No	D.O.A. 13/4/18	0.0.23 20 14/18
Lum Sum: 20 % 3 Val.: Yes or No	Survey held at	
CĂ / REV / REP. / 24 HRS'Wp'	Des. of Damages : Frt / Rear / le: IN / OUT	O/S / N/S / U/C / Rooftop or
Date: Person Contacted:		Body Structure affected due to collision.
Date/Time Action/Instruction 29/4 File pass to Cothe 1/Ly 8/9001  Reduction - 81%	vin.	
RECEIVED 2 4 A	PR 2018 .  Days Of Repair: 2	
24/04/18 Sinal Banan	Resurvey No. of Trip: 0	Survey Fee: 170
Date/Time, File Return to?		Transportation: 50
2)	Add Fee: Site Insp (\$	)S +RSSI
· · · · · ·	: Interview (\$	) Photos 9
Report Format :	Tech Invs (\$	) Others
Lump Sum / I.B.I: (\$	:Weekend (\$	and the second s
		TOTAL 229



MS First Capital Insurance Limited co.Reg. No. 195000106C GST Reg. No. MZ-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwitting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

#### MOTOR SURVEY ASSIGNMENT

Date

19-04-2018

Our Ref No. D18003045MFSH

**Accident Date** 

15-04-2018

Claim Type. Third Party

Insured Vehicle

SH6959C

Third Party Vehicle. SHC5333X

**Survey Location** 

NO. 2 ANG MO KIO STREET 63

Contact Person.

CANDY KONG

Contact No.

62876666/0

Fax No. 62571330

Survey Type

WITHOUT PREJUDICE: LIABILITY UNCLEAR - EST. COR - \$10,157.23 (ID

NON-REPORTING)

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

#### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

TRANS-CAB AUTO SERVICES PTE LTD

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

SERENE

#### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003045MFSH

Date: 24 April 2018

Our Ref: CS/FCI18007316/Ks3b

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,

# INITIAL INSPECTION REPORT OF VEHICLE NO. <u>SHC 5333X.</u>

Please be informed that we had conducted the inspection of the abovementioned vehicle on 23/04/2018 at the premises of M/s Trans-Cab Auto Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: SS	10,157.23	- 0
Revised Estimate Amount (Lump Sum)	: S\$	1,900.00	
"Check" Items Amount	: S\$	- 1-	
Market Value	: <u>S</u> \$		-
LTA Reimbursement Value	: <u>S\$</u>	% <del>=</del> %	
Nett Value	: <u>SS</u>	-	

Description of Damage:

<u>The vehicle sustained damages</u>
at the rear o/s portion.

nearside fro

Repair days: 2 Days

Comments/ Present Status:

Damages Consistent.

Yours faithfully, Kenneth Kong Automotive Assessor

### Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Tuesday, 24 April 2018 1:56 PM

To:

'Claim Workflow System'; 'assignments'

Cc:

SERENELER@MSFIRSTCAPITAL.COM.SG; 'SUR'

Subject:

FW: SURVEY ASSESSMENT - D18003045MFSH/1

Attachments:

SHC 5333X - Preli Advise.pdf

Dear Serene.

Enclosed herewith preliminary advice of SHC 5333X.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Thursday, 19 April 2018 5:02 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM

Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com

Subject: RE: SURVEY ASSESSMENT - D18003045MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 19 April, 2018 4:36 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18003045MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey. Kindly submit your report via CWS within the next 14 days.

Best Regards, Admin Team Claim Workflow System Motor Claims Department
MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	Commen
Owner ID Type:	Company
Owner ID: Vehicle Details	3878K
Vehicle No.:	SHC5333X
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 Apr 2018
/ehicle Make:	RENAULT
/ehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
ingine No.:	M9R8839C001918
Chassis No.:	VF1ABL15AUC279367
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	15 Sep 2014
First Registration Date:	15 Sep 2014
Fransfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$12,498.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2022
PARF Rebate Amount: Intended COE Rebate Details	\$9,373.00
COE Expiry Date:	14 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$27,966.00
Total Rebate Amount: Message	\$37,339.00
Please note that the 8-year COE for this vehicle cannot vehicle reaches its statutory lifespan (if applicable), whi	be further renewed. The vehicle must be de-registered upon COE expiry or when the chever is earlier.
등록 사용됐다면 있는 경험 집에 가는 사람들이 하는 사람들이 되었다면 하는 것이다.	240

The information contained herein is correct as at 16 Apr 2018

ОК

### Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666

Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHC 5333X

Not Nothers 1804-165

SHC 5333X

VF1ABL15AUC279367

RENAULT

LATITUDE

15.4.2018

FIL

\_\_\_\_

PART

T

LIST

1	1 BUMPER COVER REAR	\$ 1,108.46
2	1 BUMPER LOWER REAR	\$ nu 768.84 —
3	1 BUMPER BRACKET CTR REAR	\$ 5m 113.47 X
4	1 BUMEPR BRACKET SIDE RH REAR	\$ 135.97 ×
5	1 BUMEPR RETAINER RH REAR	\$ 5- 44.99 K
6	1 BUMPER REFLECTOR RH	\$ CM 43.61
7	1 BUMEPR BRACKET SIDE LH REAR	\$ 135.97 ×
8	1 BUMEPR RETAINER LH REAR	\$ 5~ 44.99 <
9	1 BUMPER REFLECTOR LH	\$ Sh 43.61 X
10	1 BUMPER BEAM REAR	\$ 1777.52 ✓
11	1 BUMPER BEAM BRACKET LH REAR	\$ 1 225.95 ×
12	1 BUMPER BEAM BRACKET RH REAR	\$ / 225.95 X

TOTAL	\$ 3,669.34
10%	\$ 366.93
3.70000000000 37	\$ 3,302.41

### **Specical Nett**

1 15	ET PARKING AID	\$ √ 700.00 X
	ET REAR BUMPER CLIP	\$ ra 66.00
3 15	ET BUMPER BRACKET CTR CLIP	\$ Ma 33.00 _
	ET BUMPER BRACKET SIDE CLIP RH RR	\$ 10.00 X
	ET BUMEPR RETAINER RH CLIP RR	\$ ~~ 20.00 X
	ET BUMEPR BRACKET SIDE CLIP LH RR	\$ ルへ 10.00 ×
200	ET BUMEPR RETAINER CLIP LH RR	\$ an 20.00 x
	SET BUMPER LOWER REAR RIVET	\$ en 22.00 x
	SET BUMPER LOWER REAR CLIP	\$ Ma 66.00
10	1 EXHAUST MOUNTING REAR	\$ In 17.82 X

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666

Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHC 5333X

TOTAL	\$	964.82
TOTAL PARTS	\$	4,267.23
LABOUR		
Putty And Spray Painting Of The Affected Portion.	\$	2,450.00 2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts,		
Adjust And Realign The Same	\$	2,200.00 20-1
To Rust-Proofing Of The Affected Areas.	\$	~~ 170.00 X
To reinstall rear bumper parking sensor.	\$	170.00 601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	ルへ 170.00 √
To repair and realign rear exhaust pipe.	\$	~~ 170.00 X
To drop rear exhaust box, renew the same, to repair		NA. 170.00 /
and realign centre exhaust pipe.	\$	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 X
To check steering geometry and computer wheel alignment	\$	~ 220.00 X
LKK Auto Consultants hence notify the Repairer of the following:  To Tal.	\$	5,890.00
To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis	\$	10,157.23
No illegal modification(s) is allowed  Supplementary item(s) must be resurvey (LUMP SUM) is subject to final approval from Insurance Company Pays  Repair Days	) i	2 days
Acknowledged by Repairer Signature: Date:		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

100		Affiliated to Federation Interna	tionale Des Experts En Autom	obile
FIRS	T CAPITAL INSUR	ANCE LTD	Ref : CS/FCI1800731	16/Ks3bn2
36 R #16-0	OBINSON ROAD 01 CITY HOUSESI	NGAPORE 068877	Date: 26-04-2018 Code: FCI2	
1.	To MALIN SI	Policy Particula	rs :- THIRD PARTY CLAI	M
	Insured Veh.	SH 6959C	Veh. Inspected	SHC 5333X
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18003045MFSH	Excess (\$)	0.00
	Assign From	SERENE	Assign Date	19/04/2018
2.	and the same	Vehicle Pa	rticulars & Condition	
	Make & Model	RENAULT LATITUDE (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	VF1ABL15AUC279367	Colour	METALLIC WHITE / RED
	Odometer	398294	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Con	ditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	GITI	8 mm
	L/H Front Tyre	215/60 R16	GITI	8 mm
	R/H Rear Tyre	215/60 R16	FALKEN	6 mm
	L/H Rear Tyre	215/60 R16	FALKEN	6 mm
4.			ption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR O/S PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Gen	eral Information	ACTOR STATE
	Accident Date	15/04/2018	Inspection Date	23/04/2018
	Survey held at	TRANS-CAB AUTO SERVIC	ES PTE LTD	
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a.			Remarks	THE RESERVE OF THE PERSON OF T
	DITHE INSPECTION	NSISTENT TO ACCIDENT REI ON WAS CONDUCTED ON A' CE TO YOUR INSTRUCTION	WITHOUT PREJUDICE" BA	SIS. ISED REPAIRS.
5b.			ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	2 Working Da	ys



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5333X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
1	BUMPER COVER REAR	CRACKED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED	768.84	768.84
99	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	
	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	19
1	BUMPER REFLECTOR RH	CRACKED	43.61	43.61
1	BUMPER BRACKET SIDE LH REAR	TO REPAIR SEE LABOUR	135.97	0
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	8
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	1
	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	8
1	BUMPER BEAM BRACKET LH REAR	TO REPAIR SEE LABOUR	225.95	8
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	
	LESS 10% DISCOUNT		-366.92	-192.0
			3,302.41	1,728.8
	SPECIAL NETT ITEMS	1		
1	SET PARKING AID (SN)	SERVICEABLE	700.00	
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	100000
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.0
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	
	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	
	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.0
	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	
		The state of the s	964.82	165.0

Report Ref No. CS/FCI18007316/Ks3bn2



### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		2,450.00	220.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF BUMPER BRACKET SIDE LH REAR, BUMPER BEAM BRACKET LH REAR AND BUMPER BEAM BRACKET RH REAR.		2,200.00	200.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	1
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	S .
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	(a)
	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	
			5,890.00	480.00
	GRAND TOTAL		10,157.23	2,373.82

RECOMMENDED COST OF LUMP SUM REPAIRS	,900.00
(TO ITS PRE-ACCIDENT CONDITION)	71000

Report Ref No. CS/FCI18007316/Ks3bn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.