

22/03/2003

ASS. REC. BY:

REF: CS/FCL18007317/Knbez

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person): CWS Serene Ler

of

FCL

Date/Time: 19042018 713pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 3456A

Insured:

SHC 8879T

at Workshop m/s

Trans Cab

Tel:

of

No. 2 Amk St 63

Policy No:

Claim No:

D18002923MTFS11

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

20042018

H.O.D. Endorsement:

Date/Time: 19042018 450pm

Person Contacted:

Candy

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 3456A - CA/ALG11002105/12

DA: 02022011

SHC 8879T - CS/FCL17004684/Kirbn2

DA: 01032017

73/4/18 @ 3.19pm routed to Serene by email.

61 Sq 817, 1001 (Red B 57628.36, 77%)

Surveyor

## ASSIGNMENT

From: Date: 20042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 5456A

at Workshop m/s

Trans Cab

of

No. 2 AMK St 63

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'WP'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5456A

Yr Regn:

12 / 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perant Latitude

C.C.

1985

Colour

M. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VI-1ABC-15AUC 280941

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

Prime wheel 215/60R16

Ling R: Long

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

13/4/18

D.O.I.

20/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/4 156 pass to Catherine, got injury. Action plan

RECEIVED 06 SEP 2018

Date/Time, File Pass to?

11/06/19 turner

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair: 12

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

64x15

1704960

50

30

1210

Report Format :

7P

Lump Sum / I.B.I. (\$

17100

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	17-04-2018	<b>Our Ref No.</b> D18002923MFSH
<b>Accident Date</b>	13-04-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC8879T	<b>Third Party Vehicle.</b> SHC5456A
<b>Survey Location</b>	NO. 2 ANG MO KIO STREET 63	
<b>Contact Person.</b>	CANDY KONG	
<b>Contact No.</b>	62876666/ 0	<b>Fax No.</b> 62571330
<b>Survey Type</b>	WITHOUT PREJUDICE: EST. COR PROVIDED \$74,728.36 (SJE)	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	TRANS-CAB AUTO SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SERENE	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002923MFSH

Date: 23 April 2018

Our Ref: CS/FCI18007317/Kqb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5456A .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 20/04/2018 at the premises of M/s TRANS CAB. and have the following to report:-

Workshop Estimate Amount	: S\$ 74,728.36 .
Revised Estimate Amount	: S\$ 21,349.20 .
"Check" Items Amount	: S\$ 5,591.29 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

**Description of Damage:**

The vehicle sustained damages  
at the o/s body.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	3878K
<b>Vehicle Details</b>	
Vehicle No.:	SHC5456A
Vehicle to be Exported:	Yes
Intended De-registration Date:	17 Apr 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C002335
Chassis No.:	VF1ABL15AUC280941
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	18 Dec 2014
First Registration Date:	18 Dec 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Dec 2022
PARF Rebate Amount:	\$9,373.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Dec 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,668.00
COE Rebate Amount:	\$30,139.00
<b>Total Rebate Amount:</b>	<b>\$39,512.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Apr 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/04/2018 19:11
Date Of Accident	13/04/2018 22:10
Exact Location Of Accident	HOLLAND ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5456A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L DCI (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	TAN CHOON HOW
NRIC No	S1209050A
Date Of Birth	15/08/1956
Occupation	OUTDOOR
Date Of Driving Pass	27/03/1980
Driving Experience	38 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91739782
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	32 WOODLANDS CRESCENT #14-04 CEDAR NORTHOAK
Postcode	738087
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TAMPINES NORTH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 461 TAMPINES STREET 44 #01-56 , POSTCODE: 520461 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7818999 - FAX NO: 67838603
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8879T
Vehicle Make/Model/Colour	
Details Of Properties	COMFORT TAXI
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name TAN CHOON HOW

Approximate Age

Injuries Sustain

Injured person in which vehicle? SHC5456A

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 16 APR 2018

Reporting Centre Personnel's Signature  
Name: JASMINE TAN SIEW KIM  
NRIC/FIN No.: S74056361





**SINGAPORE  
POLICE FORCE**



T/20180414/2089

1 of 3

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

Report No. T/20180414/2089

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 14/04/2018 13:51		Vide Report No.: D/20180413/0129		Station Diary No.: 10	
Name of Informant: TAN CHOON HOW		Address: 32 WOODLANDS CRESCENT #14-04 CEDAR NORTHOAK SINGAPORE 738087			
ID Type / ID No.: NRIC NO / S1209050A		Contact No.: Home/Office:		Mobile: 91739782	
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Male	Age: 61	Date of Birth: 15/08/1956	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Taxi Driver		Driving Licence Information: Class: 3		Date of Expiry:	

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 13/04/2018 22:10	Type of Location: T-Junction
Location:  HOLLAND ROAD  Along Holland Road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head On				Anyone conveyed by ambulance: Yes

SHC5456A	Car	RENAULT	LATITUDE 2.0L DCI AUTO D/AB 4DR	Red		0
SHC8879T	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Blue		0



**SINGAPORE  
POLICE FORCE**



T/20180414/2089

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

2 of 3

Report No. T/20180414/2089

**CONTINUATION OF REPORT**

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	TAN CHOON HOW	ID No.	S1209050A
Related Vehicle	SHC5456A (Car)	Contact No.	91739782
Hospital/Clinic	OEI FAMILY CLINIC	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	14/04/2018	Date Discharge	14/04/2018
No. of Days granted Medical Leave	04	Degree of Injury	NIL

**Brief Details.**

On 13/04/2018 at about 2210hrs, I was driving my taxi (SHC5456A) traveling straight along Holland Road. The traffic light was green in my favour.

Upon crossing the T-Junction, out of sudden there was a taxi (SHC8879T) which was travelling from the opposite direction wanting to make a right turn towards Sixth Avenue, collided on my taxi front right portion which resulted to damage. The taxi driver was injured. Due to the impact, my taxi surge forward and came to a complete stop but did not hit on any government property.

I did not manage to exchange particulars with him as he was injured. My taxi does not have in-car CCTV install. There is witness available at the accident scene. The witness namely Ben Dakleh and his wife, Hp: 94553275 alighted from their car and assisted to call for ambulance. The witness is willing to testify that the traffic light was green in my favour.

Shortly, SCDF doctor arrived and attended to the injured taxi driver. Moments later, the injured taxi driver was conveyed to hospital by ambulance. Traffic Police officer also arrived and conducted on scene investigation.

After the accident, I felt unwell and seek medical treatment at a private clinic. I was given 4 days of medical leave, from 14/04/2018 to 17/04/2018.



**SINGAPORE  
POLICE FORCE**



T/20180414/2089

Police Station Of Origin:  
Tampines North NPP  
461 Tampines Street 44 #01-56 SINGAPORE  
520461  
Tel No: 1800-7818999

3 of 3

Report No. T/20180414/2089

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 MUHAMMAD ISA BIN MD RASHID

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

14/04/2018 13:51

Officer In Charge Of Case:

TP / CITY SINGAPORE  
SI YE SINGAPORE  
Contact No.: 65476213



Classification Of Case:

Authentication Stamp

NP168

SIGNATURE

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5456A****AAD1804-151**

*Not Authored*  
*61 Sing & ?*  
*Book Value ?*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC 5456A**

VF1ABL15AUC280941

RENAULT

LATITUDE

13.4.2018

**FCIL**

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Tu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>bi</i> 181.75 ✓
1	BUMPER ABSORBER FRT	\$	<i>cm</i> 394.68 ✓
1	BUMPER RETAINER FRT RH	\$	<i>bi</i> 150.77 ✓
1	BUMPER SUPPORT FRT	\$	<i>sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>B</i> 914.08 ✓
1	HEADLAMP RH	\$	<i>Bu</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X <i>b</i>
1	FENDER PANEL FRT RH	\$	<i>B</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>cm</i> 278.84 ✓
1	FENDER BRACKET LOWER RH	\$	<i>R</i> 15.79 X <i>b</i>
1	FENDER INSULATOR RH	\$	<i>sn</i> 130.84 X
1	TOW COVER FRT	\$	<i>sn</i> 28.61 X
1	RADIATOR GRILLE	\$	<i>sn</i> 1,707.78 X
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>sn</i> 225.36 X
1	RADIATOR GRILLE FRAME	\$	<i>sn</i> 1,353.75 X
1	FRAME FULL SUPPORT PANEL	\$	<i>sn</i> 615.90 X
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79 X <i>b</i>
1	FRONT BRACE PANEL	\$	<i>R</i> 177.22 X <i>b</i>
1	HORN	\$	<i>sn</i> 314.17 X
1	HORN BRACKET	\$	<i>R</i> 40.45 X <i>b</i>
1	HEADLAMP RH	\$	<i>Repaired</i> 1,184.43 X
1	HEADLAMP PANEL FRT RH	\$	<i>sn</i> 152.15 X
1	SUBFRAME OUTER FRT	\$	<i>B</i> 2,652.45 ✓
1	SUBFRAME BRACKET OUTER RH	\$	<i>R</i> 92.36 X <i>b</i>
1	ENGINE UNDERTRAY	\$	<i>sn</i> 564.98 X

**Trans-cab Auto Services Pte Ltd****AAD1804-151**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5456A**

1	A/C CONDENSER	\$	Sm 2,020.37	X
1	SUBFRAME OUTER FRT L70Y	\$	Reptan 2,652.45	X
1	SUBFRAME INNER FRT L70Y	\$	R 2,284.80	X
1	SUBFRAME SUPPORT INNER L70Y	\$	R 92.36	X
1	SUBFRAME BRACKET OUTER LH L70Y	\$	R 92.36	X
1	SUBFRAME BRACKET OUTER RH L70Y	\$	R 92.36	X
1	SUBFRAME BRACKET INNER LH L70Y	\$	R 179.97	X
1	SUBFRAME BRACKET INNER RH L70Y	\$	R 179.97	X
1	ENGINE UNDERTRAY L70Y	\$	Reptan 564.98	X
1	LOWER ARM RH L70Y	\$	B 685.76	✓
1	KUNCKLE ARM RH L70Y	\$	B 846.98	—
1	KUNCKLE HUB+BEARING LH/RH L70Y	\$	B 497.69	✓
1	ABSORBER FRT RH L70Y	\$	B 360.54	—
1	ABSORBER MOUNTING KIT RHL70Y	\$	Sm 440.66	X
1	ABSORBER DUST COVER	\$	Sm 228.72	✓
1	STABILIZER BAR FRT L70Y	\$	Sm 604.65	X
1	STABILIZER LINK FRT L70Y	\$	B 117.22	✓
1	BRAKE CALIPER FRT RH L70Y	\$	Sm 656.94	X
1	BRAKE CALIPER BRACKET FRT RH L70Y	\$	Sm 555.12	X
1	BONNET	\$	R 1,941.63	✓
1	BONNET INSULATOR	\$	Sm 405.73	✓
1	BONNET STRUT LH	\$	Sm 88.61	✓
1	BONNET STRUT RH	\$	Sm 88.61	✓
1	BONNET HINGE LH	\$	R 348.31	✓
1	BONNET HINGE RH	\$	R 348.31	✓
1	BONNET LOCK	\$	R 305.48	✓
1	BONNET CABLE	\$	Sm 119.19	✓
1	BONNET CABLE COVER	\$	Sm 161.03	✓
1	BONNET SEAL OUTER	\$	Sm 92.36	✓
1	BONNET SEAL INNER	\$	Sm 157.28	✓
1	DOOR PANEL FRT RH	\$	B 2,844.66	✓
1	DOOR HINGE UPPER RH	\$	R 261.28	X
1	DOOR HINGE LOWER RH	\$	Or 300.55	✓
1	DOOR CHECK FRT RH	\$	Sm 194.77	X
1	DOOR LOCK FRT RH	\$	R 908.75	X
1	DOOR CATCH FRT RH	\$	R 131.23	X
1	DOOR HANDLE OUTER FRT RH	\$	Sm 477.76	X
1	DOOR HANDLE COVER FRT RH	\$	Sm 13.22	✓

**Trans-cab Auto Services Pte Ltd****AAD1804-151**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5456A**

1	DOOR HANDLE MODULE FRT RH	\$	SL 133.60	X
1	DOOR REGULATOR FRT RH	\$	N 505.19	X
1	DOOR REGULATOR MOTOR FRT RH	\$	SL 796.46	X
1	DOOR REGULATOR GUIDE FRT RH	\$	SL 120.97	X
1	DOOR PANEL REAR RH	\$	B 2,844.66	
1	DOOR GUIDE REAR RH	\$	SL 176.82	}
1	DOOR HINGE UPPER RH	\$	N 274.50	
1	DOOR HINGE LOWER RH	\$	N 300.55	
1	DOOR CHECK REAR LH/RH L70Y	\$	SL 203.06	
1	DOOR LOCK REAR RH	\$	N 908.75	
1	DOOR HANDLE OUTER REAR RH	\$	SL 126.49	
1	DOOR HANDLE CAP REAR RH	\$	SL 35.52	
1	DOOR HANDLE SEAL REAR RH	\$	SL 7.89	
1	DOOR HANDLE COVER REAR RH	\$	SL 13.22	
1	DOOR HANDLE MODULE REAR RH	\$	SL 133.60	
1	DOOR REGULATOR REAR RH	\$	N 1,135.10	}
1	DOOR REGULATOR MOTOR REAR RH	\$	N 893.75	
1	DOOR REGULATOR NUT REAR L70Y	\$	SL 12.43	
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	SL 6.31	
1	DOOR FINISHER REAR RH	\$	SL 423.10	
1	DOOR MOULDING REAR RH	\$	SL 176.82	
1	DOOR MOULDING CLIP L70Y	\$	N 5.92	
1	DOOR MOULDING SCREW L70Y	\$	SL 6.91	
1	DOOR CASING REAR RH	\$	SL 1,509.06	
1	DOOR WATER SHIELD REAR RH	\$	SL 30.39	
1	DOOR CASING CLIP	\$	N 12.63	}
1	DOOR CASING LIGHT L70Y	\$	SL 48.74	
1	DOOR FINISHER INNER REAR RH	\$	SL 323.44	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	SL 46.97	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	SL 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	SL 20.33	
1	DOOR FINISHER BRACKET INNER REAR RH	\$	SL 20.33	
1	DOOR GRAB HANDLE REAR RH	\$	SL 210.96	
1	DOOR BLIND REAR RH	\$	SL 741.80	
1	DOOR WHEATHESTRIIP REAR RH	\$	SL 410.66	
1	DOOR SEAL REAR RH	\$	SL 162.02	
1	DOOR GLASS RUNNER SEAL REAR RH	\$	SL 229.31	
1	DOOR WAIST SEAL OUTER REAR RH	\$	SL 334.69	



**Trans-cab Auto Services Pte Ltd**

AAD1804-151

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5456A

1	DOOR WAIST SEAL INNER REAR RH	\$	Sn 115.64	X
1	FENDER PANEL REAR RH	\$	Bz 3,299.13	✓
1	FENDER PANEL INNER TRIM REAR	\$	Sn 671.45	
1	WHEELARCH REAR RH	\$	Sn 543.47	
1	BUMPER COVER REAR	\$	N 1,108.46	
1	BUMPER LOWER REAR	\$	Sn 768.84	
1	BUMPER BRACKET CTR REAR	\$	Sn 113.47	
1	BUMEPR RETAINER LH REAR	\$	Sn 44.99	
1	BUMPER BEAM REAR	\$	N 777.52	
1	BUMPER BEAM BRACKET RH REAR	\$	N 225.95	
1	DOOR MIRROR ASSY RH	\$	Sn 1,483.40	
1	TAILLAMP RH	\$	Sn 552.55	
1	BUMPER COVER REAR	\$	Revised 1,108.46	
1	BUMPER LOWER REAR	\$	Sn 768.84	
1	BUMPER BRACKET CTR REAR	\$	Sn 113.47	
1	BUMEPR BRACKET SIDE RH REAR	\$	N 135.97	
1	BUMEPR RETAINER RH REAR	\$	Sn 44.99	
1	BUMPER REFLECTOR RH	\$	Sn 43.61	
1	BUMEPR BRACKET SIDE LH REAR	\$	Sn 135.97	
1	BUMEPR RETAINER LH REAR	\$	Sn 44.99	
1	BUMPER REFLECTOR LH	\$	Sn 43.61	
1	BUMPER BEAM REAR	\$	Revised 777.52	
1	BUMPER BEAM BRACKET LH REAR	\$	Sn 225.95	
1	BUMPER BEAM BRACKET RH REAR	\$	Sn 225.95	

\$	64,796.85
----	-----------

10% \$	6,479.68
--------	----------

\$	58,317.16
----	-----------

**Specical Nett**

1SET	BUMPER CLIP FRT	\$	N 66.00	✓
1	BUMPER BRACKET CLIP FRT LH	\$	N 12.00	X
1	BUMPER SUPPORT CLIP FRT LH	\$	N 10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	N 69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	N 70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	Sn 20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	Sn 30.00	X

**Trans-cab Auto Services Pte Ltd**

AAD1804-151

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5456A

1SET	WHEELARCH CLIP FRT LH	\$	na	30.50	✓
1	FRONT DOOR STICKER 'Trans-cab'	\$	na	80.00	60sn
1	FRONT DOOR STICKER 'Chassis'	\$	na	50.00	15sn
1	REAR DOOR STICKER '6555 3333'	\$	na	80.00	60sn
2	ABSORBER BOLT L70Y	\$	na	44.01	} X
2	ABSORBER NUT L70Y	\$	na	17.56	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR GUIDE SCREW	\$	na	10.85	
1	DOOR HINGE BOLT	\$	na	10.85	
1	DOOR HINGE NUT RH	\$	na	14.60	
1	DOOR CHECK BOLT	\$	na	22.69	
1	DOOR CHECK NUT	\$	na	3.75	
1	DOOR LOCK SCREW L70Y	\$	na	6.12	}
1	DOOR CATCH SCREW L70Y	\$	na	10.06	

<b>TOTAL</b>	<b>\$</b>	<b>681.20</b>
--------------	-----------	---------------

<b>TOTAL PARTS</b>	<b>\$</b>	<b>58,998.36</b>
--------------------	-----------	------------------

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	1200l
Putty and spray painting of the affected portion.	\$	5,000.00	1540l
To rust-proofing of the affected areas.	\$	170.00	120l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100l
To check steering geometry and computer wheel alignment	\$	220.00	60l
To transfer of tire, rim and on wheel balancing.	\$	170.00	20l
To Check Electrical Lighting Concerned.	\$	170.00	20l

**Trans-cab Auto Services Pte Ltd****AAD1804-151**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5456A**

To transfer of front fender fittings, attachment and perform water seepage test.	\$	nn 380.00 X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00 601
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00 601
Towing Fees.	\$	120.00 501
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 2501
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 }
To lift-up engine with gear box and refit.	\$	nn 440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	nn 440.00 X
To vacuum, replace, refix and recharge air condenser	\$	nn 380.00 X
To replace, refix and top up coolant for radiator	\$	nn 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	nn 170.00 X

**TOTAL \$ 15,730.00****LKK Auto Consultants Inc. Over All Total**

the Repairer of the following:

- To resurvey before/after spray painting
- To display LUMP SUM (REPAIR DAY)
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**74,728.36****20 DAYS****12 days**




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18007317/Kqbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-09-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 8879T	Veh. Inspected	SHC 5456A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002923MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	19/04/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	VF1ABL15AUC280941	Colour	METALLIC WHITE / RED	
Odometer	-	Steering	JAMMED	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	PRIMEWELL	9 mm	
L/H Front Tyre	215/60 R16	PRIMEWELL	9 mm	
R/H Rear Tyre	215/60 R16	LING LONG	8 mm	
L/H Rear Tyre	215/60 R16	LING LONG	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/04/2018	Inspection Date	20/04/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>12 Working Days</b>	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 7

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5456A**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER COVER FRT	TORN	1,259.42	1,259.42
1	BUMPER SPOILER FRT	DISTORTED	181.75	181.75
1	BUMPER ABSORBER FRT	CRACKED	394.68	394.68
1	BUMPER RETAINER FRT RH	DISTORTED	150.77	150.77
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE RH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	BENT	914.08	914.08
1	HEADLAMP RH	BROKEN	1,184.43	1,184.43
1	HEADLAMP PANEL FRT RH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT RH	BENT	783.83	783.83
1	WHEELARCH FRT RH	CRACKED	278.84	278.84
1	FENDER BRACKET LOWER RH	TO REPAIR SEE LABOUR	15.79	-
1	FENDER INSULATOR RH	SERVICEABLE	130.84	-
1	TOW COVER FRT	SERVICEABLE	28.61	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE 'RENAULT'	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	HORN	SERVICEABLE	314.17	-
1	HORN BRACKET	TO REPAIR SEE LABOUR	40.45	-
1	HEADLAMP RH	REPEATED	1,184.43	-
1	HEADLAMP PANEL FRT RH	REPEATED	152.15	-
1	SUBFRAME OUTER FRT	BENT	2,652.45	2,652.45

Report Ref No. CS/FCI18007317/Kqbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUBFRAME BRACKET OUTER RH	TO REPAIR SEE LABOUR	92.36	-
1	ENGINE UNDERTRAY	SERVICEABLE	564.98	-
1	A/C CONDENSER	SERVICEABLE	2,020.37	-
1	SUBFRAME OUTER FRT L70Y	REPEATED	2,652.45	-
1	SUBFRAME INNER FRT L70Y	TO REPAIR SEE LABOUR	2,284.80	-
1	SUBFRAME SUPPORT INNER L70Y	TO REPAIR SEE LABOUR	92.36	-
1	SUBFRAME BRACKET OUTER LH L70Y	TO REPAIR SEE LABOUR	92.36	-
1	SUBFRAME BRACKET OUTER RH L70Y	TO REPAIR SEE LABOUR	92.36	-
1	SUBFRAME BRACKET INNER LH L70Y	TO REPAIR SEE LABOUR	179.97	-
1	SUBFRAME BRACKET INNER RH L70Y	TO REPAIR SEE LABOUR	179.97	-
1	ENGINE UNDERTRAY L70Y	REPEATED	564.98	-
1	LOWER ARM RH L70Y	BENT	685.76	685.76
1	KNUCKLE ARM RH L70Y	BENT	846.98	846.98
1	KNUCKLE HUB + BEARING LH / RH L70Y	BENT	497.69	497.69
1	ABSORBER FRT RH L70Y	BENT	360.54	360.54
1	ABSORBER MOUNTING KIT RHL70Y	SERVICEABLE	440.66	-
1	ABSORBER DUST COVER	SERVICEABLE	228.72	-
1	STABILIZER BAR FRT L70Y	SERVICEABLE	604.65	-
1	STABILIZER LINK FRT L70Y	BENT	117.22	117.22
1	BRAKE CALIPER FRT RH L70Y	SERVICEABLE	656.94	-
1	BRAKE CALIPER BRACKET FRT RH L70Y	SERVICEABLE	555.12	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-

Report Ref No. CS/FCI18007317/Kqbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET LOCK	TO REPAIR SEE LABOUR	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	DOOR PANEL FRT RH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	261.28	-
1	DOOR HINGE LOWER RH	DISTORTED	300.55	300.55
1	DOOR CHECK FRT RH	SERVICEABLE	194.77	-
1	DOOR LOCK FRT RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR CATCH FRT RH	TO REPAIR SEE LABOUR	131.23	-
1	DOOR HANDLE OUTER FRT RH	SERVICEABLE	477.76	-
1	DOOR HANDLE COVER FRT RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE FRT RH	SERVICEABLE	133.60	-
1	DOOR REGULATOR FRT RH	TO REPAIR SEE LABOUR	505.19	-
1	DOOR REGULATOR MOTOR FRT RH	SERVICEABLE	796.46	-
1	DOOR REGULATOR GUIDE FRT RH	SERVICEABLE	120.97	-
1	DOOR PANEL REAR RH	BENT	2,844.66	2,844.66
1	DOOR GUIDE REAR RH	SERVICEABLE	176.82	-
1	DOOR HINGE UPPER RH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER RH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK REAR LH / RH L70Y	SERVICEABLE	203.06	-
1	DOOR LOCK REAR RH	TO REPAIR SEE LABOUR	908.75	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	126.49	-
1	DOOR HANDLE CAP REAR RH	SERVICEABLE	35.52	-
1	DOOR HANDLE SEAL REAR RH	SERVICEABLE	7.89	-
1	DOOR HANDLE COVER REAR RH	SERVICEABLE	13.22	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.60	-

Report Ref No. CS/FCI18007317/Kqbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR REGULATOR REAR RH	TO REPAIR SEE LABOUR	1,135.10	-
1	DOOR REGULATOR MOTOR REAR RH	TO REPAIR SEE LABOUR	893.75	-
1	DOOR REGULATOR NUT REAR L70Y	SERVICEABLE	12.43	-
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	SERVICEABLE	6.31	-
1	DOOR FINISHER REAR RH	SERVICEABLE	423.10	-
1	DOOR MOULDING REAR RH	SERVICEABLE	176.82	-
1	DOOR MOULDING CLIP L70Y	NOT NECESSARY	5.92	-
1	DOOR MOULDING SCREW L70Y	SERVICEABLE	6.91	-
1	DOOR CASING REAR RH	SERVICEABLE	1,509.06	-
1	DOOR WATER SHIELD REAR RH	SERVICEABLE	30.39	-
1	DOOR CASING CLIP	NOT NECESSARY	12.63	-
1	DOOR CASING LIGHT L70Y	SERVICEABLE	48.74	-
1	DOOR FINISHER INNER REAR RH	SERVICEABLE	323.44	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	46.97	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	20.33	-
1	DOOR FINISHER BRACKET INNER REAR RH	SERVICEABLE	20.33	-
1	DOOR GRAB HANDLE REAR RH	SERVICEABLE	210.96	-
1	DOOR BLIND REAR LH	SERVICEABLE	741.80	-
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	410.66	-
1	DOOR SEAL REAR RH	SERVICEABLE	162.02	-
1	DOOR GLASS RUNNER SEAL REAR RH	SERVICEABLE	229.31	-
1	DOOR WAIST SEAL OUTER REAR RH	SERVICEABLE	334.69	-
1	DOOR WAIST SEAL INNER REAR RH	SERVICEABLE	115.64	-
1	FENDER PANEL REAR RH	BENT	3,299.13	3,299.13
1	FENDER PANEL INNER TRIM REAR	SERVICEABLE	671.45	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	BUMPER COVER REAR	TO REPAIR SEE LABOUR	1,108.46	-
1	BUMPER LOWER REAR	SERVICEABLE	768.84	-
1	BUMPER BRACKET CTR REAR	SERVICEABLE	113.47	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-

Report Ref No. CS/FCI18007317/Kqbe2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BUMPER BEAM REAR	TO REPAIR SEE LABOUR	777.52	-
1	BUMPER BEAM BRACKET RH REAR	TO REPAIR SEE LABOUR	225.95	-
1	DOOR MIRROR ASSY RH	SERVICEABLE	1,483.40	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	BUMPER COVER REAR	REPEATED	1,108.46	-
1	BUMPER LOWER REAR	REPEATED	768.84	-
1	BUMPER BRACKET CTR REAR	REPEATED	113.47	-
1	BUMPER BRACKET SIDE LH REAR	REPEATED	135.97	-
1	BUMPER RETAINER RH REAR	REPEATED	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	SERVICEABLE	43.61	-
1	BUMPER BEAM REAR	REPEATED	777.52	-
1	BUMPER BEAM BRACKET LH REAR	REPEATED	225.95	-
1	BUMPER BEAM BRACKET RH REAR	REPEATED	225.95	-
	LESS 10% DISCOUNT		-6,479.68	-1,959.74
			58,317.16	17,637.70
	<b>SPECIAL NETT ITEMS</b>			
1	SET BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	SET BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	SERVICEABLE	20.00	-
2	FRAME FULL SUPPORT PANEL STUD(SN)	SERVICEABLE	30.00	-
1	SET WHEELARCH CLIP FRT LH (SN)	NECESSARY	30.50	30.50
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER "CHASSIS" (SN)	NECESSARY	50.00	15.00
1	REAR DOOR STICKER "6555 3333" (SN)	NECESSARY	80.00	60.00
2	ABSORBER BOLT L70Y (SN)	NOT NECESSARY	44.01	-

Report Ref No. CS/FCI18007317/Kqbe2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:6 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	ABSORBER NUT L70Y (SN)	NOT NECESSARY	17.56	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR GUIDE SCREW (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE BOLT (SN)	NOT NECESSARY	10.85	-
1	DOOR HINGE NUT RH (SN)	NOT NECESSARY	14.60	-
1	DOOR CHECK BOLT (SN)	NOT NECESSARY	22.69	-
1	DOOR CHECK NUT (SN)	NOT NECESSARY	3.75	-
1	DOOR LOCK SCREW L70Y (SN)	NOT NECESSARY	6.12	-
1	DOOR CATCH SCREW L70Y (SN)	NOT NECESSARY	10.06	-
			681.18	231.50
	<b>LABOUR</b>			
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF HEADLAMP PANEL FRT RH, FENDER BRACKET LOWER RH, FRAME FULL SUPPORT BRACKET, FRONT BRACE PANEL, HORN BRACKET, SUBFRAME BRACKET OUTER RH, SUBFRAME INNER FRT L70Y, SUBFRAME SUPPORT INNER L70Y, }		6,000.00	1,200.00
	SUBFRAME BRACKET OUTER LH L70Y, SUBFRAME BRACKET OUTER RH L70Y, SUBFRAME BRACKET INNER LH L70Y, SUBFRAME BRACKET INNER RH L70Y, BONNET, BONNET HINGE LH, BONNET HINGE RH, BONNET LOCK, DOOR HINGE UPPER RH, DOOR LOCK FRT RH, DOOR CATCH FRT RH, DOOR REGULATOR FRT RH, DOOR HINGE UPPER RH, DOOR HINGE LOWER RH, DOOR LOCK REAR RH, DOOR REGULATOR REAR RH, DOOR REGULATOR MOTOR REAR RH, BUMPER COVER REAR, BUMPER BEAM REAR AND BUMPER BEAM BRACKET RH REAR. }		-	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		5,000.00	1,540.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	120.00
	TO REMOVE AND REFIT INETRIOR FITTINGS, TRIMMINGS, GARNISH, FITTINGS AND OTHER, TO ENABLE REPAIR.		380.00	100.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.		170.00	20.00

Report Ref No. CS/FCI18007317/Kqbe2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:7 of 7

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		380.00	60.00
	TOWING FEES.		120.00	50.00
	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK. }		380.00	250.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR. }		380.00	-
	TO LIFT-UP ENGINE WITH GEAR BOX AND REFIT.	NOT NECESSARY	440.00	-
	TO REMOVE AND RENEW POWER STEERING PUMP, OIL COOLER PIPE AND FINAL CHECKING AND TESTING.	NOT NECESSARY	440.00	-
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR CONDENSER.	NOT NECESSARY	380.00	-
	TO REPLACE, REFILL AND TOP UP COOLANT FOR RADIATOR.	NOT NECESSARY	170.00	-
	TO VACUUM, REPLACE, REFILL AND RECHARGE AIR INTERCOOLER.	NOT NECESSARY	170.00	-
			15,730.00	3,480.00
	<b>GRAND TOTAL</b>		<b>74,728.34</b>	<b>21,349.20</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>17,100.00</b>

Report Ref No. CS/FCI18007317/Kqbe2

**KONG SENG CHEONG**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.