

21/03/2012

ASS. REC. BY:

REF: CS3 /ms617014790 / Lgbt¹² Special Instruction:

SUPERVISOR:

Richard

ASSIGNMENT (Office)

From (Person):

Fievel Foo

of

ms6

Date/Time: 19042018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJN 54567

Insured:

SJK 5079P

at Workshop m/s

Twincur

Tel:

68420051

of

2 Kak Bukit Ave 2 #01-17

Policy No:

D57770045QMY

Claim No:

511818

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28072017

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

01-08-2017

H.O.D. Endorsement:

Date/Time:

31042012 437pm

Person Contacted:

Flynn

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

Do Not include

SJN 54567 - NA/INC/17014547/C3

Dut: 280717

SJK 5079P - NA/ms617014653/k4

D.O.A: 280717

Dismantle Part: 02082017

After repair: 16082017

080717 219pm

Email to Fievel Foo thru Merimen.

US 9 200 h
 30% ~~20%~~ let me know

10 aq

2/5/18

Check MV

RECEIVED 04 MAY 2018

RECEIVED 07 MAY 2018

Surveillance **Richard**
mefman

REF: msu

Range

ASSIGNMENT

From: _____ Date: **01082017**

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: **STN 5456T**

at Workshop m/s **TwinCar**

of **2 Kaki Bukit Ave 2 #01-17**

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: **STN 5456T** Yr Regn: **2009 Feb 19**

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda Freed** c.c. **1496**

Colour: **Dark Red** A/C: Insured / Std / NI / NA

Sp. Reading: **116561** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **G13-1027015**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **195/60 R15**

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **6** mm

R/Bal. **6** mm

L/Bal. **6** mm

L/Bal. **6** mm

D.O.A. **28/7 08:30**

D.O.I. **1/8 1:15pm**

Survey held at **NSI**

Des. of Damages: FX / Rest / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair range \$8K - 10K (12 days)

[Signature]
11/9/2017

Date/Time, File Pass to?

☐ : Prel. Report

☐ : Final Report

1) **13092017**

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

Report Format : **PRS**

Lump Sum / J.B.I: (\$ _____)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jul 2017		31 Jul 2017 15:55 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	WONG MENG PONG, ID: S1393452E, Tel: +6590262257			[Created by insurer]					
Main Claimant:	MOHAMED SALIH SHAIK DAWOOD, ID: S7674191C								
Vehicle Reg. No.:	SJN5456T	Date of Loss:	28/07/2017 08:00 - :59 [101 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 524848	Policy/Cover Note No.:	D27792045QMY (Comprehensive) Coverage: 23/10/2016 - 22/10/2017						
Vehicle Reg. No. (Insured):	SJK5079P	Policy No. (Claimant):							
Repairer:	Twincar Automotive Pte Ltd (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17, 417921 Kaki Bukit - Tel: 6643 1316								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wen Yao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Richard Harjanto] ... [Final Rpt due 19/04/2018]								
Driver/Custodian (Insured):	WANG SHUMEI (), NRIC: S9144037G, Tel: +6590262257								
ASSOCIATED MAIL RECEIVED									
• MSIG_SG (17/04/2018): Report Send Back Alerts - SJN5456T (TP)			View All	Compose Case Mail					
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?
Sell it on Marketplace. Posting an advertisement is FREE!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

The Only R8 Ver.1 86 In SG.



Not For The Faint Hearted, Head
Turners Will Be Your New
Common Thing.
Direct Owner StarAd

KA-HUP

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

HOTLINE: 6741 9997 [View our cars](#)

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

7 vehicles

Honda Freed

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Honda Freed	Any	Any	2009	Any	Any	Any	Available



Honda Freed 1.5A G

\$23,800

\$10,660 /yr

14-Aug-2009

1,496 cc

104,000 km

MPV

Available

Well Maintained. Best Japan MPV With Low Insurance And Road Tax To Pay. 6 Months In House Warranty By Our Workshop. 24 Hours Free Towing Upon Emergency. Buy With No Worry. Hurry Call Now, Dont Miss It...

Posted: 02-May-2018 Tags: 2009 Honda Freed, Honda Freed, Honda, Freed, Used Honda

PREMIUM AD



Honda Freed 1.5A

\$17,777

\$9,470 /yr

28-May-2009

1,496 cc

148,799 km

MPV

Available

Drive With Assurance! Buy With Peace Of Mind From Accredited Company. Purchase And Enjoy 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistance And Replacement Vehicle Coverage. STA...

Sincere Motoring Pte Ltd

Posted: 30-Apr-2018 Tags: 2009 Honda Freed, Honda Freed, Honda, Freed, Used Honda

PREMIUM AD



Honda Freed 1.5A G

\$24,800

\$9,430 /yr

16-Dec-2009

1,496 cc

117,066 km

MPV

Available

Well Maintained And Regular Serviced By Owner. One Of The Most Fuel Efficient And Economical MPV. Good Condition. Clean And Spacious. Low Maintenance. Call Us For Viewing Now.

Posted: 26-Apr-2018 Tags: 2009 Honda Freed, Honda Freed, Honda, Freed, Used Honda



Honda Freed 1.5A G

\$26,200

\$10,660 /yr

22-Oct-2009

1,496 cc

152,991 km

MPV

Available

Top Choice Mid-Sized MPV With Sliding Doors, Freed 1.5A! Very Low Mileage Clocked Of 17800km Annually. Excellent Condition. Road Tax Till Oct 18. Nice And New Car Number. 100% Accident Free. Call Now!

Lake View Credit Pte Ltd

Posted: 24-Apr-2018 Tags: 2009 Honda Freed, Honda Freed, Honda, Freed, Used Honda

PREMIUM AD

Car Buying

Car Selling

Car Ownership

Buying a pre-owned car, but
Unsure of its Condition?

Car Aftermarket

On The Move

Lifestyle

Get STA Car Evaluation



Honda Freed 1.5A G

\$29,800

\$11,960 /yr

22-Dec-2009

1,496 cc

89,200 km

MPV

Available

Superbly Maintained By Owner, Low Mileage With Lowest Depreciation In The Market, 100% Accident Free, View To Believe, STA/Vicom Evaluation Welcome, Flexible Loan Available, High Trade-In For Your Car...

Posted: 18-Apr-2018 Tags: 2009 Honda Freed, Honda Freed, Honda, Freed, Used Honda



Honda Freed 1.5A G (New 5-yr COE)

\$42,800

\$8,560 /yr

05-Mar-2009

1,496 cc

118,000 km

MPV

Available

1 Owner! Very Low Mileage Done, Low Mileage With Lowest Depreciation In The Market, Super Well Maintained By Owner, 100% Accident Free, View To Believe, STA/VICOM Evaluation Welcome, Flexible Loan Available...

Posted: 18-Apr-2018 Tags: 2009 Honda Freed, Honda Freed, Honda, Freed, Used Honda



Honda Freed 1.5A G

\$26,438

\$10,590 /yr

02-Dec-2009

1,496 cc

118,438 km

MPV

Available

Posted: 14-Apr-2018 Tags: 2009 Honda Freed, Honda Freed, Honda, Freed, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

[Make](#)[Model](#)[Price](#)[Depreciation](#)[Reg Date](#)[Eng Cap](#)[Mileage](#)[Veh Type](#)[Status](#)[For old advertisements, view Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda Freed, Honda Freed Singapore, used Honda Freed Singapore, used Honda Freed, used vehicles Singapore or even buy used Honda Freed Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

[Compare](#)

PAR Automotive Consultancy

Regn No S2986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173. Fax : 645 36131.

Report No: 0059-18-TCA

12 March 2018

Mohamed Salih Shaik Dawood
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

INVOICE No. 0059-18-TCA


Vehicle No. SJN5456T

<u>S/NO</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$1,018.00
Total amount payable		<u>\$1,018.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



Report No: 0059-18-TCA

12 March 2018

ACCIDENT VEHICLE SURVEY REPORT

Mohamed Salih Shaik Dawood
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	SJN5456T	Odometer:	116561km
Make & Model:	Honda Freed 1.5G A	Colour:	Red
Chassis number:	GB31027015	Date of accident:	28/07/2017
Year of Regn.:	19/02/2009	Date inspected:	01/08/2017
Repairer at:	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	16/08/2017

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Bridgestone	5mm/Bridgestone	195/60R15
Rear:	4mm/Michelin	4mm/Michelin	195/60R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear and front portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
AIRCON CONDENSER	1	bent	747.80	747.80 <i>svlx</i>
AIRCON CONDENSER FAN BLADE	1	warped	46.50	46.50
AIRCON CONDENSER FAN COWLING	1	distorted	91.00	91.00
AIRCON CONDENSER FAN MOTOR	1	shorted	233.60	233.60
AIRCON CONDENSER UPPER BRACKET	1	bent	18.50	18.50
AIRCON CONDENSER UPPER RUBBER BUSH	1	distorted	16.50	16.50
AIRCON CONTROL PANEL GARNISH	1	reuse	185.00	0.00
FRONT BONNET	1	repair	662.80	0.00
FRONT BONNET MECHANISM LOCK	1	bent	93.40	93.40 <i>Rx</i>
FRONT BONNET RUBBER GUIDE STOPPER L/R	2	reuse	25.00	0.00
FRONT BONNET WEATHERSTRIP	1	reuse	15.00	0.00
FRONT BUMPER	1	squashed	988.00	988.00
FRONT BUMPER LOWER COVER	1	deformed	44.90	44.90
FRONT BUMPER REINFORCEMENT	1	bent	233.70	233.70
FRONT BUMPER SIDE RETAINER L/R	2	necessary	44.00	44.00
FRONT BUMPER TOW HOOK COVER	1	deformed	20.00	20.00
FRONT GRILLE	1	fractured	210.30	210.30
FRONT GRILLE 'H' LOGO EMBLEM	1	necessary	23.40	23.40
FRONT GRILLE CENTRE MOULDING L/R	2	fractured	76.00	76.00
FRONT GRILLE LOWER MOULDING	1	fractured	63.00	63.00
FRONT GRILLE UPPER MOULDING	1	fractured	65.90	65.90
FRONT HEADLAMP L/R	2	fractured	1,760.00	1,760.00
FRONT HEADLAMP LOWER BRACKET L/R	2	bent	94.00	94.00
FRONT HORN	1	distortion	48.60	48.60 <i>svlx</i>
FRONT SUPPORT PANEL	1	bent	663.30	663.30 <i>Rx</i>
RADIATOR (AUTO)	1	bent	1,302.90	1,302.90
RADIATOR FAN BLADE	1	warped	54.80	54.80
RADIATOR FAN COWLING	1	distorted	89.30	89.30
RADIATOR FAN MOTOR	1	shorted	309.80	309.80
RADIATOR LOWER HOSE	1	deformed	28.00	28.00
RADIATOR SPARE TANK	1	reuse	55.60	0.00
RADIATOR UPPER BRACKET L/R	2	reuse	45.00	0.00
RADIATOR UPPER BRACKET RUBBER BUSH L/R	2	distorted	25.00	25.00
RADIATOR UPPER HOSE	1	deformed	28.00	28.00
RADIO CONSOLE GARNISH	1	distorted	215.00	215.00
RADIO PLAYER UNIT	1	shorted	185.00	185.00
REAR BUMPER	1	squashed	1,177.00	1,177.00
REAR BUMPER END SEAL COVER L/R	2	deformed	265.00	265.00
REAR BUMPER INNER GARNISH L/R	2	deformed	74.80	74.80
REAR BUMPER SIDE RETAINER L/R	2	necessary	56.00	56.00
REAR BUMPER TOW HOOK COVER	1	warped	28.00	28.00
REAR END LOWER PANEL	1	bent	120.00	120.00

REAR END PANEL	1	buckled	580.30	580.30	2x
REAR END PANEL INNER TOP GARNISH	1	fractured	108.50	108.50	SUCX
REAR EXHAUST GASKET	1	necessary	34.50	34.50	SUCX
REAR EXHAUST RUBBER MOUNTING	2	distorted	33.00	33.00	SUCX
REAR EXHAUST SILENCER BOX	1	bent	820.00	820.00	SUCX
REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	2	deformed	600.00	600.00	2x
REAR FLOOR PANEL	1	repair	1,419.00	0.00	
REAR TAILGATE	1	buckled	1,460.30	1,460.30	
REAR TAILGATE 'FREED' EMBLEM	1	necessary	42.10	42.10	
REAR TAILGATE 'H' LOGO EMBLEM	1	necessary	37.00	37.00	
REAR TAILGATE DAMPER L/R	2	bent	280.00	280.00	
REAR TAILGATE HINGES L/R	2	bent	75.20	75.20	
REAR TAILGATE INNER PULL GARNISH	1	warped	85.60	85.60	
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	1	fractured	206.80	206.80	
REAR TAILGATE MECHANISM LOCK	1	bent	232.10	232.10	
REAR TAILGATE MECHANISM LOCK STRIKER	1	bent	27.50	27.50	
REAR TAILGATE OUTER GARNISH	1	fractured	287.30	287.30	
REAR TAILGATE OUTER HANDLE	1	distorted	72.30	72.30	
REAR TAILGATE RUBBER GUIDE STOPPER L/R	2	deformed	33.00	33.00	
REAR TAILGATE WEATHERSTRIP	1	deformed	198.00	198.00	
REAR TAILGATE WINDSCREEN SIDE MOULDING L/R	2	reuse	111.60	0.00	
REAR TAILGATE WINDSCREEN TOP MOULDING	1	necessary	135.00	135.00	
REAR TAILGATE WIPER MOTOR	1	shorted	280.00	280.00	
REAR TAILGATE WIRE HARNESS - SET	1	reuse	320.00	0.00	
REAR TAILLAMP BACK RUBBER GASKET L/R	2	reuse	47.00	0.00	
REAR TAILLAMP INNER PANEL L/R	2	repair	420.60	0.00	
REAR TAILLAMP L/R	2	fractured	916.20	916.20	
WIPER TANK	1	deformed	108.00	108.00	SUCX
WIPER TANK MOTOR	1	shorted	280.00	280.00	SUCX

Subtotal before discount S\$ 19,780.30 S\$ 16,473.70

Percentage discount 20% and 20%

S\$ 3,956.06 S\$ 3,294.74

Sub-total 1 S\$ 15,824.24 S\$ 13,178.96

FRONT BUMPER CLIPS - SET	1	necessary	50.00	50.00	
FRONT GRILLE CLIPS - SET	1	necessary	30.00	30.00	
FRONT NUMBER PLATE	1	bent	25.00	25.00	
FRONT NUMBER PLATE HOLDER	1	bent	50.00	50.00	
RADIATOR COOLANT - BOT	1	necessary	80.00	80.00	
REAR BUMPER CLIPS - SET	1	necessary	50.00	50.00	
REAR BUMPER REVERSE SENSOR - SET	1	shorted	350.00	350.00	
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	necessary	30.00	30.00	
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	2	necessary	100.00	100.00	NNX
REAR FLOOR PANEL INSULATOR MAT	1	necessary	500.00	500.00	NNX
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	1	necessary	60.00	60.00	
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	necessary	30.00	30.00	

REAR TAILGATE WINDSCREEN SEALANT
REAR TAILLAMP CLIPS L/R - SET

1	necessary	100.00	100.00
2	necessary	60.00	60.00
Subtotal before discount		<u>S\$ 1,515.00</u>	<u>S\$ 1,515.00</u>
Sub-total 2		S\$ 1,515.00	S\$ 1,515.00
Parts-total		<u>S\$ 17,339.24</u>	<u>S\$ 14,693.96</u>

LABOUR

To remove, change air con parts, vacuums, refill air con gas.	180.00	150.00	120
To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.	200.00	140.00	120
To remove, reinstall tailgate windscreen	300.00	120.00	✓
To remove, reinstall rear suspension and undercarriage part. (to FR)	400.00	0.00	
To road test driving, check and resetting wheel alignments system.	180.00	180.00	120
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	60.00	✓
To send vehicle for cleaning, shampoo, upholstery and cushion seat.	200.00	0.00	
Dismantle and testing of sound system	200.00	150.00	100
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,800.00	1,400.00	1200
To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.	1,300.00	1,000.00	800
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	180.00	120.00	NN x
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	3,800.00	2,640.00	1800
To mount vehicle on to Car 'O' Liner.	400.00	400.00	NN x
To apply anti-rust chemical on repaired and replaced panel.	120.00	120.00	80
Labour Total		<u>S\$ 9,400.00</u>	<u>S\$ 6,480.00</u>
Parts & Labour Total		<u>S\$ 26,739.24</u>	<u>S\$ 21,173.96</u>

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 18,000.00
and the recommended number of working days for the repairs is within 19 day(s).


B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jul 2017		31 Jul 2017 15:55 Edit Adj Rpt	S\$9,200.00 Edit Estimates	S\$9,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS [Created by insurer]																								
Insured: WONG MENG PONG , ID: S1393452E, Tel: +6590262257																								
Main Claimant: MOHAMED SALIH SHAIK DAWOOD , ID: S7674191C																								
Vehicle Reg. No.:	SJN5456T	Date of Loss:	28/07/2017 08:00 - :59 [101 Months and 9 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / 524848	Policy/Cover Note No.:	D27792045QMY (Comprehensive) Coverage: 23/10/2016 - 22/10/2017																					
Vehicle Reg. No. (Insured):	SJK5079P	Policy No. (Claimant):																						
		Excess:																						
Repairer: Twincar Automotive Pte Ltd (HQ) 2 KAKI BUKIT AVEUNE 2 #01-17, 417921 Kaki Bukit - Tel:																								
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]																								
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Richard Harjanto] ... [Final Rpt due 19/04/2018]																								
Driver/Custodian (Insured): WANG SHUMEI () , NRIC: S9144037G, Tel: +6590262257																								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail																				
MSIG_SG (17/04/2018): Report Send Back Alerts - SJN5456T (TP)																								
ALL ASSOCIATED TASKS																								
View All Search Tasks Create New Task Complete <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

*SJN5456T (524848)
[SJK5079P]
TP
MOHAMED SALIH SHAIK DAWOOD
Jul 28 2017 8:00AM
[WONG MENG PONG]
Twincar Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)					Thumbnail		Print	
1	31/07/17 14:15	Accident Statement From: SC - Reg. No: SJK5079P, Claimant: WONG MENG PONG					 Load HTM			
							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	08/09/17 14:22	General View					 Load JPG		☒	
2	08/09/17 14:22	General View					 Load JPG		☒	
3	08/09/17 14:22	General View					 Load JPG		☒	
4	08/09/17 14:22	General View					 Load JPG		☒	
5	08/09/17 14:22	General View					 Load JPG		☒	
6	08/09/17 14:22	General View					 Load JPG		☒	
7	08/09/17 14:22	General View					 Load JPG		☒	
8	08/09/17 14:22	General View					 Load JPG		☒	
9	08/09/17 14:22	General View					 Load JPG		☒	
10	08/09/17 14:22	General View					 Load JPG		☒	
11	08/09/17 14:22	General View					 Load JPG		☒	
12	08/09/17 14:22	General View					 Load JPG		☒	
13	08/09/17 14:22	General View					 Load JPG		☒	
14	08/09/17 14:22	General View					 Load JPG		☒	
15	08/09/17 14:22	General View					 Load JPG		☒	
16	08/09/17 14:22	General View					 Load JPG		☒	
17	08/09/17 14:22	General View					 Load JPG		☒	
18	08/09/17 14:22	General View					 Load JPG		☒	
19	08/09/17 14:22	General View					 Load JPG		☒	
20	08/09/17 14:22	General View					 Load JPG		☒	
21	08/09/17 14:22	General View					 Load JPG		☒	
22	08/09/17 14:22	General View					 Load JPG		☒	
23	08/09/17 14:22	General View					 Load JPG		☒	
24	08/09/17 14:22	General View					 Load JPG		☒	
25	08/09/17 14:22	General View					 Load JPG		☒	
26	08/09/17 14:22	General View					 Load JPG		☒	
27	08/09/17 14:22	General View					 Load JPG		☒	
28	08/09/17 14:22	General View					 Load JPG		☒	
29	08/09/17 14:22	General View					 Load JPG		☒	
30	08/09/17 14:22	Chassis Number					 Load JPG		☒	
31	08/09/17 14:22	Odometer Reading					 Load JPG		☒	
32	08/09/17 14:22	General View					 Load JPG		☒	
33	08/09/17 14:22	General View					 Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	08/09/17 14:22	General View	 Load JPG	☒
35	08/09/17 14:22	General View	 Load JPG	☒
36	08/09/17 14:22	General View	 Load JPG	☒
37	08/09/17 14:22	General View	 Load JPG	☒
38	08/09/17 14:22	General View	 Load JPG	☒
39	08/09/17 14:22	General View	 Load JPG	☒
40	08/09/17 14:22	General View	 Load JPG	☒
41	08/09/17 14:22	General View	 Load JPG	☒
42	08/09/17 14:22	General View	 Load JPG	☒
43	08/09/17 14:22	General View	 Load JPG	☒
44	08/09/17 14:22	General View	 Load JPG	☒
45	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
46	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
47	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
48	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
49	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
50	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
51	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
52	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
53	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
54	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
55	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
56	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
57	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
58	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
59	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
60	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
61	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
62	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
63	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
64	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
65	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
66	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
67	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
68	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
69	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
70	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
71	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
72	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
73	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
74	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
75	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
76	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
77	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
78	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
79	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
80	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
81	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
82	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
83	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
85	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
86	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
87	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
88	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
89	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
90	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
91	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
92	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
93	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
94	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
95	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
96	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
97	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
98	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
99	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
100	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
101	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
102	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
103	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
104	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
105	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
106	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
107	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
108	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
109	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
110	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
111	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
112	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
113	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
114	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
115	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
116	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
117	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
118	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
119	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
120	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
121	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
122	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
123	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
124	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
125	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
126	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
127	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
128	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
129	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
130	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
131	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
132	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
133	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
134	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
135	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
136	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
137	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
138	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
139	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
140	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
141	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
142	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
143	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
144	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
145	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
146	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
147	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
148	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
149	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
150	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
151	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
152	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
153	08/09/17 14:26	Photographs of Damaged Parts	 Load JPG	☒
154	08/09/17 14:26	Photo After Spray	 Load JPG	☒
155	08/09/17 14:26	Photo After Spray	 Load JPG	☒
156	08/09/17 14:26	Photo After Spray	 Load JPG	☒
157	08/09/17 14:26	Photo After Spray	 Load JPG	☒
158	08/09/17 14:26	Photo After Spray	 Load JPG	☒
159	08/09/17 14:26	Photo After Spray	 Load JPG	☒
160	08/09/17 14:26	Photo After Spray	 Load JPG	☒
161	08/09/17 14:26	Photo After Spray	 Load JPG	☒
162	08/09/17 14:26	Photo After Spray	 Load JPG	☒
163	08/09/17 14:26	Photo After Spray	 Load JPG	☒
164	08/09/17 14:26	Photo After Spray	 Load JPG	☒
165	08/09/17 14:26	Photo After Spray	 Load JPG	☒
166	08/09/17 14:26	Photo After Spray	 Load JPG	☒
167	08/09/17 14:26	Photo After Spray	 Load JPG	☒
168	08/09/17 14:26	Photo After Spray	 Load JPG	☒
169	08/09/17 14:26	Photo After Spray	 Load JPG	☒
170	08/09/17 14:26	Photo After Spray	 Load JPG	☒
171	08/09/17 14:26	Photo After Spray	 Load JPG	☒
172	08/09/17 14:26	Photo After Spray	 Load JPG	☒
173	08/09/17 14:26	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	31/07/17 14:15	TPD SJN5456T GIA REPORT. From: SC - Reg. No: SJK5079P, Claimant: WONG MENG PONG	 Load PDF	
2	31/07/17 14:19	PRI From Twincar Automotive	 Load PDF	
3	31/07/17 16:04	Survey Disagree on SJE	 Load PDF	
4	10/04/18 13:50	SURVEY REPORT & PHOTOS	 Load PDF	
5	10/04/18 13:51	Re-inspection & Photos	 Load PDF	
6	10/04/18 13:51	Reinspection Photos	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/18 10:09	PRS Invoice	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG17014790/LQBE2-1

Date: 07/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: D27792045QMY
 Claimant Vehicle No: SJN5456T Insured Vehicle No: SJK5079P
 Date of Loss: 28/07/2017 Nature of Claim: TP Claim No: 524848

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN5456T**
 Make & Model: HONDA FREED, 1.5 G (A) Engine No: L15A2327349
 Reg. Date: 19/02/2009 (Man. Year: 2008) Chassis No: GB31027015
 Colour: Red Odometer: 116561 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,339.24	8,684.92	8,654.32	49.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,400.00	4,520.00	4,880.00	51.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,739.24	13,204.92	13,534.32	50.62
Approved Total (Overridden) (S\$)		9,200.00		
(S\$)	26,739.24	9,200.00	17,539.24	65.59
+ GST 7.00/7.00% (S\$)	1,871.75	644.00	1,227.75	65.59
Nett Amount (S\$)	28,610.99	9,844.00	18,766.99	65.59

INSPECTION

Date of Assignment: 31/07/2017
 Date Inspected: 01/08/2017 Inspected At: Twincar Automotive Pte Ltd (HQ)
 2 KAKI BUKIT AVEUNE 2 #01-17
 Singapore 417921
 Estimated Period of Repair: 10.0 days

Adjuster: Richard Harjanto

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts:	M1-MPV	HONDA FREED 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN5456T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIRCON CONDENSER	Serviceable	747.80 FL	*- FL
2	1		*AIRCON CONDENSER FAN BLADE	Serviceable	46.50 FL	*- FL
3	1		*AIRCON CONDENSER FAN COWLING	Serviceable	91.00 FL	*- FL
4	1		*AIRCON CONDENSER FAN MOTOR	Serviceable	233.60 FL	*- FL
5	1		*AIRCON CONDENSER UPPER BRACKET	Serviceable	18.50 FL	*- FL
6	1		*AIRCON CONDENSER UPPER RUBBER BUSH	Serviceable	16.50 FL	*- FL
7	1		*AIRCON CONTROL PANEL GARNISH	Reuse	185.00 FL	*- FL
8	1		*FRONT BONNET	Repair	662.80 FL	*- FL
9	1		*FRONT BONNET MECHANISM LOCK	Repair	93.40 FL	*- FL
10	2		*FRONT BONNET RUBBER GUIDE STOPPER L/R	Reuse	25.00 FL	*- FL
11	1		*FRONT BONNET WEATHERSTRIP	Reuse	15.00 FL	*- FL
12	1		*FRONT BUMPER	Squashed	988.00 FL	*988.00 FL
13	1		*FRONT BUMPER LOWER COVER	Deformed	44.90 FL	*44.90 FL
14	1		*FRONT BUMPER REINFORCEMENT	Bent	233.70 FL	*233.70 FL
15	2		*FRONT BUMPER SIDE RETAINER L/R	Necessary	44.00 FL	*44.00 FL
16	1		*FRONT BUMPER TOW HOOK COVER	Deformed	20.00 FL	*20.00 FL
17	1		*FRONT GRILLE	Fractured	210.30 FL	*210.30 FL
18	1		*FRONT GRILLE H LOGO EMBLEM	Necessary	23.40 FL	*23.40 FL
19	2		*FRONT GRILLE CENTRE MOULDING L/R	Fractured	76.00 FL	*76.00 FL
20	1		*FRONT GRILLE LOWER MOULDING	Fractured	63.00 FL	*63.00 FL
21	1		*FRONT GRILLE UPPER MOULDING	Fractured	65.90 FL	*65.90 FL
22	2		*FRONT HEADLAMP L/R	Fractured	1,760.00 FL	*1,760.00 FL
23	2		*FRONT HEADLAMP LOWER BRACKET L/R	Bent	94.00 FL	*94.00 FL
24	1		*FRONT HORN	Serviceable	48.60 FL	*- FL
25	1		*FRONT SUPPORT PANEL	Repair	663.30 FL	*- FL
26	1		*RADIATOR (AUTO)	Serviceable	1,302.90 FL	*- FL
27	1		*RADIATOR FAN BLADE	Serviceable	54.80 FL	*- FL
28	1		*RADIATOR FAN COWLING	Serviceable	89.30 FL	*- FL
29	1		*RADIATOR FAN MOTOR	Serviceable	309.80 FL	*- FL
30	1		*RADIATOR LOWER HOSE	Serviceable	28.00 FL	*- FL
31	1		*RADIATOR SPARE TANK	Serviceable	55.60 FL	*- FL
32	2		*RADIATOR UPPER BRACKET L/R	Serviceable	45.00 FL	*- FL
33	2		*RADIATOR UPPER BRACKET RUBBER BUSH L/R	Serviceable	25.00 FL	*- FL
34	1		*RADIATOR UPPER HOSE	Serviceable	28.00 FL	*- FL
35	1		*RADIO CONSOLE GARNISH	Serviceable	215.00 FL	*- FL
36	1		*RADIO PLAYER UNIT	Serviceable	185.00 FL	*- FL
37	1		*REAR BUMPER	Squashed	1,177.00 FL	*1,177.00 FL
38	2		*REAR BUMPER END SEAL COVER L/R	Deformed	265.00 FL	*265.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	2		*REAR BUMPER INNER GARNISH L/R	Deformed	74.80 FL	*74.80 FL
40	2		*REAR BUMPER SIDE RETAINER L/R	Necessary	56.00 FL	*56.00 FL
41	1		*REAR BUMPER TOW HOOK COVER	Warped	28.00 FL	*28.00 FL
42	1		*REAR END LOWER PANEL	Bent	120.00 FL	*120.00 FL
43	1		*REAR END PANEL	Repair	580.30 FL	*- FL
44	1		*REAR END PANEL INNER TOP GARNISH	Serviceable	108.50 FL	*- FL
45	1		*REAR EXHAUST GASKET	Serviceable	34.50 FL	*- FL
46	2		*REAR EXHAUST RUBBER MOUNTING	Serviceable	33.00 FL	*- FL
47	1		*REAR EXHAUST SILENCER BOX	Serviceable	820.00 FL	*- FL
48	2		*REAR FENDER INNER UPHOLSTERY TRIM GARNISH L/R	Serviceable	600.00 FL	*- FL
49	1		*REAR FLOOR PANEL	Repair	1,419.00 FL	*- FL
50	1		*REAR TAILGATE	Buckled	1,460.30 FL	*1,460.30 FL
51	1		*REAR TAILGATE FREED EMBLEM	Necessary	42.10 FL	*42.10 FL
52	1		*REAR TAILGATE H LOGO EMBLEM	Necessary	37.00 FL	*37.00 FL
53	2		*REAR TAILGATE DAMPER L/R	Bent	280.00 FL	*280.00 FL
54	2		*REAR TAILGATE HINGES L/R	Bent	75.20 FL	*75.20 FL
55	1		*REAR TAILGATE INNER PULL GARNISH	Warped	85.60 FL	*85.60 FL
56	1		*REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	Fractured	206.80 FL	*206.80 FL
57	1		*REAR TAILGATE MECHANISM LOCK	Bent	232.10 FL	*232.10 FL
58	1		*REAR TAILGATE MECHANISM LOCK STRIKER	Bent	27.50 FL	*27.50 FL
59	1		*REAR TAILGATE OUTER GARNISH	Fractured	287.30 FL	*287.30 FL
60	1		*REAR TAILGATE OUTER HANDLE	Distorted	72.30 FL	*72.30 FL
61	2		*REAR TAILGATE RUBBER GUIDE STOPPER L/R	Deformed	33.00 FL	*33.00 FL
62	1		*REAR TAILGATE WEATHERSTRIP	Deformed	198.00 FL	*198.00 FL
63	2		*REAR TAILGATE WINDSCREEN SIDE MOULDING L/R	Reuse	111.60 FL	*- FL
64	1		*REAR TAILGATE WINDSCREEN TOP MOULDING	Necessary	135.00 FL	*135.00 FL
65	1		*REAR TAILGATE WIPER MOTOR	Shorted	280.00 FL	*280.00 FL
66	1		*SET REAR TAILGATE WIRE HARNESS	Reuse	320.00 FL	*- FL
67	2		*REAR TAILLAMP BACK RUBBER GASKET L/R	Reuse	47.00 FL	*- FL
68	2		*REAR TAILLAMP INNER PANEL L/R	Repair	420.60 FL	*- FL
69	2		*REAR TAILLAMP L/R	Fractured	916.20 FL	*916.20 FL
70	1		*WIPER TANK	Serviceable	108.00 FL	*- FL
71	1		*WIPER TANK MOTOR	Serviceable	280.00 FL	*- FL
72	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
73	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
74	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
75	1		*FRONT NUMBER PLATE HOLDER	Bent	50.00 FS	*50.00 FS
76	1		*BOT RADIATOR COOLANT	Necessary	80.00 FS	*80.00 FS
77	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
78	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	350.00 FS	*350.00 FS
79	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
80	2		*SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R	Not Necessary	100.00 FS	*- FS
81	1		*REAR FLOOR PANEL INSULATOR MAT	Not Necessary	500.00 FS	*- FS
82	1		*SET REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS	Necessary	60.00 FS	*60.00 FS
83	1		*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	30.00 FS	*30.00 FS
84	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*100.00 FS
85	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 21,295.30 10,627.40

- List Item Discount on L Items 20.00/20.00% (\$\$) 3,956.06 1,942.48

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	17,339.24 8,684.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHANGE AIR CON PARTS, VACUUMS, REFILL AIR CON GAS	New	180.00	120.00
2	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, RESETTNG HEADLAMP FOCUSING AND REWIRE FOR PARKING SENSOR	New	200.00	120.00
3	TO REMOVE, REINSTALL TAILGATE WINDSCREEN	New	300.00	120.00
4	TO REMOVE, REINSTALL REAR SUSPENSION AND UNDERCARRIAGE PART (TO FR)	New	400.00	0.00
5	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM	New	180.00	120.00
6	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR)	New	140.00	60.00
7	TO SEND VEHICLE FOR CLEANING, SHAMPOO, UPHOLSTERY AND CUSHION SEAT	New	200.00	0.00
8	DISMANTLE AND TESTING OF SOUND SYSTEM	New	200.00	100.00
9	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER	New	1,800.00	1,200.00
10	TO RE-SPRAY PAINTING ON THE FRONT BONNET, FRONT SUPPORT PANEL, FRONT FENDER (L/R) AND FRONT BUMPER	New	1,300.00	800.00
11	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT	New	180.00	0.00
12	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	3,800.00	1,800.00
13	TO MOUNT VEHICLE ON TO CAR O LINER	New	400.00	0.00
14	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	80.00
Gross Labour Cost (S\$)			9,400.00	4,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >