

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

17/04/18
(Tuesday)

12/04/2018

Owner: SKYWAY MOTOR PTE LTD

Not Authorized
11 Days 8?
Resurvey After Paint
3 days

ESTIMATE TO REPAIR TOYOTA AXIO - SLN6275T

1pc	rear tailgate
1pc	rear tailgate "COROLLA" emblem
1pc	rear tailgate "AXIO" emblem
1pc	rear tailgate "TOYOTA" logo
1pc	rear tailgate "G" emblem
2pcs	rear taillamp @\$374.75
2pcs	rear taillamp lower bracket @\$132.10
1pc	rear bumper
2pcs	rear bumper side retainer @\$132.10
1pc	rear bumper LH reflector
1pc	rear end panel
1pc	rear end panel inner garnish

<i>R</i>	\$ 1,218.45	<i>X</i>
<i>Re</i>	\$ 83.10	<i>—</i>
<i>Re</i>	\$ 83.90	<i>—</i>
<i>Re</i>	\$ 61.10	<i>—</i>
<i>Re</i>	\$ 63.90	<i>—</i>
<i>Re</i>	\$ 749.50	<i>X</i>
<i>Re</i>	\$ 264.20	<i>X</i>
<i>Bu</i>	\$ 561.60	<i>—</i>
<i>Re</i>	\$ 264.20	<i>X</i>
<i>Re</i>	\$ 141.45	<i>X</i>
	\$ 781.10	<i>?</i>
<i>Re</i>	\$ 281.50	<i>—</i>

less 25%

\$ 4,554.00
\$ 1,138.50
<u>\$ 3,415.50</u>

1set rear parking sensor

Scp/Shop s.nett \$ 280.00 *2000*

wiring
tuffkote
spray painting
labour charges
Total

\$ 50.00	<i>151</i>
<i>Re</i> \$ 60.00	<i>X</i>
\$ 800.00	<i>400</i>
\$ 900.00	<i>400</i>
<u>\$ 5,505.50</u>	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: