

ASS. REC. BY:

REF: CS/FCL18007366/Dvbe2

Special Instruction:

Survivor:

ASSIGNMENT (Office)From (Person): DUS Karen Tan of FCL Date/Time: 19042018 3:44pm

Estimated Cost: _____ Bill to: _____

OD (T) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHB 2219T Insured: SHD 3526Pat Workshop m/s: Chunni Motor Tel: 65425119of Blk 10 Amk Ind Park 2A #03-19Policy No: _____ Claim No: D18007958MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 17042018
(Client's Record)CA / REV / REP. / REV 24 HRS 'wpi' 20042018 H.O.D. Endorsement: _____Date/Time: 19042018 4:34pm Person Contacted: Lynn Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 2219T - CS/FCL17010317 / Ugh3m2 DA: 260517
	SHD 3526P - CS/FCL16001428 / D DA: 270515
23/4/18	Email preli revised to FCL

REF:

ASSIGNMENT

COE Aug 2024

From _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 15 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 2219T Yr Regn: 2016 AugType: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 293419 T/Radio: Insured / Std / NI / NAEngi No: D4FDGU662182C/No: KMHLB41UMGU092607Gen. Cond: Good / Fair / Poor / BurntSteering: Inter / Jammed / Leaked / Burnt orBrake: Inter / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 111

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Henkark

Front

Rear

R/Bal: 5 mm R/Bal: 5 mmL/Bal: 5 mm L/Bal: 5 mmD.O.A: 17/04/2018 D.O.I: 20/04/2018Survey held at Chunni AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front 4 H/S Rn

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

First Rep SHD 3526P19/04/18 To alert insurance repair cost exceed 40K
hurry L/S 40K with 15 days of m. (Recd 23, 27.76, 3790)

RECEIVED 20 JUN 2018

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 20/6- typistReport Format: CWSLump Sum / L.B.I: (\$) 40,000/-Days Of Repair: 15Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S. R. C.

Photo: 180Other: 078Total: 1149

53x15 = 795

170+795

50

50+50

334

1149

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 23 April 2018 11:19 AM
To: 'Claim Workflow System'
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002958MFSH/1, SHB 2219T
Attachments: SHB 2219T PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SHB 2219T

Date of survey: 20/4/2018

Number of days:15 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 19 April 2018 4:37 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002958MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 19 April, 2018 3:44 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002958MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18002958MFSH
Our ref: CS/FCI18007366/Dvb

Date: 23/4/2018

The Motor Claims Department
M/s First Capital Insurance Limited

Without Prejudice

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 2219T


We thank you for your instruction on 19/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/4/2018 at the premises of M/s CHUNNI MOTOR WORK PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$62,870.36
Revised Estimate Amount	: S\$29,011.68
"Check" Items Amount	: S\$28,375.96
Book Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front and n/s rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Bryan Ang
Motor Surveyor / Investigator

MOTOR SURVEY ASSIGNMENT

Date	18-04-2018	Our Ref No. D18002958MFSH
Accident Date	17-04-2018	Claim Type. Third Party
Insured Vehicle	SHD3526P	Third Party Vehicle. SHB2219T
Survey Location	BLK 10 ANG MO KIO INDUSTRIAL PARK 2AAMK AUTOPOINT #03-19	
Contact Person.	LYNN OR IRENE - 65421726	
Contact No.	64836016/ 0	Fax No. 65426039
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHUNNI MOTOR WORK PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

MCD618051170 / CantorDelGris Engineering Pte Ltd - Leyang
ENTRY DATE & TIME: 18/04/2018 08:57
SUBMITTED BY: Huang XiaoYan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 18/04/2018 08:57
Date Of Accident 17/04/2018 01:20
Exact Location Of Accident SERANGOON RD X TOWNER RD / BOON KENG RD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB2219T
Insured/Policyholder
Name Of Registered Owner CITYCAB PTE LTD
Co Reg No 199502839G
Email Address FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No
Alternative Phone No OFFICE-65508768
Vehicle Particulars
Manufacturer HYUNDAI
Model I40
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category TAXI
Insurance Company
Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy YES
Policy Number D-18088937MFSH
Cover Note Number
Driver
Name of Driver TEO KOK WAH
NRIC No S6846821C
Date Of Birth 08/12/1968
Occupation OUTDOOR
Date Of Driving Pass 18/02/1989
Driving Experience 29 YEARS AND 1 MONTH
Gender MALE
Mobile Number
Fax Number
Contact Number
EMail Address NOEMAIL

Address BLK 525 BEDOK NORTH STREET 3 #10-432
Postcode 460252
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : -
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
POLICE STATION NAME [OTHER] CHANGKAT NPP
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO POLICE REPORT : T/20180417/2088

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD3526P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver TEO HOR KIM
NRIC/Passport Number S0315782B
Contact Number 91019369
Address
Postcode
Insurance Company Name MS FIRST CAPITAL INSURANCE LTD
Nature Of Damage FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category NA/UNKNOWN

Name of Driver CONCRETE

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage NOT SURE

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TEO KOK WAH

Approximate Age 49

Injuries Sustain VARIOUS PAIN ON BODY, ON 3 DAYS MC.

Injured person in which vehicle? SHB2219T

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAB PTE LTD
O. REG. NO. 199502839G



17/4/2018



Policyholder's Signature
Date & Time: 17/4/2018

Driver's Signature
(If driver is not the policyholder) @ 17:30hrs
Date & Time:

Reporting Centre Personnel's Signature
Name: Lisa Diong
NRIC/FIN No.:

Reporting Centre Personnel's Signature
Name: Lisa Diong


**SINGAPORE
POLICE FORCE**


T/20180417/2088

1 of 3

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

Report No. T/20180417/2088

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/04/2018 15:48		Vide Report No.: A/20180417/0014		Station Diary No.: 10	
Informant's Particulars					
Name of Informant: TEO KOK WAH			Address: APT BLK 525 BEDOK NORTH STREET 3 #10-432 SINGAPORE 460525		
ID Type / ID No.: NRIC NO / S6846821C			Contact No.: Home/Office: Mobile: 83055601		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 49	Date of Birth: 08/12/1968	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3,4		Date of Expiry:

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/04/2018 01:20	Type of Location: Straight Road
Location: Along Road 1 SERANGOON ROAD				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB2219T	Car				Totally Damaged	1
SHD3526P	Car				Totally Damaged	0



**SINGAPORE
POLICE FORCE**



T/20180417/2088

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

2 of 3

Report No. T/20180417/2088

CONTINUATION OF REPORT

Brief Details.

On 17 April 2018 at about 1.17am, I was travelling along Serangoon Road towards Upper Serangoon Road with 1 passenger in my taxi (SHB2219T). Upon approaching the junction of Boon Keng Road, I proceeded straight ahead as the traffic light was green. Suddenly, another taxi (SHD3526P) hit onto the left front portion of my taxi at the middle of the junction. He was travelling at a very high speed. As a result of the impact, my taxi hit onto the pillar.

As a result of the accident, my car sustained a totally damaged bonnet and left portion of the taxi damaged as well.

Another driver helped to call the Police.

I had an in-car camera that was recording the incident at that point of time. I have passed the memory card to the traffic police officer who was at the scene.

I went to see a doctor at Tan Tock Seng Hospital and obtained a 3-day MC from 17 April 2018 to 19 April 2018. I have injuries on many various parts of my body.



**SINGAPORE
POLICE FORCE**



T/20180417/2088

3 of 3

Report No. T/20180417/2088

Police Station Of Origin:
Changkat NPP
109 Tampines Street 11 #01-261
SINGAPORE 521109
Tel No: 1800-7819999

CONTINUATION OF REPORT**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sgt 2 WONG TARYN ESMERELDA XIN YI

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
17/04/2018 15:48

Officer In Charge Of Case:
TP / GIT /
Staff Sgt LEE GUANG HU
Contact No.: 65476138

Classification Of Case:

Authentication Stamp
NP188



**SINGAPORE
POLICE FORCE**

SIGNATURE

CHUNNI MOTOR WORK PTE LTD

To Hurley by LKK

REPAIR ESTIMATE*

VEHICLE NO : SHB 2219T

DATE : 18.04.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039 FCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Bonnet <i>fine</i>			\$ 1,526.00	<i>✓</i>
	Bonnet Hinge (LH/RH) <i>Br</i>		\$ 91.30	\$ 182.60	<i>✓</i>
	Bonnet Lock <i>Br</i>			\$ 50.90	<i>✓</i>
	Bonnet Absorber <i>Br</i>		\$ 73.90	\$ 147.80	<i>✓</i>
	Bonnet Insulator <i>cramped</i>			\$ 243.00	<i>✓</i>
	Bonnet Insulator Clips <i>the</i>			\$ 8.40	<i>✓</i>
	Radiator Grille <i>broken</i>			\$ 1,480.00	<i>✓</i>
	Radiator Grille H Emblem <i>missing</i>			\$ 290.80	<i>✓</i>
	Radiator Grille Chrome Moulding <i>broken</i>			\$ 395.50	<i>✓</i>
	Front Bumper Cover <i>distorted</i>			\$ 1,052.20	<i>✓</i>
	Front Bumper Sponge <i>corn</i>			\$ 142.20	<i>✓</i>
	Front Bumper Reinforcement <i>fine</i>			\$ 526.10	<i>✓</i>
	Front Bumper Grille (LH/RH) <i>distorted</i>		\$ 285.50	\$ 571.00	<i>✓</i>
	Front Bumper Grille Airduct (LH/RH) <i>distorted</i>		\$ 155.00	\$ 310.00	<i>✓</i>
	Front Bumper Lip <i>distorted</i>			\$ 62.50	<i>✓</i>
	Front Bumper Bracket Top (LH/RH) <i>the</i>		\$ 22.40	\$ 44.80	<i>✓</i>
	Front Bumper Bracket (LH/RH) <i>the</i>		\$ 24.60	\$ 49.20	<i>✓</i>
	Front Bumper Retainer Mounting <i>the</i>		\$ 9.20	\$ 18.40	<i>✓</i>
	Headlamp Support Top Cover <i>chipped</i>			\$ 398.00	<i>✓</i>
	Headlamp Support Panel Assy <i>broken</i>			\$ 1,067.50	<i>✓</i>
	Headlamp (LH/RH) <i>broken</i>		\$ 1,388.00	\$ 2,776.00	<i>✓</i>
	Headlamp Halogen Bulb (LH/RH) <i>the</i>		\$ 14.40	\$ 28.80	<i>✓</i>
	Radiator <i>pinch</i>			\$ 850.20	<i>✓</i>
	Radiator Fan Blade, Cowling, Motor Assy <i>broken</i>			\$ 792.95	<i>✓</i>
	Radiator Bracket (RH/LH) <i>NA</i>		\$ 6.50	\$ 13.00	<i>X</i>
	Radiator Hose Upper <i>se damaged</i>			\$ 47.40	<i>X</i>
	Radiator Hose Lower <i>se damaged</i>			\$ 47.40	<i>X</i>
	Radiator Expansion Tank <i>Se</i>			\$ 48.00	<i>X</i>
	Radiator Guard <i>broken</i>		\$ 35.00	\$ 70.00	<i>X</i>
	Horn Unit (LH/RH) <i>Dem</i>		\$ 86.75	\$ 173.50	<i>✓</i>
	Horn Wire <i>Dem</i>			\$ 156.50	<i>✓</i>
	Front Fender (LH/RH) <i>Dem</i>		\$ 619.00	\$ 1,238.00	<i>✓</i>
	Front Fender Apron Panel (LH) <i>the</i>			\$ 1,575.50	<i>✓</i>
	Front Fender Shield (LH/RH) <i>turn</i>		\$ 169.80	\$ 339.60	<i>✓</i>
	Aircon Condenser <i>pinch</i>			\$ 1,137.35	<i>✓</i>
	Aircon Suction & Liquid Hose <i>the</i>			\$ 658.90	<i>✓</i>
	Aircon Discharge Hose <i>the</i>			\$ 233.30	<i>✓</i>
	Aircon Compressor <i>the</i>			\$ 2,857.55	<i>✓</i>
	Battery Tray <i>the</i>			\$ 55.45	<i>X</i>
	Front Windscreen Pillar Outer (LH/RH) <i>the</i>		\$ 1,843.10	\$ 3,686.20	<i>1843.10</i>
	Front Wheel Rim (LH) <i>the</i>			\$ 351.90	<i>✓</i>
	Front Wheel Hub Cap (LH) <i>broken</i>			\$ 150.70	<i>✓</i>
	Front Wheel Bearing <i>the</i>			\$ 258.50	<i>✓</i>
	Front Drive Shaft (LH) <i>the</i>			\$ 1,069.55	<i>✓</i>
	Rack & Pinion Assy <i>the</i>			\$ 2,184.00	<i>✓</i>
	STG Tie End <i>the</i>		<i>27477.10</i>	\$ 69.50	<i>✓</i>

SHB 2219T

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Stabilizer Bar <i>SVL</i>			\$ 252.30	<i>✓</i> X
	Stabilizer Bar Bush (LH) <i>SVL</i>			\$ 16.10	<i>✓</i> X
	Stabilizer Bar Link <i># distro</i>			\$ 81.70	<i>✓</i> L
	Stabilizer Bracket <i>SVL</i>			\$ 24.00	<i>✓</i> X
	Front Suspension Lower Arm (LH) <i>distro</i>			\$ 715.10	<i>✓</i> L
	Front Chasis Member <i>RHS</i>			\$ 1,575.85	<i>✓</i> L
	Knuckle Arm (LH) <i>distro</i>			\$ 582.95	<i>✓</i> L
	Engine Mounting <i>2 R</i>			\$ 481.90	<i>✓</i> L
	Engine Under Cover <i>distro</i>			\$ 343.10	<i>✓</i>
	Engine Crossmember <i>distro</i>			\$ 2,236.90	<i>✓</i> L
	Engine Mtg (Rear) <i>1st</i>			\$ 279.60	<i>✓</i> L
	Engine Support Bracket Assy <i>HH</i>			\$ 546.60	<i>✓</i> X
	Gearbox Mounting <i>distro</i>			\$ 342.50	<i>✓</i> L
	Starter Motor Assy <i>Dem</i>			\$ 1,140.00	<i>✓</i> L
	Inter Cooler <i>punctured</i>			\$ 921.90	<i>✓</i>
	Wiring-Engine <i>brake</i>			\$ 3,326.00	<i>✓</i> L
	Wiring-ECM <i>ton</i>			\$ 3,243.00	<i>✓</i> L
	Auto Gear Oil <i>SVL</i>			\$ 110.40	<i>✓</i> X
	Engine Top Cover <i>crack</i>			\$ 386.00	<i>✓</i> L
	Throttle Body Assy <i>crack</i>			\$ 1,096.60	<i>✓</i> L
	Intake Manifold Assy <i>crack</i>			\$ 1,212.40	<i>✓</i> L
	Airbag Complete <i>distro</i>			\$ 2,948.50	<i>✓</i>
	Airbag Control Module <i>distro</i>			\$ 1,894.00	<i>✓</i>
	Steering Angle Assy <i>HH</i>			\$ 1,150.60	<i>✓</i> X
	Front windscreen <i>crack</i>			1059.25	<i>✓</i>
	SUB TOTAL			\$ 54,344.65	
	LESS 20%			\$ 10,868.93	
	DISCOUNTED TOTAL			\$ 43,475.72	
	Front Number Plate <i>missing</i>			\$ 25.00	Nett <i>✓</i>
	Front No Plate Trim Cover <i>missing</i>			\$ 30.00	Nett <i>15/-</i>
	New Battery <i>SVL</i>			\$ 207.00	Nett <i>✓</i>
	Front Door Comfort Logo (LH) <i>HH</i>			\$ 75.00	Nett <i>✓</i>
	Front Windscreen Sealant <i>HH</i>			\$ 46.00	Nett <i>✓</i>
	Front ERP Sticker <i>HH</i>			\$ 26.00	Nett <i>✓</i>
	Front Cushion Seat (RH) <i>HH</i>			\$ 1,500.00	Nett <i>✓</i>
	Gearbox <i>Dem</i>			\$ 8,000.00	Nett <i>✓</i>
	Front Tyre (LH) <i>cut 50%</i>			\$ 216.00	Nett <i>108</i>
				\$ 10,125.00	

SEIB 2219T

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,600.00 1400/-
	Spray Painting Charge			\$ 1,200.00 1000/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 80.00 40/-
	Towing Charge			\$ 50.00 50/-
	Front Chassis Alignment Charge			\$ 120.00 80/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00 180/-
	FRT Wheel Alignment			\$ 80.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 80/-
	Remove/Refix Front Windscreen Glass			\$ 100.00 80/-
	TOTAL LABOUR			\$ 3,630.00
	Rear Bumper			\$ 603.60 ✓
	Rear Fender (LH)			\$ 2,020.10 ✓
	Rear Windscreen Moulding			\$ 60.00 ✓
	Rear Wheel Hub-Cap (LH)			\$ 150.70 ✓
	Stabilizer Bar			\$ 204.60 ✗
	Stabilizer Link			\$ 68.15 ✓
	Rear Upper Arm (LH)			\$ 335.75 ✓
	Rear Lower Arm (LH)			\$ 204.35 ✓
	Rear Knuckle Arm (LH)			\$ 574.80 ✓
	SUB TOTAL			\$ 4,222.05
	LESS 20%			\$ 844.41
	DISCOUNTED TOTAL			\$ 3,377.64
	Rear Windscreen Sealant			\$ 46.00 Nett ✓
	Rear Tyre (LH)			\$ 216.00 Nett ✗
				\$ 262.00
	Labour Charge			
	Panel Beating			\$ 800.00 600/-
	Spray Painting Charge			\$ 600.00 400/-
	Wiring Charge			\$ 50.00 40/-
	Tuff Kote			\$ 50.00 40/-
	Remove/Refix Cushion & Upholstery Rear			\$ 80.00 60/-
	Remove/Refix Rear Windscreen Glass			\$ 100.00 80/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 180/-
	Rear Wheel Alignment			\$ 120.00 80/-
	TOTAL LABOUR			\$ 2,000.00
	ESTIMATE TOTAL			\$ 62,870.36

20/04/2018 @ 1130am
NOT Actual
1/5m 15dys
2 KKK Auto

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18007366/Dvbe2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 27-06-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3526P	Veh. Inspected	SHB 2219T
Policy No.		Coverage (\$)	0.00
Claim No.	D18002958MFSH	Excess (\$)	0.00
Assign From	KAREN TAN	Assign Date	19/04/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU092607	Colour	YELLOW
Odometer	293419	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	5 mm
L/H Front Tyre	205/60 R16	HANKOOK	5 mm
R/H Rear Tyre	205/60 R16	HANKOOK	5 mm
L/H Rear Tyre	205/60 R16	HANKOOK	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND N/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/04/2018	Inspection Date	20/04/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 2219T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	BUCKLED	1,526.00	1,526.00
2	BONNET HINGE (LH/RH) @\$91.30	BENT	182.60	182.60
1	BONNET LOCK	BENT	50.90	50.90
2	BONNET ABSORBER @\$73.90	BENT	147.80	147.80
1	BONNET INSULATOR	CRUMPLED	243.00	243.00
1	BONNET INSULATOR CLIPS	NECESSARY	8.40	8.40
1	RADIATOR GRILLE	BROKEN	1,480.00	1,480.00
1	RADIATOR GRILLE H EMBLEM	MISSING	290.80	290.80
1	RADIATOR GRILLE CHROME MOULDING	BROKEN	395.50	395.50
1	FRONT BUMPER COVER	DISLODGE	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	TORN	142.20	142.20
1	FRONT BUMPER REINFORCEMENT	BUCKLED	526.10	526.10
2	FRONT BUMPER GRILLE (LH/RH) @\$285.50	DISLODGE	571.00	571.00
2	FRONT BUMPER GRILLE AIRDUCT (LH/RH) @\$155.00	DISLODGE	310.00	310.00
1	FRONT BUMPER LIP	DISLODGE	62.50	62.50
2	FRONT BUMPER BRACKET TOP (LH/RH) @\$22.40	NECESSARY	44.80	44.80
2	FRONT BUMPER BRACKET (LH/RH) @\$24.60	NECESSARY	49.20	49.20
2	FRONT BUMPER RETAINER MOUNTING @\$9.20	NECESSARY	18.40	18.40
1	HEADLAMP SUPPORT TOP COVER	DEFORMED	398.00	398.00
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	1,067.50	1,067.50
2	HEADLAMP (LH/RH) @\$1388.00	BROKEN	2,776.00	2,776.00
2	HEADLAMP HALOGEN BULB (LH/RH) @\$14.40	NECESSARY	28.80	28.80
1	RADIATOR	PUNCTURE	850.20	850.20
1	RADIATOR FAN BLADE, COWLING, MOTOR ASSY	BROKEN	792.95	792.95
2	RADIATOR BRACKET (RH/LH) @\$6.50	NOT NECESSARY	13.00	-
1	RADIATOR HOSE UPPER	DEFORMED	47.40	47.40
1	RADIATOR HOSE LOWER	DEFORMED	47.40	47.40
1	RADIATOR EXPANSION TANK	SERVICEABLE	48.00	-
2	RADIATOR GUARD @\$35.00	BROKEN	70.00	70.00
2	HORN UNIT (LH/RH) @\$86.75	DAMAGED	173.50	173.50
1	HORN WIRE	DAMAGED	156.50	156.50

Report Ref No. CS/FCI18007366/Dvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	FRONT FENDER (LH/RH) @\$819.00	DENTED	1,238.00	1,238.00
1	FRONT FENDER APRON PANEL (LH)	BUCKLED	1,575.50	1,575.50
2	FRONT FENDER SHIELD (LH/RH) @\$169.80	TORN	339.60	339.60
1	AIRCON CONDENSER	PUNCTURE	1,137.35	1,137.35
1	AIRCON SUCTION & LIQUID HOSE	BENT	658.90	658.90
1	AIRCON DISCHARGE HOSE	DEFORMED	233.30	233.30
1	AIRCON COMPRESSOR	DISTORTED	2,857.55	2,857.55
1	BATTERY TRAY	NOT NECESSARY	55.45	-
2	FRONT WINDSCREEN PILLAR OUTER (LH/RH) @\$1843.10	O/S BUCKLED / N/S TO REPAIR SEE LABOUR	3,686.20	1,843.10
1	FRONT WHEEL RIM (LH)	DISTORTED	351.90	351.90
1	FRONT WHEEL HUB CAP (LH)	BROKEN	150.70	150.70
1	FRONT WHEEL BEARING	DAMAGED	258.50	258.50
1	FRONT DRIVE SHAFT (LH)	DISTORTED	1,069.55	1,069.55
1	RACK & PINION ASSY	DISTORTED	2,184.00	2,184.00
1	STG TIE END	BENT	69.50	69.50
1	STABILIZER BAR	SERVICEABLE	252.30	-
1	STABILIZER BAR BUSH (LH)	SERVICEABLE	16.10	-
1	STABILIZER BAR LINK	DISTORTED	81.70	81.70
1	STABILIZER BRACKET	SERVICEABLE	24.00	-
1	FRONT SUSPENSION LOWER ARM (LH)	DISTORTED	715.10	715.10
1	FRONT CHASSIS MEMBER	N/S BENT	1,575.85	1,575.85
1	KNUCKLE ARM (LH)	DISTORTED	582.95	582.95
1	ENGINE MOUNTING	BENT	481.90	481.90
1	ENGINE UNDER COVER	DISLODGE	343.10	343.10
1	ENGINE CROSSMEMBER	DISTORTED	2,236.90	2,236.90
1	ENGINE MTG (REAR)	BENT	279.60	279.60
1	ENGINE SUPPORT BRACKET ASSY	NOT NECESSARY	546.60	-
1	GEARBOX MOUNTING	DISTORTED	342.50	342.50
1	STARTER MOTOR ASSY	DAMAGED	1,140.00	1,140.00
1	INTER COOLER	PUNCTURE	921.90	921.90
1	WIRING - ENGINE	BROKEN	3,326.00	3,326.00
1	WIRING - ECM	TORN	3,243.00	3,243.00

Report Ref No. CS/FCI18007366/Dvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	AUTO GEAR OIL	SERVICEABLE	110.40	-
1	ENGINE TOP COVER	CRACKED	386.00	386.00
1	THROTTLE BODY ASSY	CRACKED	1,096.60	1,096.60
1	INTAKE MANIFOLD ASSY	CRACKED	1,212.40	1,212.40
1	AIRBAG COMPLETE	ACTIVATED	2,948.50	2,948.50
1	AIRBAG CONTROL MODULE	ACTIVATED	1,894.00	1,894.00
1	STEERING ANGLE ASSY	NOT NECESSARY	1,150.60	-
1	FRONT WINDSCREEN	CRACKED	1,059.25	1,059.25
1	REAR BUMPER	CUT	603.60	603.60
1	REAR FENDER (LH)	DENTED	2,020.10	2,020.10
1	REAR WINDSCREEN MOULDING	NECESSARY	60.00	60.00
1	REAR WHEEL HUP-CAP (LH)	CRACKED	150.70	150.70
1	STABILIZER BAR	NOT NECESSARY	204.60	-
1	STABILIZER LINK	BENT	68.15	68.15
1	REAR UPPER ARM (LH)	DISTORTED	335.75	335.75
1	REAR LOWER ARM (LH)	DISTORTED	204.35	204.35
1	REAR KNUCKLE ARM (LH)	DISTORTED	574.80	574.80
	LESS 20% DISCOUNT		-11,925.19	-11,072.36
			47,700.76	44,289.44
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	MISSING	25.00	25.00
1	FRONT NO PLATE COVER (SN)	MISSING	30.00	15.00
1	NEW BATTERY (SN)	SERVICEABLE	207.00	-
1	FRONT DOOR COMFORT LOGO (LH) (SN)	NECESSARY	75.00	75.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	FRONT ERP STICKER (SN)	NECESSARY	26.00	26.00
1	FRONT CUSHION SEAT (RH) (SN)	NOT NECESSARY	1,500.00	-
1	GEARBOX (SN)	DAMAGED	8,000.00	4,000.00
1	FRONT TYRE (LH) (50%) (SN)	CUT	216.00	108.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
1	REAR TYRE (LH) (SN)	SERVICEABLE	216.00	-
			10,387.00	4,341.00

Report Ref No. CS/FCI18007366/Dvbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.		2,400.00	2,000.00
	SPRAY PAINTING CHARGE.		1,800.00	1,400.00
	WIRING CHARGE.		100.00	30.00
	TUFF KOTE.		130.00	80.00
	TOWING CHARGE.	NOT NECESSARY	50.00	-
	FRONT CHASSIS ALIGNMENT CHARGE.		120.00	80.00
	REMOVE / REFIX UNDERCARRIAGE (FRT)		200.00	180.00
	FRT WHEEL ALIGNMENT.		80.00	60.00
	REMOVE / REFIX AIRCON & REFILL GAS.		150.00	80.00
	REMOVE / REFIX FRONT WINDSCREEN GLASS.		100.00	80.00
	REMOVE / REFIX CUSHION & UPHOLSTERY REAR.		80.00	60.00
	REMOVE / REFIX REAR WINDSCREEN GLASS.		100.00	80.00
	REMOVE / REFIX UNDERCARRIAGE (RR).		200.00	80.00
	REAR WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			5,630.00	4,210.00
	GRAND TOTAL		63,717.76	52,840.44
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			40,000.00

Report Ref No. CS/FCI18007366/Dvbe2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.