

12/03/2002

ASS. REC. BY:

REF:

CS/MSH/1800-7368/Ugbona

Special Instruction:

Survivor:

MOROS

ASSIGNMENT (Office)

Melimen

From (Person):

Katherine Wong

of

MSH

Date/Time:

19042018 313pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 5662 G

Insured:

YN 7603 U

at Workshop m/s

Liu's Brother

Tel:

of

Blk 1 Kaki Bukit Ave 6 #01-01

Policy No:

29078335MKF

Claim No:

555781

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09042018

CA / REV / REP. / REV 24 HRS WP

20042018

H.O.D. Endorsement:

Date/Time:

19042018 3:42pm

Person Contacted:

Susan

Vehicle:

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GBE 5662 G

- REC / III 17073688 / Ujag

Def: 041217

YN 7603 U - x

23/04/18

@ 15.09pm. revised to Katherine Wong Chew Sheng via merimen.

REF: msh

ASSIGNMENT

From: Date: 20042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBE 56626

at Workshop m/s: Liu's Brothers
of: Bk 1 Kaki Bukit Ave 6 #0101

Insured:

Policy No:


Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

DAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: GBE 56626 Yr Regn: 1 / 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M /

Make: Toyota hiace C.C. 2982

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 78576 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTFHT02P X 00180437

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 1 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 12/4/18 D.O.I. 20/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

23/4/18 Confirmed 2/5 & 2400 with Suban.
(Recd \$3114.70, 5670)
To obtain after car photo
car sum 24/04/2018

RECEIVED 24 APR 2018

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 3

1) 24/4/2018

☐

Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format: MER-TP

Lump Sum / I.B.I: (\$ 2400)

Survey Fee: 150

Transportation: 10

S + RS SI

Photos

Others

TOTAL

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2018		19 Apr 2018 15:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	UNICURD FOOD CO (PRIVATE) LIMITED, Co. Reg. No.: 198000259H		
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	GBE5662G	Date of Loss:	09/04/2018 15:00 - :59 [26 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 555281	Policy/Cover Note No.:	29078335MKF (Comprehensive) Coverage: 01/04/2018 - 31/03/2019
Vehicle Reg. No. (Insured):	YN7603U	Policy No. (Claimant):	
		Excess:	
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 20/04/2018]		
Driver/Custodian (Insured):	NEO CHIN TECK (), NRIC: S7233972Z, Tel: +6596858630		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 23 Apr 2018

Preliminary Advice

Insured Vehicle No	: YN7603U	Accident Date	: 09/04/2018
TP Vehicle No	: GBE5662G	Assignment Date	: 19/04/2018
Make	: TOYOTA HIACE	Est. Duration of Repair	: 3 days
Date of Inspection	: 20/04/2018		
Inspection At	: Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	5,514.70
Revised Amount	:SS	3,065.08
Check Items (Estimated)	:SS	0.00
Total	:SS	3,065.08

Lump Sum Repair	:SS	
-----------------	-----	--

Total Loss Consideration

New for Old Value	:SS	
Pre-Accident Value	:SS	
COE / PARF Rebate	:SS	
Salvage Value	:SS	
Margin for Repair	:SS	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
 Owner ID: 1196N

Vehicle Details

Vehicle No.: GBE5662G
 Vehicle to be Exported: No
 Intended De-registration Date: 19 Apr 2018
 Vehicle Make: TOYOTA
 Vehicle Model: TOYOTA HIACE VAN TURBO 5 DR MANUAL
 Primary Colour: White
 Manufacturing Year: 2015
 Engine No.: 1KD2562478
 Chassis No.: JTFHT02PX00180437
 Maximum Power Output: -
 Open Market Value: \$27,741.00
 Original Registration Date: 18 Jan 2016
 First Registration Date: 18 Jan 2016
 Transfer Count: 1
 Actual ARF Paid: \$1,388.00

Intended PARF Rebate Details

PARF Eligibility: No
 PARF Eligibility Expiry Date: -
 PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Jan 2026
 COE Category: C - Goods Vehicle & Bus
 COE Period(Years): 10
 PQP Paid: \$41,373.00
 COE Rebate Amount: \$32,041.00
 Total Rebate Amount: \$32,041.00

The information contained herein is correct as at 19 Apr 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 1196N

Vehicle Details

Vehicle No.: GBE5662G

Vehicle to be Exported: No

Intended De-registration Date: 20 Apr 2018

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE VAN TURBO 5 DR
MANUAL

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 1KD2562478

Chassis No.: JTFHT02PX00180437

Maximum Power Output: -

Open Market Value: \$27,741.00

Original Registration Date: 18 Jan 2016

First Registration Date: 18 Jan 2016

Transfer Count: 1

Actual ARF Paid: \$1,388.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 17 Jan 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$41,373.00

COE Rebate Amount: \$32,030.00

Total Rebate Amount: \$32,030.00

Message

Please note that the National Environment Agency (NEA) is offering an incentive of up to \$3,500 for owners of older, more pollutive motorcycles which were registered before 1 July 2003, to de-register their motorcycles on or before 5 April 2023.

The last registered owner of this motorcycle will receive \$2,000 if it is de-registered on or before 5 April 2023. If this motorcycle's COE is not renewed on or after 7 April 2018, the last registered owner will receive an additional \$1.500 upon its de-registration on or before 5

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01, Auto Bay @ Kaki Bukit Singapore 417887

HOB No. 512017931, Tel: 6740 1700 - 7311, Fax: 6744 5746, Email: lbr@lbr.com.sg

Invoice/Ref No: GBE5662G180409

Estimate**Customer**

Name: MSIG Insurance (Singapore) Pte Ltd
 Address: Motor Claims Department
 4 Shenton Way #21-01
 SGX Centre 2 Singapore 068807

Date: 19-04-18
 Vehicle No: GBE5662G
 Model/Make: Toyota Hiace Van
 Turbo 5 DR Manual

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate <i>3065.00 / 1927.10</i>	\$ 2,051.60	
2	Tail Lamp <i>11</i>	\$ 365.10	<i>X</i>
3	Bumper <i>30/02</i>	\$ 465.00	
4	Tailgate "8 PAX" Sticker <i>nu</i>	\$ 12.00	SN 10
5	Tailgate "70 KM/H" Sticker <i>nu</i>	\$ 12.00	SN 10
6	Tailgate Windscreen Glass Moulding <i>nu 68</i>	\$ 219.00	
7	Tailgate Windscreen Glass Sealant <i>nu</i>	\$ 50.00	SN 40
8	"Corporate" Advertisement Sticker <i>nu</i>	\$ 800.00	SN 400
	Remove and refix rear tailgate components & wiper mechanism	\$ 80.00	<i>60</i>
	To check all wiring & electrical component for proper function	\$ 60.00	<i>20</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	<i>300</i>
	To putty & spray painting & including touch up paint on accident affected area	\$ 600.00	<i>250</i>
	To apply Rust Proofing, rescal tuff-coating treatment on accident area	\$ 80.00	<i>30</i>
	Remove & reinstall Windscreen Glass to facilitate repairs	\$ 120.00	<i>100</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 5,514.70

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$

SDLS:



M/s Liu's Brother Auto Engrg Wks

not Allowed
L/K/L
2/50 2400
3 day.
20/4/18
the photo after repair

P- 2460.1
1845.07
S.W - 460
Labour - 760
3065.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-059221

Date of Request: 19/04/2018

Your Ref No:

Online Purchase

LIU'S BROTHER AUTO WORKSHOP

1 Kaki Bukit Ave 6 #01-01

Auto Bay@Kaki Bukit

Singapore 417883

Dear Sir/Madam,

Enquiry Date: 19/04/2018
Enquiry By: Susan Low Siew Yian
TP Vehicle No: YN7603U
Accident Date: 10/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
YN7603U	MSIG Insurance (Singapore) Pte. Ltd.	01/04/2018-31/03/2019	+65 6827 7888

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-059221
Date of Request: 19/04/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date: 19/04/2018
Enquiry By: Susan Low Siew Yian
TP Vehicle No: YN7603U
Accident Date: 10/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007368/UQBN2

Date: 25/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29078335MKF
Claimant Vehicle No :	GBE5662G	Insured Vehicle No :	YN7603U
Date of Loss:	09/04/2018	Nature of Claim:	TP
		Claim No:	555281

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE5662G	Engine No:	1KD2562478
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Chassis No:	JTFHT02PX00180437
Reg. Date:	18/01/2016 (Man. Year: 2015)	Odometer:	78576 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15	Rear Tyre Size:	195R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,974.70	2,305.07	1,669.63	42.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,540.00	760.00	780.00	50.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,514.70	3,065.07	2,449.63	44.42
Approved Total (Overridden) (\$\$)		2,400.00		
Nett Amount (\$\$)	5,514.70	2,400.00	3,114.70	56.48

INSPECTION

Date of Assignment:	19/04/2018	
Date Inspected:	20/04/2018 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 25 Apr 2018)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE5662G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	2,051.60 F	*1,927.10 FL
2	1		*REAR TAIL LAMP	Not Necessary	365.10 F	*- FL
3	1		*REAR BUMPER	Dented/Deformed	465.00 F	*465.00 FL
4	1		*REAR TAILGATE WINDSCREEN GLASS MOULDING	Necessary	219.00 F	*68.00 FL
5	1		*REAR TAILGATE 8 PAX STICKER	Necessary	12.00 FS	*10.00 FS
6	1		*REAR TAILGATE 70KM/H STICKER	Necessary	12.00 FS	*10.00 FS
7	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	50.00 FS	*40.00 FS
8	1		*REAR CORPORATE ADVERTISEMENT STICKER	Necessary	800.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,974.70	2,920.10
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	615.03
Total Parts (\$\$)	3,974.70	2,305.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM	New	80.00	60.00
2	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	60.00	20.00
3	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS,ETCS	New	600.00	300.00
4	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS	New	600.00	250.00
5	TO APPLY RUST PROOFING,RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	80.00	30.00
6	REMOVE & REINSTALL WINDSCREEN GLASS TO FACILITATE REPAIRS	New	120.00	100.00
Gross Labour Cost (S\$)			1,540.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >