

22/03/2002

ASS. REC. BY:

REF: CS/MSG18007371/TVb22

Special Instruction:

Surveyor: Paula

ASSIGNMENT (Office)

From (Person): Eng Shu Xiang of MSLH Date/Time: 19/04/2018 353pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGY 2609S Insured: Public Liabilityat Workshop m/s Perfurman Tel: 81214600of 303 Alexandra RdPolicy No: _____ Claim No: MSC/M/18-000125

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13/04/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi'

04052018 @ 10am owner waiting

H.O.D. Endorsement:

Date/Time: 20/04/18 9.0am Person Contacted: Inthiran Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SGY 2609S - x</u>
	<u>Public Liability - x</u>
<u>7/5/18</u>	<u>Email preli revised to Shu Xiang</u>
<u>18/6/18</u>	<u>@ 319 pm Inthiran said vehicle has not send in for repair</u>
<u>18/6/18</u>	<u>Submit preli report</u>

Girgaur

Tanjil

REF: msh

ASSIGNMENT

From: Date: 04052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 56Y 2609S

at Workshop m/s

of

Performance
303 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Tathiran

(Policy Condition)

10 am
owner waitingRemark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Tathiran

Veh No: 56Y2609S Yr Regn: 2012 / out

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW X3

C.C

1997

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

54647

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBSAWX32 0306 B2615

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil 4S/Rim / STD A/Rim or

Tyre Size:

F:

245/50R18

R:

1 7

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIP / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

4/5/18 @ 1030

Survey held at

BMW PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Public Liability, No GIA

RECEIVED 18 JUN 2018

Date/Time, File Pass to?



Prefi. Report



Final Report

1)

Date/Time, File Return to?

2)

18/6 - typst

Report Format:

TP

Lump Sum / I.B.I. (\$)

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation

) \$ + P\$ \$

) Photos

) Others

TOTAL

150

#

150

Catherine Chong (LKK Auto)

From: Ong Shu Xiang <shuxiang_ong@sg.msig-asia.com>
Sent: Thursday, 19 April, 2018 3:53 PM
To: assignments; SUR
Subject: Incident involving SGY2609S at Mount Elizabeth Hospital on 13 April 2018 - MSIG
Ref: MSC/M/18-000125
Attachments: img-417110221-0001.pdf; Photos of the incident.docx

Dear Sirs

We will like LKK to arrange for a survey on a third party vehicle, SGY2609S on a Without Prejudice basis.

Briefly, the vehicle SGY2609S was hit by concrete fallen from the ceiling on its left side whilst it was parked in our Insured's carpark. We are enclosing these documents for your review:-

1. Repair estimate from Performance Motors
2. Coloured photographs taken on the day of the incident

We understand that the vehicle is currently not in the workshop.

Please contact Mr Inthiran of Performance Motors at 8121 4600 to arrange for the survey.

Thank you.

Ong Shu Xiang
Executive, Claims Services
D: +65 6643 1337 | F: +65 6643 1349 | shuxiang_ong@sg.msig-asia.com



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 7 May 2018 1:52 PM
To: 'Ong Shu Xiang'
Cc: SUR
Subject: RE: Incident involving SGY2609S at Mount Elizabeth Hospital on 13 April 2018 - MSIG Ref: MSC/M/18-000125
Attachments: SGY 2609S PRELI REVISED.pdf

Dear Shu Xiang,

Enclosed preliminary revised of vehicle SGY 2609S
Date of survey: 4/5/2018
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Friday, 20 April 2018 9:07 AM
To: 'Ong Shu Xiang' <shuxiang_ong@sg.msig-asia.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Incident involving SGY2609S at Mount Elizabeth Hospital on 13 April 2018 - MSIG Ref: MSC/M/18-000125

Dear Shu Xiang,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ong Shu Xiang [mailto:shuxiang_ong@sg.msig-asia.com]
Sent: Thursday, 19 April, 2018 3:53 PM
To: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Incident involving SGY2609S at Mount Elizabeth Hospital on 13 April 2018 - MSIG Ref: MSC/M/18-000125

Dear Sirs

We will like LKK to arrange for a survey on a third party vehicle, SGY2609S on a Without Prejudice basis.

Briefly, the vehicle SGY2609S was hit by concrete fallen from the ceiling on its left side whilst it was parked in our Insured's carpark. We are enclosing these documents for your review:-

1. Repair estimate from Performance Motors
2. Coloured photographs taken on the day of the incident

We understand that the vehicle is currently not in the workshop.

Please contact Mr Inthiran of Performance Motors at 8121 4600 to arrange for the survey.

Thank you.

Ong Shu Xiang

Executive, Claims Services

D: +65 6643 1337 | F: +65 6643 1349 | shuxiang_ong@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: MSC/M/18-000125
Our ref: CS/MSG18007371/T1vb

Date: 7/5/2018

The Motor Claims Department
M/s: MSIG Insurance Singapore Pte Ltd

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SGY 2609S


We thank you for your instruction on 19/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 4/5/2018 at the premises of M/s Performance Motors Ltd and have the following to report:-

Workshop Estimate Amount	: S\$3,160.00
Revised Estimate Amount	: S\$2,505.00
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automobile Assessor

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46627
Date Estimated : 17/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -

Sharmila Chauhan
7 Siglap Road
#18-53

Singapore 448909

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGY2609S	0B26115	31/10/2012	X3 xDrive20i	0

DESCRIPTION

To repair rear right fender.

VALUE

850 1,275.00

Painting rear right fender and roof frame.

1465 1,628.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

40 80.00

Total Labour 1: 3,160.00

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 4/5/18 @ 1030 Excess S\$ _____

Surveyor's Name Tanjun Sign _____

Surveyor's Tel 97495749 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail tanjun@lkkauto.com

No. of Working Days Recommend 4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Labour 1	:	3,160.00
Parts	:	0.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	221.20
Grand Total	:	3,381.20

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18007371/T1vbe2	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 19-06-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PUBLIC LIABILITY		Veh. Inspected	SGY 2609S
Policy No.			Coverage (\$)	0.00
Claim No.	MSC/M/18-000125		Excess (\$)	0.00
Assign From	ONG SHU XIANG		Assign Date	19/04/2018
2. Vehicle Particulars & Condition				
Make & Model	BMW X3		c.c	1997
Engine No.	HIDDEN		Year of Reg.	2012
Chassis No.	WBAWX320300B26115		Colour	WHITE
Odometer	54647		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R18	PIRELLI	6 mm	
L/H Front Tyre	245/50 R18	PIRELLI	6 mm	
R/H Rear Tyre	245/50 R18	PIRELLI	6 mm	
L/H Rear Tyre	245/50 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/04/2018		Inspection Date	04/05/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGY 2609S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	NECESSARY		
	SUNDRIES (SN)		80.00	40.00
			80.00	40.00
	<u>LABOUR</u>			
	TO REPAIR REAR RIGHT FENDER.		1,275.00	850.00
	PAINING REAR RIGHT FENDER AND ROOF FRAME.		1,628.00	1,465.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.		177.00	150.00
			3,080.00	2,465.00
GRAND TOTAL			3,160.00	2,505.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				2,505.00

Report Ref No. CS/MSG18007371/T1vbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.