

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





| NTUC INCOME INSURANCE CO-OPERATIVE LTD | | | Ref: | NS/INC18007408/Nrbn2 | | |
|--|---|--------------------------------------|---------------|----------------------|--------------------|--|
| 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 | | | Date: | 04-05-2018 INC4 | | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | SHC 6794S | Veh. Ir | nspected | SH 6314M | |
| | Policy No. | 5095103893 | Coverage (\$) | | 0.00 | |
| | Claim No. | MT/0991056-002 | Exces | s (\$) | 0.00 | |
| | Assign From | | Assign | n Date | 20/04/2018 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | HYUNDAI SONATA | c.c | | 1991 | |
| | Engine No. | HIDDEN | Year o | f Reg. | 2012 | |
| | Chassis No. | KMHET41VMCA822744 | Colou | r | BLUE | |
| | Odometer | 406828 | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modifi | cation | STANDARD ALLOY RIM | |
| | General | FAIR | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/60 R16 | WEST | LAKE | 4 mm | |
| | L/H Front Tyre | 215/60 R16 | WEST | LAKE | 4 mm | |
| | R/H Rear Tyre | 215/60 R16 | WEST | | 4 mm | |
| | L/H Rear Tyre | 215/60 R16 | WEST | | 4 mm | |
| 4. | | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 19/04/2018 | Inspec | tion Date | 20/04/2018 | |
| | Survey held at | at COMFORTDELGRO ENGINEERING PTE LTD | | | | |
| | | 59 LOYANG DRIVE SINGAPORE 508969 | | | | |
| 5a. | 5a. Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. Estimate Days of Repair | | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days | | | | | |