

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/FWD18007411/GQBE2

**Date:** 18/09/2018

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2016-00000214-01

**Claimant Vehicle No :** SDA8336B **Insured Vehicle No :** SLF3604P

Date of Loss: 19/04/2018 Nature of Claim: TP Claim No: 1201800004851

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SDA8336B</b>		
Make & Model:	PORSCHE BOXSTER, 2.7 (A)	Engine No:	65V06590
Reg. Date:	26/05/1997 (Man. Year: 1997)	Chassis No:	WPOZZZ98ZVS603944
Colour:	Yellow	Odometer:	115955 km
Engine Capacity:	2480 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	600.00	1,950.00	76.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>2,550.00</b>	<b>600.00</b>	<b>1,950.00</b>	<b>76.47</b>

### INSPECTION

Date of Assignment:	23/04/2018	
Date Inspected:	24/04/2018	Inspected At: Flatsix Pte Ltd (HQ) B/176 Sin Ming Drive #02-16 Singapore 575721
Estimated Period of Repair:	2.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 18 Sep 2018)

**Parts:** M1-COUPE      PORSCHE BOXSTER 2.7 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SDA8336B)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REPAIR LEFT DOOR, ADJUST AND ALIGN LEFT DOOR	New	800.00	100.00
2	TO PUTTY, PREP AND RESPRAY LEFT DOOR	New	400.00	200.00
3	TO REPAIR LEFT FRONT FENDER	New	800.00	100.00
4	TO PUTTY, PREP AND RESPRAY LEFT FRONT FENDER	New	400.00	200.00
5	COMPUTERISED WHEEL ALIGNMENT	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>2,550.00</b>	<b>600.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >