

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18007412/GZ4BS2
Date: 08/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100469098
Claimant Vehicle No : SKP6802Z **Insured Vehicle No :** SLD8861R
Date of Loss: 17/04/2018 Nature of Claim: TP Claim No: 6184156710SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP6802Z**
Make & Model: VOLKSWAGEN JETTA, 1.4 TSI (A) Engine No: CAXE85017
Reg. Date: 30/09/2014 (Man. Year: 2014) Chassis No: WVVZZZ16ZEM059100
Colour: Black Odometer: 117639 km
Engine Capacity: 1390 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/04/2018
Date Inspected: 23/04/2018 Inspected At: Gforce Autotechnik Pte Ltd (HQ)
10 Kaki Bukit Road 2, #01-34 First East Centre
Singapore 417866
Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Damaged	0.00 F	*- F	
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
3	1		*REAR BUMPER BRACKET INNER	Broken	0.00 F	*- F	
4	1		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F	
5	1		*REAR BUMPER REFLECTOR	Scratched	0.00 F	*- F	
6	1		*REAR BUMPER LOWER SPOILER	Cut	0.00 F	*- F	
7	1		*REVERSE SENSOR	Short Circuit	0.00 F	*- F	
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F	
9	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F	
10	1		*BOOTLID	Repair	0.00 F	*- F	
11	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F	
12	1		*BOOTLID LAMP RH	Scratched	0.00 F	*- F	
13	1		*BOOTLID LOCK	Dented	0.00 F	*- F	
					Total Parts (\$\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >