



Car Times Autolution Pte Ltd (Co.Reg.No:20165716G)
160 Sin Ming Drive,
#02--04
AutoCity
Singapore 575722

Tel: 6471 5111 Email: claims@cartimes.com.sg

INSURER: AXA

PARTICULARS OF CLAIM

| | | | |
|-------------------------------|------------------------|-----------------------|-------------------|
| Claim Type: | OD (OWN DAMAGE) | Ref. No: | |
| Policy No: | GA239841/1 | Date of Accident: | 15/4/2018 |
| Vehicle Reg. No.: | SKH 9798 A | Driveable? | YES |
| Driver Age/Info: | 48/MALE | Party At Fault: | DRIVER |
| TP Injury Involved? | NO | Third Party Involved? | YES |
| Insured/Claimant: | KELVIN TAN CHEOW CHONG | Contact No: | +65 9764 2764 |
| Driver: | KELVIN TAN CHEOW CHONG | | |
| Make/Model: | MERCEDES GLC 250 | Vehicle Reg. Date: | 7 JUL 2017 |
| Vehicle Colour: | WHITE | Chassis No: | WDC2533462F190633 |
| Engine No: | 27492030906357 | | |
| Total Loss? | 5 days | | |
| Est. Duration of Repair (day) | | | |

Description of Accident/Loss: PLEASE SEE ATTACHED SKETCH
Present Location: CAR TIMES AUTOLUTION PTE LTD

| COST OF CLAIMS | Amount |
|------------------------------|----------------|
| Parts | 8050.90 |
| Special Nett Items | 85.00 |
| Labour | 1280.00 |
| Calculated Gross Total (S\$) | 9415.90 |
| - Excess (S\$) | -500.00 |
| Nett Amount (S\$) | 8915.90 |
| + GST (S\$) | 624.11 |
| Total (S\$) | 9540.00 |

Estimates on Parts

| NO. | QTY | DESCRIPTION | CONDITION | REPAIRER'S ESTIMATE(\$) | SURVEYOR'S ADJUSTMENT |
|-------------------------|-----|---------------------------|-----------|----------------------------|--------------------------|
| PARTS | | | | | |
| 1 | 1 | TOWING EYE COVER | Damaged | 33.00 | |
| 2 | 1 | IMPACT ABSORBER | Damaged | 63.00 | |
| 3 | 1 | CONSOLE | Damaged | 26.00 | |
| 4 | 1 | COVER BUMPER | Damaged | 58.00 | |
| 5 | 1 | BASIC MOUNTING | Damaged | 90.00 | |
| 6 | 1 | BASIC MOUNTING 2538852200 | Damaged | 47.00 | |
| 7 | 1 | HOOD | Damaged | 982.00 | |
| 8 | 1 | FRONT FENDER | Damaged | 490.00 | |
| 9 | 1 | TRIM BUMPER | Damaged | 775.00 | |
| 10 | 1 | HEADLAMP UNIT | Damaged | 1458.00 | |
| 11 | 1 | RADIATOR GRILLE FRAME | Damaged | 135.00 | |
| 12 | 1 | ORNAMENTAL | Damaged | 92.00 | |
| 13 | 1 | ORNAMENTAL | Damaged | 92.00 | |
| 14 | 1 | ORNAMENTAL GRILLE | Damaged | 92.00 | |
| 15 | 1 | ORNAMENTAL GRILLE | Damaged | 92.00 | |
| 16 | 1 | PROTECTIVE GRILLE | Damaged | 123.00 | |
| 17 | 1 | ORNAMENTAL | Damaged | 31.00 | |
| 18 | 1 | ORNAMENTAL | Damaged | 31.00 | |
| 19 | 1 | BEAM | Damaged | 37.00 | |
| 20 | 1 | MERCEDES STAR | Damaged | 27.00 | |
| 21 | 1 | TRIM BUMPER | Damaged | 28.00 | |
| 22 | 1 | AIR FLOW SERRATION | Damaged | 26.00 | |
| 23 | 1 | AIR DUCT SEGMENT | Damaged | 15.00 | |
| 24 | 1 | COMPANY SIGN | Damaged | 33.00 | |
| 25 | 1 | CROSS MEMBER | Damaged | 195.00 | |
| 26 | 1 | LICENSE PLATE | Damaged | 60.00 | |
| 27 | 1 | HEADLAMP UNIT | Damaged | 1458.00 | |
| 28 | 2 | DISTANCE SENSOR | Damaged | 170.00 | |
| 29 | 1 | ORNAMENTAL MOULDING | Damaged | 230.00 | |
| 30 | 1 | CONTROL UNIT | Damaged | 330.00 | |
| Sub total | | | | 7319.00 | |
| + Margin on items (10%) | | | | 731.90 | |
| Total parts | | | | 8050.90 | |

*****SUPPLEMENTRY PARTS TO CONFIRM AFTER DISMANTLING *****

| NO. | QTY | DESCRIPTION | CONDITION | REPAIRER'S ESTIMATE(\$\$) | SURVEYOR'S ADJUSTMENT |
|-------------------------------|--------|-----------------------------|-----------|------------------------------|--------------------------|
| SPECIAL NETT ITEMS | | | | | |
| 1 | 1 sets | Front bumper clips | Necessary | 40.00 | |
| 2 | 1 | Front number plate w/holder | Necessary | 45.00 | |
| Total special nett | | | | 85.00 | |

| S/N | DESCRIPTION | REPAIRER'S ESTIMATE (\$\$) | SURVEYOR'S ADJUSTMENT |
|----------------------------|--|-------------------------------|--------------------------|
| LABOUR | | | |
| 1 | To remove the affected parts & fittings to commence repairs; replace damaged parts and components | 500.00 | |
| 2 | To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired | 600.00 | |
| 3 | To remove and re-refix wiring and check all electrical components at Damaged areas for proper functions. | 20.00 | |
| 4 | To remove and replace front bumper sensor & check for proper function. | 60.00 | |
| 5 | Perfrom diagnois on vehicle | 100.00 | |
| Gross labour cost : | | 1280.00 | |
| | | | |
| | | | |

IMPORTANT NOTE: SUPPLEMENTARY PARTS & LABOUR

Additional parts and labour charges will be included to this initial estimate when parts (which are hidden) are confirmed damaged after dismantling the damaged areas.