

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18007425/APS3Q2

Date: 14/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLR5285A	Insured Vehicle No :	SHD3575Y
Date of Loss: 19/04/2018	Nature of Claim: TP	Claim No: MCT18040537

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR5285A		
Make & Model:	TOYOTA SIENTA HYBRID, 1.5 X CVT (A)	Engine No:	1NZR516008
Reg. Date:	17/08/2017 (Man. Year: 2017)	Chassis No:	NHP1707088352
Colour:	Black	Odometer:	54068 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,107.76	7,966.51	5,141.25	39.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,890.00	2,730.00	1,160.00	29.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,997.76	10,696.51	6,301.25	37.07
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	16,997.76	7,500.00	9,497.76	55.88
+ GST 7.00/7.00% (S\$)	1,189.84	525.00	664.84	55.88
Nett Amount (S\$)	18,187.60	8,025.00	10,162.60	55.88
+ Loss of Use (9.0 x S\$60.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,572.45		

INSPECTION

Date of Assignment:	20/04/2018	
Date Inspected:	20/04/2018 Inspected At:	MG Solution Pte Ltd (HQ) 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre Singapore 415933
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Oct 2019)
Parts:	M1-MPV	TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR5285A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Dented	420.00 FL	*420.00 FL
2	1		*FRONT WHEEL COWLING LH	Deformed	195.45 FL	*195.45 FL
3	1		*FRONT FENDER EMBLEM LH HYBRID	Necessary	70.50 FL	*70.50 FL
4	1		*FRONT DOOR LH	Distorted	1,200.00 FL	*1,200.00 FL
5	1		*FRONT DOOR HINGE (UPPER) LH	Not Necessary	90.30 FL	*- FL
6	1		*FRONT DOOR HINGE (LOWER) LH	Not Necessary	90.30 FL	*- FL
7	1		*FRONT DOOR LOCK	Damaged	501.20 FL	*501.20 FL
8	1		*FRONT DOOR LOCK CATCH	Not Necessary	62.00 FL	*- FL
9	1		*FRONT DOOR INNER BOARD LH	Cracked	800.30 FL	*800.30 FL
10	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	90.30 FL	*- FL
11	1		*FRONT POWER WINDOW MOTOR LH	Not Necessary	563.40 FL	*- FL
12	1		*FRONT POWER WINDOW REGULATOR LH	Damaged	422.30 FL	*422.30 FL
13	1		*ROCKER PANEL LH	Dented	890.00 FL	*890.00 FL
14	1		*CENTER PILLAR LH	Dented	630.00 FL	*630.00 FL
15	1		*REAR SLIDING DOOR LH	Dented	1,950.00 FL	*1,232.80 FL
16	1		*REAR DOOR LOCK LH	Damaged	960.30 FL	*380.40 FL
17	1		*REAR DOOR LOCK CATCH LH	Not Necessary	60.30 FL	*- FL
18	1		*REAR DOOR INNER BOARD LH	Cracked	750.30 FL	*750.30 FL
19	1		*REAR SLIDING DOOR GARNISH LH	Cut	260.00 FL	*260.00 FL
20	1		*REAR SLIDING DOOR MOTOR LH	Damaged	1,850.00 FL	*980.00 FL
21	1		*SLIDING DOOR WEATHERSTRIP LH	Not Necessary	680.20 FL	*- FL
22	1		*REAR WINDOW POWER WINDOW MOTOR	Not Necessary	650.30 FL	*- FL
23	1		*REAR WINDOW POWER WINDOW REGULATOR	Not Necessary	530.00 FL	*- FL
24	1		*FRONT KNUCKLE ARM WITH BEARING LH	Damaged	605.40 FL	*605.40 FL
25	1		*FRONT LOWER ARM LH	Bent	616.70 FL	*616.70 FL
26	1		*FRONT STABILIZER LINK LH	Not Necessary	180.50 FL	*- FL
27	1		*FRONT SHOCK ABSORBER LH	Not Necessary	490.30 FL	*- FL
28	1		*SET FRONT FENDER INNER COWLING CLIPS	Necessary	25.00 FS	*25.00 FS
29	1		*SET FRONT DOOR INNER BOARD CLIPS	Necessary	25.00 FS	*25.00 FS
30	1		*REAR DOOR GARNISH CLIPS	Necessary	25.00 FS	*25.00 FS
31	1		*SET REAR DOOR INNER BOARD LH	Necessary	25.00 FS	*25.00 FS
32	1		*WHEEL TYRE	Not Necessary	450.00 FS	*- FS
33	1		*WHEEL RIM	Cut	850.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	17,010.35	10,455.35
- List Item Discount on L Items 25.00/25.00% (S\$)	3,902.59	2,488.84
Total Parts (S\$)	13,107.76	7,966.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	1,200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	1,000.00
3	TUFF COAT	New	80.00	60.00
4	TO REMOVE AND REFIX FRONT AND REAR DOOR FITTING	New	280.00	160.00
5	WIRING CHECK	New	80.00	30.00
6	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	New	350.00	200.00
7	WHEEL ALIGNMENT	New	100.00	80.00
Gross Labour Cost (S\$)			3,890.00	2,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >